

CRREL


REPORT 86-17



**US Army Corps
of Engineers**

Cold Regions Research &
Engineering Laboratory

Atmospheric icing on communication masts in New England



CRREL Report 86-17

December 1986



Atmospheric icing on communication masts in New England

Nathan D. Mulherin

REPORT DOCUMENTATION PAGE

Form Approved
OMB No. 0704-0188
Exp. Date: Jun 30, 1986

1a. REPORT SECURITY CLASSIFICATION Unclassified		1b. RESTRICTIVE MARKINGS	
2a. SECURITY CLASSIFICATION AUTHORITY		3. DISTRIBUTION / AVAILABILITY OF REPORT Approved for public release; distribution is unlimited.	
2b. DECLASSIFICATION / DOWNGRADING SCHEDULE		4. PERFORMING ORGANIZATION REPORT NUMBER(S) CRREL Report 86-17	
4. PERFORMING ORGANIZATION REPORT NUMBER(S)		5. MONITORING ORGANIZATION REPORT NUMBER(S)	
6a. NAME OF PERFORMING ORGANIZATION U.S. Army Cold Regions Research and Engineering Laboratory	6b. OFFICE SYMBOL (if applicable) CRREL	7a. NAME OF MONITORING ORGANIZATION Office of the Chief of Engineers	
6c. ADDRESS (City, State, and ZIP Code) Hanover, New Hampshire 03755-1290		7b. ADDRESS (City, State, and ZIP Code) Washington, D.C. 20314-1000	
8a. NAME OF FUNDING / SPONSORING ORGANIZATION	8b. OFFICE SYMBOL (if applicable)	9. PROCUREMENT INSTRUMENT IDENTIFICATION NUMBER	
8c. ADDRESS (City, State, and ZIP Code)		10. SOURCE OF FUNDING NUMBERS	
		PROGRAM ELEMENT NO. 6.11.02A	PROJECT NO. 4A16- 1102AT24
		TASK NO. FS	WORK UNIT ACCESSION NO. 005
		6.27.30A	4A762730- AT42
11. TITLE (Include Security Classification) ATMOSPHERIC ICING ON COMMUNICATION MASTS IN NEW ENGLAND		SS	002, 003
12. PERSONAL AUTHOR(S) Nathan D. Mulherin			
13a. TYPE OF REPORT	13b. TIME COVERED FROM _____ TO _____	14. DATE OF REPORT (Year, Month, Day) December 1986	15. PAGE COUNT 52
16. SUPPLEMENTARY NOTATION			
17. COSATI CODES		18. SUBJECT TERMS (Continue on reverse if necessary and identify by block number)	
FIELD	GROUP	SUB-GROUP	
			Antennas Cold weather Icing
			Atmospheric precipitation Ice Radio towers
			Cold regions Ice formation
19. ABSTRACT (Continue on reverse if necessary and identify by block number) Rime icing and freezing precipitation are of concern to the radio and television broadcasting industry. This report contains the results of a study seeking to document the severity and extent of transmitter tower icing and related problems in the northeastern United States. Information was obtained via mail questionnaire and telephone interviews with 85 station owners and engineers concerning 118 different stations. Results show that television and FM broadcasters are seriously impacted by tower icing; however, AM operators are usually not affected by expected New England icing levels. Combined annual costs for icing protection and icing-related repairs averaged \$121, \$402 and \$3066 for AM, FM and TV stations respectively. None of the AM stations polled employ any icing protection measures whereas all the TV stations do. The percentage of FM stations having icing protection in the three northern states averaged 80%, indicating a significant concern for icing in that region. In contrast, the percentage of FM stations with icing protection was 63.5% for the southern New England states. The usage of guyed versus non-guyed towers was a poor indicator of icing costs. However, the factors of increasing mast height and mast top elevation are significant to increasing costs. The data show that stations with mast			
20. DISTRIBUTION / AVAILABILITY OF ABSTRACT <input checked="" type="checkbox"/> UNCLASSIFIED/UNLIMITED <input type="checkbox"/> SAME AS RPT. <input type="checkbox"/> DTIC USERS		21. ABSTRACT SECURITY CLASSIFICATION Unclassified	
22a. NAME OF RESPONSIBLE INDIVIDUAL Nathan D. Mulherin		22b. TELEPHONE (Include Area Code) 603-646-4260	22c. OFFICE SYMBOL CRREL-RS

19. Abstract (cont'd).

heights greater than 275 m (900 ft) and top elevations exceeding 760 m (2500 ft) above mean sea level are at risk and need icing protection. Ocean proximity seemed to have a moderating influence on icing: average costs were \$341 for FM stations within 5 km of the coast, versus \$472 per year for all FM stations with icing protection. Annual icing costs for all AM stations averaged \$121 compared to \$75 for coastal AM stations. Current methods of icing protection and their efficiency are discussed herein.

PREFACE

This report was prepared by Nathan D. Mulherin, Research Physical Scientist, Snow and Ice Branch, Research Division, U.S. Army Cold Regions Research and Engineering Laboratory, Hanover, New Hampshire.

Funding for this work was provided under DA Project 4A762730AT42, *Design, Construction, and Operations Technology for Cold Regions*, Task Area SS, *Combat Service Support*, Work Units 002, *Mechanical Design for Icing Environments*, and 003, *Atmospheric Icing Alleviation*. Funding was also provided under DA Project 4A161102AT24, *Research in Snow, Ice and Frozen Ground*, Task Area FS, *Fire Support*, Work Unit 005, *Cold Regions Meteorological Processes*.

The author thanks Stephen Ackley and Michael Ferrick of the Snow and Ice Branch for continued support and encouragement and technical review of this work; Gioia Cattabriga for editorial review; Mary Maxfield for preliminary data collection; and Elizabeth Holt and Mary Manning for data collection. Special thanks are extended to Paul Hurd (WHDH Corporation, Boston, Massachusetts) for sharing observations and photographs of icing at his station, and to Clement Payeur (WCSH-TV, Portland, Maine) and Dr. Kazuhiko Itagaki (CRREL) for their photographic contributions.

CONTENTS

	Page
Abstract	i
Preface	iii
Introduction	1
Background	1
Types of accretions.....	1
Problems caused by icing.....	2
Prevention and shedding methods.....	4
Results.....	7
The survey.....	7
Data presentation.....	9
Discussion.....	12
Survey response distribution.....	12
Effect of icing protection on parameter averages.....	14
Effect of tower type on parameter averages.....	15
Moderate and more severe icing locations.....	18
Relationship of climate, geography and topography to icing severity.....	20
Total annual costs.....	21
Conclusions	21
Literature cited.....	22
Appendix A: Tower icing survey.....	25
Appendix B: Station summaries.....	31

ILLUSTRATIONS

Figure

1. Wreckage of WCSH-TV's 1300-ft tower felled by severe icing on 9 March 1983.....	3
2. Radomes over microwave relays following a riming event on the summit of Mt. Washington	5
3. Radio and TV towers at the summit of Mt. Washington.....	6
4. Tower locations of all stations responding to the survey.....	8
5. Station response to survey.....	14
6. Icing-related station costs.....	16
7. Icing-related station costs (with and without icing protection).....	16
8. Icing protection.....	17
9. Icing-related station costs (guyed vs non-guyed towers).....	18
10. Tower locations of stations with moderate and more severe icing.....	19

TABLES

Table

1. Types and properties of atmospheric ice.....	2
2. Details of mast installations of all respondents.....	10
3. Stations with moderate and more severe icing grouped by degree of icing.....	13
4. Parameter averages.....	15

Atmospheric Icing on Communication Masts in New England

NATHAN D. MULHERIN

INTRODUCTION

Much research has been conducted on the phenomenon of atmospheric ice accretion on structures. However, relatively little investigation has focused on the problem specific to television and radio transmission disruption. Atmospheric icing of radio and television towers has long been recognized by broadcasters as a source of numerous problems. These problems range in severity from transmission distortion (which may or may not be significant) to complete tower collapse, and include structural fatigue, stretching and wearing of guy lines, and equipment damage from falling ice. Ice sometimes forms between antenna radiating elements, causing electrical shorting and equipment burnout. Installations near populated areas have the added liability for falling ice damage to life and surrounding property.

This report presents summarized information obtained through telephone and mail inquiries to 85 owners, engineers and other station personnel throughout New England regarding their experiences with atmospheric icing. The purpose of our inquiry was to assess four areas of interest:

1. The industry's concern regarding ice accretion on towers
2. The current methods used to prevent or control disruption to normal operations
3. The success of these methods
4. The influence of geographic, topographic and climatic factors on the severity of icing on these structures.

BACKGROUND

Types of accretions

For maximum radiating capability, radio and television antennas are often situated in elevated locations that are subject to wind and storms. Ex-

posed structural members provide a site for the accumulation of supercooled moisture from the atmosphere and subsequent icing. Two sources of atmospheric ice accretion are recognized: 1) in-cloud icing, where the supercooled droplets are small enough to remain suspended, and contact with a surface is brought about by air movement; 2) precipitational icing, where the droplets are massive enough to fall from the atmosphere onto the accreting surface. Precipitational icing may give rise to either rime or glaze ice buildup. In-cloud icing, however, can produce these and a third condition known as "frost." Frosting occurs during very quiet air conditions whereby a surface collects moisture from the air directly from the vapor phase. The resulting growth of fine-crystallized ice is usually slight in thickness due to the limited availability of moisture at low temperatures and to a low vapor flux to the surface with the lack of air circulation. Frosting creates no major problems in broadcasting and will not be considered further in this study.

Glaze ice is usually the product of freezing rain or of airborne spray from nearby bodies of water (precipitational icing) accreting at relatively high temperatures (0° to -3°C). It appears on surfaces as a tightly bonded, clear, glass-like coating, and is very dense ($\geq 0.9 \text{ Mg/m}^3$, the density of pure ice being 0.92). It may or may not be uniform in thickness because icicles often form on the underside of an object as the water flows before freezing. The factors which favor its formation are large droplet size, rapid accretion rate, low degree of supercooling, and slow latent heat dissipation after contact. This type of icing is the most serious threat to structures due to its density and the large additional loads it can impart. Damage from falling ice and tower failures is most likely to occur during and after glaze ice storms.

Rime formation occurs more frequently in mountainous areas than does glaze and therefore

Table 1. Types and properties of atmospheric ice. After MEP Limited (1984), Minsk (1980) and Makkonen (1984).

<i>Types of ice</i>	<i>Appearance</i>	<i>Density (Mg/m³)</i>	<i>Conditions</i>
Glaze	Clear, smooth, hard ice, tightly bonded to surface. Usually icicles present.	> 0.9	Air temperatures near 0°C, windspeeds of 1-20 m/sec, surface temperature of accreting surface = 0°C.
Hard rime	Hard, granular white or translucent ice growing outward from the windward side of accreting surface.	0.6-0.9	Air temperatures approximately -3 to -8°C, windspeeds of 5-10 m/sec, surface temperature of accreting surface < 0°C. Droplets flow and coalesce somewhat before freezing.
Soft rime	Opaque-white, feathery, granular ice, loosely bonded and growing outward from the windward side of accreting surface.	< 0.6	Air temperatures approximately -5 to -25°C, windspeeds of 1-5 m/sec. Supercooling rate is high enough that droplets freeze immediately on contact.

the total number of damaging events, while less serious, is probably higher for rime. Rime ice varies from “soft” to “hard” depending on its density, clarity, and crystal structure. Its formation is favored by small droplet size, slow accretion rate, a high degree of supercooling, and rapid dissipation of latent heat. Soft rime forms at lower temperatures (-5° to -25°C) and low windspeeds (1 to 5 m/s). The impinging droplets freeze very quickly, trapping air as the accretion grows. The large amount of entrapped air is responsible for its opaque-white and fluffy appearance. Close examination often reveals a delicate needle-like or dendritic structure. Due to its lower density (0.6 Mg/m³ or less), soft rime is a lesser problem for broadcasters. Hard rime, on the other hand, is intermediate to glaze and soft rime in terms of its density, clarity, and hardness. It is formed at more moderate temperatures (-3° to -8°C) and higher windspeeds (5 to 10 m/s). The impinging droplets flow somewhat before freezing, which creates a smoother appearance. The slower freezing rate allows less air to be entrapped as the ice is forming, resulting in a translucent, denser structure (0.6 to 0.9 Mg/m³). The preceding descriptions of the various accretion types are summarized in Table 1.

Bennett (1959) points out that icing on structures is not limited to only one type. Instead, surface features such as shape, exposure, heat dissipation characteristics, etc. can contribute to the buildup of various ice types.

Problems caused by icing

Rime icing and freezing precipitation annually cause many thousands of dollars in damages to

stations in New England. Transmitter tower icing is a normal component of operating costs for most broadcasters in northern latitudes. However, an acceptable level of risk must be decided upon in balancing initial construction cost against future maintenance. Generally, station engineers must devise their own icing protection based on field experience. Prior to construction, one may use the Electronic Industries Association (EIA) Standard RS-222-C or a number of other available reports which discuss design load calculations (Glukov 1971, 1974, Williamson 1973, Chaine et al. 1974, Chaine and Skeates 1974, Zavarina et al. 1977). Design loads are a combination of dead weight and wind load. Icing imparts additional dead weight to the structure and also presents a larger surface area to the wind. Since icing intensity and frequency are highly variable geographically, and data are usually lacking, the EIA code does not specify design loads. Two sections of the code are as follows:

2.1.5 Design load shall be the specified combination of wind, ice, and deadweight applied to the tower...

2.2.2 When ice is considered, it shall not be less than the minimum specified radial thickness on all members of the structure, including guys. Unless otherwise stated, ice shall be considered solid.

(Note: This standard does not specifically state an ice thickness requirement ...)

The note following section 2.2.2 is important because the determination of a probable ice thickness is left to the designer. The difficulty arises in estimating an expected radial thickness value,



Figure 1. Wreckage of WCSH-TV's (Portland, Maine) 1300-foot tower felled by severe icing on 9 March 1983.

which is crucial for the calculations. Climatic records and site-specific considerations are used to estimate the likelihood of a worst-case combination of storm conditions. Icing intensity has been shown by numerous studies and case histories to be dependent on topography, microclimate, and accreting surface characteristics (Raevskii 1961, Lomalina 1977, Ahti and Makkonen 1982). There are also some published statistical analyses of climatic records that aid in forecasting regional icing expectation (Austin and Hensel 1956, Bennett 1959, Bilello 1971, Tattelman and Gringorten 1973). Ice load determinations for towers should therefore be the joint assessment of designer, field engineer, and meteorologist. The need exists for more complete data that define frequency and intensity and the effectiveness of protection measures so that engineers can better weigh costs and benefits of the various design alternatives.

Towers must be periodically surveyed for signs of structural fatigue from repeated ice accretion and wind loading, and guylines should be inspected for wear and retensioned to counteract stretching. Guyed towers are especially prone to failure from uneven shedding as can be seen in Figure 1. Heavy ice loading on the guys exerts tremendous tension on the system, and when individual guylines suddenly release a load, torsional forces can overcome the strength of the tower. Work is currently underway in Finland to gather data on tower stresses induced by natural icing (Lehtonen and Laiho, in press).

Harmonic oscillation of supporting guylines, or "guy galloping," is a rare but extreme type of stress that affects tall towers. At times, it can become severe enough to topple structures. It follows from a sequence of events that is highly specific to each particular guyline it affects. It has

been proposed that a small amount of ice building up on the windward side causes a cable to assume the shape of an airfoil. A moderate wind can then induce the cable to move due to aerodynamic lift and drag phenomena (Edwards 1970). Galloping is produced when the movement matches the resonant frequency of the cable, resulting in increasing oscillation amplitudes. The danger lies in the fact that galloping usually affects only one or two lines of an entire guy system during any one event, which can produce violent twisting of the tower. An added danger is the fact that metal becomes more brittle and subject to failure when cold. Low frequency, high amplitude (LFHA) cable dampers are commercially available that purport to inhibit galloping. Parkinson and Santosham (1967) show that the critical wind velocity that produces galloping is equal to:

$$V_c = \frac{4\beta m \omega}{h A_1 \rho} \quad (1)$$

- where β = fraction of critical damping
- ω = natural frequency of system
- m = mass per unit length of conductor plus ice
- ρ = density of air
- h = transverse dimension of conductor plus ice
- A_1 = constant related to the lift and drag characteristics of the ice conductor.

LFHA dampers are designed to increase the damping in the system as wind and ice loading occur. Translational motion of the cable also varies the damping and the resulting critical velocity. During a galloping event in December 1966, the engineer for WHDH Corporation in Boston, Massachusetts, successfully utilized this idea by hiring a large tow-truck to winch onto a guyline supporting his 400-m-high tower.

The dielectric properties of an ice coating can affect the antenna's RF wave propagation. Instead of signal propagation outward, some of the radiated power is reflected back into the antenna and the voltage standing wave ratio (VSWR, reflected power versus radiated power) is increased. The VSWR level must be kept within established operating limits. A little icing results in signal distortion and diminished power at the station's licensed broadcasting frequency. More icing can produce severe signal feedback and voltage overloading of circuitry. The VSWR level is monitored electronically, and when it reaches a preset thresh-

old a warning system alerts station personnel so that corrective measures can be taken. Unlike that used for FM or TV broadcasting, VSWR for AM broadcasting is not as sensitive to ice buildup due to the longer wavelength of transmission; AM stations therefore rarely employ deicing measures.

Tall masts are also subject to damage from falling ice chunks shed from the upper levels. Vulnerable items include transmission lines, reflector dishes and antenna elements. Reports of missiles of considerable size and weighing tens of kilograms are common during shedding events. Icing and shedding are usually the result of specific storm patterns, and station personnel can often predict from past experience the onset of a dangerous situation. Knowing the likely storm track and the associated wind directions, ground-based support systems are situated normally to the windward side of the tower for protection from falling ice. The aforementioned vulnerable items, mounted at lower heights on the tower, are shielded from above with wood, sheet metal or wire frame construction. Transmitter roof buildings are likely to be constructed to absorb impacts and resist punctures. Even more serious is the threat posed by towers located in densely populated areas to surrounding life and property. In many instances, ice chunks have smashed through building and car roofs. Fortunately, few personal injuries have occurred in the past. The fear of such an occurrence, though, is reflected in the large annual cost of a station's liability insurance. Currently, falling ice damage is perhaps the most difficult problem to deal with because there are no feasible proven means of prevention available for tall masts. The best way to guard against damage to adjacent property is to restrict land usage in the icfall shadow of the tower. Initially, the tower should be constructed on a vacant parcel of land large enough to encompass the highly probable fall zone. Thereafter, land-use planners should be cognizant of the danger and restrict development in this zone.

Prevention and shedding methods

Many different approaches have been taken to prevent ice accretion, to minimize its severity, or to aid in its removal. These can be grouped as either anti- or deicing methods. Anti-icing methods minimize or prevent accretion, whereas deicing methods remove the ice once it has formed. Makkonen (1984) provides a summary of current technology in this area. However, there is not much literature pertaining to radio and television

applications. Due to the large size of transmitting towers, many of the traditional anti-icing and de-icing methods are not cost-effective. The following is a summary of available methods.

Atmospheric icing has been shown in theory to be diminished by increasing the diameter of superstructure elements, thereby reducing the collection efficiency of the surface. The collection efficiency is defined as the ratio of the mass of droplets impinging on the surface to the total mass that would have impacted if not for deflection of the airstream around the object. This idea has been utilized with success on arctic oil drilling platforms by enclosing the superstructure in a solid panelwork. Application of this concept to broadcasting is limited to short, sturdy towers where the additional wind loading would not be excessive.

Radomes are an example of the use of this principle. These are rigid covers constructed of polyurethane, fiberglass, or sheet metal which enclose the radiating elements of an antenna or the reflecting surfaces of a receiver. Although they improve the system's capabilities during an icing event, severe conditions can still present a problem as seen in Figure 2. The WMTW-TV tower at the summit

of Mount Washington is an example of a tower radome (Fig. 3). Today, their primary antenna is mounted atop a 120-foot tower completely inside a steel tubular enclosure. The old tower, with steel framework exposed, now supports only their emergency backup antenna. During an icing event, the two adjacent towers provide a clear illustration of the new tower's diminished propensity to icing. In addition, outfitting radomes or exposed elements with a flexible sheathing has been successful at some installations. Flexure is caused either passively by wind and vibratory action, or by an active pneumatic system (Hartranft 1972, Ackley et al. 1973). In some cases the entire tower structure has been enclosed, but only after the danger of increased wind loading has been carefully considered. In general, only the radiating elements are enclosed.

Ice was removed from the guys of an antenna tower in Finland during the winter of 1981-82 using a common concrete vibrator attached to a guyline (Jaakola et al. 1983). The frequency used was reportedly 20-30 Hz. Recent laboratory tests conducted at CRREL produced evidence that a glaze ice layer on a steel beam was unaffected by con-




Figure 2. Radomes over microwave relays following a riming event on the summit of Mt. Washington. Manual deicing of the radomes by on-site personnel using ordinary hand tools is often necessary.



Figure 3. Radio and TV towers at the summit of Mt. Washington. WMTW-TV's tower, shown at extreme right, is radome-enclosed and less prone to icing than their old tower with exposed framework.

stant vibratory frequencies of 19 and 30 Hz (Donaldson 1985). The beam was a 2.44-m-long section of steel channel iron with cross-sectional dimensions of 25.4×6.6 cm. It was rigidly mounted and partially treated with a commercially available hydrophobic paint. However, sufficient amplitudes were produced to remove ice during the startup and shutdown of the vibrator when the beam passed through its characteristic resonant frequency. Mid-span beam displacement was approximately 1.6 cm at maximum amplitude. During the controlled coldroom tests, the vibrator successfully removed as much as 80% of a 2.5-cm-thick ice cover during a single 20-second cycle from start, to full speed, and back to stop. Tests conducted on various ice thicknesses in the range of 0.6 to 2.5 cm showed that the thinner layers were more difficult to remove. Although the amplitudes necessary to remove ice from stiff members may prove to be too extreme for a tower's structural integrity, the technique seems worthy of further testing, especially for guylines and less rigid towers.

Another approach to icing protection has been in the area of icephobic or low ice adhesion coatings. Sayward (1979) summarizes the theory from the standpoint of interfacial chemistry and pre-

sents a list of abstracts on the subject. Makkonen (1984) also gives a general summary of previous work. The types of coatings studied have been freezing point depressants and low wettability substances. Freezing point depressants, such as glycol solutions, soluble salt solutions, and gas-evolving coatings, function by contaminating the accreting droplets and reducing the freezing point below that of pure water. Sloping or vertical surfaces will then shed the liquid so ice doesn't form. Horizontal surfaces are more troublesome. As such, freezing point depressants are classified as "sacrificial coatings" because they are continually being washed away and must somehow be replenished. Highway salting and aircraft wing de-icing are common uses of these materials (Hanamoto et al. 1980, Itagaki 1984). Low-wettability oils, greases, and permanent coatings have been pursued because of their hydrophobicity. However, it is incorrect to assume that hydrophobicity implies icephobicity. During the early stages of icing, these substances allow the droplets to run off a sloping surface more rapidly before freezing can occur. Eventually some droplets accrete before they can be shed. In turn, these create sites for further accretion and the hydrophobic coating thereafter becomes rapidly coated with ice. Studies have shown

that certain polymer coatings exhibit a lower adhesive strength for ice than bare metal surfaces (Phan et al. 1977, Jellinek et al. 1978).

Bulk-formed ice is less adhesive than that formed by impacting droplets, and higher windspeeds increase the adhesive strength of accretions. It is proposed that the impacted water penetrates more deeply into the surface roughness, creating a stronger mechanical bond upon freezing (Stallabrass and Price 1963, Phan et al. 1977). Panuiskin et al. (1974) showed a direct relationship between adhesive strength and surface roughness. Assuming that surface roughness increases over time through oxidation, erosion, ice shedding and damage from icefall, the useful lifetime of surface coatings is questionable.

The suitability of coatings for radio and TV towers is also debatable because of the dimensions involved. To date, no experimental work has been conducted that points conclusively to a family of coatings that will satisfy the requirements of durability, low cost, and simplicity of application. Clearly, to coat and recoat an entire mast structure is not an attractive anti-icing alternative. Numerous papers have suggested the possibility of using low-energy coatings in conjunction with other techniques to ease removal once ice has formed (Ackley et al. 1973, Makkonen 1984). It is conceivable that troublesome sections on towers could be coated for easier ice removal by natural or artificial means (wind, gravity, heat, vibration, impact, etc.). At least two station owners in our study believe that their icing problems are diminished because their antenna elements are polymer-coated.

The choice of paint color is another worthwhile consideration. Darker colors absorb more solar radiation and would therefore heat up to dislodge ice more rapidly following a storm event. During a storm, however, when there is little solar gain through fog and clouds, the amount of ice buildup would be equivalent to that on light colored elements. The value of color choice would be to speed the return to normal operations once the weather clears. Although the Federal Communications Commission requires that all towers be painted with a standard red/white pattern for greater visibility to air traffic, certain tower attachments and antenna elements could be darker for the solar gain advantage.

At the present time, the only totally effective anti-icing method available is heating, and it is the method of choice for most station owners in New England who employ icing protection. Calcula-

tions in the past have ruled out the possibility of heating the entire tower as much too costly. Makkonen (1984) cites the power requirement of 2 kW/m² for an icing rate of 3 g/cm² hr to prevent accretion on the steel superstructure of ships. Jaakola et al. (1983) mention attempts in Finland in 1974 to deice an antenna tower shaft and guylines by heating with heat cables. In this case, the power required to remove ice ranged from 50–120 W/m and a deicing period of approximately eight hours was required for difficult accretions. Given the large power demands, heating is, in general, only used to prevent icing of the radiating elements of FM and TV antennas. The popular heating units are factory-built into "batwing" or whip-type antennas and must be activated in advance of an icing event. These low-wattage heaters usually cannot keep up with the accretion rate if ice is allowed to accumulate appreciably before the heaters are activated. Some station operators manually activate heaters based on the local weather forecast or individual judgment. Others prefer the more cautious alternative of operating deicers for the entire season. A third alternative is to provide for auto-activation via thermal, precipitation, and/or icing sensors.

RESULTS

The survey

In the summer of 1984, approximately 25 radio and television stations were contacted by telephone to preliminarily ascertain their level of concern over ice accretion. No statistical considerations were made in selecting these stations. In fact, the majority were chosen specifically because problems were suspected due to the location or elevation of their towers. Based on the difficulties experienced by these stations, there clearly existed a need for better solutions, and a more thorough investigation was begun. In December 1984, we distributed a two-part mail questionnaire to all New England stations with mast heights greater than 50 feet. Predominantly short-answer, multiple-choice, and fill-in type questions were asked to ensure greater participation in the survey. Part 1 solicited general subjective data about icing and specific site descriptors for each location. The respondents were asked to provide brief summaries of their mast designs and to list all attachments and equipment thereon. The current use of any protection measures was questioned. The presence of any meteorological equipment at the site was




Figure 4. Tower locations of all stations responding to the survey. For key to station number, see Appendix B.

also of interest to allow measurements during a future icing event. A "General Icing History" portion listed various problems and urged subjective response on the frequency and severity of each that could be expected in a normal season. We also obtained average annual cost ranges for wind/ice damage repairs and for maintenance of protective equipment for each station.

Of the 432 questionnaires (Appendix A) that were mailed, 108 stations (25%) returned Part I by 1 April 1985. The information in this report is derived from the 108 responses and 10 AM- and FM-combination stations, totaling 118 when considered separately. The tower locations of all responding stations are shown in Figure 4.

Part II of our survey was a form whereby station personnel could report icing experienced throughout the 1984-85 winter. We were interested in obtaining dates and descriptions of the events as they occurred, along with concurrent meteorological parameters such as temperature, windspeed, wind direction, humidity, precipitation, and percentage of sunshine. We also sought identical information for shedding events. It was hoped that frequency, synoptic conditions responsible, and the distribution of events throughout New England could be learned. Station personnel were requested to submit their choice of two forms, whichever was most convenient for their particular situation. Section A of Part II requested information for an individual event. An instruction sheet urged operators to complete and return this form following each event if icing was rare at their location. Realizing that some installations frequently suffer heavy and extended icing, we provided an optional Section B which asked instead for a monthly summary of icing and shedding.

The data obtained from Part II were incomplete and unsatisfactory. Although 35 stations indicated in Part I that they would document icing over the ensuing winter, only 15 had sent follow-up information as of 15 May 1985. Nine stations sent a total of 15 Section A reports on individual events. Only three other stations chose to summarize, with a total of five monthly reports (Section B). The three other stations reported at the end of the season that they had experienced no icing. Considering the sparsity of data, we are not confident that all icing events at these stations were documented. We therefore conclude that a voluntary mail survey of this type is not an effective means for obtaining quantitative intensity, frequency, and areal distribution data on atmospheric icing.

A cover letter explaining the scientific purpose of the study was included, but our questionnaire still met with resistance and suspicion on the part of some station managers, leading to reluctance to candidly describe their icing problems. The data obtained should therefore be analyzed with this fact in mind.

Ambiguity in data interpretation is always a problem with a subjective survey. Many of our questions elicited qualitative responses which are not directly comparable between stations. The "degree of icing" response is especially difficult to interpret, as some respondents described icing frequency and severity in general while others tempered their answers by noting the effect icing had on their business operations. For example, a station with highly successful protection and hence few problems may experience severe icing based on frequency and magnitude, whereas another station may often suffer transmission problems from relatively mild icing. However, both might be described by those responding as severe cases. Therefore it is advisable to study all the information provided in Appendix B and Table 2 concerning any particular station before drawing conclusions about its icing degree.

Data presentation

Appendix B contains a summary of the information obtained from all stations responding. It lists them alphabetically by state and then by city with the tower location, if different, in parentheses. The name of the person contacted is also given. Elevations in meters above mean sea level (AMSL) of the tower base and the uppermost element of the mast appear in column 2. Column 3 is the respondent's subjective evaluation of the overall degree of his icing-related problems. The next two columns give average annual cost categories for *maintenance* of icing protection equipment and related energy costs and *repairs* to equipment from ice and wind damage. The last column lists specific icing problems experienced or expected, along with subjective evaluations of frequency and severity of each, types of icing protection devices in use, and general comments.

Table 2 provides more detailed information on the mast and its site. The cost entry is a combination of the respondents' average annual costs for maintenance of icing protection equipment and repairs of icing-related damage. To arrive at the cost figure, we assumed the midpoint of the two cost ranges selected by the respondent for questions 7 and 8 in Part 1 of the survey. Summing the two

Table 2. Details of mast installations of all respondents.

<i>Sta</i>	<i>ID</i>	<i>Cost</i>	<i>Grnd</i>	<i>Base</i>	<i>Mast</i>	<i>Top</i>	<i>G</i>	<i>RU</i>	<i>OP</i>	<i>LHM</i>	<i>AFT</i>	<i>Sea</i>	<i>IPD</i>
1	1	125	2	2	91	93	N	R	O	L	A	4	None
2	1	125	xxxx	xxxx	104	xxxx	Y	U	M	H	A	4	None
3	1	250	223	223	81	304	N	R	M	H	AF	40	Ht
4	3	750	122	122	408	530	Y	U	M	H	F	48	C
5	1	125	8	8	47	54	N	U	M	H	A	4	None
6	1	250	213	213	27	241	N	R	O	M	F	40	W
7	0	0	46	107	8	114	N	U	M	H	F	32	None
8	1	250	145	145	12	165	Y	R	O	H	F	8	None
9	4	1125	195	195	277	472	Y	R	P	H	T	16	Hi
10	2	500	35	35	114	149	Y	R	M	H	F	4	Hm
11	1	125	160	160	146	306	Y	R	M	H	T	24	Ht + p
12	1	125	160	160	146	306	Y	R	M	H	F	24	None
13	1	250	189	189	90	279	Y	R	M	L	T	24	R,S
14	1	250	49	49	114	163	N	U	M	H	AF	4	Ht
15	1	125	46	46	124	170	Y	R	M	H	A	48	None
16	1	250	377	377	34	411	Y	R	P	H	F	129	Hm
17	2	500	4	238	8	246	N	U	O	L	F	4	Hm
18	1	125	5	48	60	107	Y	U	O	L	F	4	None
19	1	125	117	117	24	142	Y	R	O	H	F	97	None
20	1	125	51	61	9	70	Y	R	M	H	F	40	None
21	x	xxxx	263	263	24	287	Y	R	P	H	F	153	None
22	3	750	267	267	158	426	Y	R	O	M	F	10	Hi
23	2	375	110	110	57	167	Y	U	M	H	A	105	None
24	1	125	4	4	56	60	Y	U	O	H	A	16	None
25	1	125	335	335	47	383	Y	R	O	H	A	153	None
26	1	125	76	76	61	137	Y	U	O	L	A	161	None
27	x	xxxx	61	61	123	184	Y	RU	M	L	AF	32	None
28	1	250	xxxx	xxxx	9	xxxx	Y	U	M	H	F	40	Ht
29	2	500	67	67	29	96	N	U	M	H	F	4	Ht
30	5	17500	37	37	324	361	N	U	M	H	T	16	Hi,R,E
31	4	6000	30	30	411	441	Y	U	M	L	F	16	R,S
32	1	125	68	68	69	137	Y	R	O	H	A	24	None
33	2	500	616	616	46	661	Y	R	M	M	F	177	Hm
34	1	250	193	193	70	263	Y	R	M	M	F	129	R
35	1	125	309	309	67	376	Y	U	M	L	A	145	None

Key:

Sta = Station alphabetical number from Appendix B.

ID = Icing degree, where:

5 = > \$10,000 4 = \$1000-9999 3 = \$650-999

2 = \$350-649 1 = \$1-349 0 = zero dollars

Cost = The sum of the midpoints of average annual cost ranges for icing-related repairs and maintenance.

Grnd = Ground elevation at tower location (meters above mean sea level).

Base = Elevation at base of tower (mAMSL).

Mast = Overall height of mast installation (meters).

Top = Elevation at top of mast installation (mAMSL).

Site descriptors:

G = Guyed tower? Yes or No or Both types in use.

RU = Rural or Urban.

OP = Open, Protected, or Mixed.

LHM = Level, Hilly, or Mountainous.

AFT = AM radio, FM radio, or Television station.

Sea = Approximate distance to ocean (miles).

IPD = Icing protection devices in use, where:

C = surface coating, E = emergency backup antenna in place, R = radome, S = ice shield,

W = wide-band antenna in use, H = electric heater, where m = manually activated, i = ice detector

activated, t = temperature activated, p = precipitation activated.

Table 2 (cont'd).

<i>Sta</i>	<i>ID</i>	<i>Cost</i>	<i>Grnd</i>	<i>Base</i>	<i>Mast</i>	<i>Top</i>	<i>G</i>	<i>RU</i>	<i>OP</i>	<i>LHM</i>	<i>AFT</i>	<i>Sea</i>	<i>IPD</i>
36	1	250	540	540	46	586	Y	R	M	M	F	145	Ht + p
37	3	750	38	38	293	331	Y	R	M	L	T	24	Ht,R
38	0	0	195	195	70	265	Y	R	O	L	A	89	None
39	2	375	250	250	46	296	Y	R	O	H	F	89	Hm
40	3	875	366	366	47	413	Y	R	M	M	T	121	Hm
41	1	125	22	22	107	129	N	U	O	L	AF	97	None
42	3	875	267	267	158	426	Y	R	O	M	T	97	Hi
43	1	125	67	67	21	88	Y	R	P	H	F	40	None
44	1	125	64	64	56	120	Y	R	M	L	A	32	None
45	1	250	38	38	366	404	Y	U	M	H	F	16	R
46	1	250	335	335	59	394	N	R	M	H	F	80	H
47	1	125	250	250	116	366	N	R	M	H	A	72	None
48	0	0	61	61	56	117	N	xx	xx	xx	A	32	None
49	1	125	48	58	22	80	Y	U	O	H	F	48	None
50	1	250	232	232	44	276	Y	R	M	H	F	40	S
51	2	375	55	55	123	178	B	U	O	H	A	48	None
52	1	250	43	43	110	152	Y	R	M	H	F	4	C
53	3	750	61	61	85	146	Y	R	M	H	F	16	Hm
54	2	500	88	88	89	178	Y	U	M	H	F	4	Ht
55	1	250	114	114	128	242	Y	R	O	L	AF	129	Hm
56	3	875	210	210	193	403	Y	R	M	H	T	32	Hm,R
57	1	250	143	143	152	296	Y	R	O	H	F	24	Ht
58	3	875	1906	1906	37	1943	Y	R	O	M	T	113	R
59	5	17500	375	375	398	773	Y	R	M	M	T	40	Ht,R,S
60	1	125	23	23	88	111	Y	R	M	L	F	8	R
61	1	125	76	76	142	218	Y	R	O	L	F	16	None
62	1	125	15	15	54	69	Y	R	O	L	A	16	None
63	0	0	15	15	74	89	Y	R	O	L	A	1	None
64	2	375	23	23	69	91	Y	U	O	P	F	4	Hm
65	2	500	0	0	79	79	N	U	M	L	AF	0	Ht
66	0	0	283	283	24	308	Y	R	M	H	F	72	R
67	1	125	87	87	94	181	Y	R	P	L	A	7	None
68	1	125	194	194	30	224	Y	R	P	H	F	72	Hm
69	1	125	137	137	73	210	Y	R	M	M	A	72	None
70	1	125	372	372	24	396	N	R	M	M	F	72	None
71	1	125	140	140	90	230	Y	R	P	L	A	40	None
72	3	875	122	122	152	274	Y	R	M	H	T	48	Hm
73	1	125	18	18	62	81	Y	R	P	H	A	16	None
74	1	250	324	324	49	404	Y	R	P	H	AF	145	Hm
75	1	125	146	146	53	200	Y	U	O	L	A	121	None
76	1	125	160	160	46	206	Y	R	O	L	A	145	None
77	1	125	61	61	114	175	Y	U	M	L	A	56	None
78	2	500	390	390	38	428	Y	R	M	H	F	64	Hm
79	1	125	61	61	91	152	N	U	O	L	A	56	None
80	1	250	594	594	37	632	Y	R	M	M	F	89	Hm
81	1	125	171	171	63	234	Y	R	M	H	A	56	None
82	1	125	xxxx	94	12	107	Y	R	M	H	F	16	None
83	1	250	50	50	123	173	Y	R	M	H	F	8	Ht
84	1	125	46	67	21	89	N	R	O	H	F	4	None
85	1	125	9	9	98	107	Y	R	O	L	A	4	None
86	1	250	73	73	149	223	N	R	M	H	AF	8	Hm + i
87	0	0	3	3	134	137	Y	xx	xx	xx	A	4	None
88	1	125	12	12	166	181	Y	R	M	H	AF	4	W
89	2	500	69	69	305	373	Y	R	M	H	T	24	Ht + p
90	1	125	76	76	61	137	Y	R	M	L	A	8	None
91	0	0	101	101	46	146	Y	R	P	H	A	153	None

Table 2 (cont'd). Details of mast installations of all respondents.

<i>Sta</i>	<i>ID</i>	<i>Cost</i>	<i>Grnd</i>	<i>Base</i>	<i>Mast</i>	<i>Top</i>	<i>G</i>	<i>RU</i>	<i>OP</i>	<i>LHM</i>	<i>AFT</i>	<i>Sea</i>	<i>IPD</i>
92	0	0	469	469	46	515	Y	xx	xx	xx	F	15	W
93	3	750	1219	1219	40	1259	N	R	O	M	T	225	Hm,S
94	3	875	1259	1259	32	1291	N	R	O	M	T	225	Hi
95	1	250	87	87	110	197	Y	xx	xx	xx	F	257	Ht
96	1	125	31	31	90	122	Y	R	O	L	A	257	None
97	4	1500	1280	1280	92	1372	Y	R	O	M	T	225	Hi,S
98	1	125	131	131	37	168	N	R	M	H	F	257	None
99	1	125	140	151	6	157	Y	U	M	L	F	209	None
100	2	500	290	296	26	321	Y	R	M	H	F	161	Ht
101	1	125	198	198	53	251	Y	R	M	H	A	193	None
102	2	500	1291	1291	18	1309	N	R	O	M	F	185	Hm + t, R
103	1	125	226	226	56	282	Y	R	P	H	A	161	None
104	3	875	1032	1032	40	1072	N	R	O	M	T	161	Hi
105	1	250	244	244	91	335	Y	R	O	H	AF	145	Hm
106	1	125	134	134	75	209	Y	R	O	H	A	145	None
107	1	250	305	305	61	366	Y	R	O	M	F	145	Hm
108	4	6000	920	920	49	969	Y	R	O	M	T	145	Ht

midpoints resulted in the single maintenance/repair value shown in column 2. For example, Station 9, as shown in Appendix B, selected the range \$250–500 for its annual maintenance costs, the midpoint being \$375. Its repair costs range from \$500–1000 annually, the midpoint being \$750. The sum of these two values, \$1125, appears as the cost entry in Table 2. Based on this value, the stations have been categorized in the five levels of icing degree (ID) shown below:

<u>ID</u>	<u>Cost</u>	<u>No. of stations</u>
5	\$10,000 or greater	2
4	\$1000–9999	4
3	\$750–999	12
2	\$350–749	15
1	\$1–349	74
0	0 or unknown	11

Table 3 lists in decreasing order of severity those stations with annual icing-related costs of \$350 or more, meaning that those with ID values of 2 or greater make up our list of stations with moderate and more severe icing.

In all tables, the base elevation differs from ground elevation when a tower is located atop a building. For example, WERS-FM’s base elevation on the roof of the Prudential Center in Boston is 238 m, whereas the ground elevation is only 4 m AMSL.

DISCUSSION

Survey response distribution

In general, the survey response rate was highest for TV stations, with FM stations slightly higher than AM stations. It might be inferred that the response rate would be higher for those stations with greater sensitivity toward atmospheric icing. Those stations would be inclined to seek solutions and therefore be more interested in participating in the survey. Figure 5 shows the distribution of response percentages on a state-by-state basis and by station type. The states with higher response rates were New Hampshire, Vermont and Rhode Island, and we might conclude that these states experience more icing. New Hampshire and Vermont may be more susceptible due to the higher latitude, higher elevations, mountain proximity, and storm track influences. Rhode Island’s high rate may be due to ocean proximity but is more likely due to sample error since only 30 stations were contacted, the lowest number for any state.

We consolidated parameter averages for all respondents based on station type, use of icing protection, and guyed versus non-guyed towers; Table 4 summarizes the information obtained. For example, the average ground elevation of responding AM stations is half of that for FM stations, which is in turn less than half the elevation of TV stations. Mast height in the study for TV stations tends to be more than twice that for AM and FM stations, which were equivalent. The average mast

Table 3. Stations with moderate and more severe icing grouped by degree of icing.

Rank	Sta	ID	Cost	Grnd	Base	Mast	Top	G	RU	OP	LHM	AFT	Sea	IPD
1	59	5	17500	375	375	398	773	Y	R	M	M	T	40	Ht,R,S
	30	5	17500	37	37	324	361	N	U	M	H	T	16	Hi,R,E
2	108	4	6000	920	920	49	969	Y	R	O	M	T	145	Ht
	31	4	6000	30	30	411	441	Y	U	M	L	F	16	R,S
3	97	4	1500	1280	1280	92	1372	Y	R	O	M	T	225	Hi,S
4	9	4	1125	195	195	277	472	Y	R	P	H	T	16	Hi
5	104	3	875	1032	1032	40	1072	N	R	O	M	T	161	Hi
	94	3	875	1259	1259	32	1291	N	R	O	M	T	225	Hi
	72	3	875	122	122	152	274	Y	R	M	H	T	48	Hm
	58	3	875	1906	1906	37	1943	Y	R	O	M	T	113	R
	56	3	875	210	210	193	403	Y	R	M	H	T	32	Hm,R
	42	3	875	267	267	158	426	Y	R	O	M	T	97	Hi
	40	3	875	366	366	47	413	Y	R	M	M	T	121	Hm
6	93	3	750	1219	1219	40	1259	N	R	O	M	T	225	Hm,S
	53	3	750	61	61	85	146	Y	R	M	H	F	16	Hm
	37	3	750	38	38	293	331	Y	R	M	L	T	24	Ht,R
	22	3	750	267	267	158	426	Y	R	O	M	F	10	Hi
	4	3	750	122	122	408	530	Y	U	M	H	F	48	C
7	102	2	500	1291	1291	18	1309	N	R	O	M	F	185	Hm + t,R
	100	2	500	290	296	26	321	Y	R	M	H	F	161	Ht
	89	2	500	69	69	305	373	Y	R	M	H	T	24	Ht + p
	78	2	500	390	390	38	428	Y	R	M	H	F	64	Hm
	65	2	500	0	0	79	79	N	U	M	L	AF	0	Ht
	54	2	500	88	88	89	178	Y	U	M	H	F	4	Ht
	33	2	500	616	616	46	661	Y	R	M	M	F	177	Hm
	29	2	500	67	67	29	96	N	U	M	H	F	4	Ht
	17	2	500	4	238	8	246	N	U	O	L	F	4	Hm
	10	2	500	35	35	114	149	Y	R	M	H	F	4	Hm
8	64	2	375	23	23	69	91	Y	U	O	P	F	4	Hm
	51	2	375	55	55	123	178	B	U	O	H	A	48	None
	39	2	375	250	250	46	296	Y	R	O	H	F	89	Hm
	23	2	375	110	110	57	167	Y	U	M	H	A	105	None

Key:

Sta = Station alphabetical number from Appendix B.

ID = Icing degree, where:

5 = > \$10,000 4 = \$1000-9999 3 = \$650-999
 2 = \$350-649 1 = \$1-349 0 = zero dollars

Cost = The sum of the midpoints of average annual cost ranges for icing-related repairs and maintenance.

Grnd = Ground elevation at tower location (meters above mean sea level).

Base = Elevation at base of tower (mAMSL).

Mast = Overall height of mast installation (meters).

Top = Elevation at top of mast installation (mAMSL).

Site descriptors:

G = Guyed tower? Yes or No or Both types in use.

RU = Rural or Urban.

OP = Open, Protected, or Mixed.

LHM = Level, Hilly, or Mountainous.

AFT = AM radio, FM radio, or Television station.

Sea = Approximate distance to ocean (miles).

IPD = Icing protection devices in use, where:

C = surface coating, E = emergency backup antenna in place, R = radome, S = ice shield,
 W = wide-band antenna in use, H = electric heater, where m = manually activated, i = ice detector
 activated, t = temperature activated, p = precipitation activated.




Figure 5. Station response to survey (state-by-state percentages). Numbers at top of columns represent total number of stations.

top elevations for AM, FM and TV-only stations are 178, 295 and 724 m AMSL respectively. In terms of average distance to the ocean, AM and FM masts were nearly equidistant at 72 and 66 km respectively, whereas TV masts averaged 92 km. Figure 6 shows the average annual costs for icing-related repairs and maintenance based on station type. It can be seen that by far the higher costs are incurred by television stations at over \$3000 per year. AM stations expend an average of only \$121 per year while the cost to FM stations is more than three times greater at \$402 per year. The higher costs to FM and TV broadcasters may be partly attributable to their higher average elevations and mast heights. Distance to the ocean seems to be inversely related to degree of icing, as TV stations with high cost are on average further from the coast.

Effect of icing protection on parameter averages

Another indication of icing degree is the distribution of stations that use icing protection devices. Fifty-seven, or 48% of the total 118 stations, use some form of protection, and 77% of those employ the active method of electrically heating

transmission elements. The remaining 23% use the passive methods of radomes, polymer coatings, shields, or wide-band antennas. Shown below is the per-state breakdown of stations using some form of icing protection, the total number reporting, and the percentage of the total.

Conn.	Maine	Mass.	N.H.	R.I.	Vt.
8/19	12/21	16/34	6/19	4/13	11/20
(42%)	(57%)	(47%)	(32%)	(31%)	(55%)

The higher latitude states of Maine and Vermont are the highest percentage users. The exception is New Hampshire, which is inexplicably low based on our overall latitude and elevation assumptions. Comparisons of the various parameters between stations with and without IPDs are shown in Table 4b. Two facts are immediately obvious. None of the 34 AM stations in the study use IPDs, whereas all 17 TV stations use some form of protection. This can be interpreted to mean that AM transmission is nearly insensitive to expected New England icing levels, and operators in general do not consider icing a problem for this type of broadcast. Conversely, TV transmission is highly sensitive to

Table 4. Parameter averages.

<i>Station type</i>	<i>No. of stations</i>	<i>Cost (dollars)</i>	<i>Grnd (mAMSL)</i>	<i>Base (mAMSL)</i>	<i>Mast (m)</i>	<i>Top (mAMSL)</i>	<i>Sea (km)</i>
a. By station type							
All stations*	118	689	214	216	93	312	71
AM-only stations	34	121	102	102	76	178	72
All stations w/AM†	44	148	105	105	83	189	69
FM-only stations	47	402	207	213	76	295	66
All stations w/FM†	57	377	190	195	81	282	64
TV stations only	17	3066	567	567	157	724	92
b. Parameter averages of stations with or without icing protection devices							
All stations with	57	1246	327	332	114	448	72
All stations without	53	113	102	105	68	174	70
AM stations with	0	—	—	—	—	—	—
AM stations without	34	121	102	102	76	178	72
FM stations with	40	472	223	229	96	328	64
FM stations without	17	125	109	118	47	169	68
TV stations with	17	3066	567	567	157	724	92
TV stations without	0	—	—	—	—	—	—
c. Parameter averages of stations with guyed or non-guyed towers							
All stations guyed	90	609	200	200	98	303	72
All stations nonguyed	29	897	249	260	78	338	63
AM stations guyed	34	136	113	113	80	195	80
AM stations nonguyed	11	205	73	73	96	104	34
FM stations guyed	43	415	185	184	90	282	68
FM stations nonguyed	14	268	205	227	54	282	60
TV stations guyed	13	2471	469	469	172	641	72
TV stations nonguyed	4	5000	887	887	109	996	158

* Combination AM-FM stations are double-counted.

† Includes 10 combination AM-FM stations.

icing, and icing protection is costly, averaging over \$3000 per year per station. Figure 7 illustrates the large difference in icing costs for the three station types, depending on whether or not IPDs are used. Since the usage of IPDs was clearly specific according to broadcast type, we chose to look only at the distribution of protected FM stations; Figure 8 shows state-by-state percentages. Admittedly, the sample size is small, but this graph does in fact show the higher latitude states of Maine, Vermont and New Hampshire as high-percentage users. New Hampshire's percentage is increased when the 10 AM stations are factored out of the total of 19 reporting. The evidence that the mountainous northern states are more subject to icing is strengthened. Table 4b also illustrates the relationship of IPD usage with respect to ground elevation and mast height. The average ground elevation of FM stations *with* protection is 223 m AMSL, or roughly twice that of FM stations *without* IPDs. The elevation of FM stations without protection is

equivalent to that of AM stations, at 102 m AMSL. Taller masts (average 96 m) are in use at FM stations with IPDs than at stations without them (average 47 m). This lends credence to the assumption that icing severity is dependent upon elevation above sea level and mast height above local ground elevation. The average distance to the ocean for FM stations with and without IPDs is virtually the same, indicating that in New England ocean proximity has little to do with the need for protection.

Effect of tower type on parameter averages

Parameter averages were tabulated for the respondents based on the use of guyed versus nonguyed towers (Table 4c). Over 75% of all reporting stations use guyed towers. It was initially thought that guyed towers might have a higher maintenance/repair cost-average due to a larger ice-fall zone about the tower base. Icing would oc-




Figure 6. Icing-related station costs (average cost per year). Numbers at top of columns represent total number of stations.




Figure 7. Icing-related station costs (with and without icing protection). Numbers at top of columns represent total number of stations.




Figure 8. Icing protection (state-by-state percentages, FM stations only). Numbers at top of columns represent total number of stations.

cur not only on the tower, but also on the guy cables, which would increase the possibility of ice falling onto adjacent property. For urban facilities this could be the source of higher associated costs. As the data show, it is difficult to make conclusions about costs based on the use of guyed or non-guyed towers alone. The cost averages are plotted in Figure 9 according to station type. A large difference is evident between guyed and non-guyed TV stations: \$2471 and \$5000 per year respectively. Non-guyed TV towers are more than twice as expensive to maintain as those that are guyed. In this case, the first appearance is misleading since the sample of non-guyed TV towers consists of only four stations and one of these is WNEV in Newton, Massachusetts. Its average yearly cost is \$17,500, which highly exaggerates the averages for the other three stations. WNEV has a 324-m-high mast in a heavily developed area, and even though ice-falls are infrequent the resulting damage to adjacent property is sometimes very high. The other three stations have short towers, on the average of 37 m high, and are located on mountaintops where ice falling from guy cables has no economic impact. Disregarding station

WNEV, average cost for non-guyed TV stations is only \$833 per year.

Average mast heights for guyed and non-guyed AM towers and guyed FM towers are all nearly the same (80, 96 and 90 m respectively). Yet non-guyed FM towers average only 54 m high. Yearly cost in this case parallels mast height. Non-guyed AM towers are taller and cost more to maintain than guyed AM towers. Conversely, for FM towers, the non-guyed type are shorter and cost less per year than those with guy systems. It is interesting to note that the top elevations for both types of FM towers are identical at 282 m AMSL.

The cost averages for urban towers only are equally inexplicable regarding the presence (16 stations) or absence (9 stations) of guy cables. Disregarding two high-cost stations with outlying values (WNEV-TV and WCSH-TV), costs for guyed and non-guyed towers were nearly identical at \$242 and \$266 per year respectively. Even though the average mast height and ground elevation of guyed urban towers were higher than those of non-guyed urban towers, icing costs were slightly lower. From the information available, it must be concluded that tower type alone is not a good pre-




Figure 9. Icing-related station costs (guyed versus non-guyed towers). Numbers at top of columns represent total number of stations.

dictor of icing costs and that elevation, exposure, and mast height are more influential factors.

Moderate and more severe icing locations

Table 3 lists stations judged to have moderate-to-severe icing; their locations are shown in Figure 10. The table contains just 2 AM-only stations out of the total of 32, and these are the only stations in Table 3 that do not use icing protection. The remaining 30 stations use IPDs of some type, and 26 of these use electrical antenna heaters. Fifteen of the 17 TV stations in the study appear in Table 3, and 14 have ID values of 3 or greater. Another 15 stations in Table 3 are FM broadcasters with an average \$900 per year in icing costs.

One might expect the summit of Mt. Washington to have the greatest icing severity due to its elevation, exposure and fierce weather conditions. Personnel at WMTW-TV (station 58) there report that icing occurs during 8-9 months of the year. It is interesting that WMTW's maintenance/repair costs tie it with seven other stations in fifth place on our list, lower than was expected. They do not use conventional antenna heaters but instead successfully employ radomes, short towers, and manual deicing techniques. Their station-to-transmit-

ter microwave dishes are housed inside a large chamber attached to the transmitter building that is heated with the waste heat of a diesel power generator. The exterior wall is fiberglass which infrequently requires manual deicing. Given the severe environment of Mt. Washington, WMTW has remarkable control over their icing-related maintenance and repair costs, which average only about \$875 per year.

Portland, Maine's WCSH-TV (station 59) topped the list, having both severe icing conditions and high maintenance/repair costs. They have the tallest mast of all the responding mountaintop installations. Their annual cost for maintenance of protective equipment is reportedly \$5,000-10,000, with annual damage expenses (due mainly to falling ice) of over \$10,000. A severe buildup of rime and glaze in March 1983 toppled their 400-m mast, causing approximately \$34,000 in damages and days of lost airtime before a temporary, less powerful system could be put on-line. It was many months before a new tower was erected and operations returned to normal. The tremendous size of their tower, its high base elevation, and its northerly location are factors contributing to their severe icing problems.




Figure 10. Tower locations of stations with moderate and more severe icing, showing those with mast heights greater than 275 m and top elevations exceeding 760 m above sea level.

Two other stations that were top-ranked in icing severity are located within 0.3 km of each other in Newton, Massachusetts. WNEV (station 30) owns a massive self-supported TV tower, whereas WZOU's FM tower (station 31) is guyed. Both stand over 300 m high. As they are situated in an urban area, their costs stem mainly from serious falling ice damage to surrounding property. It should be mentioned that information received from these two stations is more extensive, as their owners were particularly interested in the study. WNEV-TV has installed instrumentation on their tower to record both icing and shedding events in progress. The data obtained from meteorological sensors and video equipment mounted at multiple levels will be made available to us for analysis as the icing season progresses. It is hoped that the data will lead to better understanding of synoptic conditions and the physical processes involved. Detailed records of ice-fall incidents and resulting damage were made available for this study for the entire 28-year history of the WZOU tower (Hurd and Frank 1985). From the 1957–58 winter through 1983–84 (27 years), 16 ice-falls from their tower were significant enough to report. An undetermined number of minor ice-falls went unrecorded, but from the information available, the frequency of 16 “significant” ice-falls in 27 years yields a mean of one every 1.7 years. The actual interval between events was highly erratic, ranging from two weeks to one period of over five years (std dev = 1.6 years). Of the 16 incidents, 8 resulted in damage to tower equipment or surrounding property and 1 involved minor bodily injury (mean frequency of damaging events = 3.0 years, std dev = 2.6 years). Broken windows, dented vehicles, damaged transmission equipment and punctured roofs were most typically reported.

Relationship of climate, geography and topography to icing severity

Prior to our survey, we believed that there might be a strong correlation between degree of icing and proximity to the ocean. We reasoned that the liquid water content of the air and the frequency of fogs would be higher and thus cause more icing events. Published maps based on frequency studies of meteorological data (AAF Weather Service 1943, Bennett 1959, McKay and Thompson 1969, and Tattelman and Gringorten 1973) have suggested a relationship between frozen precipitation and coastal proximity. Although the data are inconclusive, the maps indicate that, for the Canadian Maritimes, the influence is toward higher ic-

ing frequency, due perhaps to the prevalence of colder air masses. Coastal New England, however, being lower in latitude, appears to be affected in an opposite way, with the latent heat of the ocean perhaps lowering the frequency of icing. Of a total of 17 stations in our study located less than 5 km from the coast, only 6 appear in Table 3. Even those appear low on the list in order of severity; none have an ID number greater than 2. Indeed, all 11 stations within 5 km of the ocean that use IPDs are FM stations, and even though 9 of these stations use antenna deicers, their yearly icing costs average only \$341. The cost average for all FM stations with IPDs is \$472. Five AM-only stations within 5 km of the coast responded to the survey. Their average yearly costs were only \$75 as compared to \$121 for all AM-only stations. No TV stations closer than 16 km to the coast, with one exception, responded to our survey, so we are not able to make any statements about ocean influence on this type of broadcast. Our data therefore lend support to the contention that atmospheric icing is moderated by ocean proximity in New England.

Mast height and top elevation appear to be two factors contributing to icing severity. Of the 18 stations with severity values of 3 or greater, 13 have either a mast height greater than 275 m or a top elevation exceeding 760 m AMSL. All six with ID values of 4 or greater have one or the other characteristic, and top-ranked WCSH-TV (station 59) has both. Interestingly, all eight stations in the study with top elevations over 760 m AMSL, and all but one of the eight stations with mast heights in excess of 275 m, appear in Table 3, generally with an ID value of 3 or greater. The only study case not following this trend was WCRB-FM, located in Newton, Massachusetts, less than 1.5 km from previously mentioned WNEV and WZOU. Since they rent space on WBZ-TV's 366-m-tall structure, WCRB is accountable only for icing costs incurred by their own equipment on the tower. Though WBZ-TV declined to participate in this study, they indicated in the preliminary investigation that they commonly experience icing. But with antenna deicers, ice shields, and a concrete transmitter building roof, extraordinary ice-fall damage is not a problem. Aerial photographs show that WBZ's tower is located in an undeveloped, forested area. They are thereby protected from large damage claims by surrounding property owners, which plague WNEV and WZOU.

Not unexpectedly, mountaintop installations dominated the ranks of stations with higher icing

costs. The 13 most severely affected stations (icing costs \$875/yr and greater) are an average of 90 km from the ocean at a mean ground elevation of 615 m AMSL. Three of the top six stations are about 16 km from the coast but all three have mast heights of at least 360 m, which more likely is the cause of their icing-related costs. Ten of 18 stations with severity values of 3 or more are located in mountainous terrain where orographic contribution to precipitation and icing is considerable.

We used least-squares regression analysis to test the correlations of icing-related maintenance/repair costs with ground elevation, mast height, distance to the ocean, etc. for all stations surveyed. We believe that due to the ambiguity and subjectivity in our cost categories, we found poor correlation using simple monopolynomial regression. The best simple relationship was cost versus mast height, with a correlation coefficient of $R = 0.542$. Costs versus distance to ocean showed an especially poor trend ($R = 0.137$). Multiple regression of top elevation and mast height together yielded the best correlation with costs. Least-squares bipolynomial equations of:

$$1. \text{ Costs} = a + bx + cy \quad (\text{simple})$$

$$2. \text{ Costs} = a + bx + cy + dx^2 + exy + fy^2 \quad (\text{quadratic})$$

$$3. \text{ Costs} = a + bx + cy + dx^2 + exy + fy^2 + gx^3 + hx^2y + icy^2 + jy^3 \quad (\text{cubic})$$

where x = mast height, y = top elevation and $a-j$ = coefficients, were generated from the two data sets of all survey respondents and then the 32 stations with moderate and more severe icing. The correlation measures for the bipoynomials are:

	Simple	Quadratic	Cubic
All respondents	0.551	0.664	0.721
Moderate and more severe icing cases	0.564	0.643	0.725

Three-parameter multiple regression, adding “distance to ocean,” produced less favorable correlations. The fact that, at best, only 53% of the variation in our data is explained by the cubic bipolynomial ($R^2 = 0.725^2 = 0.53$) suggests either ambiguity and immeasurable subjectivity in our data or a dependence on other information that we did not obtain. These factors could be related to microclimatic influences or undocumented structural

design variations as two possibilities. However, it does appear that there is some correlation between icing costs and the variables of top elevation and mast height. As the ground elevation and the height of the mast above the ground increase, icing becomes more severe and related costs become greater. A warning signal for designers in this region is the fact that 15 out of 16 existing stations in our study having top elevations exceeding 760 m, or mast heights greater than 275 m, all reported moderate or more severe icing.

Total annual costs

The damage and maintenance cost ranges in Appendix B for all stations were totaled and are shown below:

Annual cost of icing protection maintenance	\$19,000– 52,000
Annual icing damage estimate	\$34,000– 61,000
Total annual icing-related costs	\$53,000–113,000

Since the figures are for a survey return of 25% for New England alone, and since many participants undoubtedly tempered the seriousness of their problems, tower icing is clearly a problem of considerable economic importance. At least three TV towers in Maine (WCSH, WVII and WABI) and one on Mt. Greylock in Massachusetts (WCDC) have collapsed due to icing just since 1983. In our estimates of annual costs, we have not included tower replacement costs or revenue losses during replacement periods. The total 1983 damages for the WCDC accident alone were estimated to be \$500,000.

CONCLUSIONS

High towers on mountaintops are most likely to experience atmospheric icing and associated problems. Costs are higher on average for the northern states of Maine, New Hampshire and Vermont. However, ocean proximity for all New England seems to result in lower annual costs. To protect the quality and dependability of their broadcasts, owners of high-risk installations must employ protection measures. Forty-eight percent of all stations surveyed use some type of icing protection. Deicing of antenna elements and safeguarding against falling ice is a necessity for TV and the majority of FM transmitters. With the current technology, deicing is most often accomplished by ac-

tivating resistance heating methods in advance of the icing event. Seventy-seven percent of protected stations use electric antenna deicers. AM transmission facilities are not as sensitive to atmospheric icing, although falling ice still must be considered as a potential cost of operation. Costs due to icing appear to increase with the tower's height and overall top elevation, and decrease with ocean proximity. With one exception, all stations with at least 275 m mast heights and/or top elevations in excess of 760 m AMSL reported at least moderate icing. According to our data, icing costs were not related to the use of guyed or non-guyed towers, as other factors were influential and produced contradictory results in analyzing tower type. Total expenditures for maintenance of icing protection systems and damage repairs for our 25% sampling of New England stations were between \$53,000 and \$113,000 annually, discounting tower replacement costs and revenue losses during replacement periods.

Icing is an important consideration for designers, owners, and engineers. Local climatological records for tower sites can be a valuable tool if carefully studied to determine expected frequency and severity of icing. Based on these data and the type of broadcasting equipment in use or to be installed, protective measures can be better evaluated for their cost effectiveness.

LITERATURE CITED

- Ackley, S.F., K. Itagaki and M.D. Frank** (1973) An evaluation of passive deicing, and mechanical deicing and ice detection. Final report for the Federal Aviation Administration, Washington, D.C. Systems Research and Development Service. 50 pp.
- Ahti, K. and L. Makkonen** (1982) Observations on rime formation in relation to routinely measured meteorological parameters. *Geophysica*, 19 (1): 75-85.
- Austin, J.M. and S.L. Hensel** (1956) Analysis of freezing precipitation along the eastern North American coastline. Massachusetts Institute of Technology Meteorology Department, Technical Report no. 112.
- Bennett, I.** (1959) Glaze: Its meteorology and climatology, geographical distribution, and economic effects. Quartermaster Research and Engineering Center, Technical Report EP-105, 217 pp.
- Billello, M.A.** (1971) Frozen precipitation: Its frequency and associated temperatures. USA Cold Regions Research and Engineering Laboratory, Preprint for paper delivered at the Eastern Snow Conference, Fredericton, New Brunswick, 13 pp.
- Chaine, P.M., R.W. Verge, G. Castonguay and J. Gariepy** (1974) Wind and ice loading in Canada. Industrial Meteorology Study II, Environment Canada, Atmospheric Environment, Toronto, 32 pp.
- Chaine, P.M. and P. Skeates** (1974) Wind and ice-loading criteria selection. Industrial Meteorology Study III, Environment Canada, Atmospheric Environment, Toronto, 14 pp.
- Donaldson, R.** (1985) Vibration applied in the control of atmospheric icing on radio and television transmission towers. Bachelor of Engineering Project, Thayer School of Engineering, Dartmouth College, Hanover, New Hampshire, 38 pp.
- Edwards, A.T.** (1970) Conductor galloping. Paper presented by Working Group 01 of Study Committee No. 22, Ontario Hydro, Toronto, 48 pp.
- Electronic Industries Association** (1976) Structural standards for steel antenna towers and antenna supporting structures. EIA Standard RS-222-C, pp. 2-3.
- Glukov, V.G.** (1971) Evaluations of ice loads on high structures from upper air observations. *Soviet Hydrology*, 3: 223-228.
- Glukov, V.G.** (1974) Distribution of glaze-rime deposits in the lower 300-meter layer of the atmosphere. Army Foreign Science and Technology Center, Charlottesville, Virginia, 18 pp.
- Hanamoto, B., J.J. Gagnon and B. Pratt** (1980) Deicing a satellite communication antenna. USA Cold Regions Research and Engineering Laboratory, Special Report 80-18, 14 pp.
- Hartranft, G.J.** (1972) Evaluation of a polyurethane shroud designed to prevent TACAN weather outages. Prepared for DOT-FAA Systems Research and Development Service, Washington, D.C, Report no. FAA-RD-72-78, 32 pp.
- Hurd, P. and J. Frank** (1985) Personal interview and telephone communication.
- Itagaki, K.** (1984) Polyethylene glycol as an ice control coating. USA Cold Regions Research and Engineering Laboratory, CRREL Report 84-28, 15 pp.
- Jaakola, Y., J. Laiho and M. Vuorenvirta** (1983) Ice accumulation on tall radio and TV towers in Finland. In *Proceedings of the First International Workshop on Atmospheric Icing of Structures* (L.D. Minsk, Ed.). USA Cold Regions Research and Engineering Laboratory, Special Report 83-17, pp. 249-260.

- Jellinek, H.H.G., H. Kachi, S. Kittaka, M. Lee, and R. Yakota** (1978) Ice-releasing block copolymer coatings. *Colloid and Polymer Science*, **256**: 544–551.
- Lehtonen, P. and J. Laiho** (In press) Ice- and wind-loading measurements on a guyed TV-mast in Finland. In *Proceedings of the Second International Workshop on Atmospheric Icing of Structures, Trondheim, Norway*.
- Lomalina, L.E.** (1977) The effect of relief on glaze-ice and rime deposition. *Soviet Meteorology and Hydrology*, **2**: 39–43.
- Makkonen, L.** (1984) Atmospheric icing on sea structures. USA Cold Regions Research and Engineering Laboratory, CRREL Monograph 84-2, pp. 62–76.
- Meteorological and Environmental Planning (MEP), Ltd. and Ontario Hydro** (1984) *Climatological ice accretion modelling*. Downsview, Ontario, 195 pp.
- McKay, A. and H.A. Thompson** (1969) Estimating the hazard of ice accretion in Canada from climatological data. *Journal of Applied Meteorology*, **8**: 927–935.
- Minsk, L.D.** (1980) Icing on structures. USA Cold Regions Research and Engineering Laboratory, CRREL Report 80-31, 22 pp.
- Panuishkin, V.B., Z.I. Shvaishtein, N.A. Surgacheva and V.S. Podokshik** (1974) Experimental investigations of ice adhesion to construction materials. In *Investigations of the Physical Nature of Ship Icing*. USA Cold Regions Research and Engineering Laboratory, Draft Translation 411, pp. 92–97.
- Parkinson, G.V. and T.V. Santosham** (1967) Cylinders of rectangular section as aeroelastic nonlinear oscillators. ASME Vibrations Conference, Boston, Massachusetts, March 29–31.
- Phan, L.C., P. McComber, and A. Mansiaux** (1977) Adhesion of rime ice and glaze on conductors protected by various materials. *Transactions of the CSME*, **4**(4): 204–208.
- Raevskii, A.N.** (1961) Effect of special relief features on distribution of glaze-ice depositions. *Trudy GGO*, Issue 122, pp. 45–52.
- Sayward, J.M.** (1979) Seeking low ice adhesion. USA Cold Regions Research and Engineering Laboratory, Special Report 79-11, 83 pp.
- Stallabrass, J.R. and R.D. Price** (1963) On the adhesion of ice to various materials. *Canadian Aeronautics and Space Journal*, **9**: 199–204.
- Tattelman, P.** (1982) An objective method for measuring surface ice accretion. *Journal of Applied Meteorology*, **21**: 599–612.
- Tattelman, P. and I.I. Gringorten** (1973) Estimated glaze ice and wind loads at the earth's surface for the contiguous United States. Air Force Cambridge Research Laboratories, Bedford, Massachusetts, 35 pp.
- U.S. Army Air Forces, Weather Information Branch** (1943) Occurrence of wet snow or freezing rain over North America, November through March. Special Study No. 21, 7 pp.
- Williamson, R.A.** (1973) Stability study of a guyed tower under ice loads. *Journal of the Structural Division of the ASCE*, **Dec**: 2391–2408.
- Zavarina, M.V., V.G. Gluchov and M.N. Mytarev** (1977) Method for calculating ice loads on high structures. USA Cold Regions Research and Engineering Laboratory, Draft Translation 620, 12 pp.

APPENDIX A: TOWER ICING SURVEY

TOWER ICING SURVEY - PART 1

Date _____

Station name/channel _____

Address _____

Telephone number _____

Station engineer or person completing questionnaire _____

A. Tower and Location Data

1. Tower manufacturer _____

2. Tower model _____

3. Year installed _____

4. Check one: Self-supporting Guyed

5. Brief description of tower design: _____

6. Do you presently have any weather sensing equipment in place on/at the tower?

7. List all attached apparatus and their approximate location on the tower (ie antennae, anemometer, STL cables, dishes, etc.):

8a. Ground elevation at tower base: _____

b. Height of tower: _____

c. Total height of tower plus antennae: _____

9. List all icing-protection devices now in use (ie radomes, deicers, surface coatings, shields, etc.) and how they are activated (ie manually, temperature-, load-controlled, etc): _____

10. The terrain about the tower is:

a. rural urban

b. totally open totally protected/forested mixed

c. level hilly mountainous

B. General Icing History

1. Do you consider your icing related problems to be:
 insignificant
 less than serious
 moderately serious
 severe

2. Do you consider your wind-related problems to be:
 insignificant
 less than serious
 moderately serious
 severe

3. Please check the appropriate boxes for each of the following wind/ice problems you experience along with the frequency and severity of each:

	Never	Sometimes	Often		Less than serious	Moderately serious	Severe
a.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Diminished transmission signal	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Stretched or frayed guys	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Broken guys	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Wind damage to equipment	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Falling ice damage to tower and equipment	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
f.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Falling ice damage to surrounding property	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
g.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Total broadcast outage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

- 4a. We have experienced complete tower collapse:
 never once more than once

- b. which was caused by:
 icing wind neither both

5. If you do not consider icing to be a problem, which statement is most descriptive of your situation?
 Weather and/or location prevent ice accumulation/damage.
 Protective devices are adequate in preventing ice accumulation/damage.

6. For your station :
- a. What dollar amount of icing damage would you consider major? _____
- b. How often do these major events occur ?
 never times per year once every years

7. Our average annual cost for wind/ice damage repairs is:
- 0 to \$250
 - 250 to \$500
 - 500 to \$1000
 - 1000 to \$5000
 - 5000 to \$10,000
 - > \$10,000
8. Our average annual cost for maintaining icing protective equipment is:
- 0 to \$250
 - 250 to \$500
 - 500 to \$1000
 - 1000 to \$5000
 - 5000 to \$10,000
 - > \$10,000
9. Our dollar cost for lost air time is \$_____ per min/hr/day.
10. We are/are not interested in participating in the second part of the survey to document individual icing events during the coming winter season.
11. Comments/Questions _____

Please return completed questionnaire to :

Nathan Mulherin
 Snow and Ice Branch
 Cold Regions Research and Engineering Laboratory
 72 Lyme Road
 Hanover, New Hampshire 03755

Thank you.

TOWER ICING SURVEY - PART 2

INSTRUCTIONS: This part of the survey is to be used to provide detailed information on the icing events as they occur this winter (1984-85).

We would like information on all incidences of transmitter tower icing.

USE A PHOTOCOPY of this questionnaire to file your reports.

We realize that many stations receiving this survey deal with icing constantly throughout the winter so we ask instead that you summarize your situation on a monthly basis using Section B. In addition to the monthly summary however, each damaging or disruptive event should be reported separately using Section A of Part 2.

Please return each report as it is completed to:

Nathan Mulherin
Snow and Ice Branch
Cold Regions Research and
Engineering Laboratory
72 Lyme Road
Hanover, New Hampshire 03755

If you have experienced no incidences that you would consider reportable by May 15th (1985), please mark the space below and return this page only.

_____ no icing experienced this year

Today's date _____

Station name/channel _____

Address _____

TOWER ICING SURVEY - PART 2

Station name/channel _____

Address _____

SECTION A :

Person completing questionnaire _____

Today's date _____

1. Time of icing:

a. icing began _____ (date)

b. icing ended _____ (date)

2a. Type of ice (check all that were present and circle that which was most abundant) :

___ soft rime (breaks easily) ___ hard rime (smoother, denser)

___ clear glaze

b. Did the ice build up uniformly? _____ (yes/no)

c. How thick? _____

3. Please provide the following information (if available or your best estimate) of the conditions at ground elevation immediately preceding ice formation on the tower :

temperature	_____	_____
windspeed	_____	_____
wind direction	_____	_____
humidity	_____	_____
precipitation	_____	_____

4. If falling ice occurred, please answer the following :

a. Date when shedding began _____

b. Date when shedding ended _____

c. The pieces that fell ranged in size from _____ to _____ .

d. I believe the icfall was caused by :

___ wind ___ warm weather ___ both ___ other (_____)

e. Please provide the following information (if available or your best estimate) of the conditions at ground elevation immediately preceding the icfall from the tower :

temperature	_____	_____
windspeed	_____	_____
wind direction	_____	_____
humidity	_____	_____
precipitation	_____	_____
percent sunshine	_____	_____

5. If damage or disruption occurred as a result of icing (ie falling ice damage, structural stress, signal interference, etc.),

a. describe the problem(s) _____

b. Dollar cost estimate of damage _____ .

c. Lost broadcast time _____ (mins/hrs/days) .

ALTERNATE REPORT

TOWER ICING SURVEY - PART 2

Station name/channel _____

Address _____

SECTION B :

Person completing questionnaire _____

SUMMARY FOR THE MONTH OF _____

1. Number of days with each type of ice and the thickness range :

___ Soft rime _____ to _____ thick

___ Hard rime _____ to _____ thick

___ Clear glaze _____ to _____ thick

2. Number of days during which ice fell from the tower : _____ .

3. Give percentage of days you believe that the icefall was caused by :

___ Wind

___ Sun

___ Warm weather (cloudy)

___ Combination of two of the above conditions

___ Other (_____)

4. The pieces that fell from the tower ranged in size from

_____ to _____ (soft rime)

_____ to _____ (hard rime)

_____ to _____ (clear glaze)

Station:Offices (Main location, if different) Respondent	Transmitter Elevation 1	Icing Degree 2	Maintenance 3	Repairs 4	Specific Problems, Frequency 5 and Degree 2		
<u>Connecticut</u>							
1. WICC-AM: Bridgeport L. Ludovici	B = 2 91 T = 93	M	0	1	Wind damage to equipment Falling ice damage to equipment	S	L
2. WNAB-AM: Bridgeport R. Pieger	- 104 -	L	0	1	Stretched or frayed guys Icing not a problem - no protective devices in use	S	L
3. WLAD-AM/WDAQ-FM: Danbury R. Cihak	223 81 304	I	1	1	Protective devices prevent most problems (temp-activated FM antenna heaters)		
4. WRCH-FM: Farmington T. Ray	122 408 530	M	2	2	Diminished signal Falling ice damage to equipment Falling ice damage to surrounding property Polymer surface coating on FM antenna elements	S	M
5. WGCH-AM: Greenwich F. Haidu	8 47 54	L	0	-	Diminished signal Falling ice damage to equipment Falling ice damage to surrounding property	S	S

- 1 - Elevations given in meters above mean sea level: B = elevation at base of tower, T = elevation at top of uppermost element on tower.
- 2 - Degree of icing is an overall subjective evaluation by individual responding to questionnaire:
I - insignificant, L = less than serious, M = moderately serious, S - serious.
- 3 - Average cost per year for maintenance of icing protective equipment using same key as below.
- 4 - Average cost per year for icing damage repairs: 0 = 0 dollars, 1 = 0-\$250, 2 = 250-\$500,
3 = 500-\$1000, 4 = 1000-\$5000, 5 = 5000-\$10,000, 6 =>\$10,000.
- 5 - S = sometimes, O = often.

Station:Offices
(Mast location, if different)
Respondent

Transmitter
Elevation ¹

Icing Degree ²

Maintenance ³

Repairs ⁴

Specific Problems, Frequency ⁵ and Degree ²

Connecticut (cont.)

6. WLHV-FM: Hartford (Meriden) D. Dornfeld	B = 213 27 T = 241	M-S	0	1	Diminished signal Falling ice damage to surrounding property Total broadcast outage Wide-band FM antenna currently in use but not adequate - may install antenna heaters in near future.	S S S	M M S
7. WESU-FM: Middletown R. Stoller	107 8 114	I	0	0	No problems in 4 yr. history of present set-up (small tower) Icing not a problem - no protective devices in use		
8. WSLX-FM: New Canaan M. Cashian	145 12 165	I	0	1	Icing not a problem - no protective devices in use No problems since installed 8/84 (small tower)		
9. WTNH-TV: New Haven B. Russo	195 277 472	M	2	3	Diminished signal Falling ice damage to equipment Falling ice damage to surrounding property Total broadcast outage Ice detector-activated TV antenna heaters	S O O S S	M M M M M
10. WLYQ-FM: Norwalk C. Mills	35 114 149	I	2	1	Diminished signal Protective devices prevent most problems (manually activated FM antenna heaters left on all winter)	S	L
11. WEDN-TV: Norwich J. Kean	160 146 306	L	1	1	Diminished signal Protective devices prevent most problems (temp and sleet activated TV antenna heaters)	S	L
12. WNPR-FM: Norwich J. Kean	160 146 306	L	0	1	Diminished signal Falling ice damage to equipment	S S	M I
13. WBCT-TV: Seymour J. Goertz	189 90 279	L	1	1	Wind damage to equipment Falling ice damage to equipment Protective devices prevent most problems (radomes on microwave dishes, steel grating ice shields on transmission lines)	S S S	I L L

Station:Offices
(Mast location, if different)
Respondent

Transmitter
Elevation ¹

Icing Degree ²

Maintenance ³

Repairs ⁴

Specific Problems, Frequency ⁵ and Degree ²

Station:Offices (Mast location, if different) Respondent	Transmitter Elevation ¹	Icing Degree ²	Maintenance ³	Repairs ⁴	Specific Problems, Frequency ⁵ and Degree ²		
<u>Connecticut (cont.)</u>							
14. WSTC-AM/WYRS-FM: C. Mills	B = 49 114 T = 163	I	1	1	Protective devices prevent most problems (temp. activated FM antenna heaters)		
15. WILI-AM: Willimantic C. Rice	46 124 170	L	0	1	Diminished signal Icing not a problem - no protective devices in use	S	L
<u>Massachusetts</u>							
16. WFCR-FM: Amherst (Mt. Lincoln, Pelham) C. Ferguson	377 34 411	M	1	1	Diminished signal Stretched guys Total broadcast outage Protective devices prevent most problems (manually activated FM antenna heaters)	S S S	M L S
17. WERS-FM: Boston R. Levy	238 8 246	L	1	2	Protective devices prevent most problems (manually activated FM antenna heaters) Plan to convert to radomes soon		
18. WRBB-FM: Boston C. Tarver	48 60 107	L	0	1	Diminished signal Icing not a problem now - no protective devices in use. No problems since at new location in 1983.	S	L
19. WBPC-FM: Charlton	117 24 142	I	0	1	Stretched or frayed guys Broken guys Icing not a problem - no protective devices in use	S S	M L
20. WIQH-FM: Concord N. Roos	61 9 70	I	0	1	Diminished signal Total broadcast outage Small tower - have no real icing problems	S	S 2/yr.
21. WGAJ-FM: Deerfield J. Hemingway	263 24 287	--	--	--	New installation - no history .		

Station:Offices (Mast location, if different) Respondent	Transmitter Elevation ¹		Icing Degree ²	Maintenance ³	Repairs ⁴	Specific Problems, Frequency ⁵ and Degree ²
<u>Massachusetts (cont.)</u>						
22. WAQY-FM: E. Longmeadow K. Jones	B = 267 <u>158</u> T = 426	M	3	0		Antenna space leased from WWLP-TV, Springfield, MA
23. WIXY-AM: E. Longmeadow K. Jones	110 (4) <u>57</u> 167	L	0	2		Four-tower directional array Diminished signal S L Falling ice damage to surrounding property S L Short, sturdy tower - have no real icing problems No serious problems in 5 yr. history No protective devices in use
24. WALE-AM: Fall River G. Faltus	4 <u>56</u> 60	L	0	1		Diminished signal S L Stretched or frayed guys (wind) S M Wind damage to equipment S M Ice/snow buildup on satellite dish 1-2/mo. Icing not a big problem - no protective devices in use
25. WGAW-AM: Gardiner G. Wiley	335 <u>47</u> 383	I	0	1		Diminished signal ~3/yr. Icing not a problem - no protective devices in use
26. WPOE-AM: Greenfield (J. Hemingway)	76 <u>61</u> 137	I	0	1		Icing not a problem - no protective devices in use.
27. WCCM-AM/WCGY-FM: Lawrence (Andover) J. Soucise	61 <u>123</u> 184	--	0	--		Unknown (new engineer) No protective devices in use
28. WJUI-FM: Lowell R. Weston	- <u>9</u> -	I	1	1		Total broadcast outage S L Protective devices prevent most problems (temp-activated FM antenna heaters)
29. WMLN-FM: Milton A. Frank	67 <u>29</u> 96	L	2	1		Experienced much signal reflection prior to installation of temp. activated FM antenna heater in early 1983 - no problem since.

Station:Offices
(Mast location, if different)
Respondent

Transmitter
Elevation 1

Icing Degree 2

Maintenance 3

Repairs 4

Specific Problems, Frequency 5 and Degree 2

Massachusetts (cont.)

30. WNEV-TV: Boston (Newton) A. Rouff	B = 37	S	5	6	Diminished signal	S	S	
	324					Wind damage to equipment	S	S
	T = 361					Falling ice damage to equipment	S	M
						Falling ice damage to surrounding property	S	S
						Ice detector activated TV antenna heaters, dish radomes, emergency stand-by antenna in place		
31. WZOU-FM : Boston (Newton) P. Hurd	30	S	4	4	Wind damage to equipment	S	L	
	411				Falling ice damage to equipment	S	M	
	441				Falling ice damage to surrounding property	S	S	
					Antenna radomes, iron grillwork ice shields			
32. WJCC-AM: Norfolk S. Callahan	68	L	0	1	Diminished signal	S	L	
	69				Stretched or frayed guys	S	L	
	137				Total broadcast outage	S	L	
					Icing not a big problem - no protective devices in use			
33. WMNB-FM: N. Adams P. Willey	616	L	2	1	Diminished signal	S	M	
	46				Protective devices prevent most problems (manually activated FM antenna heaters left on all winter)			
	661							
34. WHMP- FM Northampton R. Rzeszutek	193	I	1	1	Diminished signal	S	L	
	70				Protective devices prevent most problems (fiber-glass radomes over FM antenna)			
	263							
35. WUNH-AM: Pittsfield R. Backstrom	309	I	0	1	Falling ice damage to surrounding property	S	M	
	67				Total broadcast outage (wind)	S	S	
	376				Icing not a big problem - no protective devices in use			

Station:Offices
(Mast location, if different)
Respondent

Transmitter
Elevation ¹

Icing Degree ²

Maintenance ³

Repairs ⁴

Specific Problems, Frequency ⁵ and Degree ²

Massachusetts (cont.)

36.	WUPE-FM: Pittsfield R. Backstrom	B = 540	L	1	1	Wind damage to equipment	S	M	
		<u>46</u>					Falling ice damage to equipment	S	M
		T = 586				Falling ice damage to surrounding property	S	M	
						Total broadcast outage	S	S	
						Protective devices prevent most problems (precip/ temp-activated FM antenna heaters)			
37.	WSTG-TV: Rehoboth J. Rogers	38	M	3	--	Has been on the air only two winters			
		<u>293</u>					Wind damage to equipment	S	L
		331					Falling ice damage to surrounding property	S	M
						Temp-activated heaters for radomes on TV and FM antennae			
38.	WESO-AM: Southbridge (Dudley) R. LaVallee	195	I	0	0	Tower is overdesigned for its present capacity, no problems experienced in 30 yr. history			
		<u>70</u>							
		265							
39.	WQVR-FM: Southbridge (Dudley) R. LaVallee	250	I	2	0	Protective devices prevent most problems (manually- activated FM antenna heaters left on all winter)			
		<u>46</u>							
		296							
40.	WGGB-TV: Springfield (Holyoke) T. Gratoski	366	L	1	3	Diminished signal	S	L	
		<u>47</u>					Falling ice damage to surrounding property	S	L
		413					Total broadcast outage	S	L
							Protective devices prevent most problems (manually- activated TV antenna heaters)		
41.	WMAS-AM/FM: Springfield B. Shotwell	22	L	0	1	Diminished signal	S	L	
		<u>107</u>					Icing not a problem - no protective devices in use		
		129							
42.	WWLP-TV: Springfield L. Chenenvert	267	L	3	1	Protective devices prevent most problems (ice detector-activated TV antenna heaters)			
		<u>158</u>							
		426							

Station:Offices
(Mast location, if different)
Respondent

Transmitter
Elevation ¹

Icing Degree²

Maintenance³

Repairs⁴

Specific Problems, Frequency⁵ and Degree²

Massachusetts (cont.)

43. WYAJ-FM: Sudbury G. Beth	B = 67 <u>21</u> T = 88	L	0	1	Diminished signal Wind damage to equipment Total broadcast outage Icing not a big problem - no protective devices in use (small tower)	S S S	1 1 1
44. WPEP-AM: Taunton S. Callahan	64 <u>56</u> 120	I	0	1	Stretched or frayed guys Icing not a problem - no protective devices in use		
45. WCRB-FM: Waltham (Needham) D. Maxson	38 <u>366</u> 404	L	1	1	Wind damage to equipment Falling ice damage to equipment Protective devices prevent most problems (radomes on FM antenna)		1/6yr. 1/6yr
46. WSRB-FM: Worcester D. Gaffney	335 <u>59</u> 394	L	1	1	Protective devices prevent most problems (FM antenna heaters)		
47. WTAG-AM: Worcester J. Andrews	250 (1) 250 (2) <u>99</u> <u>116</u> 349 366	L	0	1	Three-tower directional array Diminished signal Falling ice damage to equipment Total broadcast outage Tower collapse (wind - 1938 (3), 1954 (1))	S S S	1 1 1
<u>Maine</u>							
48. WLAM-AM: Auburn H. Wiles	61 (2) <u>56</u> 117	I	0	0	Two-tower directional array Icing not a problem - no protective devices in use		
49. WHSN-FM: Bangor P. Roy	58 <u>22</u> 80	M	0	1	Diminished signal Total broadcast outage	O O	S S

Station:Offices (Mast location, if different Respondent	Transmitter Elevation ¹		Icing Degree ²	Maintenance ³	Repairs ⁴	Specific Problems, Frequency ⁵ and Degree ²		
<u>Maine</u> (cont.)								
50. WPBC-FM: Bangor N. Wetmore	B = 232 44 T = 276		M	1	1	Diminished signal Total broadcast outage Ice shield on the antenna tuning controls	S	M
51. WZON-AM: Bangor N. Wetmore	55 55 123 62 178 117		I	0	2	Stretched or frayed guys Wind damage to equipment Falling ice damage to equipment Falling ice damage to equipment Falling ice damage to surrounding property Total broadcast outage Icing not a big problem - no protective devices in use	S	L
52. WIGY-FM: Bath R. Brace	43 110 152		L	1	1	Diminished signal Protective devices prevent most problems (teflon-coated FM antenna elements)	S	L
53. WQDY-FM: Calais R. Holst	61 85 146		M	2	2	Diminished signal Falling ice damage to equipment Total broadcast outage Manually activated antenna heaters Plan to install a VSWR monitor/activator for heaters	S	S
54. WKSQ-FM: Ellsworth M. Osborne	88 89 178		L	2	1	Diminished signal Temp - activated antenna heaters	S	L
55. WHOU-AM/FM: Houlton N. Wetmore	114 128 242		L	1	1	Wind damage to equipment Protective devices prevent most problems (manually activated FM antenna heaters)	S	L
56. WCBB-TV: Lewiston (Litchfield) R. Desjardins	210 210 193 77 403 287		M	1	3	Falling ice damage to equipment Falling ice damage to surrounding property Downed powerlines Manually-activated antenna heaters, radomes on microwave dishes	S	L

Station:Offices (Mast location, if different) Respondent	Transmitter Elevation 1		Icing Degree 2	Maintenance 3	Repairs 4	Specific Problems, Frequency 5 and Degree 2		
Maine (cont.)								
57. WKZS-FM: Lewiston H. Wiles	B = 143 <u>152</u> T = 296	L	1	1		Diminished signal Protective devices prevent most problems (manually-activated antenna heaters)	S	L
58. WMTW-TV: Poland Springs (Mt. Washington, NH) J. Ricker	1906 <u>37</u> 1943	S	3	1		Diminished signal Stretched or frayed guys Wind damage to equipment Falling ice damage to equipment Glaze ice/high wind damage to microwave dish Icing occurs 8-9 months of year Protective devices and short tower prevent most problems (metal tower radome, fiberglass TV antenna radome)	S S S O ~2-3/y	L M M M
59. WCSH-TV: Portland R. Dean	375 <u>398</u> 773	S	5	6		Diminished signal Wind damage to equipment Falling ice damage to equipment Falling ice damage to surrounding property Total broadcast outage Tower collapse (icing-3/83) Temp-activated antenna heaters, radomes on antenna and microwave dish, ice shield (steel I-beams w/oak boards & chain link fence on roof of transmitter building)	S S O S S	L L S M L
60. WDCS-FM: Portland G. Terwilliger	23 <u>88</u> 111	I	0	1		Protective devices prevent most problems (radomes on FM antenna)		
61. WJBQ-FM: Portland (Gorham) G. Terwilliger	76 <u>142</u> 218	L	0	1		Diminished signal Wind damage to equipment Total broadcast outage Icing not a big problem - no protective devices in use	S S S	L L L

Station:Offices (Mast location, if different) Respondent	Transmitter Elevation ¹	Icing Degree ²	Maintenance ³	Repairs ⁴	Specific Problems, Frequency ⁵ and Degree ²
<u>Maine (cont.)</u>					
62. WMER-AM: Portland (Westbrook) G. Terwilliger	B = 15 54 T = 69	I	0	1	Three-tower directional array Icing not a problem - no protective devices in use
63. WYNZ-AM: Portland (Scarborough) J. Goran	15 74 89	L	0	0	Icing not a big problem - no protective devices in use. (based only on last two winters)
64. WYNZ-FM: Portland J. Goran	23 69 91	M	2	1	Diminished signal S L Falling ice damage to equipment S L Falling ice damage to surrounding property S L No damage in last two years Protective devices prevent most problems (manually activated FM antenna heaters)
65. WRKD-AM/WCMC-FM: (Rockland) E. Hammond	0 79 79	L	2	1	Diminished FM signal S L Protective devices prevent most problems (temp- activated FM antenna heaters)
<u>New Hampshire</u>					
66. WJYY-FM: Concord L. Collins	283 24 308	L	0	0	Diminished signal S L Protective devices prevent most problems (radomes on FM antenna)
67. WKXL-AM: Concord L. Leblanc	87 94 181	I	1	0	Icing not a problem - no protective devices in use. Never lost airtime due to icing.
68. WKXL-FM: Concord L. Leblanc	194 30 224	I	1	0	Protective devices prevent most problems (manually- activated FM antenna heaters) Never lost airtime due to icing, since 1946.
69. WBNC-AM: Conway S. Sherman	137 73 210	I	0	1	Diminished signal S L Icing not a problem - no protective devices in use

Station:Offices
(Mast location, if different)
Respondent

Transmitter
Elevation ¹

Icing Degree²

Maintenance³

Repairs⁴

Specific Problems, Frequency⁵ and Degree²

New Hampshire (cont.)

70. WMWV-FM: Conway S. Sherman	B = 372 24 T = 396	L	0	1	Diminished signal Icing not a problem - no protective devices in use	S	I.
71. WDER-AM: Derry K. Slotin	140 (4) 90 230	I	0	1	Four-tower directional array Icing not a problem - no protective devices in use		
72. WNDS-TV: Derry (Hudson) G. Chadwick	122 152 274	L	1	1	Diminished signal Stretched or frayed guys Wind damage to equipment Total broadcast outage Protective devices prevent most problems (manually - activated TV antenna heaters) "Most problems are wind related"	S S S S	M I. S L
73. WTSN-AM: Dover P. LeBlanc	18 (4) 62 81	M	0	1	Four-tower directional array Icing not a problem - no protective devices in use.		
74. WDCR-AM/WFRD-FM: Hanover (W. Lebanon) G. Bourozikas	324 49 404	I	1	1	Diminished signal Protective devices prevent most problems (manually - activated FM antenna heaters)	S	I.
75. WKBK-AM: Keene L. Collins	146 53 200	I	0	1	Icing not a problem - no protective devices in use		
76. WTSL-AM: Lebanon D. Clarke	160 46 206	I	0	1	Icing not a problem - no protective devices in use		
77. WFEA-AM: Manchester S. Vanni	(1) 61 (2) 61 114 61 175 122	I	0	0	Three-tower directional array Icing not a problem - no protective devices in use		

Station:Offices (Most location, if different) Respondent	Transmitter Elevation 1		Icing Degree 2	Maintenance 3	Repairs 4	Specific Problems, Frequency 5 and Degree 2		
<u>New Hampshire (cont.)</u>								
78. WCIR-FM: Manchester W. Small	B = 390 38 T = 428	MS	2	1		Diminished signal Falling ice damage to equipment Manually activated FM antenna heaters left on all winter. Had only one damage incident in last 6½ years	S	M
79. WCIR-AM: Manchester W. Small	61(4) 91 152	L	0	1		Four-tower directional array Diminished signal Icing not a big problem - no protective devices in use	S	L
80. WMDK-FM: Peterborough D. Buren	594 37 632	M	1	1		Diminished signal Broken guys Wind damage to equipment Falling ice damage to equipment Falling ice damage to surrounding property Manually-activated FM antenna heaters left on all winter	S	L M L M S
81. WASR-AM: Wolfboro A. Severy	171 63 234	L	0	0		Icing not a problem - no protective devices in use		
<u>Rhode Island</u>								
82. WCVY-FM: Coventry S. Jurczyk	94 12 107	I	0	1		Diminished signal Total broadcast outage Icing not a problem - no protective devices in use	S	L L
83. WRIU-FM: Kingston D. Egan	50 123 173	L	1	1		Protective devices prevent most problems (temp-activated FM antenna heaters) Will install ice detector - summer '85		
84. WOTB-FM: Middletown D. Egan	67 21 89	I	0	1		Diminished signal Wind damage to equipment Falling ice damage to surrounding property Icing not a problem - no protective devices in use	S	L L L

Station:Offices (Main location, if different) Respondent	Transmitter Elevation 1	Icing Degree ²	Maintenance ³	Repairs ⁴	Specific Problems, Frequency ⁵ and Degree ²		
						S	L
<u>Rhode Island (cont.)</u>							
85. WADK-AM: Newport R. Sullivan	B = 9 98 T = 107	I	0	1	Broken guys Icing not a problem - no protective devices in use	S	L
86. WEAN-AM/WPJB-FM: Providence D. Puopolo	73 149 223				Diminished signal Wind damage to equipment Falling ice damage to equipment Total broadcast outage Protective devices prevent most problems (ice detector/temp-activated FM antenna heaters) Icing events fluctuate from 0 to 3-4 times/yr.	S	M
87. WHJJ-AM: Providence (Riverside) P. Philbrook	3 134 137	L	1	1	Two-tower directional array "Extra heavy-duty tower construction and few freezing rainstorms responsible for few problems"		
88. WHJY-FM/WBRU-FM/WHIM-AM: Providence P. Philbrook	12 166 181	L	1	1	Diminished signal Tower collapse (wind-1954) Freezing rain 2-3 times/yr.	S	L
89. WJAR-TV: Providence (Rehoboth, MA) R. Kane	69 69 305 152 373 221	I	1	1	Diminished signal Falling ice damage to surrounding property Protective devices prevent most problems (temp/moisture-activated FM and TV antennae heaters)	S	L
90. WKRI-AM: W. Warwick J. Mattias	76 61 137	I	0	1	Total broadcast outage Tower collapse (wind, rusted guys) Icing not a problem - no protective devices in use	S	L
<u>Vermont</u>							
91. WKVT-AM: Brattleboro	101 46 147	L	0	1	Icing not a problem - no protective devices in use		
92. WKVT-FM: Brattleboro	469 46	M	0	0	Diminished signal Protective devices prevent most problems (wide-		~2/yr

43

Station:Offices
(Mast location, if different)
Respondent

Transmitter
Elevation ¹

Icing Degree ²

Maintenance ³

Repairs ⁴

Specific Problems, Frequency ⁵ and Degree ²

Vermont (cont.)

93. WCAX-TV: Burlington
(Mt. Mansfield)
T. Teffner

B = 1219
40
T = 1259

S

3

0

Diminished signal
Falling ice damage to equipment
Protective devices prevent most problems (manually-
activated TV antenna heaters, wooden transmission
line ice shields)

S L
S L

94. WETK-TV: Burlington
(Mt. Mansfield)
R. Whitcomb

1259
32
1291

M

3

1

Diminished signal
Wind damage to equipment
Falling ice damage to equipment
Falling ice damage to surrounding property
Protective devices prevent most problems (ice
detector-activated TV antenna heaters)

S M
S M
S M
S M

95. WJOY-AM/WQCR-FM:
Burlington
D. Snyder

87
110
197

I

1

1

Diminished signal
Falling ice damage to equipment
"Freezing rain occurs about 6 times/yr but severity
of events is moderated by Lake Champlain proximity."
Protective devices prevent most problems (temp-activated
FM antenna heaters)

S I
S I

96. WVMT-AM: Burlington
(Colchester)
M. Seguin

31 (3)
90
122

I

0

1

Three-tower directional array
Diminished signal
Icing not a big problem - no protective devices in use

S L

97. WVNY-TV: Burlington
(Mt. Mansfield)
R. McClintock

1280
92
1372

M

3

3

Diminished signal
Wind damage to equipment
Falling ice damage to equipment
Falling ice damage to surrounding property
Ice detector - activated TV antenna heaters
Ice shields on FM and two-way antennae
 $\frac{1}{2}$ " boiler plate steel shielding over transmission
line bridge
Steel I-beam rafters w/ $\frac{1}{2}$ " boiler plate steel roof on
transmitter building

S M
O S
S L
S L

Station:Offices
(Mast location, if different)
Respondent

Transmitter
Elevation ¹

Icing Degree ²

Maintenance ³

Repairs ⁴

Specific Problems, Frequency ⁵ and Degree ²

Vermont (cont.)

98. WXXX-FM: Burlington H. Ginsberg	B = 131 37 T = 168	-	0	-	Installed 11/84 Diminished signal (4 times last winter) No protective devices in use	S	M
99. WIUV-FM: Castleton W. Freeman	151 6 157	L	0	1	Diminished signal Icing not a big problem - no protective devices in use (short tower)	S	L
100. WWLR-FM: Lyndonville C. Parker	296 26 321	L	2	1	Diminished signal Protective devices prevent most problems (temp- activated FM antenna heaters)	S	L
101. WSKI-AM: Montpelier G. Marcotte	198 53 251	L	0	1	Diminished signal Wind damage to equipment Total broadcast outage Icing not a problem - no protective devices in use "Can't recall any problems from ice in past 3 yrs."	S S S	L L L
102. WRUT-FM: Rutland (Mt. Killington) D. French	1291 18 1309	S	2	1	Diminished signal Falling ice damage to equipment Falling ice damage to surrounding property Total broadcast outage Tower collapse (icing) Protective devices prevent most problems (fiberglass radome on STL dish with temp-activated heaters, manually-activated FM antenna heaters)	S S S S	L M M M once
103. WSTJ-AM: St. Johnsbury P. Morton	226 56 282	I	0	1	Diminished signal Broken guvs Falling ice damage to equipment Icing not a problem - no protective devices in use	S S S	L L L

Station:Offices
(Mast location, if different)
Respondent

Transmitter
Elevation ¹

Icing Degree ²

Maintenance ³

Repairs ⁴

Specific Problems, Frequency ⁵ and Degree ²

Vermont (cont.)

104. WVTB-TV: St. Johnsbury (Burke Mtn.) R. Whitcomb	B = 1032 40 T = 1072	M	3	1	Diminished signal Wind damage to equipment Falling ice damage to equipment Falling ice damage to surrounding property Protective devices prevent most problems (ice detector-activated TV antenna heaters)	S S S S	
105. WCFR-AM/FM: Springfield I. Wilner	244 91 335	I	1	1	Diminished signal Protective devices prevent most problems (manually-activated FM antenna heaters)	S	I.
106. WNHV-AM: White River Jct. A. Leckart	134 75 209	I	0	1	Icing not a problem - no protective devices in use		
107. WNHV-FM: White River Jct. (W. Lebanon, NH) A. Leckart	305 61 366	I	1	1	Protective devices prevent most problems (manually-activated FM antenna heaters)		
108. WNNE-TV: White River Jct. (Mt. Ascutney) J. Alvin	920 49 969	S	4	4	Diminished signal Wind damage to equipment Falling ice damage to equipment Total broadcast outage Temp-activated heaters on TV antenna and dishes	S O O S	M S S M