**US Army Corps
of Engineers®**
Engineer Research and
Development Center

Fort McCoy, Wisconsin WWII Buildings and Landscapes

Sunny E. Adams, Megan W. Tooker, and Adam Smith

November 2020

The U.S. Army Engineer Research and Development Center (ERDC) solves the nation's toughest engineering and environmental challenges. ERDC develops innovative solutions in civil and military engineering, geospatial sciences, water resources, and environmental sciences for the Army, the Department of Defense, civilian agencies, and our nation's public good. Find out more at www.erdc.usace.army.mil.

To search for other technical reports published by ERDC, visit the ERDC online library at <http://acwc.sdp.sirsi.net/client/default>.

Cover: Aerial view of the 100 Block from the south, 1988 (Library of Congress).

Fort McCoy, Wisconsin WWII Buildings and Landscapes

Sunny E. Adams, Megan W. Tooker, and Adam Smith

*Construction Engineering Research Laboratory
U.S. Army Engineer Research and Development Center
2902 Newmark Drive
Champaign, IL 61822*

Final Technical Report (TR)

Approved for public release; distribution is unlimited.

Prepared for Cultural Resource Manager
Directorate of Public Works
Fort McCoy, WI 54656

Under Project Number 474178, "Inventory/Integrity Analysis of WWII Buildings,
Fort McCoy, WI"

Abstract

The U.S. Congress codified the National Historic Preservation Act of 1966 (NHPA) mostly through the National Register of Historic Places (NRHP), which requires federal agencies to address their cultural resources. Section 110 of the NHPA requires federal agencies to inventory and evaluate their cultural resources, and Section 106 requires them to determine the effect of federal undertakings on those potentially eligible for the NRHP.

This report provides a World War II development history and analysis of 786 buildings, and determinations of eligibility for those buildings, on Fort McCoy, Wisconsin. Evaluation of the WWII buildings and landscape concluded that there are too few buildings with integrity to form a cohesive historic district. While the circulation patterns and roads are still intact, the buildings with integrity are scattered throughout the cantonment affecting the historic character of the landscape. Only Building 100 (post headquarters), Building 656 (dental clinic), and Building 550 (fire station) are ELIGIBLE for listing on the NRHP at the national level under Criterion A for their association with World War II temporary building construction (1942-1946) and under Criterion C for their design, construction, and technological innovation.

DISCLAIMER: The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official endorsement or approval of the use of such commercial products. All product names and trademarks cited are the property of their respective owners. The findings of this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

DESTROY THIS REPORT WHEN NO LONGER NEEDED. DO NOT RETURN IT TO THE ORIGINATOR.

Contents

Abstract.....	ii
Figures and Tables.....	vii
Preface	xli
1 Methodology.....	1
1.1 Background	1
1.2 Objective	2
1.3 Researchers	24
1.4 Site Visits.....	25
1.1.1 Fort McCoy	25
1.1.2 Archival repositories	25
1.1.3 Analysis and evaluation	25
2 WWII Development History	27
1.2 Cantonment Design	27
1.3 Block Areas	33
1.4 Architectural Building Construction.....	36
1.4.1 Living Quarters	38
1.4.2 Administration/Recreation Buildings	65
1.4.3 Administration Buildings.....	71
1.4.4 Recreation Buildings	89
1.4.5 Mess Halls	98
1.4.6 Storehouse Buildings.....	108
1.4.7 Repair and Service Buildings.....	116
1.4.8 Support Buildings	119
3 Character-defining features.....	144
1.5 Landscape Features.....	144
1.5.1 Layout and design	144
1.5.2 Land use.....	147
1.5.3 Transportation networks.....	149
1.5.4 Expressions of military culture.....	155
1.5.5 Building Clusters.....	157
1.5.6 Vegetation	159
1.5.7 Small-scale features.....	165
1.5.8 Views and viewsheds.....	170
1.6 WWII temporary building features for the 800 Series.....	173
1.6.1 Exterior	174
1.6.2 Interior.....	181
2 Current Condition Buildings	191
2.1 Number 1 Type.....	191

2.1.1	Living Quarters	193
2.1.2	Administration/Recreation Combination	198
2.1.3	Administration Buildings	206
2.1.4	Recreation Buildings	219
2.1.5	Mess Halls	224
2.1.6	Storehouse Buildings	231
2.1.7	Support Buildings	236
2.2	Number 2 Type	251
2.2.1	Living Quarters	257
2.2.2	Administration/Recreation Combination Buildings	262
2.2.3	Administration Buildings	264
2.2.4	Recreation Buildings	268
2.2.5	Mess Halls	270
2.2.6	Storehouse Buildings	273
2.2.7	Repair and Service Buildings	275
2.2.8	Support Buildings	278
2.4	Number 3 Type	283
2.4.1	Living Quarters	297
2.4.2	Administration/Recreation Combination Buildings	304
2.4.3	Administration Buildings	307
2.4.4	Recreation Buildings	309
2.4.5	Mess Halls	313
2.4.6	Storehouse Buildings	318
3.1.1	Repair and Service Buildings	319
2.4.7	Support Buildings	321
4	Current Condition of Landscape	326
4.1	Whole Cantonment Landscape	326
4.2	Company Blocks	328
2.4.8	Number 1, 2, 3 Types in Cantonment Blocks	328
2.4.9	100 Block	329
4.2.1	200 Block	332
4.2.2	300 Block	333
4.2.3	400 Block	335
4.2.4	500 Block	337
4.2.5	600 Block	340
4.2.6	700 Block	344
4.2.7	800 Block	348
4.2.8	900 Block	352
4.2.9	1000 Block	354
4.2.10	1100 Block	357
4.2.11	1200 Block	361
4.2.12	1300 Block	365
4.2.13	1400 Block	369
4.2.14	1500 Block	372
4.2.15	1600 Block	375

4.2.16	1700 Block	379
4.2.18	1800 Block	384
4.2.19	1900 Block	387
4.2.20	2000 Block	390
4.2.21	2100 Block	396
4.2.22	2200 Block	399
4.2.23	2300 Block	400
2.4.10	2400 Block	401
4.2.24	2500 Block	404
4.2.25	2600 Block	409
4.2.26	2700 Block	414
4.2.27	2800 Block	416
5	Determination of Significance	422
5.1	Categories of Historic Properties	422
5.2	NRHP Definitions and Criteria	423
5.3	Final recommendations of significance	424
2.4.11	WWII temporary buildings significance	425
2.4.12	Historic District	426
2.4.13	National, state, or local significance	426
6	Aspects of Integrity	427
6.1	Seven aspects of integrity	427
6.2	Integrity determinations	428
2.4.14	General exterior architectural elements	430
2.4.15	74-man barracks	431
2.4.17	Officers' quarters – Types BOQ-40, OBQ-40, OQM-40, OQ-40	436
2.4.18	Officers' quarters – Types BOQ-44	437
2.4.19	Officers' quarters – Type OQ-23, 700 Series	438
2.4.20	WAC barracks	439
2.4.21	Brigade general's quarters – Type BGQ-1	439
2.4.22	Regimental commander's quarters – Type RCQ-1	440
2.4.23	Company storehouse, administration, and recreation building	440
2.4.25	Company storehouse, administration, and recreation building [MOD]	442
2.4.26	Administration building – Type IBA-1	443
2.4.28	Administration building – Type A-3	444
2.4.29	Administration building – Type A-10	444
2.4.30	Unit guard house, Type UGH-12	445
2.4.32	Unit guard house, Type UGH-24	446
2.4.34	Unit guard house, Type UGH-36	447
2.4.36	Post administration building, Division Headquarters, Type DHQ-1	448
2.4.37	Recreation building – gymnasium (RB-1)	449
2.4.38	Recreation building – Type RB-2	450
2.4.39	Recreation building – Type RB-4	451
2.4.40	Service clubs	452
2.4.41	Type M-112-man mess halls	453

2.4.42 Type M-152-man mess halls	454
2.4.43 Type M-172-man mess halls	455
2.4.44 Type M-228-man mess halls	456
2.4.45 Standard storehouse, Type SH-8.....	457
2.4.46 Standard storehouse, Type SH-9.....	458
2.4.47 Standard storehouse, Type SH-13.....	459
2.4.48 Standard storehouse, Type SH-18.....	459
2.4.49 Grease rack enclosure building.....	460
2.4.50 Vehicle storage building.....	460
2.4.51 Carpentry shop.....	461
2.4.52 Motor repair shop.....	462
2.4.53 Railroad shop.....	463
2.4.54 Utility shop.....	463
2.4.55 G.U. Dispensary – Type G.U.D.-1	464
2.4.56 Dental clinic – Type DC-1	465
2.4.57 Infirmary.....	465
2.4.58 Regimental exchange.....	466
2.4.59 Regimental chapels.....	467
2.4.61 Fire stations	468
2.4.63 Post office	469
7 Final Recommendations for Eligibility and Conclusion	470
2.5 WWII Temporary Buildings.....	471
2.6 Overall WWII Military Landscape.....	471
2.7 Proposed Historic District.....	476
2.8 Conclusion.....	480
2.9 Inventory Forms.....	513
References.....	515
Acronyms and Abbreviations.....	517
Conversion Factors.....	518
Report Documentation Page (SF 298).....	519

Figures and Tables

Figure		Page
1	Boundary outline and location of Fort McCoy, WI (DPW, Fort McCoy)	2
2	Fort McCoy cantonment map, 2014 (DPW, Fort McCoy)	3
3	Adaptation of a typical layout at Camp McCoy showing relationship of units to their training areas, March 1942 (<i>Engineering Manual of the Office of the Chief of Engineers</i>)	28
4	Photograph of Camp Robinson light artillery, c 1918 (WI Historical Society)	29
5	Plan 614-179, prepared by the Site Planning Unit, depicting a typical layout for a triangular division, dated October 7, 1941	31
6	Master Plan for Camp McCoy, 1941 (DPW, Fort McCoy)	33
7	Plan of cantonment regimental grouping, 1940 (Garner 1993, 66)	34
8	Typical block plan from 1941 plan for Camp McCoy (barracks (B), mess halls (M), recreation buildings (RB) and administration (SA) (DPW, Fort McCoy)	35
9	Aerial view of the 1800 Block showing fire breaks, 1988 (Library of Congress)	35
10	General view looking north of fire break at end of East Eaton Road and East 12th Street, 1988 (Library of Congress)	36
11	800 Series floor plans for 74-man barracks, Plan Number 800-443, 1941 (Library of Congress)	40
12	74-man barracks framing details, Plan Number 800-444, 1941 (courtesy Fort McCoy DPW)	40
13	Details of wooden platform and wooden ladder on rear elevation of 74-man barracks, Plan Number 800-445, 1941 (courtesy of Fort McCoy DPW)	41
14	Southeast oblique of Building 1129, 74-man barracks, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-A-2)	41
15	South (front) side of 800 Series 74-man barracks at Fort McCoy, 1988 (Library of Congress, HABS WIS, 41-SPAR. V, 1-A-6)	42
16	Rear side of a 74-man barracks, showing one set of original doors, wooden platform, and wooden ladder and the removal and opening modification of the other set, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-A-7)	42
17	Second floor squad room in Building 1129, 74-Man barracks at Fort McCoy, 1988 (Library of Congress, HABS WIS, 41-SPAR.V,1-A-16)	43
18	Interior view of the toilet room on the first floor in Building 1129, 74-Man barracks at Fort McCoy, 1988 (Library of Congress, HABS WIS,41-SPAR.V,1-A-13)	43

Figure		Page
19	Quarters and Mess, Officers, Type OMQ-40, Plan Number 700-1257 (modified at McCoy), 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-S-7)	45
20	Northeast oblique of Building 655, bachelor officers' quarters, Type BOQ-40, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-S-2)	45
21	Southeast oblique of Building 655, bachelor officers' quarters, Type BOQ-40, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-S-1)	46
22	Northwest oblique of Building 655, officers' quarters, Type BOQ-40, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-S-3)	46
23	Interior view of entry vestibule looking at the staircase leading to the second floor in Building 655, officers' quarters, Type BOQ-40, 1988 (Library of Congress, HABS WI, 41-SPAR. V, 1-S-4)	47
24	Interior view of dayroom in Building 655, officers' quarters, Type BOQ-40, 1988 (Library of Congress, HABS WI, 41-SPAR. V, 1-S-5)	47
25	Interior view of typical single bedroom in Building 655, officers' quarters, Type BOQ-40, 1988 (Library of Congress, HABS WI, 41-SPAR. V, 1-S-6)	48
26	Northeast oblique of Building 453, bachelor officers' quarters, Type BOQ-44, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1Q-1)	50
27	Southwest oblique of Building 453, bachelor officers' quarters, Type BOQ-44, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1Q-2)	50
28	Typical bedroom in Building 453, bachelor officers' quarters, Type BOQ-44, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1Q-4)	51
29	Interior view of washroom in Building 453, bachelor officers' quarters, Type BOQ-44, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1Q-5)	51
30	Plan Number 700-1254 (modified at Fort McCoy) – Quarters and Mess Officers' Type OQM-9-9 Officers, Type OQM-3-3 Officers, two-story building, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-13)	53
31	Plan Number 700-1300 – Quarters and Mess Officers', two-story building, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-14)	54
32	Front side of Building 1863, officers' quarters – 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-5)	54
33	Rear and side of Building 1863, officers' quarters – 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-6)	55
34	Detailed view of the front eaves on Building 1863, officers' quarters – 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-8)	55
35	Interior view of central corridor, looking from the front entry in Building 1863, officers' quarters – 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-9)	56

Figure		Page
36	Interior view of central stair hall from the side entry in Building 1863, officers' quarters – 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-10)	56
37	Interior view of dayroom in Building 1863, officers' quarters – 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-12)	57
38	Interior view of toilet room in Building 1863, officers' quarters – 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-11)	57
39	Plan Number 800-307, architectural, structural, and details for brigade general's quarters, Type BGQ-1, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EY-6)	59
40	Southeast oblique of Building 1247, brigade general's quarters, Type BGQ-1, 1988 (Library of Congress, HABS WIS, 41- SPAR.V, 1-EY-1)	59
41	Northeast oblique of Building 1247, brigade general's quarters, Type BGQ-1, 1988 (Library of Congress, HABS WIS, 41- SPAR.V, 1-EY-2)	60
42	Southwest oblique of Building 1247, brigade general's quarters, Type BGQ-1, 1988 (Library of Congress, HABS WIS, 41- SPAR.V, 1-EY-3)	60
43	Interior view of living room in Building 1247, brigade general's quarters, Type BGQ-1, 1988 (Library of Congress, HABS WIS, 41- SPAR.V, 1-EY-4)	61
44	Interior view of kitchen (former heater room) in Building 1247, brigade general's quarters, Type BGQ-1, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EY-5)	61
45	Plan Number 800-308, architectural, structural, and details for regimental commander's quarters, Type RCQ -1, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-U-7)	63
46	Plan Number 800-308, close-up of the floor plan for regimental commander's quarters, Type RCQ -1, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-U-7)	63
47	West side of Building 901, regimental commander's quarters, Type RCQ -1, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-U-7)	64
48	Northeast oblique of Building 901, regimental commander's quarters, Type RCQ -1, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-U-3)	64
49	Interior view of bedroom in Building 901, regimental commander's quarters, Type RCQ-1, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-U-4)	65
50	Plan 800-661 (modified at Fort McCoy), single storehouse and company administration – Types SA-1 and SA-2, stockade/office building Type SO-1. Plans, elevations, and sections, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-B-13)	67
51	Plan 800-460, recreation building Type RB-4, 1941 (Library of Congress, HABS, WIS, 41-SPAR.V, 1-B-14)	68

Figure		Page
52	Fort McCoy drawing 6150-38B, combined building revised floor plan (Library of Congress, HABS WIS, 41 SPAR.V, 1-B-12)	68
53	Southwest oblique of Building 801, company storehouse, administration, and recreation building, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-B-2)	69
54	Close-up detail of concrete stoop, cast-iron metal handrails, wood panel and divided-light doors, and multi-pane wood sash window and screen on Building 801, company storehouse, administration, and recreation building, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-5)	69
55	Interior view of the storeroom showing the wood sliding door and exposed structural system in Building 801, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-B-7)	70
56	Interior view of the recreation area in Building 801, looking south into the storeroom, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-B-10)	70
57	Interior view of recreation area looking towards the storeroom in Building 801, 1988 (Library of Congress, HABS WIS, 4-SPAR.V, 1-B-10)	71
58	Plan Number 800-222, administration building, Type IBA-1, plans and elevations, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-7)	72
59	Close-up of Plan Number 800-222, administration building, Type IBA-1, floor plan, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-7)	73
60	Southeast oblique of Building 555, administration building, Type IBA-1, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-1)	73
61	Northwest oblique of Building 555, administration building, Type IBA-1, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-2)	74
62	Interior view of office area in Building 555, administration building, Type IBA-1, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-3)	74
63	Interior view of private office spaces in Building 555, administration building, Type IBA-1, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-4)	75
64	Interior view of clerk's toilet room in Building 555, administration building, Type IBA-1, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-5)	75
65	Interior view of storeroom in oblique of Building 555, administration building, Type IBA-1, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-6)	76
66	Plan Number 800-1007, floor plan for unit guard house, Type UGH-24, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-O-7)	77
67	Southeast oblique of Building 449, unit guard house, Type UGH-24, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-O-1)	78

Figure		Page
68	Northeast oblique of Building 449, unit guard house, Type UGH-24, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-O-2)	78
69	Northwest oblique of Building 449, unit guard house, Type UGH-24, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-O-3)	79
70	Interior view of guard room in Building 449, unit guard house, Type UGH-24, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-O-5)	79
71	Interior view of corridor looking towards the guard room in Building 449, unit guard house, Type UGH-24, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-O-4)	80
72	Plan Number 800-1009, unit guard house, Type UGH-36, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-FV-6)	81
73	Close-up of the floor plan for Plan Number 800-1009, unit guard house, Type UGH-36, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-FV-6)	82
74	Southwest oblique of Building 2671, unit guard house, Type UGH-36, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FV-1)	82
75	Northwest oblique of Building 2671, unit guard house, Type UGH-36, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FV-2)	83
76	Southeast oblique of Building 2671, unit guard house, Type UGH-36, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FV-3)	83
77	Interior view of guard room Building 2671, unit guard house, Type UGH-36, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FV-4)	84
78	Interior view of toilet room showing original fixtures in Building 2671, unit guard house, Type UGH-36, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FV-5)	84
79	Floor plans for Building 100, post headquarters, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-K-5)	85
80	Sections for Building 100, post headquarters, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-K-5)	86
81	South (front) side of Building 100, post headquarters, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-K-2)	87
82	North (rear) side of Building 100, post headquarters, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-K-4)	88
83	Interior view of main entrance in Building 100, post headquarters, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-K-5)	88
84	Looking east at Building 2667 in 2019 (HABS photos were not found for this building type (ERDC-CERL, 2019)	90
85	First floor plan for Building 2000, service club, Drawing #800-517, 1941 (courtesy Fort McCoy DPW)	92

Figure		Page
86	Second floor plan for Building 2000, service club, Drawing #800-517, 1941 (courtesy Fort McCoy DPW)	92
87	South front side of Building 2000, service club, 1952 (NARA College Park, RG 111-SC)	93
88	Northwest oblique of the north wing of Building 2000, service club, 1988 (Library of Congress, HABS WIS,41-SPAR.V,1-J-6)	93
89	Interior view of the dance hall looking north towards the fireplaces in Building 2000, service club, 1952 (NARA College Park, RG 111-SC)	94
90	Interior view of the first-floor library in the east wing of Building 2000, service club, 1952 (NARA College Park, RG 111-SC)	94
91	Interior view of the second floor of the billiards room in Building 2000, service club, 1988 (Library of Congress, HABS WIS,41-SPAR.V,1-J-11)	95
92	Close-up of the fireplace, hearth, and mantle on the balcony level of the dance hall in Building 2000, service club, 1988 (Library of Congress, HABS WIS,41-SPAR.V,1-J-12)	95
93	Interior view of truss in main roof of the dance hall showing the skylight in Building 2000, service club, 1988 (Library of Congress, HABS WIS,41-SPAR.V,1-J-10)	96
94	Close-up of the floor plan for a recreation building, Type RB-2, Plan Number 800-459, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-DZ-1)	97
95	South oblique of Building 10118, recreation building Type RB-2, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-EA-1)	97
96	North oblique of Building 10118, recreation building Type RB-2, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-EA-2)	98
97	Plan Number 800-805, floor plans and schedules for Type M 112-, 152-, 172, and 228--man mess halls, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-9)	100
98	Close-up of floor plan and expansion details Type M 112-, 152-, 172, and 228-man mess halls, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-9)	101
99	Plan Number 800-806 elevations and details for Type M 112-, 152-, 172, and 228-man mess halls, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-10)	101
100	Northeast oblique of Building 1106, 112-man mess hall, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EV-1)	102
101	Southwest oblique of Building 1106, 112-man mess hall, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EV-3)	102

Figure		Page
102	Side of Building 635, 152-man mess hall. Left side of the door is the dining area and the right side is the kitchen space, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-4)	103
103	Oblique of kitchen and storage area entry and long side of Building 635, 152-man mess hall, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-2)	103
104	Front side of Building 635, 152-man mess hall, showing entry door into the dining area, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-3)	104
105	Southeast oblique of Building 450, 172-man mess hall, (Library of Congress, HABS WIS, 41-SPAR.V, 1-P-1)	104
106	Northwest oblique of Building 450, 172-man mess hall, (Library of Congress, HABS WIS, 41-SPAR.V, 1-P-2)	105
107	Southwest oblique of Building 1506, 228-man mess hall, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-FC-3)	105
108	Interior view of the kitchen looking into the dining area in Building 1106, 112-man mess hall, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EV-4)	106
109	Interior view of Building 635, 152-man mess hall, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-6)	106
110	Interior view of the kitchen space in Building 635, 152-man mess hall. The kitchen sink has been removed from the wall and is placed in the middle of the room in this photo, 1988 (Library of Congress, HABS WIS, 41- SPAR.V, 1-C-7)	107
111	Interior view of the kitchen in Building 450, 172-man mess hall (Library of Congress, HABS WIS, 41-SPAR.V, 1-P-4)	107
112	Interior view of the storeroom in Building 1506, 228-man mess hall (Library of Congress, HABS WIS, 41-SPAR.V, 1-FC-6)	108
113	Close-up of the floor plan storehouse, Type SH-8, Plan Number 800-663, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-EZ-6),	109
114	Northeast oblique of Building 1263, standard storehouse, Type SH-8, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EZ-1)	109
115	Southwest oblique of Building 1263, standard storehouse, Type SH-8, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EZ-2)	110
116	Overall interior view in Building 1263, standard storehouse, Type SH-8, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EZ-3)	110
117	Front door detail in Building 1263, standard storehouse, Type SH-8, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EZ-5)	111

Figure		Page
118	Plan Number 800-664, plans, elevations, sections for standard storehouse 25'-0" wide, Type SH-9, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-FA-4)	112
119	Northeast oblique of Building 1264, standard storehouse, Type SH-9, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-FA-1)	112
120	Southwest oblique of Building 1264, standard storehouse, Type SH-9, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-FA-2)	113
121	Plan Number 800-654 for standard storehouse, Type SH-18, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-FJ-8)	114
122	South side of Building 2122, storehouse, Type SH-18, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FJ-2)	114
123	Interior view of storehouse area in Building 2122, storehouse, Type SH-18, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FJ-3)	115
124	Detail of original wooden storehouse sliding door in Building 2122, storehouse, Type SH-18, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FJ-5)	115
125	Plans, elevations, and sections for enclosure for grease racks, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-FF-6)	117
126	Southwest oblique of Building 1876, grease rack enclosure building, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FF-1)	117
127	Southeast oblique of Building 1876, grease rack enclosure building, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FF-2)	118
128	East side of Building 1876, grease rack enclosure building, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FF-1)	118
129	Interior view of Building 1876, grease rack enclosure building, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FF-1)	119
130	Plan Number 800-1559, G.U. Dispensary, Type G.U.D.-1, 1941 (ERDC-CERL, architectural files)	120
131	Oblique of a G.U. dispensary, Type G.U.D.-1, Building 2556, (ERDC-CERL, 2019)	121
132	Interior view of lab area in Building 1033, clinic/dispensary, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-AZ-3)	121
133	Interior view of storeroom showing cabinet and drawers in Building 1003, clinic/dispensary, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-1X-1)	122
134	Interior view of a storage room and lab space in Building 1033, clinic/dispensary, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-AZ-5)	122

Figure		Page
135	Northeast oblique of Building 656, dental clinic, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-T-1)	124
136	Southwest oblique of Building 656, dental clinic, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-T-2)	125
137	Interior view, first floor hall in Building 656, dental clinic, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-T-3)	125
138	Interior view, second floor in Building 656, dental clinic, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-T-4)	126
139	Interior view of toilet room on the second floor in Building 656, dental clinic, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-T-5)	126
140	Close-up of the floor plan for a regimental exchange, Type E-3 from Plan Number 800-480, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-N-8)	128
141	Plan Number 800-479, miscellaneous details for a regimental exchange, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-N-7)	129
142	Southeast oblique of Building 352, regimental exchange, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-N-1)	129
143	Southwest oblique of Building 352, regimental exchange, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-N-3)	130
144	Interior view of the exchange room in Building 352, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-N-4)	130
145	Interior view of the scullery in Building 352, regimental exchange, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-N-5)	131
146	Interior view of the barber shop in Building 352, regimental exchange, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-N-6)	131
147	Southwest oblique of Building 1146, chapel, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-2)	133
148	South side of Building 1146, chapel, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-5)	133
149	North side of Building 1146, chapel, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-6)	134
150	Interior view of the nave looking towards the altar in Building 1146, chapel, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-7)	134
151	Interior view of the nave looking towards the entrance in Building 1146, chapel, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-8)	135
152	Close-up view of the exposed wood truss system in Building 1146, chapel, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-10)	135
153	Plan Number 800-558, regimental chapel, Type CH-1, details of truss, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-11)	136

Figure		Page
154	Original construction drawing, Series 800-800, plans and elevations for Building 550, Fire Station (courtesy Fort McCoy DPW)	137
155	Northwest side of Building 1555, fire station, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FD-1)	138
156	Fire hose tower from the northeast, Building 1555, fire station, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FD-4)	138
157	Interior view of apparatus room in Building 1555, fire station, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FD-5)	139
158	Interior view of the squad room in Building T-1555, Fire Station, DATE (HABS WIS, 41-SPAR.V, 1FD-6)	139
159	Plan Number 800-217, plans, elevations, sections for Type PO-2 post office, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-FW-7)	141
160	East side of Building 2675, post office, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FW-1)	141
161	Northwest oblique of Building 2675, post office (Library of Congress, HABS WI, 41-SPAR.V, 1-FW-2)	142
162	Interior view of lobby in Building 2675 (modified since original), 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FW-4)	142
163	Interior view of Building 2675, post office, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FW-5)	143
164	Cantonment map of Camp McCoy, 1942 (Garner 1993, 71)	146
165	Close up of 1600 Block in southern leg of cantonment showing arrangement of barracks (red), mess halls (purple) and other buildings to motor storage area, 1941 (DPW, Fort McCoy)	147
166	Layout of Camp McCoy showing land use patterns, March 1942 (<i>Engineering Manual of the Office of the Chief of Engineers</i>)	149
167	Historic postcard view down an unknown block at Camp McCoy, circa 1940s (ERDC-CERL Collection)	151
168	Close up of curved road at west end of southern leg and site of service club (Building 2000), 1941 (DPW, Fort McCoy)	151
169	Rail lines south of Fort McCoy cantonment, 1988 (HABS, Library of Congress)	152
170	Close up of warehouse area located to the south of the cantonment, 1941 (DPW, Fort McCoy)	152
171	Rail lines at South H Street and South 6 th Avenue looking east (ERDC-CERL 2018)	153
172	Historic postcard showing walkways at rear of barracks in an unknown block, date unknown (ERDC-CERL Collection)	153

Figure		Page
173	Sidewalks and culverts in the 1300 Block (ERDC-CERL 2018)	154
174	Older style culverts in the 2700 Block (ERDC-CERL 2018)	154
175	View showing newer sidewalks and corrugated metal culverts in the 1600 Block (ERDC-CERL 2018)	155
176	Photograph of Headquarters Building (100) and flagpole, 1965 (NARA College Park)	156
177	Aerial of 600 Block, 1988 (HABS, Library of Congress)	158
178	Showing close-up of 600 Block and building cluster arrangement, 2014 (DPW, Fort McCoy)	158
179	Cantonment map showing demolished 200, 300, 400, 500, and 1500 blocks (in red), 2014 (Fort McCoy)	159
180	Historic postcard showing evergreen plantings along walkways to buildings, date unknown (ERDC-CERL Collection)	160
181	Historic photograph showing trees planted around barracks in regimental block areas, date unknown (HABS, Library of Congress)	161
182	Historic postcard view showing evergreen foundation plantings around chapel (location unknown), date unknown (ERDC-CERL Collection)	161
183	View of foundation plantings around service club (Building 2000) located in the southwest corner of triad, 1978 (NARA, College Park)	162
184	View today showing scattered trees along South Headquarters Avenue toward Building 100 (ERDC-CERL, 2018)	162
185	Scattered trees adjacent to Building 2545 (ERDC-CERL, 2018)	163
186	Ornamental trees seen in front of service club (Building 2000), undergoing renovation (ERDC-CERL, 2018)	163
187	Service club (Building 905) [reconstructed in 1952] and Building 904 with foundation plantings in the southeast corner of the triad (ERDC-CERL, 2018)	164
188	Regimental commander's quarters (Building 2566) with heavy foundation plantings (ERDC-CERL, 2018)	164
189	Aerial showing large areas of vegetation and scattered trees in cantonment, 1988 (HABS, Library of Congress)	165
190	View of flagpole in front of Building 100, 1961 (NARA College Park)	166
191	View of Fort McCoy sign in front of flagpole and Building 100 (ERDC-CERL, 2018)	167
192	View of flagpole and plaza in front of Building 100 (ERDC-CERL 2018)	167
193	Chain link fencing around Building 855 (ERDC-CERL, 2018)	168
194	View of bollards and chain used around museum and picnic area (ERDC-CERL, 2018)	168

Figure		Page
195	Remnants of a gazebo in 2700 Block (ERDC-CERL, 2018)	169
196	Addition of a bus stop shelter in 2700 Block (ERDC-CERL, 2018)	169
197	Way finding signage throughout cantonment (ERDC-CERL, 2018)	170
198	Historic postcard view towards headquarters and flagpole, circa early 1940s (DPW, Fort McCoy)	171
199	View looking north of Building 100, flagpole, and Fort McCoy sign from South Headquarters Avenue (ERDC-CERL, 2018)	171
200	Historic postcard view down an unknown regimental street, date unknown (ERDC-CERL Collection)	172
201	View down East R Street from East 12 th Avenue in the 800 Block, 1988 (HABS, Library of Congress)	172
202	View looking southeast down West H Street from West 13 th Avenue in the 2700 Block (ERDC-CERL 2018)	173
203	Detail from War Department 800 Series plans for mess hall, 1942 (Library of Congress)	174
204	Asbestos shingle siding with scalloped bottom on Building 550 (ERDC-CERL, 2018)	175
205	Close-up of Camp McCoy postcard showing red asphalt roofing, 1942 (ERDC-CERL Collection)	175
206	Multipaned window with screen on Building 849 (ERDC-CERL, 2018)	176
207	Detail of wood window trim on Building 849 (ERDC-CERL, 2018)	176
208	Multipaned doors with panels below on Building 849 (ERDC-CERL, 2018)	177
209	Interior wooden screen door in Building 1129 (ERDC-CERL, 2018)	177
210	Wood door trim on Building 849 (ERDC-CERL, 2018)	178
211	Wood foundation skirting on Building 849 (ERDC-CERL, 2018)	178
212	External brick chimney on Building 629 (ERDC-CERL, 2018)	179
213	Example of an internal brick chimney at Camp McCoy, 1965 (NARA College Park, RG111SC)	179
214	Example of wood steps and railing at Camp McCoy, 1951 (NARA College Park, RG111SC)	180
215	Detail of platform and ladder from War Department 800 Series plans for barracks, 1942 (Library of Congress)	180
216	Detail of Camp McCoy postcard showing ladders and platforms, 1942 (ERDC-CERL Collection)	181
217	Detail of barracks showing ladders and platforms, 1950 (NARA College Park, RG111SC)	181
218	Example of an open squad bay in Building 1129 (ERDC-CERL, 2018)	182

Figure		Page
219	Example of the sink area in a barracks latrine in Building 1129 (ERDC-CERL, 2018)	182
220	Example of the toilet area in a barracks latrine in Building 1129 (ERDC-CERL, 2018)	183
221	Example of the shower heads in a barracks latrine in Building 1129 (ERDC-CERL, 2018)	183
222	Example of the NCO room in Building 1129 (ERDC-CERL, 2018)	184
223	Open mess hall area in Building 2008 (ERDC-CERL, 2018)	184
224	Stove area in Building 2008 (ERDC-CERL, 2018)	185
225	Bare wood floor in barracks, Building 1129 (ERDC-CERL, 2018)	185
226	Concrete floor in the latrine of Building 550 (ERDC-CERL, 2018)	186
227	Fiberboard walls in Building 849 (ERDC-CERL, 2018)	186
228	Fiberboard walls with wainscoting in Building 1866 (ERDC-CERL, 2018)	187
229	Fiberboard ceiling in Building 550 (ERDC-CERL, 2018)	187
230	Ceiling vent in Building 550 (ERDC-CERL, 2018)	188
231	Metal heater duct in Building 1129 (ERDC-CERL, 2018)	188
232	Former ballroom in Building 2000 (ERDC-CERL, 2018)	189
233	Exposed wood trusses in library of Building 2000 (ERDC-CERL, 2018)	189
234	Brick fireplace in Building 2000 (ERDC-CERL, 2018)	190
235	Original glass globes for pendant light fixtures (ERDC-CERL, 2019)	190
236	Southwest oblique of Building 1117, 74-man barracks (ERDC-CERL, 2019)	193
237	South oblique of Building 624, 74-man barracks (ERDC-CERL, 2019)	194
238	Typical 8/8 wood-sash double-hung window, window trim, and asbestos shingle siding with scalloped bottom edge on a 74-man barracks (ERDC-CERL, 2019)	194
239	Interior view of the open bunk area in a 74-man barracks, Building 624 (ERDC-CERL, 2019)	195
240	Original built-in wooden shelving in the bunk room in a 74-man barracks, Building 624 (ERDC-CERL, 2019)	195
241	Interior view of the washroom on the first floor in Building 624, 74-man barracks (ERDC-CERL, 2019)	196
242	Interior view of the toilet room on the first floor of Building 629, 74-man barracks (ERDC-CERL, 2019)	196
243	Wooden staircase in Building 624, 74-man barracks (ERDC-CERL, 2019)	197
244	Typical interior wood panel door for 74-man barracks (ERDC-CERL, 2019)	197

Figure		Page
245	Northwest oblique of Building 1132, company storehouse, administration, and recreation building (ERDC-CERL, 2019)	198
246	South side of Building 1132, company storehouse, administration, and recreation building (ERDC-CERL, 2019)	198
247	Original asbestos shingle siding with scalloped bottom edge, 8/8 wood window with simple window trim, and original divided-light wood panel door, on a company storehouse, administration, and recreation building (ERDC-CERL, 2019)	199
248	Original 4/4 wood-sash double-hung window, window trim, and asbestos shingle siding with a scalloped bottom edge on a company storehouse, administration, and recreation building (ERDC-CERL, 2019)	199
249	Close-up of original wood foundation skirting underneath added metal skirting (ERDC-CERL, 2019)	200
250	Interior view of the company storehouse area in a company storehouse, administration, and recreation building, Building 1133 (ERDC-CERL, 2019)	200
251	Interior view of the recreation area in a company storehouse, administration, and recreation building, Building 1133 (ERDC-CERL, 2019)	201
252	Close-up of original exposed wood rafters and wallboard interior walls in a company storehouse, administration, and recreation building, Building 1133 (ERDC-CERL, 2019)	201
253	Original wood divided-light and panel interior doors and wood steps leading from the storehouse area to the recreation area in a company storehouse, administration, and recreation building, Building 1133 (ERDC-CERL, 2019)	202
254	Northeast oblique of Building 857, company storehouse, administration, and recreation building (ERDC-CERL, 2019)	203
255	Southwest oblique of Building 857, company storehouse, administration, and recreation building (ERDC-CERL, 2019)	203
256	Original 4/4 and 8/8 wood-sash double-hung windows with wooden screens and a simple architrave and original asbestos shingle siding with a scalloped bottom edge on company storehouse, administration, and recreation building type (ERDC-CERL, 2019)	204
257	Original wood sliding door on company storehouse, administration, and recreation building type (ERDC-CERL, 2019)	204
258	Original divided-light wood panel exterior door on company storehouse, administration, and recreation building type (ERDC-CERL, 2019)	205
259	Interior view of the administration space in company storehouse, administration, and recreation building type (ERDC-CERL, 2019)	205
260	Original globe ceiling fixture in company storehouse, administration, and recreation building type (ERDC-CERL, 2019)	206

Figure		Page
261	Northeast oblique of Building 848, interior battalion administration building, Type IBA-1 (ERDC-CERL, 2019)	206
262	Southwest oblique of Building 848, interior battalion administration building, Type IBA-1 (ERDC-CERL, 2019)	207
263	Original 8/8 wood-sash double-hung window with wooden screen and simple architrave on an interior battalion administration building, Type IBA-1 (ERDC-CERL, 2019)	207
264	Original divided-light and wood panel door with concrete porch on an interior battalion administration building, Type IBA-1 (ERDC-CERL, 2019)	208
265	Original set of divided-light and wood panel exterior doors leading into the heater room, concrete block foundation of the heater room, and wood foundation skirting of the pier foundation for an interior battalion administration building, Type IBA-1 (ERDC-CERL, 2019)	208
266	Original asbestos shingle siding with a scalloped bottom edge and wood foundation skirting on an interior battalion administration building, Type IBA-1 (ERDC-CERL, 2019)	209
267	Northeast oblique of Building 849, unit guard house, Type UGH-24 (ERDC-CERL, 2019)	209
268	Southwest oblique of Building 849, unit guard house, Type UGH-24 (ERDC-CERL, 2019)	210
269	Original 8/8 wood-sash double-hung window with wooden screen and simple architrave of a unit guard house, Type UGH-24 (ERDC-CERL, 2019)	210
270	Original divided-light and wood panel exterior door with a concrete porch and cast-iron handrails on a unit guard house, Type UGH-24 (ERDC-CERL, 2019)	211
271	Original set of divided-light and wood panel exterior doors leading into the heater room of a unit guard house, Type UGH-24 (ERDC-CERL, 2019)	211
272	Original asbestos shingle siding with a scalloped bottom edge, concrete block foundation of the heater room, and wood foundation skirting of a unit guard house, Type UGH-24 (ERDC-CERL, 2019)	212
273	Interior view of the guard room looking towards the corridor, heater room, and toilet room in a unit guard house, Type UGH-24 (ERDC-CERL, 2019)	212
274	West oblique of Building 2560, unit guard house, Type UGH-36 (ERDC-CERL, 2019)	213
275	East oblique of Building 2560, unit guard house, Type UGH-36 (ERDC-CERL, 2019)	213
276	Original 8/8 wood-sash double-hung window with wooden screen and a simple wood architrave on a unit guard house, Type UGH-36 (ERDC-CERL, 2019)	214

Figure		Page
277	Original set of divided-light and wood panel exterior doors, concrete porch, and cast-iron handrails on a unit guard house, Type UGH-36 (ERDC-CERL, 2019)	214
278	Original asbestos shingle siding with a scalloped bottom edge on a unit guard house, Type UGH-36 (ERDC-CERL, 2019)	215
279	Original wood foundation skirting on a unit guard house, Type UGH-36 (ERDC-CERL, 2019)	215
280	Original interior view of the open guard space in a unit guard house, Type UGH-36 (ERDC-CERL, 2019)	216
281	Interior view in the corridor leading into the guard space in a unit guard house, Type UGH-36 (ERDC-CERL, 2019)	216
282	Interior view of a toilet room with original tongue-and-groove walls, concrete floor, and fixtures (ERDC-CERL, 2019)	217
283	Original standard five-panel wood interior door in a unit guard house, Type UGH-36 (ERDC-CERL, 2019)	217
284	Original standard divided-light and wood panel interior door leading from corridor into the guard space in a unit guard house, Type UGH-36 (ERDC-CERL, 2019)	218
285	Original exposed suspended mechanical ducts in a unit guard house, Type UGH-36 (ERDC-CERL, 2019)	218
286	Oblique of a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019)	219
287	Oblique of a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019)	219
288	Original 8/8 wood-sash double-hung windows, wooden screen, simple wood architrave, and asbestos shingle siding with a scalloped bottom edge on a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019)	220
289	Original paired 8/8 wood-sash double-hung windows, wooden screen, and a simple wood architrave, recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019)	220
290	Original set of divided-light and wood panel entry doors and simple wood door surround on a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019)	221
291	Original divided-light and wood panel door, concrete porch, and cast-iron handrails on a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019)	221
292	Original wooden interior screen door on a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019)	222

Figure		Page
293	Original wooden foundation skirting on a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019)	222
294	Interior view of the open recreation area in the recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019)	223
295	Looking towards the main vestibule space in the recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019)	223
296	Original standard five-panel wood interior door in a recreation building Type RB-1 type, Building 2557 (ERDC-CERL, 2019)	224
297	Oblique of Building 1237, 112-man mess hall (ERDC-CERL, 2019)	225
298	Interior view of dining area in a 112-man mess hall, Building 1237 (ERDC-CERL, 2019)	225
299	Oblique of Building 1116, 152-man mess hall (ERDC-CERL, 2019)	226
300	Interior view of from kitchen area to the dining area in a 152-man mess hall, Building 1116 (ERDC-CERL, 2019)	226
301	Oblique of Building 627, 172-man mess hall (ERDC-CERL, 2019)	227
302	Original asbestos shingle siding with scalloped bottom edge and original wooden foundation skirting on Building 627, 172-man mess hall (ERDC-CERL, 2019)	227
303	Interior view of kitchen area in Building 627, 172-man mess hall looking at the glazed tile wall where the stove and ovens would have been located (ERDC-CERL, 2019)	228
304	Interior view of the kitchen area in Building 627, 172-man mess hall looking at the original washing station (ERDC-CERL, 2019)	228
305	Interior view of dining area in a 172-man mess hall, Building 627 (ERDC-CERL, 2019)	229
306	Oblique of Building 2006, 228-man mess hall (ERDC-CERL, 2019)	229
307	Interior view of from kitchen area to the dining area in a 228-man mess hall, Building 2008 (ERDC-CERL, 2018)	230
308	Typical interior wood panel door leading into the storeroom room (ERDC-CERL, 2019)	230
309	Front side of a standard storehouse building, Type SH-8, Building 1153 (ERDC-CERL, 2019). (ERDC-CERL, 2019)	231
310	Oblique of a standard storehouse building, Type SH-8, Building 1153 (ERDC-CERL, 2019)	231
311	Oblique of a standard storehouse building, Type SH-8, Building 1153 (ERDC-CERL, 2019)	232

Figure		Page
312	Original 8/8 wood-sash double-hung window, simple wood architrave, and asbestos shingle siding with a scalloped bottom edge for a standard storehouse, Type SH-8, Building 1153 (ERDC-CERL, 2019)	232
313	Original wood sliding door and metal track for a standard storehouse, Type SH-8, Building 1153 (ERDC-CERL, 2019)	233
314	Interior view of a of a standard storehouse building, Type SH-8, Building 1153 (ERDC-CERL, 2019)	233
315	Front side of a standard storehouse, Type SH-9, Building 109 (ERDC-CERL, 2019)	234
316	Oblique of a standard storehouse, Type SH-9 (ERDC-CERL, 2019)	234
317	Original 8/8 wood-sash double-hung window, simple wood architrave, and asbestos shingle siding for a standard storehouse, Type SH-9, Building 109 (ERDC-CERL, 2019)	235
318	Original wood sliding door and metal track for a standard storehouse, Type SH-9, Building 109 (ERDC-CERL, 2019)	235
319	Interior view of the open space in a standard storehouse, Type SH-9, Building 109 (ERDC-CERL, 2019)	236
320	Oblique of a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019)	237
321	Oblique of a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019)	237
322	Oblique of a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019)	238
323	Original 8/8 wood-sash double-hung windows, wooden screen, simple wood architrave, and asbestos shingle siding for a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019)	238
324	Original divided-light and wood panel entry door with wooden screen door for a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019)	239
325	Original set of divided-light and wood panel doors leading into the heater room for a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019)	239
326	Original wooden foundation skirting and concrete pier foundation for a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019)	240
327	Interior view of the original waiting room in a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019)	240
328	Original corridor with wood flooring and horizontal plank wainscoting on the walls in a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019)	241

Figure		Page
329	Original wood built-ins and cabinets in a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019)	241
330	Original standard five-panel wood interior door in a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019)	242
331	Treatment Room in a G.U. dispensary, Type G.U.D.-1, Building 2556, (ERDC-CERL, 2019)	242
332	Original standard glass globe ceiling fixture in a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019)	243
333	Oblique of a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019)	243
334	Rear side of a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019)	244
335	Original 8/8 wood-sash double-hung windows with a simple architrave and brick chimney stack for a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019)	244
336	Original divided-light and wood panel exterior door and asbestos shingle siding with a scalloped bottom edge with a concrete porch and cast-iron handrails, for a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019)	245
337	Original set of divided-light and wood panel exterior doors leading into the heater room, and concrete block foundation for a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019)	245
338	Original wooden foundation skirting for a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019)	246
339	Interior view of the open general treatment room on the second floor of the dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019)	246
340	Interior wood switchback staircase in a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019)	247
341	Oblique of Building 1750, regimental exchange (Fort McCoy, 2020)	247
342	Oblique of regimental exchange, Building 1750 (Fort McCoy, 2020)	248
343	Original divided-light and wood panel doors with a concrete stoop and cast-iron metal handrails on a regimental exchange, Building 1750 (Fort McCoy, 2020)	248
344	Original wooden foundation skirting and replacement in-kind asbestos shingle siding on regimental exchange, Building 1750 (Fort McCoy, 2020)	249
345	Replacement divided-light vinyl window and replacement metal security screen on the regimental exchange, Building 1750 (Fort McCoy, 2020)	249
346	Interior view of open exchange space in regimental exchange building, Building 1750 (Fort McCoy, 2020)	250
347	Southwest oblique of fire station, Building 550 (ERDC-CERL, 2019)	250
348	Oblique of a 74-man barracks, Building 1209 (ERDC-CERL)	257

Figure		Page
349	Oblique of a 74-man barracks, Building 1209 (ERDC-CERL, 2019)	258
350	Oblique of an officers' quarters, Type BOQ-40, Building 2666, (ERDC-CERL, 2019)	258
351	Oblique of an officers' quarters, Type BOQ-44, Building 452, (ERDC-CERL, 2019)	259
352	Oblique of an officers' quarters, Type BOQ-44, Building 1250, (ERDC-CERL, 2019)	260
353	Oblique of a 700 Series bachelor officers' quarters, Type OQ-23, Building 904 (ERDC-CERL, 2019)	260
354	Rear side of a brigade general quarters, Type BGQ-1, Building 659 (ERDC-CERL, 2019)	261
355	Front side of a regimental commander's quarters, Type RCQ-1, Building 1754 (ERDC-CERL, 2019)	262
356	Typical modified interior of a regimental commander's quarters, Type RCQ-1, Building 1754 (ERDC-CERL, 2019)	262
357	Rear and side view of a company storehouse, administration, and recreation building, Building 1201 (ERDC-CERL, 2019)	263
358	Front and side view of a company storehouse, administration, and recreation building, Building 1211 (ERDC-CERL, 2019)	263
359	South oblique of a one roof version of, company storehouse, administration, and recreation building, Building 2832 (ERDC-CERL, 2019)	264
360	Front side of a division headquarters [Post Headquarters], Type DHQ-1, Building 100 (ERDC-CERL, 2019)	265
361	Front side of an administration building, Type IBA-1, Building 1446 (ERDC-CERL, 2019)	265
362	Oblique of an administration building, Type A-3, Building 1254 (ERDC-CERL, 2019)	266
363	Oblique of an administration building, Type A-10, Building 2168 (ERDC-CERL, 2019)	266
364	Front side of recreation building, gymnasium, Building 1448, (ERDC-CERL, 2019)	267
365	Oblique of a unit guard house, Type UGH-36, Building 1748 (ERDC-CERL, 2019)	268
366	Front side of recreation building, gymnasium, Building 1448, (ERDC-CERL, 2019)	269
367	Oblique of a recreation building, Type RB-2, Building 1243 (ERDC-CERL, 2019)	269

Figure		Page
368	Front side of a recreation building, Type RB-4, Building 1653 (ERDC-CERL, 2019)	270
369	Oblique of a 112-man mess hall, Building 1205 (ERDC-CERL, 2019)	271
370	Oblique of a 112-man mess hall, Building 1206 (ERDC-CERL, 2019)	271
371	Oblique of Building 639, 152-man mess hall (ERDC-CERL, 2019)	272
372	Oblique of Building 1215, 172-man mess hall (ERDC-CERL, 2019)	272
373	Oblique of Building 1756, 228-man mess hall (ERDC-CERL, 2019)	273
374	Oblique of a standard storehouse, Type SH-8, Building 1263 (ERDC-CERL, 2019)	274
375	Oblique of a standard storehouse, Type SH-9, Building 1264 (ERDC-CERL, 2019)	274
376	Oblique of a grease rack enclosure building, Building 547 (ERDC-CERL, 2019)	275
377	Interior view of the open space of grease rack enclosure building, Building 547 (ERDC-CERL, 2019)	276
378	Front side of a grease rack enclosure building, Building 1152 [both of these have the same building number] (ERDC-CERL, 2019)	276
379	Oblique of vehicle storage building, Building 1659 (ERDC-CERL, 2019)	277
380	Oblique of motor repair shop building, Building 1262 (ERDC-CERL, 2019)	277
381	Oblique of a G.U. dispensary building, Building 1347 (ERDC-CERL, 2019)	278
382	Interior view of the waiting room in a G.U. dispensary, Building 1865 (ERDC-CERL, 2019)	278
383	Interior view of the hallway with exam and storage rooms in a G.U. dispensary, Building 1865 (ERDC-CERL, 2019)	279
384	Original wood built-in shelves and cabinets in a G.U. dispensary, Building 1865 (ERDC-CERL, 2019)	279
385	Oblique of a regimental exchange building, Building 1256 (ERDC-CERL, 2019)	280
386	View of modified interior of a regimental exchange building, Building 1256 (ERDC-CERL, 2019)	281
387	Modified interior of a regimental exchange building, Building 1256 (ERDC-CERL, 2019)	281
388	Oblique of a regimental exchange building, Building 1445 (ERDC-CERL, 2019)	282
389	Rear oblique of a regimental chapel, Building 1759 (ERDC-CERL, 2019)	283
390	Interior view of a modified regimental chapel, Building 1759 (ERDC-CERL, 2019)	283

Figure		Page
391	Oblique of a 74-man barracks, Building 608 (ERDC-CERL, 2019)	299
392	Oblique of a 74-man barracks, Building 1603 (ERDC-CERL, 2019)	299
393	Interior view of the modified bunk area in a 74-man barracks (ERDC-CERL, 2019)	300
394	Interior view of a modified NCO room in a 74-man barracks (ERDC-CERL, 2019)	300
395	Interior view of the latrine in a 74-man barracks (ERDC-CERL, 2019)	301
396	Oblique of an officers' quarters, Type BOQ-40, Building 655 (ERDC-CERL, 2019)	301
397	Oblique of an officers' quarters, Type BOQ-44, Building 2562 (ERDC-CERL, 2019)	302
398	Oblique of a 700 Series bachelor officers' quarters, Type OQ-23, Building 2561 (ERDC-CERL, 2019)	303
399	Oblique looking northeast of the WACS barracks, Building 2171 (ERDC-CERL, 2019)	303
400	Oblique of a company storehouse, administration, and recreation building, Building 1111 (ERDC-CERL, 2019)	304
401	Interior view of a modified storehouse space with newer partition wall in a company storehouse, administration, and recreation building (ERDC-CERL, 2019)	305
402	Interior view of a modified storehouse space looking towards a new ramp leading to the administration space in a company storehouse, administration, and recreation building (ERDC-CERL, 2019)	305
403	Interior view of a modified administration space new partition walls, flooring, and ceiling in a company storehouse, administration, and recreation building (ERDC-CERL, 2019)	306
404	Interior view of a modified administration and recreation space with all new finishes in a company storehouse, administration, and recreation building (ERDC-CERL, 2019)	306
405	Oblique of a company storehouse, administration, and recreation building with modified roofline, Building 634 (ERDC-CERL, 2019)	307
406	Front side of administration building Type IBA-1 building, Building 1848 (ERDC-CERL, 2019)	308
407	Oblique of a Type A-10 building, Building 657 (ERDC-CERL, 2019)	308
408	North side of a Type A-10 building, Building 2117 (ERDC-CERL, 2019)	309
409	Oblique of a recreation building, gymnasium, Building 1255 (ERDC-CERL, 2019)	309

Figure		Page
410	View of modified interior space in a recreation building – gymnasium, Building 1255 (ERDC-CERL, 2019)	310
411	Oblique of a Type RB-2 building, Building 658 (ERDC-CERL, 2019)	310
412	Front side of service club, Building 2000 (ERDC-CERL, 2019)	311
413	Rear side of service club, Building 2000 (ERDC-CERL, 2019)	312
414	Interior of dance hall space in modified service club, Building 2000 (ERDC-CERL, 2019)	312
415	Example of modified mess-hall with cross-gable side addition, Building 2637 (ERDC-CERL, 2019)	314
416	Example of a modified mess hall with a large side addition that houses bathroom and storage rooms, Building 1606 (ERDC-CERL, 2019)	314
417	Example of a modified mess hall with a hyphen addition connecting two mess halls together Building 2615 (ERDC-CERL, 2019)	315
418	Example of a modified mess hall with a hyphen addition connecting two mess halls together, Building 2827 (left) and Building 2828 (right) (ERDC-CERL, 2019)	315
419	Interior view of a modified mess hall currently used for classroom space (ERDC-CERL, 2019)	316
420	Interior view of the bathroom addition on a mess hall, Building 1606 (ERDC-CERL, 2019)	316
421	Interior view of a modified mess hall, Building 1616 (ERDC-CERL, 2019)	317
422	Interior view of the hallway addition connecting two mess halls, standing in Building 1617 looking towards Building 1616 (ERDC-CERL, 2019)	317
423	Oblique of standard storehouse, Type SH-13 buildings, Buildings 2149, 2147, 2143, and 2141 (ERDC-CERL, 2019)	318
424	Oblique of standard storehouse, Type SH-18 buildings, Buildings 2125, and 2121 (ERDC-CERL, 2019)	318
425	Front side of a carpentry shop, Building 2115 (ERDC-CERL, 2019)	319
426	Oblique of railroad shop, Building 2109 (ERDC-CERL, 2019)	320
427	Looking at the north side of the utility shop, Building 2116 (ERDC-CERL, 2019)	320
428	Oblique of a G.U. dispensary, Building 750 (ERDC-CERL, 2019)	321
429	East side of exchange, Building 110 (ERDC-CERL, 2019)	322
430	Oblique of a regimental exchange, Building 2558 (ERDC-CERL, 2019)	322
431	View of modified interior space in a regimental exchange building, Building 2874 (ERDC-CERL, 2019)	323
432	View of the west side of the bakery, Building 2113 (ERDC-CERL, 2019)	323

Figure	Page
433 Front oblique of a regimental chapel, Building 2672 (ERDC-CERL, 2019)	324
434 Oblique of fire station, Building 2111 (ERDC-CERL, 2019)	325
435 Oblique of a post office, Building 2675 (ERDC-CERL, 2019)	325
436 Master Plan for Camp McCoy showing triad layout, 1941 (DPW, Fort McCoy)	327
437 Current map of Fort McCoy, 2014 (Fort McCoy)	327
438 Color key for 1941 plan (Fort McCoy)	328
439 Number 1 Type buildings are shown in red, Number 2 Type buildings in blue and Number Type 3 buildings in green on Fort McCoy map, 2014. (Fort McCoy DPW, modified by ERDC-CERL, 2019)	329
440 Crop of 100 Block from Camp McCoy plan, 1941 (Fort McCoy)	330
441 Crop of 100 Block, 2014 map (Fort McCoy)	330
442 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 100 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	331
443 View north to Building 100 (ERDC-CERL, 2018)	331
444 View toward flagpole and Buildings 100 and 110 (in background) (ERDC-CERL, 2018)	332
445 Crop of 200 Block from Camp McCoy plan, 1941 (Fort McCoy)	332
446 Crop of 200 Block, 2014 map (Fort McCoy)	333
447 Crop of 300 Block from Camp McCoy plan, 1941 (Fort McCoy)	333
448 Crop of 300 Block, 2014 map (Fort McCoy)	334
449 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 300 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	334
450 View to the southeast of the 300 Block with Building 352 (ERDC-CERL, 2018)	335
451 Crop of 400 Block from Camp McCoy plan, 1941 (Fort McCoy)	335
452 Crop of 400 Block, 2014 map (Fort McCoy)	336
453 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 400 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	336
454 View to the southwest of the 400 Block and Buildings 451-454 (ERDC-CERL, 2018)	337
455 Crop of 500 Block from Camp McCoy plan, 1941 (Fort McCoy)	338
456 Crop of 500 Block, 2014 map (Fort McCoy)	338
457 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 500 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	339
458 Southwest oblique of the fire station (Building 550) (ERDC-CERL, 2018)	339

Figure	Page
459 View of front side of vehicle storage building (Building 547) (ERDC-CERL, 2018)	340
460 Crop of 600 Block from Camp McCoy plan, 1941 (Fort McCoy)	341
461 Crop of 600 Block, 2014 map (Fort McCoy)	341
462 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 600 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	342
463 View of front side of Building 626 (ERDC-CERL, 2019)	343
464 Oblique view of Building 625 (ERDC-CERL, 2019)	343
465 View of new ammunition storage building (Building 615), in brick veneer on right, looking north up East N Street (ERDC-CERL, 2019)	344
466 Crop of 700 Block from Camp McCoy plan, 1941 (Fort McCoy)	345
467 Crop of 700 Block, 2014 map (Fort McCoy)	345
468 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 700 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	346
469 View south down East P Street with Building 710 on right (ERDC-CERL, 2019)	346
470 View south at front side of Building 732 and walkway along rears of Buildings 731, 730 and 729 (ERDC-CERL, 2019)	347
471 View looking south down East Q Street with Building 731 on right (ERDC-CERL, 2019)	347
472 Crop of 800 Block from Camp McCoy plan, 1941 (Fort McCoy)	348
473 Crop of 800 Block, 2014 map (Fort McCoy)	348
474 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 800 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	349
475 View south down East R Street with Building 810 on right (ERDC-CERL, 2019)	350
476 Oblique view looking west at Building 806 (ERDC-CERL, 2019)	350
477 Oblique view of Building 855 (ERDC-CERL, 2019)	351
478 View looking north at front side of Building 857 (ERDC-CERL, 2019)	351
479 Crop of 900 Block from Camp McCoy plan, 1941 (Fort McCoy)	352
480 Crop of 900 Block, 2014 map (Fort McCoy)	352
481 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 900 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	353
482 Front side of service club (Building 905) which was reconstructed in 1952 after a fire (ERDC-CERL, 2018)	353
483 View of side of Building 904, in background, and the new picnic pavilion and restroom Building 900, in middle ground (ERDC-CERL, 2019)	354

Figure	Page
484 Crop of hospital complex (1000 Block) from Camp McCoy plan, 1941 (Fort McCoy)	355
485 Aerial view of hospital complex (1000 Block), 1988 (HABS, Library of Congress)	355
486 Oblique view of Building 1046, 1988 (HABS, Library of Congress)	356
487 Current aerial of hospital complex, 2019 (google.com, accessed 8 November 2019)	356
488 View of hospital complex looking east down South 9 th Avenue from South V Street (ERDC-CERL 2019)	357
489 Crop of 1100 Block from Camp McCoy plan, 1941 (Fort McCoy)	358
490 Crop of 1100 Block, 2014 map (Fort McCoy)	358
491 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1100 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	359
492 View of front sides of storehouse buildings (Buildings 1154 and 1153) (ERDC-CERL, 2019)	360
493 Oblique view of grease rack enclosure building (Building 1152) (ERDC-CERL, 2019)	360
494 View looking west at infill construction (Buildings 1122 and 1127) (ERDC-CERL, 2018)	361
495 Crop of 1200 Block from Camp McCoy plan, 1941 (Fort McCoy)	362
496 Crop of 1200 Block, 2014 map (Fort McCoy)	362
497 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1200 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	363
498 Obliques of Buildings 1255 and 1256 (ERDC-CERL, 2019)	364
499 View looking east along South 10 th Avenue in 1200 Block (ERDC-CERL, 2019)	364
500 View of motor pool buildings in 1200 Block (ERDC-CERL, 2019)	365
501 Crop of 1300 Block from Camp McCoy plan, 1941 (Fort McCoy)	366
502 Crop of the 1300 Block, 2014 map (Fort McCoy)	366
503 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1300 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	367
504 Oblique of Building 1332 (ERDC-CERL, 2019)	368
505 View of side of Building 1331 from South 11 th Avenue (ERDC-CERL, 2019)	368
506 View down South N Street toward NCO Academy (ERDC-CERL, 2019)	369
507 Crop of 1400 Block from Camp McCoy plan, 1941 (Fort McCoy)	370
508 Crop of 1400 Block, 2014 map (Fort McCoy)	370
509 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the	

Figure		Page
	1400 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	371
510	Obliques of Buildings 1448, 1446 and 1445 front South 11 th Avenue (ERDC-CERL, 2019)	372
511	Crop of 1500 Block from Camp McCoy plan, 1941 (Fort McCoy)	373
512	Crop of 1500 Block, 2014 map (Fort McCoy)	373
513	1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1500 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	374
514	View to the southwest of Building 1501 (ERDC-CERL, 2018)	375
515	Crop of 1600 Block from Camp McCoy plan, 1941 (Fort McCoy)	376
516	Crop of 1600 Block, 2014 map (Fort McCoy)	377
517	1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1600 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	378
518	View looking west of Building 1645 on left and new building 1655 on right (ERDC-CERL, 2019)	378
519	View of front side of Building 1645 showing addition (ERDC-CERL, 2019)	379
520	View looking west on South Regimental Avenue with Building 1649 on left (ERDC-CERL, 2019)	379
521	Crop of 1700 Block from Camp McCoy plan, 1941 (Fort McCoy)	380
522	Crop of 1700 Block, 2014 map (Fort McCoy)	381
523	1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1700 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	382
524	Looking south down South G Street from South Regimental Avenue (ERDC-CERL, 2019)	382
525	Front side of Building 1751 (ERDC-CERL, 2019)	383
526	View toward chapel (Building 1759) looking north on South F Street (ERDC-CERL, 2019)	383
527	Crop of 1800 Block from Camp McCoy plan, 1941 (Fort McCoy)	384
528	Crop of 1800 Block, 2014 map (Fort McCoy)	384
529	1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1800 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	385
530	View looking west toward Buildings 1864, 1865, and 1861 (ERDC-CERL, 2019)	385
531	Side view of Building 1868 (ERDC-CERL, 2019)	386
532	View south down South E Street from South Regimental Avenue (ERDC-CERL, 2019)	386
533	Looking southwest along South 11 th Avenue with Building 1856 on right and new dining hall on left (ERDC-CERL, 2018)	387

Figure	Page
534 Crop of 1900 Block from Camp McCoy plan, 1941 (Fort McCoy)	388
535 Crop of 1900 Block, 2014 map (Fort McCoy)	388
536 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1900 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	389
537 View east on South 10 th Avenue with Buildings 1923 and 1941 on left (ERDC-CERL, 2019)	389
538 Front sides of Buildings 1921 and 1922 with new picnic shelter in rear (ERDC-CERL, 2019)	390
539 Crop of 2000 Block from Camp McCoy plan, 1941 (Fort McCoy)	391
540 Crop of 2000 Block, 2014 map (Fort McCoy)	391
541 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 2000 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	392
542 View of front side of Service Club (Building 2000) during renovation (ERDC-CERL, 2019)	393
543 Front side of Building 2001 (ERDC-CERL, 2019)	393
544 Front side of new laundromat (Building 2002) (ERDC-CERL, 2019)	394
545 Oblique view of two recreation buildings (Buildings 2004 and 2005) (ERDC-CERL, 2019)	394
546 Front side of Building 2005 (ERDC-CERL, 2019)	395
547 Front side of Buildings 2008 and 2009 (ERDC-CERL, 2019)	395
548 Crop of 2100 Block from Camp McCoy plan, 1941 (Fort McCoy)	396
549 Crop of 2100 Block, 2014 map (Fort McCoy)	397
550 Side view of Buildings 2107 and 2117 from South H Street (ERDC-CERL, 2019)	397
551 Oblique view of Buildings 2125, 2121 and 2119 from South H Street (ERDC-CERL, 2019)	398
552 Oblique view of Buildings 2149, 2147, 2143, and 2141 from South H Street (ERDC-CERL, 2019)	398
553 Crop of stockade complex (2200 Block) from Camp McCoy plan, 1941 (Fort McCoy)	399
554 Aerial view of 2200 Block, 2019 (www.google, accessed 8 November 2019)	399
555 Crop of stockade complex (2300 Block) from Camp McCoy plan, 1941 (Fort McCoy)	400
556 Aerial view of 2300 Block, 2019 (www.google, accessed 8 November 2019)	400
557 Crop of 2400 Block from Camp McCoy plan, 1941 (Fort McCoy)	401
558 Crop of 2400 Block, 2014 map (Fort McCoy)	401
559 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the	

Figure	Page
2400 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	402
560 View along West 13 th Avenue looking north in 2400 Block (ERDC-CERL, 2019)	402
561 View looking northeast down West B Street in 2400 Block (ERDC-CERL, 2019)	403
562 View northeast down West C Street showing missing mess hall (Building 2437 or 2438) on left (ERDC-CERL, 2019)	403
563 Oblique view of new buildings (Buildings 2450-2454) along West A Street (ERDC-CERL, 2019)	404
564 Crop of 2500 Block from Camp McCoy plan, 1941 (Fort McCoy)	404
565 Crop of 2500 Block, 2014 map (Fort McCoy)	405
566 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 2500 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	406
567 View northeast down West D Street with Buildings 2512 and 2510 in foreground. Note demolished mess halls on right (ERDC-CERL, 2019)	406
568 View northeast down West E Street, missing mess halls on left (ERDC-CERL, 2019)	407
569 Front side of Building 2557 (ERDC-CERL, 2019)	407
570 Oblique view of Buildings 2566, 2565, 2564 and 2463 (ERDC-CERL, 2019)	408
571 Oblique view of Building 2545 (ERDC-CERL, 2019)	408
572 View of new motor pool buildings (Buildings 2576 and 2577) from West 13 th Avenue (ERDC-CERL, 2019)	409
573 Crop of 2600 Block from Camp McCoy plan, 1941 (Fort McCoy)	410
574 Crop of 2600 Block, 2014 map (Fort McCoy)	410
575 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 2600 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	411
576 View of front sides of Buildings 2656 and 2657 with new brick dining facility in rear on left and new brick laundromat in rear on right (ERDC-CERL, 2019)	411
577 View of new dining facility (Building 2674) and large parking lot (ERDC-CERL, 2019)	412
578 View of new ammunition storage lockers (AV26 A and B) from West 12 th Avenue (ERDC-CERL, 2019)	412
579 View along West 12 th Avenue with Building 2665 to right (ERDC-CERL, 2019)	413
580 View of new motor pool buildings 2681-2688 west of West 13 th Avenue (ERDC-CERL, 2019)	413

Figure	Page
581 Crop of 2700 Block from Camp McCoy plan, 1941 (Fort McCoy)	414
582 Crop of 2700 Block, 2014 map (Fort McCoy)	414
583 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 2700 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	415
584 View south down West 13 th Avenue with Building 2744 on left (ERDC-CERL, 2019)	415
585 View down West I Street with Building 2734 on left (ERDC-CERL, 2019)	416
586 View of new motor pool complex west of 2700 Block (ERDC-CERL, 2019)	416
587 Crop of 2800 Block from Camp McCoy plan, 1941 (Fort McCoy)	417
588 Crop of 2800 Block, 2014 map (Fort McCoy)	417
589 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 2800 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019)	418
590 View of West J Street and missing Building 2813. (ERDC-CERL, 2019)	418
591 View along West 13 th Avenue of Buildings 2812, 2833, 2832, and 2831 (ERDC-CERL, 2019)	419
592 View along West 13 th Avenue showing changes to motor pool area (ERDC-CERL, 2019)	419
593 View down West K Street at new Building 2840 (ERDC-CERL, 2019)	420
594 Oblique view of new laundromat (Building 2877) (ERDC-CERL, 2019)	420
595 Oblique view of Building 2829 and new ammunition storage lockers in rear (ERDC-CERL, 2019)	421
596 Window comparison of the original eight-over-eight wood double-hung window with a simple wood architrave and asbestos shingle siding with a scalloped bottom edge on a 74-man barracks (left) to the current replacement one-over-one vinyl window and vinyl siding (right) (left: Library of Congress, HABS; right: ERDC-CERL, 2018)	431
597 Original asbestos shingle siding with a scalloped bottom edge detail and wood foundation skirting (left) compared to current replacement vinyl siding and plywood foundation skirting (right) (left: Library of Congress, HABS; right: ERDC-CERL, 2018)	431
598 Front side of a 74-man barracks with comparison of the original construction, design, and materials from 1950 (left) to 1988 (middle) to 2018 (right). Note, the original wood porches, steps, and handrails have already been removed and replaced with a concrete stoop and metal handrails in the middle images (left: NARA; middle: Library of Congress, HABS; right: ERDC-CERL)	434
599 Left side of a 74-man barracks with comparison of the original construction, design, and materials as extant in 1988 (left) to 2018 (right) (left: Library of Congress, HABS; right: ERDC-CERL)	434

Figure		Page
600	Interior view of the original open-bay entry vestibule with wood screen doors leading to the first floor and to the open wood staircase (left) compared to the modified entry vestibule with partition wall and replacement wood interior doors (right) (left: Library of Congress, HABS; right: ERDC-CERL, 2018)	434
601	Interior view of an open-bay squad room in a 74-man barracks (left) compared to the modified squad room in 2018 (left: ERDC-CERL; right: ERDC-CERL, 2018)	435
602	Interior view of an original NCO room on the second floor of a 74-man barracks (left) compared to a modified NCO room from 2018 (right) (left: ERDC-CERL; right: ERDC-CERL)	435
603	Interior view of the original sink area in the latrine on the first floor of a 74-man barracks (left) compared to the modified sink area in 2018 (left: ERDC-CERL; right: ERDC-CERL)	435
604	Front and side of an officers' quarters, Type BOQ-40 with comparison of the original construction, design, and materials as extant in 1988 (left) to a Number 2 type (middle) and a Number 3 type (right) (left: Library of Congress, HABS; middle and right: ERDC-CERL)	437
605	Front and sides of an officers' quarters, Type BOQ-44 with comparison of the original construction, design, and materials as extant in 1988 (left) to a Number 2 type (middle) and a Number 3 type (right) (left: Library of Congress, HABS; middle and right: ERDC-CERL)	438
606	Diagram outlining major areas of the cantonment at Fort McCoy (ERDC-CERL)	470
607	This view of the 500 Block exemplifies the complete demolition of sections of the northeast leg of the cantonment (ERDC-CERL, 2019)	472
608	Aerial view of center of southern leg of cantonment showing large scale new buildings in place of original WWII regimental blocks (www.google.com , accessed 21 May 2020)	473
609	New construction (Building 651, laundromat) in northwest leg showing difference of materials, feeling, mass, and setback (ERDC-CERL, 2019)	474
610	View of Headquarters Building, Building 100, and flagpole (ERDC-CERL 2018)	475
611	Looking northwest at new construction (Building 2100) in warehouse area (ERDC-CERL, 2018)	475
612	View looking northeast of former hospital area showing only trees and no WWII buildings left (ERDC-CERL, 2018)	476
613	Proposed Fort McCoy Headquarters historic district boundary (in blue) as shown on a map of the entire cantonment (ERDC-CERL, 2019)	477

Figure		Page
614	Close-up view of proposed Historic District showing boundary in blue (ERDC-CERL on aerial map from google.com, accessed 21 May 2020)	478
615	View of Building 100 and flagpole in historic postcard, circa 1945 (DPW, Fort McCoy)	479
616	Current view of Building 100, flagpole, plaza, and sign (ERDC-CERL, 2019)	479

Table		Page
1	List of 786 buildings at Fort McCoy, WI that were given to ERDC-CERL for evaluation, 2019 (ERDC-CERL)	3
2	Number 1 Type WWII buildings (compiled by ERDC-CERL, 2019)	191
3	of Number 2 Type buildings (compiled by ERDC-CERL, 2019)	251
4	Number 3 Type WWII buildings (compiled by ERDC-CERL, 2019)	284
5	List of 74-man barracks buildings per Number 1, 2, or 3 type classification (ERDC-CERL)	432
6	List of officers' quarters, Type BOQ-40 buildings per Number 1, 2, or 3 type classification (ERDC-CERL)	436
7	List of officers' quarters, Type BOQ-44 buildings per Number 1, 2, or 3 type designation (ERDC-CERL)	437
8	List of officers' quarters, Type OQ-23, 700 Series buildings per Number 1, 2, or 3 type designation (ERDC-CERL)	438
9	List of WAC barracks buildings per Number 1, 2, or 3 type designation (ERDC-CERL)	439
10	List of brigade general's quarters, Type BGQ-1 per Number 1, 2, or 3 type designation (ERDC-CERL)	439
11	List of regimental commander's quarters, Type RCQ-1 per Number 1, 2, or 3 type designation (ERDC-CERL)	440
12	List of company storehouse, administration, and recreation building per Number 1, 2, or 3 type designation (ERDC-CERL)	441
13	List of company storehouse, administration, and recreation building with single roof per Number 1, 2, or 3 type designation (ERDC-CERL)	442
14	List of interior administration building, Type IBA-1 per Number 1, 2, or 3 type designation (ERDC-CERL)	443
15	List of Administration buildings, Type A-3 per Number 1, 2, or 3 type designation (ERDC-CERL)	444
16	List of administration Type A-10 buildings per Number 1, 2, or 3 type designation (ERDC-CERL)	445

Table		Page
17	List of unit guard house Type UGH-12 buildings per Number 1, 2, or 3 type designation (ERDC-CERL)	445
18	List of unit guard house, Type UGH-24 per Number 1, 2, or 3 type designation (ERDC-CERL)	446
19	List of unit guard house, Type UGH-36 per Number 1, 2, or 3 type designation (ERDC-CERL)	447
20	List of post administration building, Division Headquarters, Type DHQ-1 per Number 1, 2, or 3 type designation (ERDC-CERL)	448
21	List of recreation building – gymnasium (Type RB-1) per Number 1, 2, or 3 type designation (ERDC-CERL)	449
22	List of recreation buildings, Type RB-2 per Number 1, 2, or 3 Type designation (ERDC-CERL)	450
23	List of recreation buildings, Type RB-4 per Number 1, 2, or 3 Type designation (ERDC-CERL)	451
24	List of service clubs per Number 1, 2, or 3 Type designation (ERDC-CERL)	452
25	List of Type M 112-man mess hall per Number 1, 2, or 3 Type designation (ERDC-CERL)	453
26	List of Type M 152-man mess hall per Number 1, 2, or 3 Type designation (ERDC-CERL)	454
27	List of Type M 172-man mess hall per Number 1, 2, or 3 Type designation (ERDC-CERL)	455
28	List of Type M 228-man mess hall per Number 1, 2, or 3 Type designation (ERDC-CERL)	456
29	List of standard storehouses, Type SH-8 per Number 1, 2, or 3 Type designation (ERDC-CERL)	457
30	List of standard storehouses, Type SH-9 per Number 1, 2, or 3 Type designation (ERDC-CERL)	458
31	List of standard storehouses, Type SH-13 per Number 1, 2, or 3 Type designation (ERDC-CERL)	459
32	List of standard storehouses, Type SH-13 per Number 1, 2, or 3 Type designation (ERDC-CERL)	459
33	List of grease rack enclosure buildings per Number 1, 2, or 3 Type designation (ERDC-CERL)	460
34	List of vehicle storage buildings per Number 1, 2, or 3 Type designation (ERDC-CERL)	460
35	List of carpentry shop per Number 1, 2, or 3 Type designation (ERDC-CERL)	461

Table		Page
36	List of motor repair shops per Number 1, 2, or 3 Type designation (ERDC-CERL)	462
37	List of railroad shops per Number 1, 2, or 3 Type designation (ERDC-CERL)	463
38	List of utility shops per Number 1, 2, or 3 Type designation (ERDC-CERL)	463
39	List of G.U. dispensary, Type G.U.D.-1 buildings per Number 1, 2, or 3 Type designation (ERDC-CERL)	464
40	List of dental clinics, Type DC-1 per Number 1, 2, or 3 Type designation (ERDC-CERL)	465
41	List of dental clinics, Type DC-1 per Number 1, 2, or 3 Type designation (ERDC-CERL)	465
42	List of regimental exchange buildings, Type E-3 per Number 1, 2, or 3 Type designation (ERDC-CERL)	466
43	List of regimental chapels per Number 1, 2, or 3 Type designation (ERDC-CERL)	467
44	List of fire stations per Number 1, 2, or 3 Type designation (ERDC-CERL)	468
45	List of post offices per Number 1, 2, or 3 Type designation (ERDC-CERL)	469
46	Recommendations of eligibility for all 786 buildings inventoried (compiled by ERDC-CERL, 2019)	480
47	Number 1 Type WWII buildings (compiled by ERDC-CERL, 2019)	513

Preface

This study was conducted for the Cultural Resources Program, Natural Resource Branch, Environmental Division, Directorate of Public Works (DPW) at Fort McCoy, Wisconsin, under Project 474178, “Inventory/Integrity Analysis of WWII Buildings, Fort McCoy, WI.” The technical monitors were Dr. Kira E. Kaufmann (Cultural Resources Manager, DPW) and Timothy Wilder (Natural Resources Branch Chief, DPW).

The work was performed by the Land and Heritage Conservation Branch, of the Installations Division, of the Engineer Research and Development Center, Construction Engineering Research Laboratory (ERDC-CERL). At the time of publication, Mr. Jedediah Alvey was Chief, Land and Heritage Conservation Branch; Ms. Michelle Hanson was Chief, Installations Division; and Mr. Alan Anderson was the Technical Director for Environmental Quality and Installations. The Acting Director of ERDC-CERL was Dr. Kumar Topudurti.

COL Teresa A. Schlosser was Commander of ERDC, and Dr. David W. Pittman was the Director.

THIS PAGE INTENTIONALLY LEFT BLANK

1 Methodology

1.1 Background

The U.S. Congress codified the National Historic Preservation Act of 1966 (NHPA), the nation's most effective cultural resources legislation to date, in order to provide guidelines and requirements for identifying tangible elements of our nation's past. This legislative requirement was met through creation of the National Register of Historic Places (NRHP). Contained within this piece of legislation (NHPA Sections 110 and 106) are requirements for federal agencies to address their cultural resources, defined as any prehistoric or historic district, site, building, structure, or object. Section 110 requires federal agencies to inventory and evaluate their cultural resources. Section 106 requires the determination of effect of federal undertakings on properties deemed eligible or potentially eligible for the NRHP.

Fort McCoy is located in west-central Wisconsin, east of La Crosse, in between Sparta and Tomah. Fort McCoy lies entirely within Monroe County (Figure 1-1). The U.S. Army first established Sparta Maneuver Tract in 1909 as a field artillery training site. The post was renamed Camp McCoy in 1926, and a Citizens' Military Training Camp (CMTC)* was established at the southern end of the post. A Civilian Conservation Corps (CCC)[†] was established in 1933 at the former CMTC and existed until 1939. After this, a new cantonment was planned north of the Chicago, Milwaukee, St. Paul, and Pacific Railroad utilizing 800 Series War Department mobilization building plans laid out in triangular formation or a "triad." The Army deactivated Camp McCoy on February 1, 1953, after which it was utilized for National Guard and Army Reserve training. The Army reactivated the post in 1970, and it was redesignated Fort McCoy in 1974.

* CMTC was a program that allowed male citizens to obtain basic military training without an obligation to call-up for active duty.

[†] The CCC was a public works relief program for environmental projects that operated from 1933 to 1942 for unemployed, unmarried men of ages 17-28. It was one of President Franklin D. Roosevelt's New Deal programs during the Great Depression.

Figure 1-1. Boundary outline and location of Fort McCoy, WI (DPW, Fort McCoy).

1.2 Objective

The objective of this effort was to inventory all extant WWII buildings, most of them constructed in 1942, at Fort McCoy, Wisconsin and to determine their integrity and eligibility for inclusion in the National Register of Historic Places per Section 110 of the National Historic Preservation Act. The report covers 786 buildings constructed in 1942 identified by Fort McCoy in the cantonment (Figure 1-2). The report includes an inventory and an assessment of the condition of all 786 WWII buildings. The project will also review historic maps of the “Triad” and determine if there is a potential historic district from the remaining WWII temporary buildings.

Figure 1-2. Fort McCoy cantonment map, 2014 (DPW, Fort McCoy).

Analyses of the 786 buildings (Table 1-1) was performed, including basic history and assessment of current conditions. To qualify as eligible for listing on the NRHP, a property must meet at least one of the National Register Criteria for Evaluation as established by the National Park Service (NPS), must be significantly associated with an important historic context, and must retain sufficient integrity to convey its significance.*

Table 1-1. List of 786 buildings at Fort McCoy, WI that were given to ERDC-CERL for evaluation, 2019 (ERDC-CERL).

Fac. No.	Year Built	Original Use	Current Use
100	1942	Post Administration Building, Division Headquarters	Post Administration Building, Division Headquarters
102	1942	Administration	Administration General Purpose
103	1942	Administration (Finance)	Administration General Purpose
104	1942	Administration	Brigade Headquarters Building Transient Training
105	1942	Brigade General Quarters	Recreation Billets

* NPS (National Park Service). National Register Bulletin #15: How to Apply the National Register Criteria for Evaluation (Washington, DC: U.S. Department of the Interior, National Park Service, 1997).

Fac. No.	Year Built	Original Use	Current Use
106	1942	Type M – 152-Man Mess Hall	Company Headquarters Building Transient Training
107	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers' Quarters
108	1942	Brigade General Quarters	Unaccompanied Officers' Quarters Military
109	1942	Standard Storehouse, Type SH-9	Organizational Storage Building
110	1942	Exchange	Administration General Purpose
352	1942	Regimental Exchange Building	General Instruction Building
451	1942	Officers' Quarters – Type BOQ-44	Training Collective UH
452	1942	Officers' Quarters – Type BOQ-44	Training Collective UH
453	1942	Officers' Quarters – Type BOQ-44	Training Collective UH
454	1942	Officers' Quarters – Type BOQ-44	Training Collective UH
547	1942	Grease Rack Enclosure Building	Vehicle Storage Installation
550	1942	Fire Station	Vehicle Storage Installation
601	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
602	1942	74-Man Barracks	Transient Training Enlisted Barracks
603	1942	74-Man Barracks	Transient Training Enlisted Barracks
604	1942	74-Man Barracks	Transient Training Enlisted Barracks
605	1942	Type M – 228-Man Mess Hall	General Instruction Building
606	1942	Type M – 228-Man Mess Hall	General Instruction Building
607	1942	74-Man Barracks	Battalion Headquarters Building Transient Training
608	1942	74-Man Barracks	Company Headquarters Building Transient Training
609	1942	74-Man Barracks	Company Headquarters Building Transient Training
610	1942	74-Man Barracks	Company Headquarters Building Transient Training
611	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
612	1942	74-Man Barracks	Transient Training Enlisted Barracks
613	1942	74-Man Barracks	Transient Training Enlisted Barracks
614	1942	74-Man Barracks	Transient Training Enlisted Barracks
616	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
617	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
618	1942	74-Man Barracks	Transient Training Enlisted Barracks
619	1942	74-Man Barracks	Transient Training Enlisted Barracks
620	1942	74-Man Barracks	Transient Training Enlisted Barracks
621	1942	Company Storehouse, Administration, and Recreation Building	Unaccompanied Personal Housing Laundry Detached
622	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
623	1942	74-Man Barracks	Transient Training Enlisted Barracks
624	1942	74-Man Barracks	Transient Training Enlisted Barracks
625	1942	74-Man Barracks	Transient Training Enlisted Barracks
626	1942	Type M – 172-Man Mess Hall	General Instruction Building
627	1942	Type M – 172-Man Mess Hall	General Instruction Building
628	1942	74-Man Barracks	Transient Training Enlisted Barracks
629	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
632	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
633	1942	Company Storehouse, Administration, and Recreation	General Instruction Building
634	1942	Company Storehouse, Administration, and Recreation	Battalion Headquarters Building Transient Training
638	1942	Company Storehouse, Administration, and Recreation	General Instruction Building
639	1942	Type M – 152-Man Mess Hall	Dining Facility Transient Training
640	1942	74-Man Barracks	Transient Training Enlisted Barracks
641	1942	74-Man Barracks	Transient Training Enlisted Barracks
642	1942	74-Man Barracks	Transient Training Enlisted Barracks
649	1942	Administration	Company Headquarters Building Transient Training
652	1942	Officers' Quarters - Type BOQ-44	Transient Training Enlisted Barracks
653	1942	Officers' Quarters - Type BOQ-44	Transient Training Enlisted Barracks
654	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers' Quarters
655	1942	Officers' Quarters - Type BOQ-40	Transient Training Enlisted Barracks
656	1942	Dental Clinic	Battalion Headquarters Building Transient Training
657	1942	Administration	General Instruction Building
658	1942	Recreation Building – Type RB-2	General Instruction Building
659	1942	Brigade General's Quarters – Type BGQ-1	Recreational Billets
660	1942	Recreation Building – Type RB-2	Battalion Headquarters Building Transient Training
701	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
702	1942	74-Man Barracks	Transient Training Enlisted Barracks
703	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
704	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
705	1942	Type M – 228-Man Mess Hall	Brigade Headquarters Building Transient Training
706	1942	Type M – 228-Man Mess Hall	Brigade Headquarters Building Transient Training
707	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
708	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
709	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
710	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
711	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
712	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
713	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
714	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
718	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
719	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
720	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
721	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
722	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training

Fac. No.	Year Built	Original Use	Current Use
723	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
724	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
725	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
726	1942	Type M – 228-Man Mess Hall	Brigade Headquarters Building Transient Training
727	1942	Type M – 228-Man Mess Hall	Brigade Headquarters Building Transient Training
728	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
729	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
730	1942	74-Man Barracks	Brigade Headquarters Building
731	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
732	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
733	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
734	1942	74-Man Barracks	Transient Training Enlisted Barracks
735	1942	74-Man Barracks	Transient Training Enlisted Barracks
736		74-Man Barracks	Transient Training Enlisted Barracks
740	1942	74-Man Barracks	Transient Training Enlisted Barracks
741	1942	74-Man Barracks	Transient Training Enlisted Barracks
742	1942	74-Man Barracks	Transient Training Enlisted Barracks
743	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
744	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
749	1942	Administration	General Instruction Building
750	1942	G.U. Dispensary - Type G.U.D. -1	General Instruction Building
751	1942	Regimental Exchange Building	General Instruction Building
756	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building
757	1942	Company Storehouse, Administration, and Recreation Building	Battalion Headquarters Building
801	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
802	1942	74-Man Barracks	Transient Training Enlisted Barracks
803	1942	74-Man Barracks	Transient Training Enlisted Barracks
804	1942	74-Man Barracks	Transient Training Enlisted Barracks
805	1942	Type M – 228-Man Mess Hall	General Instruction Building
806	1942	Type M – 228-Man Mess Hall	General Instruction Building
807	1942	74-Man Barracks	Transient Training Enlisted Barracks
808	1942	74-Man Barracks	Transient Training Enlisted Barracks
809	1942	74-Man Barracks	Transient Training Enlisted Barracks
810	1942	74-Man Barracks	Transient Training Enlisted Barracks
811	1942	Company Storehouse, Administration, and Recreation Building	ARM Force Center
812	1942	74-Man Barracks	USAR Center
813	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
814	1942	74-Man Barracks	Transient Training Enlisted Barracks
816	1942	Type M – 228-Man Mess Hall	General Instruction Building
817	1942	Type M – 228-Man Mess Hall	General Instruction Building
818	1942	74-Man Barracks	Transient Training Enlisted Barracks
819	1942	74-Man Barracks	Transient Training Enlisted Barracks
820	1942	74-Man Barracks	Transient Training Enlisted Barracks
821	1942	Company Storehouse, Administration, and Recreation Building	ARM Force Center
823	1942	74-Man Barracks	USAR Center
824	1942	74-Man Barracks	USAR Center
825	1942	74-Man Barracks	USAR Center
826	1942	Type M – 172-Man Mess Hall	ARM Force Center
827	1942	Type M – 152-Man Mess Hall	ARM Force Center
828	1942	74-Man Barracks	USAR Center
829	1942	74-Man Barracks	USAR Center
832	1942	Company Storehouse, Administration, and Recreation Building	ARM Force Center
833	1942	Company Storehouse, Administration, and Recreation Building	ARM Force Center
839	1942	Type M – 112-Man Mess Hall	Heritage Center Facility
840	1942	74-Man Barracks	Heritage Center Facility
841	1942	74-Man Barracks	Heritage Center Facility
842	1942	74-Man Barracks	Heritage Center Facility
843	1942	Company Storehouse, Administration, and Recreation Building	Heritage Center Facility
848	1942	Interior Battalion Administration Building	Company Headquarters Building Transient Training
849	1942	Unit Guard House – Type Ugh-24	Company Headquarters Building Transient Training
851	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers' Quarters
852	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers' Quarters
853	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers' Quarters
855	1942	Company Storehouse, Administration, and Recreation Building	United States Army Reserve Center
857	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
901	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets
902	1942	Administration	Heritage Center Facility
903	1942	Recreation Building – Type RB-2	Heritage Center Facility
904	1942	Bachelor Officers' Quarters - 700-Series, Type OQ-23	Transient Training Officers Quarters
1101	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1105	1942	74-Man Barracks	Transient Training Enlisted Barracks
1106	1942	Type M – 112-Man Mess Hall	Administration General Purpose
1108	1942	74-Man Barracks	Administration General Purpose

Fac. No.	Year Built	Original Use	Current Use
1111	1942	Company Storehouse, Administration, and Recreation Building	Administration General Purpose
1113	1942	74-Man Barracks	Transient Training Enlisted Barracks
1114	1942	74-Man Barracks	Transient Training Enlisted Barracks
1115	1942	Type M – 152-Man Mess Hall	Simulation Center
1116	1942	Type M – 152-Man Mess Hall	Physical Fitness Center
1117	1942	74-Man Barracks	Transient Training Enlisted Barracks
1118	1942	74-Man Barracks	Transient Training Enlisted Barracks
1121	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building
1129	1942	74-Man Barracks	Organizational Storage Building
1130	1942	74-Man Barracks	Transient Training Enlisted Barracks
1132	1942	Company Storehouse, Administration, and Recreation	Company Headquarters Building Transient Training
1133	1942	Company Storehouse, Administration, and Recreation	Skill Development (Na)
1145	1942	Administration	Brigade Headquarters Building Transient Training
1152	1942	Grease Rack Enclosure Building	Engineering/Housing Maintenance
1153	1942	Standard Storehouse, Type SH-8	Organizational Storage Building
1154	1942	Standard Storehouse, Type SH-8	Organizational Storage Building
1201	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1203	1942	74-Man Barracks	Transient Training Enlisted Barracks
1204	1942	74-Man Barracks	Transient Training Enlisted Barracks
1205	1942	Type M – 112-Man Mess Hall	Miscellaneous Facilities, Detached
1206	1942	Type M – 112-Man Mess Hall	Company Headquarters Building Transient Training
1207	1942	Type M – 112-Man Mess Hall	Brigade Headquarters Building Transient Training
1208	1942	74-Man Barracks	Transient Training Enlisted Barracks
1209	1942	74-Man Barracks	Transient Training Enlisted Barracks
1210	142	74-Man Barracks	Transient Training Enlisted Barracks
1211	1942	Company Storehouse, Administration, and Recreation Building	Eng/Housing Maintenance
1213	1942	74-Man Barracks	Transient Training Officers Quarters
1214	1942	74-Man Barracks	Transient Training Enlisted Barracks
1215	1942	Type M – 172-Man Mess Hall	Company Headquarters Building Transient Training
1216	1942	Type M – 112-Man Mess Hall	Brigade Headquarters Building Transient Training
1217	1942	74-Man Barracks	Transient Training Enlisted Barracks
1221	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1222	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1224	1942	74-Man Barracks	Training Collective UH
1225	1942	74-Man Barracks	Training Collective UH
1226	1942	Type M – 112-Man Mess Hall	Organizational Classroom
1227	1942	Type M – 112-Man Mess Hall	Organizational Classroom

Fac. No.	Year Built	Original Use	Current Use
1228	1942	Type M – 112-Man Mess Hall	Brigade Headquarters Building Transient Training
1229	1942	74-Man Barracks	Transient Training Enlisted Barracks
1230	1942	74-Man Barracks	Transient Training Enlisted Barracks
1231	1942	74-Man Barracks	Transient Training Enlisted Barracks
1232	1942	Company Storehouse, Administration, and Recreation	Organizational Storage Building
1233	1942	Company Storehouse, Administration, and Recreation	Company Headquarters Building Transient Training
1235	1942	74-Man Barracks	Transient Training Enlisted Barracks
1236	1942	74-Man Barracks	Transient Training Enlisted Barracks
1237	1942	Type M – 112-Man Mess Hall	Organizational Storage Building
1239	1942	74-Man Barracks	Transient Training Enlisted Barracks
1243	1942	Recreation Building – Type RB-2	Battalion Headquarters Building Transient Training
1244	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1245	1942	Administration	USAR Center
1246	1942	G.U. Dispensary	Company Headquarters Building Transient Training
1247	1942	Brigade General's Quarters – Type BGQ-1	Recreation Billets
1248	1942	Type M – 152-Man Mess Hall	Company Headquarters Building Transient Training
1249	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
1250	1942	Officers' Quarters – Type BOQ-44	Training Collective UH
1251	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
1254	1942	Administration	Battalion Headquarters Building Transient Training
1255	1942	Recreation Building - Gymnasium	General Instruction Building
1256	1942	Regimental Exchange Building	General Instruction Building
1257	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1258	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1260	1942	Motor Repair Shop	Organizational Storage Building
1261	1942	Motor Repair Shop	Organizational Storage Building
1262	1942	Motor Repair Shop	Organizational Storage Building
1263	1942	Standard Storehouse – Type SH-8	Organizational Storage Building
1264	1942	Standard Storehouse – Type SH-9	Organizational Storage Building
1265	1942	Standard Storehouse – Type SH-8	Organizational Storage Building
1301	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1304	1942	74-Man Barracks	Transient Training Enlisted Barracks
1305	1942	74-Man Barracks	Transient Training Enlisted Barracks
1308	1942	74-Man Barracks	Transient Training Enlisted Barracks
1311	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1313	1942	74-Man Barracks	Transient Training Enlisted Barracks
1314	1942	74-Man Barracks	Transient Training Enlisted Barracks
1315	1942	Type M – 112-Man Mess Hall	General Instruction Building

Fac. No.	Year Built	Original Use	Current Use
1316	1942	Type M – 112-Man Mess Hall	General Instruction Building
1321	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1324	1942	74-Man Barracks	Transient Training Enlisted Barracks
1325	1942	74-Man Barracks	Transient Training Enlisted Barracks
1326	1942	Type M – 112-Man Mess Hall	General Instruction Building
1327	1942	Type M – 112-Man Mess Hall	General Instruction Building
1328	1942	Type M – 112-Man Mess Hall	General Instruction Building
1329		74-Man Barracks	Transient Training Enlisted Barracks
1330	1942	74-Man Barracks	Transient Training Enlisted Barracks
1331	1942	74-Man Barracks	Transient Training Enlisted Barracks
1332	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1335	1942	74-Man Barracks	Transient Training Enlisted Barracks
1336	1942	74-Man Barracks	Transient Training Enlisted Barracks
1337	1942	Type M – 152-Man Mess Hall	General Instruction Building
1338	1942	Type M – 112-Man Mess Hall	General Instruction Building
1339	1942	74-Man Barracks	Transient Training Enlisted Barracks
1343	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1344	1942	Company Storehouse, Administration, and Recreation Building	Drug/Alcohol Abuse Building
1345	1942	Administration	Brigade Headquarters Building Transient Training
1346	1942	G. U. Dispensary	Brigade Headquarters Building Transient Training
1347	1942	Infirmary	Company Headquarters Building Transient Training
1348	1942	Unit Guard House – Type Ugh-24	Brigade Headquarters Building Transient Training
1349	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1359	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1401	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1404	1942	74-Man Barracks	Transient Training Enlisted Barracks
1405	1942	Type M – 112-Man Mess Hall	General Instruction Building
1406	1942	Type M – 112-Man Mess Hall	General Instruction Building
1407	1942	74-Man Barracks	Transient Training Enlisted Barracks
1408	1942	74-Man Barracks	Transient Training Enlisted Barracks
1409	1942	74-Man Barracks	Transient Training Enlisted Barracks
1411	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1413	1942	74-Man Barracks	Transient Training Enlisted Barracks
1414	1942	74-Man Barracks	Transient Training Enlisted Barracks
1415	1942	Type M – 112-Man Mess Hall	Organizational Storage Building
1416	1942	Type M – 112-Man Mess Hall	Organizational Storage Building
1417	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
1421	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1424	1942	74-Man Barracks	Transient Training Enlisted Barracks
1425	1942	74-Man Barracks	Transient Training Enlisted Barracks
1426	1942	74-Man Barracks	Transient Training Enlisted Barracks
1427	1942	Type M – 112-Man Mess Hall	Organizational Storage Building
1428	1942	Type M – 112-Man Mess Hall	General Instruction Building
1429	1942	74-Man Barracks	Transient Training Enlisted Barracks
1432	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1435	1942	74-Man Barracks	General Instruction Building
1436	1942	74-Man Barracks	Transient Training Enlisted Barracks
1437	1942	Type M – 112-Man Mess Hall	General Instruction Building
1439	1942	74-Man Barracks	Transient Training Enlisted Barracks
1440	1942	74-Man Barracks	General Instruction Building
1441	1942	74-Man Barracks	Transient Training Enlisted Barracks
1443	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building
1444	1942	Company Storehouse, Administration, and Recreation Building	Unaccompanied Personal Housing Laundry Detached
1445	1942	Post Exchange	General Instruction Building
1446	1942	Administration	Brigade Headquarters Building Transient Training
1447	1942	Unit Guard House – Type UGH-12	General Instruction Building
1448	1942	Recreation Building - Gymnasium	Auditorium General Purpose
1501	1942	Company Storehouse, Administration, and Recreation Building	Credit Union
1601	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1602	1942	74-Man Barracks	Transient Training Enlisted Barracks
1603	1942	74-Man Barracks	Transient Training Enlisted Barracks
1604	1942	74-Man Barracks	Transient Training Enlisted Barracks
1605	1942	Type M – 228-Man Mess Hall	General Instruction Building
1606	1942	Type M – 228-Man Mess Hall	General Instruction Building
1607	1942	74-Man Barracks	Transient Training Enlisted Barracks
1608	1942	74-Man Barracks	Transient Training Enlisted Barracks
1609	1942	74-Man Barracks	Transient Training Enlisted Barracks
1610	1942	74-Man Barracks	Transient Training Enlisted Barracks
1612	1942	74-Man Barracks	Transient Training Enlisted Barracks
1613	1942	74-Man Barracks	Transient Training Enlisted Barracks
1614	1942	74-Man Barracks	Transient Training Enlisted Barracks
1615	1942	74-Man Barracks	Transient Training Enlisted Barracks
1616	1942	Type M – 228-Man Mess Hall	General Instruction Building
1617	1942	Type M – 228-Man Mess Hall	General Instruction Building
1618	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
1619	1942	74-Man Barracks	Transient Training Enlisted Barracks
1620	1942	74-Man Barracks	Transient Training Enlisted Barracks
1621	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1622	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1623	1942	74-Man Barracks	Transient Training Enlisted Barracks
1624	1942	74-Man Barracks	Transient Training Enlisted Barracks
1625	1942	74-Man Barracks	Transient Training Enlisted Barracks
1626	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
1627	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
1628	1942	74-Man Barracks	Transient Training Enlisted Barracks
1629	1942	74-Man Barracks	Transient Training Enlisted Barracks
1630	1942	74-Man Barracks	Transient Training Enlisted Barracks
1631	1942	74-Man Barracks	Transient Training Enlisted Barracks
1632	1942	Bachelor Officers' Quarters - 700-Series, Type OQ-23	Transient Training Enlisted Barracks
1634	1942	74-Man Barracks	Transient Training Enlisted Barracks
1635	1942	74-Man Barracks	Transient Training Enlisted Barracks
1636	1942	74-Man Barracks	Transient Training Enlisted Barracks
1637	1942	74-Man Barracks	Transient Training Enlisted Barracks
1638	1942	Type M – 228-Man Mess Hall	General Instruction Building
1639	1942	Type M – 228-Man Mess Hall	General Instruction Building
1640	1942	74-Man Barracks	Transient Training Enlisted Barracks
1641	1942	74-Man Barracks	Transient Training Enlisted Barracks
1642	1942	74-Man Barracks	Transient Training Enlisted Barracks
1643	1942	Company Storehouse, Administration, and Recreation Building	Arms Storage-Battalion
1644	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1645	1942	Type M – 228-Man Mess Hall	Military Clothing Sale
1646	1942	Company Storehouse, Administration, and Recreation Building	Exchange Branch
1647	1942	Recreation Building – Type RB-4	Brigade Headquarters Building Transient Training
1648	1942	Administration	Company Headquarters Building Transient Training
1649	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1650	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building
1651	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1652	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1653	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training
1654	1942	Company Storehouse, Administration, and Recreation Building	Print Plant

Fac. No.	Year Built	Original Use	Current Use
1656	1942	Regimental Commander's Quarters - Type RCQ-1	Recreation Billets
1657	1942	Officers' Quarters - Type BOQ-44	Unaccompanied Personal Housing Senior Non-Commissioned Officer
1658	1942	Officers' Quarters - Type BOQ-44	Recreation Billets
1659	1942	Vehicle Storage Building	Organizational Storage Building
1660	1942	Officers' Quarters - Type BOQ-44	Recreation Billets
1661	1942	Officers' Quarters - Type BOQ-44	Recreation Billets
1662	1942	Bachelor Officers' Quarters - 700-Series, Type OQ-23	Transient Training Officers Quarters
1663	1942	G.U. Dispensary	Exchange Service Outlet
1664	1942	Infirmary	Company Headquarters Building Transient Training
1701	1942	Company Storehouse, Administration, and Recreation Building	Unaccompanied Personal Housing Laundry Detached
1702	1942	74-Man Barracks	Transient Training Enlisted Barracks
1703	1942	74-Man Barracks	Transient Training Enlisted Barracks
1704	1942	74-Man Barracks	Transient Training Enlisted Barracks
1705	1942	Type M - 228-Man Mess Hall	General Instruction Building
1706	1942	Type M - 228-Man Mess Hall	General Instruction Building
1707	1942	74-Man Barracks	Transient Training Enlisted Barracks
1708	1942	74-Man Barracks	Transient Training Enlisted Barracks
1709	1942	74-Man Barracks	Transient Training Enlisted Barracks
1710	1942	74-Man Barracks	Transient Training Enlisted Barracks
1712	1942	74-Man Barracks	Transient Training Enlisted Barracks
1713	1942	74-Man Barracks	Transient Training Enlisted Barracks
1714	1942	74-Man Barracks	Transient Training Enlisted Barracks
1715	1942	74-Man Barracks	Transient Training Enlisted Barracks
1716	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
1717	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
1718	1942	74-Man Barracks	Transient Training Enlisted Barracks
1719	1942	74-Man Barracks	Transient Training Enlisted Barracks
1720	1942	74-Man Barracks	Transient Training Enlisted Barracks
1721	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1722	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1723	1942	74-Man Barracks	Transient Training Enlisted Barracks
1724	1942	74-Man Barracks	Transient Training Enlisted Barracks
1725	1942	74-Man Barracks	Transient Training Enlisted Barracks
1728	1942	74-Man Barracks	Transient Training Enlisted Barracks
1729	1942	74-Man Barracks	Transient Training Enlisted Barracks
1730	1942	74-Man Barracks	Transient Training Enlisted Barracks
1731	1942	74-Man Barracks	Transient Training Enlisted Barracks
1732	1942	74-Man Barracks	Transient Training Enlisted Barracks
1736	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
1737	1942	74-Man Barracks	Transient Training Enlisted Barracks
1738	1942	Type M – 228-Man Mess Hall	General Instruction Building
1739	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
1740	1942	74-Man Barracks	Transient Training Enlisted Barracks
1741	1942	74-Man Barracks	Transient Training Enlisted Barracks
1742	1942	74-Man Barracks	Transient Training Enlisted Barracks
1743	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1744	1942	74-Man Barracks	Transient Training Enlisted Barracks
1745	1942	Administration	Child Development Center Under 6 Years
1747	1942	Company Storehouse, Administration, and Recreation Building	Child Development Center Under 6 Years
1748	1942	Unit Guard House – Type Ugh-36	Battalion Headquarters Building Transient Training
1749	1942	G. U. Dispensary	Company Headquarters Building Transient Training
1750	1942	Regimental Exchange Building	Organizational Storage Building
1751	1942	Recreation Building – Type RB-4	Battalion Headquarters Building Transient Training
1753	1942	Administration	Company Headquarters Building Transient Training
1754	1942	Regimental Commander's Quarters – Type RCQ-1	Child Development Center Under 6 Years
1755	1942	Administration	Battalion Headquarters Building Transient Training
1756	1942	Type M – 228-Man Mess Hall	Organizational Storage Building
1757	1942	Recreation Building – Type RB-4	Battalion Headquarters Building Transient Training
1758	1942	Recreation Building - Gymnasium	Auditorium General Purpose
1759	1942	Regimental Chapel	Chapel
1760	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training
1761	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training
1764	1942	Motor Repair Shop	Organizational Storage Building
1801	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1802	1942	74-Man Barracks	Transient Training Enlisted Barracks
1803	1942	74-Man Barracks	Transient Training Enlisted Barracks
1804	1942	74-Man Barracks	Transient Training Enlisted Barracks
1805	1942	Type M – 228-Man Mess Hall	General Instruction Building
1806	1942	Type M – 228-Man Mess Hall	General Instruction Building
1807	1942	74-Man Barracks	Transient Training Enlisted Barracks
1808	1942	74-Man Barracks	Transient Training Enlisted Barracks
1809	1942	74-Man Barracks	Transient Training Enlisted Barracks
1810	1942	74-Man Barracks	Transient Training Enlisted Barracks
1812	1942	74-Man Barracks	Transient Training Enlisted Barracks
1813	1942	74-Man Barracks	Transient Training Enlisted Barracks
1814	1942	74-Man Barracks	Transient Training Enlisted Barracks
1815	1942	74-Man Barracks	Transient Training Enlisted Barracks
1816	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
1817	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training

Fac. No.	Year Built	Original Use	Current Use
1818	1942	74-Man Barracks	Transient Training Enlisted Barracks
1819	1942	74-Man Barracks	Transient Training Enlisted Barracks
1820	1942	74-Man Barracks	Transient Training Enlisted Barracks
1821	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1822	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1823	1942	74-Man Barracks	Transient Training Enlisted Barracks
1824	1942	74-Man Barracks	Transient Training Enlisted Barracks
1825	1942	74-Man Barracks	Transient Training Enlisted Barracks
1826	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
1827	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
1828	1942	74-Man Barracks	Transient Training Enlisted Barracks
1829	1942	74-Man Barracks	Transient Training Enlisted Barracks
1830	1942	74-Man Barracks	Transient Training Enlisted Barracks
1831	1942	74-Man Barracks	Transient Training Enlisted Barracks
1832	1942	74-Man Barracks	Transient Training Enlisted Barracks
1834	1942	74-Man Barracks	Transient Training Enlisted Barracks
1835	1942	74-Man Barracks	Transient Training Enlisted Barracks
1836	1942	74-Man Barracks	Transient Training Enlisted Barracks
1837	1942	74-Man Barracks	Transient Training Enlisted Barracks
1838	1942	Type M – 228-Man Mess Hall	General Instruction Building
1840	1942	74-Man Barracks	Transient Training Enlisted Barracks
1842	1942	74-Man Barracks	Transient Training Enlisted Barracks
1843	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1844	1942	74-Man Barracks	Transient Training Enlisted Barracks
1846	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1847	1942	Administration	Company Headquarters Building Transient Training
1848	1942	Administration	Company Headquarters Building Transient Training
1851	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1852	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1853	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets
1854	1942	Administration	Company Headquarters Building Transient Training
1855	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1857	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
1858	1942	Officers' Quarters – Type BOQ-44	Recreation Billets
1859	1942	Officers' Quarters – Type BOQ-44	Recreation Billets
1862	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
1863	1942	Bachelor Officers' Quarters – Type OQ-23	Transient Training Officers Quarters
1864	1942	Bachelor Officers' Quarters – Type OQ-23	Transient Training Officers Quarters

Fac. No.	Year Built	Original Use	Current Use
1865	1942	G. U. Dispensary	Company Headquarters Building Transient Training
1866	1942	Unit Guard House – Type UGH-36	Confinement Facility
1868	1942	Post Exchange	Battalion Headquarters Building Transient Training
1869	1942	Recreation Building – Type RB-1	Battalion Headquarters Building
1913	1942	74-Man Barracks	Administration General Purpose
1914	1942	74-Man Barracks	Transient Training Enlisted Barracks
1915	1942	74-Man Barracks	Transient Training Enlisted Barracks
1916	1942	Type M – 228-Man Mess Hall	Dining Facility: Transient Training
1918	1942	74-Man Barracks	Transient Training Enlisted Barracks
1919	1942	74-Man Barracks	Transient Training Enlisted Barracks
1920	1942	74-Man Barracks	Transient Training Enlisted Barracks
1921	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1922	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1923	1942	74-Man Barracks	Transient Training Enlisted Barracks
1924	1942	74-Man Barracks	Transient Training Enlisted Barracks
1925	1942	74-Man Barracks	Transient Training Enlisted Barracks
1926	1942	Type M – 228-Man Mess Hall	General Instruction Building
1928	1942	74-Man Barracks	Transient Training Enlisted Barracks
1929	1942	74-Man Barracks	Transient Training Enlisted Barracks
1930	1942	74-Man Barracks	Transient Training Enlisted Barracks
1931	1942	74-Man Barracks	Transient Training Enlisted Barracks
1932	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
1934	1942	74-Man Barracks	Transient Training Enlisted Barracks
1935	1942	74-Man Barracks	Transient Training Enlisted Barracks
1936	1942	74-Man Barracks	Transient Training Enlisted Barracks
1937	1942	74-Man Barracks	Transient Training Enlisted Barracks
1940	1942	74-Man Barracks	Transient Training Enlisted Barracks
1941	1942	74-Man Barracks	Transient Training Enlisted Barracks
1943	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1944	1942	74-Man Barracks	Transient Training Enlisted Barracks
1945	1942	Administration	Company Headquarters Building Transient Training
1946	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building
1947	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building
1948	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1949	1942	Type M – 228-Man Mess Hall	Organizational Storage Building
1950	1942	Interior Battalion Administration	Organizational Storage Building
1951	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
2000	1942	Service Club	Administration General Purpose

Fac. No.	Year Built	Original Use	Current Use
2001	1942	Regimental Exchange Building	Brigade Headquarters Building Transient Training
2004	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2005	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2006	1942	Type M – 228-Man Mess Hall	Limit Use Instruction
2007	1942	74-Man Barracks	Transient Training Officers Quarters
2008	1942	Type M – 228-Man Mess Hall	Limit Use Instruction
2009	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
2010	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
2011	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
2107	1942	Storehouse – Type SH-13	Storage General Purpose
2108	1942	Storehouse – Type SH-13	Storage General Purpose
2109	1942	Railroad Equipment	Maintenance Storage DOL
2111	1942	Fire Station	ACS Center
2113	1942	Bakery	Televideo Center
2115	1942	Carpenter Shop	Engineering/Housing Maintenance
2116	1942	Utility Shop	Maintenance Storage DOL
2117	1942	Administration	Company Headquarters Building Transient Training
2119	1942	Storehouse – Type SH-18	Storage General Purpose
2121	1942	Storehouse – Type SH-18	Storage General Purpose
2123	1942	Storehouse – Type SH-18	Storage General Purpose
2125	1942	Storehouse – Type SH-18	Storage General Purpose
2141	1942	Storehouse – Type SH-13	Storage General Purpose
2142	1942	Storehouse – Type SH-13	Central Issue Facility
2143	1942	Storehouse – Type SH-13	Storage General Purpose
2145	1942	Storehouse – Type SH-13	Storage General Purpose
2147	1942	Storehouse – Type SH-13	Storage General Purpose
2149	1942	Storehouse – Type SH-13	Storage General Purpose
2161	1942	Storehouse – Type SH-18	Organizational Storage Building
2168	1942	Administration	Administration General Purpose
2171	1942	WAC Barracks	Administration General Purpose
2180	1942	Administration	Administration General Purpose
2184	1942	Storehouse – Type SH-18	Organizational Storage Building
2402	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2403	1942	74-Man Barracks	Transient Training Enlisted Barracks
2404	1942	74-Man Barracks	Transient Training Enlisted Barracks
2405	1942	74-Man Barracks	Transient Training Enlisted Barracks
2406	1942	Type M – 228-Man Mess Hall	General Instruction Building
2407	1942	Type M – 228-Man Mess Hall	General Instruction Building
2408	1942	74-Man Barracks	Transient Training Enlisted Barracks
2409	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
2410	1942	74-Man Barracks	Transient Training Enlisted Barracks
2411	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2412	1942	74-Man Barracks	Transient Training Enlisted Barracks
2413	1942	74-Man Barracks	Transient Training Enlisted Barracks
2414	1942	74-Man Barracks	Transient Training Enlisted Barracks
2415	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2416	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2417	1942	74-Man Barracks	Transient Training Enlisted Barracks
2418	1942	74-Man Barracks	Transient Training Enlisted Barracks
2419	1942	74-Man Barracks	Transient Training Enlisted Barracks
2420	1942	74-Man Barracks	Transient Training Enlisted Barracks
2421	1942	74-Man Barracks	Transient Training Enlisted Barracks
2423	1942	74-Man Barracks	Transient Training Enlisted Barracks
2424	1942	74-Man Barracks	Transient Training Enlisted Barracks
2425	1942	74-Man Barracks	Transient Training Enlisted Barracks
2426	1942	74-Man Barracks	Transient Training Enlisted Barracks
2427	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2428	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2429	1942	74-Man Barracks	Transient Training Enlisted Barracks
2430	1942	74-Man Barracks	Transient Training Enlisted Barracks
2431	1942	74-Man Barracks	Transient Training Enlisted Barracks
2432	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2433	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2434	1942	74-Man Barracks	Transient Training Enlisted Barracks
2435	1942	74-Man Barracks	Transient Training Enlisted Barracks
2436	1942	74-Man Barracks	Transient Training Enlisted Barracks
2439	1942	74-Man Barracks	Transient Training Enlisted Barracks
2440	1942	74-Man Barracks	Transient Training Enlisted Barracks
2441	1942	74-Man Barracks	Transient Training Enlisted Barracks
2442	1942	74-Man Barracks	Transient Training Enlisted Barracks
2444	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2445	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2446	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2447	1942	Type M – 228-Man Mess Hall	General Instruction Building
2448	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets
2501	1942	74-Man Barracks	Transient Training Enlisted Barracks
2502	1942	74-Man Barracks	Transient Training Enlisted Barracks
2503	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
2504	1942	74-Man Barracks	Transient Training Enlisted Barracks
2505	1942	74-Man Barracks	Transient Training Enlisted Barracks
2508	1942	74-Man Barracks	Transient Training Enlisted Barracks
2509	1942	74-Man Barracks	Transient Training Enlisted Barracks
2510	1942	74-Man Barracks	Transient Training Enlisted Barracks
2511	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2512	1942	74-Man Barracks	Transient Training Enlisted Barracks
2513	1942	74-Man Barracks	Transient Training Enlisted Barracks
2514	1942	74-Man Barracks	Transient Training Enlisted Barracks
2515	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2516	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2517	1942	74-Man Barracks	Transient Training Enlisted Barracks
2518	1942	74-Man Barracks	Transient Training Enlisted Barracks
2519	1942	74-Man Barracks	Transient Training Enlisted Barracks
2520	1942	74-Man Barracks	Transient Training Enlisted Barracks
2521	1942	74-Man Barracks	Transient Training Enlisted Barracks
2523	1942	74-Man Barracks	Transient Training Enlisted Barracks
2524	1942	74-Man Barracks	Transient Training Enlisted Barracks
2525	1942	74-Man Barracks	Transient Training Enlisted Barracks
2526	1942	74-Man Barracks	Transient Training Enlisted Barracks
2527	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2528	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2529	1942	74-Man Barracks	Transient Training Enlisted Barracks
2530	1942	74-Man Barracks	Transient Training Enlisted Barracks
2531	1942	74-Man Barracks	Transient Training Enlisted Barracks
2532	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training
2533	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training
2534	1942	74-Man Barracks	Transient Training Enlisted Barracks
2535	1942	74-Man Barracks	Transient Training Enlisted Barracks
2536	1942	74-Man Barracks	Transient Training Enlisted Barracks
2539	1942	74-Man Barracks	Transient Training Enlisted Barracks
2540	1942	74-Man Barracks	Transient Training Enlisted Barracks
2541	1942	74-Man Barracks	Transient Training Enlisted Barracks
2544	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2545	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
2546	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2547	1942	Administration	General Instruction Building
2548	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2549	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training

Fac. No.	Year Built	Original Use	Current Use
2550	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
2551	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2552	1942	Administration	Company Headquarters Building Transient Training
2553	1942	Administration	Company Headquarters Building Transient Training
2554	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2555	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2556	1942	G.U. Dispensary	Company Headquarters Building Transient Training
2557	1942	Recreation Building – Type RB-1	Auditorium General Purpose
2558	1942	Regimental Exchange Building	Auditorium General Purpose
2560	1942	Unit Guard House – Type Ugh-36	Company Headquarters Building Transient Training
2561	1942	Bachelor Officers' Quarters – Type BOQ-23	Transient Training Officers Quarters
2562	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters
2563	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
2564	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters
2565	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters
2566	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets
2601	1942	74-Man Barracks	Transient Training Enlisted Barracks
2602	1942	74-Man Barracks	Transient Training Enlisted Barracks
2603	1942	74-Man Barracks	Transient Training Enlisted Barracks
2604	1942	74-Man Barracks	Transient Training Enlisted Barracks
2605	1942	74-Man Barracks	Transient Training Enlisted Barracks
2606	1942	Type M – 228-Man Mess Hall	General Instruction Building
2607	1942	Type M – 228-Man Mess Hall	General Instruction Building
2608	1942	74-Man Barracks	Transient Training Enlisted Barracks
2609	1942	74-Man Barracks	Transient Training Enlisted Barracks
2610	1942	74-Man Barracks	Transient Training Enlisted Barracks
2611	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2612	1942	74-Man Barracks	Transient Training Enlisted Barracks
2613	1942	74-Man Barracks	Transient Training Enlisted Barracks
2614	1942	74-Man Barracks	Transient Training Enlisted Barracks
2615	1942	Type M – 228-Man Mess Hall	General Instruction Building
2617	1942	74-Man Barracks	Transient Training Enlisted Barracks
2618	1942	74-Man Barracks	Transient Training Enlisted Barracks
2619	1942	74-Man Barracks	Transient Training Enlisted Barracks
2620	1942	74-Man Barracks	Transient Training Enlisted Barracks
2621	1942	74-Man Barracks	Transient Training Enlisted Barracks
2623	1942	74-Man Barracks	Transient Training Enlisted Barracks
2624	1942	74-Man Barracks	Transient Training Enlisted Barracks
2625	1942	74-Man Barracks	Transient Training Enlisted Barracks
2626	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
2627	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2628	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2629	1942	74-Man Barracks	Transient Training Enlisted Barracks
2630	1942	74-Man Barracks	Transient Training Enlisted Barracks
2631	1942	74-Man Barracks	Transient Training Enlisted Barracks
2632	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training
2633	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training
2634	1942	74-Man Barracks	Transient Training Enlisted Barracks
2635	1942	74-Man Barracks	Transient Training Enlisted Barracks
2636	1942	74-Man Barracks	Transient Training Enlisted Barracks
2637	1942	Type M – 228-Man Mess Hall	General Instruction Building
2638	1942	Type M – 228-Man Mess Hall	General Instruction Building
2639	1942	74-Man Barracks	Transient Training Enlisted Barracks
2640	1942	74-Man Barracks	Transient Training Enlisted Barracks
2641	1942	74-Man Barracks	Transient Training Enlisted Barracks
2642	1942	74-Man Barracks	Transient Training Enlisted Barracks
2644	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2656	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2657	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2658	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2659	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2660	1942	Administration	Company Headquarters Building Transient Training
2661	1942	Type M – 228-Man Mess Hall	General Instruction Building
2662	1942	Company Storehouse, Administration, and Recreation Building	Exchange Branch
2663	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2664	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2665	1942	Administration	Company Headquarters Building Transient Training
2666	1942	Officers' Quarters – Type BOQ-40	Battalion Headquarters Building Transient Training
2667	1942	Recreation Building – Type RB-1	Auditorium General Purpose
2668	1942	Administration	Company Headquarters Building Transient Training
2669	1942	Regimental Exchange Building	Battalion Headquarters Building Transient Training
2672	1942	Regimental Chapel	Chapel
2675	1942	Post Office	Religious Educational Facility
2701	1942	74-Man Barracks	Transient Training Enlisted Barracks
2702	1942	74-Man Barracks	Transient Training Enlisted Barracks
2703	1942	74-Man Barracks	Transient Training Enlisted Barracks
2704	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
2705	1942	74-Man Barracks	Transient Training Enlisted Barracks
2706	1942	Type M – 228-Man Mess Hall	General Instruction Building
2707	1942	Type M – 228-Man Mess Hall	General Instruction Building
2708	1942	74-Man Barracks	Transient Training Enlisted Barracks
2709	1942	74-Man Barracks	Transient Training Enlisted Barracks
2710	1942	74-Man Barracks	Transient Training Enlisted Barracks
2711	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2712	1942	74-Man Barracks	Transient Training Enlisted Barracks
2713	1942	74-Man Barracks	Transient Training Enlisted Barracks
2714	1942	74-Man Barracks	Transient Training Enlisted Barracks
2715	1942	Type M – 228-Man Mess Hall	General Instruction Building
2717	1942	74-Man Barracks	Transient Training Enlisted Barracks
2718	1942	74-Man Barracks	Transient Training Enlisted Barracks
2719	1942	74-Man Barracks	Transient Training Enlisted Barracks
2720	1942	74-Man Barracks	Transient Training Enlisted Barracks
2721	1942	74-Man Barracks	Transient Training Enlisted Barracks
2723	1942	74-Man Barracks	Transient Training Enlisted Barracks
2724	1942	74-Man Barracks	Transient Training Enlisted Barracks
2725	1942	74-Man Barracks	Transient Training Enlisted Barracks
2726	1942	74-Man Barracks	Transient Training Enlisted Barracks
2727	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2728	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2729	1942	74-Man Barracks	Transient Training Enlisted Barracks
2730	1942	74-Man Barracks	Transient Training Enlisted Barracks
2731	1942	74-Man Barracks	Transient Training Enlisted Barracks
2732	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training
2733	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training
2734	1942	74-Man Barracks	Transient Training Enlisted Barracks
2735	1942	74-Man Barracks	Transient Training Enlisted Barracks
2736	1942	74-Man Barracks	Transient Training Enlisted Barracks
2737	1942	Type M – 228-Man Mess Hall	General Instruction Building
2738	1942	Type M – 228-Man Mess Hall	General Instruction Building
2739	1942	74-Man Barracks	Transient Training Enlisted Barracks
2740	1942	74-Man Barracks	Transient Training Enlisted Barracks
2741	1942	74-Man Barracks	Transient Training Enlisted Barracks
2742	1942	74-Man Barracks	Transient Training Enlisted Barracks
2744	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2762	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
2764	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2765	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training

Fac. No.	Year Built	Original Use	Current Use
2766	1942	Administration	Company Headquarters Building Transient Training
2767	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
2768	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2769	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2770	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2771	1942	Administration	Company Headquarters Building Transient Training
2772	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
2773	1942	Type M – 228-Man Mess Hall	General Instruction Building
2774	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
2775	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
2778	1942	Bachelor Officers' Quarters – Type OQ-23	Transient Training Officers Quarters
2779	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters
2780	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets
2801	1942	74-Man Barracks	Transient Training Enlisted Barracks
2802	1942	74-Man Barracks	Transient Training Enlisted Barracks
2803	1942	74-Man Barracks	Transient Training Enlisted Barracks
2804	1942	74-Man Barracks	Transient Training Enlisted Barracks
2805	1942	74-Man Barracks	Transient Training Enlisted Barracks
2806	1942	Type M – 228-Man Mess Hall	General Instruction Building
2807	1942	Type M – 228-Man Mess Hall	General Instruction Building
2808	1942	74-Man Barracks	Transient Training Enlisted Barracks
2809	1942	74-Man Barracks	Transient Training Enlisted Barracks
2810	1942	74-Man Barracks	Transient Training Enlisted Barracks
2811	1942	74-Man Barracks	Company Headquarters Building Transient Training
2812	1942	74-Man Barracks	Transient Training Enlisted Barracks
2814	1942	74-Man Barracks	Transient Training Enlisted Barracks
2815	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2816	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2817	1942	74-Man Barracks	Transient Training Enlisted Barracks
2818	1942	74-Man Barracks	Transient Training Enlisted Barracks
2819	1942	74-Man Barracks	Transient Training Enlisted Barracks
2820	1942	74-Man Barracks	Transient Training Enlisted Barracks
2821	1942	74-Man Barracks	Transient Training Enlisted Barracks
2823	1942	74-Man Barracks	Transient Training Enlisted Barracks
2824	1942	74-Man Barracks	Transient Training Enlisted Barracks
2825	1942	74-Man Barracks	Transient Training Enlisted Barracks
2826	1942	74-Man Barracks	Transient Training Enlisted Barracks
2827	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2828	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2829	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
2830	1942	74-Man Barracks	Transient Training Enlisted Barracks
2831	1942	74-Man Barracks	Transient Training Enlisted Barracks
2832	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2833	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2863	1942	Administration	Company Headquarters Building Transient Training
2864	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2865	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2867	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2868	1942	Type M – 228-Man Mess Hall	General Instruction Building
2869	1942	Administration	Company Headquarters Building Transient Training
2870	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2871	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2872	1942	Unit Guard House –Type UGH-36	Company Headquarters Building Transient Training
2873	1942	G.U. Dispensary	Company Headquarters Building Transient Training
2874	1942	Regimental Exchange Building	Auditorium General Purpose
2875	1942	Administration	Company Headquarters Building Transient Training
2876	1942	Recreation Building – Type RB-1	Auditorium General Purpose

This final report's main text includes an architectural history of the cantonment landscape and the built environment (Chapter 2), character-defining features of the landscape and built environment (Chapter 3), current condition of the cantonment landscape and built environment (Chapters 4 and 5), evaluation of the cantonment landscape and built environment (Chapter 6), determination of significance (Chapter 6), aspects of integrity (Chapter 7), final recommendations for eligibility and conclusion (Chapter 8), and an appendix with individual building inventory forms.

1.3 Researchers

This project was conducted by the U.S. Army Corps of Engineers, Engineering Research Development Center, Construction and Engineering Research Laboratory (ERDC-CERL), based in Champaign, Illinois. The research team included Adam D. Smith, Master of Architecture, as project manager with 23 years of experience in military architectural history, Sunny E. Adams, Master of Architecture, as architectural historian with 17

years of experience, and Megan W. Tooker, Master of Landscape Architecture, as historic landscape architect with 23 years of experience.

1.4 Site Visits

1.1.1 Fort McCoy

ERDC-CERL personnel made two trips to Fort McCoy to inventory the buildings in November 2018 and June 2019. During these two weeks, team members evaluated the buildings for their historic architectural integrity and evaluated the entire Fort McCoy cantonment landscape and layout for its integrity.

1.1.2 Archival repositories

ERDC-CERL researchers conducted a review of books, archival repositories, and online resources related to Fort McCoy and WWII temporary building construction. The following places were contacted and/or searched:

- NRHP listings and nomination forms (online at <https://www.nps.gov/Nr/publications/index.htm>);
- Historic drawings, maps, photographs, and information were provided by the Cultural Resources Office of the Directorate of Public Works (DPW), the Historian's Office, and the Real Property Office's database at Fort McCoy;
- National Archives and Records Administration (NARA), College Park, Maryland (NARA 111-SC and 111-CCS).

1.1.3 Analysis and evaluation

After initial research was completed, the team analyzed the gathered information. Archival information and field information were integrated throughout the course of the project. The information available was contained in text documents, photographs, and historic maps. Using archival sources, the research team extracted relevant historical information. The material was then combined to tell the story in both text and images.

Using information from the historic context, the overarching historic integrity was evaluated per the definition in the NRHP bulletins. A cultural resource can retain or lose its historic integrity, meaning that it either does

or does not convey its historic significance. From this evaluation process, a recommendation of eligibility to the NRHP was made. The evaluation followed guidelines published by the National Park Service (NPS) in National Register Bulletin #15, *How to Apply the National Register Criteria for Evaluation*;* National Register Bulletin #16A, *How to Complete the National Register Registration Form*;† the National Register Bulletin, *How to Prepare National Historic Landmark Nominations*;‡ and *The Secretary of the Interior's Standards for the Treatment of Historic Properties with Guidelines for the Treatment of Cultural Landscapes*.§

* NPS, *National Register Bulletin #15: How to Apply the National Register Criteria for Evaluation* (Washington, DC: U.S. Department of the Interior, National Park Service, 1997).

† NPS, *National Register Bulletin #16A: How to Complete the National Register Registration Form* (Washington, DC: U.S. Department of the Interior, National Park Service, 1997).

‡ NPS, *National Register Bulletin: How to Prepare National Historic Landmark Nominations* (Washington, DC: U.S. Department of the Interior, National Park Service, 1999).

§ Kay D. Weeks and Anne E. Grimmer, *Secretary of the Interior's Standards for the Treatment of Historic Properties with Guidelines for the Treatment of Cultural Landscapes* (Washington, DC: U.S. Department of the Interior, National Park Service, 1995).

2 WWII Development History

Below is a discussion of cantonment planning, design, and construction of buildings. For a full Fort McCoy history, please refer to ERDC-CERL report, *Determination of NRHP Eligibility for 26 Buildings at Fort McCoy, Wisconsin* (ERDC-CERL TR-18-38).*

1.2 Cantonment Design

World War II cantonments differed from those built for World War I. Most WWII cantonments were triangular or quadrangular in layout, with each leg serving as a brigade, which differed from the earlier linear and U-shaped configurations of WWI. Division size determined whether the cantonment was three or four sides. The division layouts and plans were developed in 1941 by Leon H. Zach, formerly with Olmsted Associates, landscape architects and planners, for the Engineering Department of the Construction Division. It was believed the centralized plans offered better administration oversight. Training areas were located adjacent to each of the brigades to provide efficient movement into the field (Figure 2-1).[†]

* Smith, Adam D., and Sunny E. Adams. *Determination of NRHP Eligibility for 26 Buildings at Fort McCoy, Wisconsin* (ERDC-CERL TR-18-38), (Champaign, IL: ERDC-CERL, 2018).

† Garner, John S. *World War II Temporary Military Buildings; A Brief Historic of the Architecture and Planning of Cantonments and Training Stations in the United States* (USACERL TR CRC-93/01), (Champaign, IL: USACERL, 1993), 65.

Figure 2-1. Adaptation of a typical layout at Camp McCoy showing relationship of units to their training areas, March 1942 (*Engineering Manual of the Office of the Chief of Engineers*).

Camp McCoy was constructed over a 6-month period in 1942 as a mobilization cantonment capable of housing 35,000 soldiers of the United States Army. The site, now known as Fort McCoy, had been used for training exercises for the Wisconsin National Guard since 1909. The War Department purchased 14,000 acres of land from Robert Bruce McCoy, who later became a WWI general. The site was used as a National Guard camp in 1917 and 1918 and called Camp Robinson (Figure 2-2). Any WWI buildings were dismantled after the war although the site was still used for summer maneuvers. It was formally named after General McCoy in 1926 and became the location of a CCC camp beginning in 1933.

Figure 2-2. Photograph of Camp Robinson light artillery, c 1918 (WI Historical Society).

In 1941, an additional 55,000 acres were acquired for a new WWII cantonment. The new cantonment was located at the juncture of two service roads just north of the old camp [also sometimes referred to as the south cantonment and the north cantonment]. Camp McCoy was planned for a triangular division of infantry. The plan was based on the principles set forth in the typical layout plans prepared by Leon Zach and the Site Planning Unit of the Construction Division (Figure 2-3). In Wisconsin, the

Construction Division sought the architectural design services of Mead, Ward and Hunt, of Madison, WI.

Mead, Ward and Hunt used the Zach layout for the cantonment. The sample design issued by the War Department in the summer of 1941 was guided foremost by the training requirements of a triangular Army division, the core of which was three infantry regiments (see also Figure 2-1). One side of the central parade ground was occupied by six blocks pertaining to the three regiments, which could march to their training areas on the opposite side from the parade field without encountering traffic resulting from the movement of non-infantry troops. The artillery batteries of the division and detachments of special troops were arranged on the other two sides of the parade field, allowing them to engage in their training activities without interfering with those of the infantry.*

The design also included city planning principles in the model layout. Service, social, and cultural buildings, such as infirmaries, service clubs, theaters, and chapels were located within easy reach of each residential block. Incompatible mixtures of land use were avoided, and the warehouse and maintenance structures were concentrated in a single block away from the troop housing areas. The hospital block, which was not shown on the typical plan, was to be isolated from the cantonment area to reduce the effect of noise and dirt on patients. Traffic circulation for motorized vehicles was carefully considered, with two parallel, main arteries flanking the ends of all troop blocks to avoid congestion and the compactness of the overall configuration reducing travel time. Parking areas were located along the outside of each block and firebreaks were located between each block in the cantonment. Finally, Zach provided ample open space for recreation and designated the central parade ground for such use.†

* Also see the discussion of military training requirements in a triangular division plan found in Part III—Army Ground Forces Stations, Chapter III—"Site Planning," *Engineering Manual*, Office of the Chief of Engineers (Washington, DC: War Department, April 1943), sections 3-20 to 3-21.

† See Figure 4 herein; "Selection of Sites for Structures and Facilities for Economy, Section 3.03 in "Part I—"Selection of Sites, *Engineering Manual* (February 1943); "Part III – Army Ground Forces Stations," Sections 3-20 through 3-23.

Figure 2-3. Plan 614-179, prepared by the Site Planning Unit, depicting a typical layout for a triangular division, dated October 7, 1941.

In designing the site plan for the new Camp McCoy cantonment, Mead, Ward and Hunt adopted the block and regimental arrangements in the typical layout and observed the city planning principles implied in the model design. In the design, the architect-engineers arranged three curvilinear segments, each containing from five to nine battalion blocks, in a triangular pattern. The three infantry regiments of the triangular division would occupy the northern segment which was situated close to the infantry training areas in the proposed reservation. The eastern half of the southern segment were intended for the artillery of the division and battalions of special troops attached to the division. The artillery batteries, at the end of the southern segment, were located a short distance north of the firing ranges constructed earlier for artillery practice at the original Camp McCoy. Thus, the two principal groups of troops in a triangular division, the infantry and artillery, could travel quickly and unimpeded to their training areas, as shown in the layout design.

Along the western half of the southern segment and along the entirety of the northwestern segment, the general plan called for occupancy by "non-divisional" troops, which would consist principally of detachments from the various service corps in the Army. The Ordnance Department, Signal Corps, Quartermaster Corps, Medical Corps, tank destroyer detachments,

and other non-divisional units adjacent to the railroad and warehouse areas. Within the triangle formed by the segments was to be built the headquarters of the infantry division, located roughly the same distance from all three segments, for ease of communication.

Mead, Ward and Hunt discarded the gridiron pattern of the typical design and substituted curving lines in all of the north and south segments and in the southern half of the northwest section. The inspiration for the curvilinear design derived from the informal tradition in American city planning and the varied street patterns of suburbs laid out by pioneer landscape architect Frederick Law Olmsted and others which reached a peak of popularity with model communities planned after World War I.

Mead, Ward and Hunt placed the service areas of the cantonment outside the triangular housing area, much as the model plan had recommended. The hospital block, a gridiron section containing over 100 buildings, was to be located about a thousand feet east of the juncture of the northeastern and southern segments of the triangle. The warehouse district and post headquarters were placed in a rectangular block southwest of the south segment and detention barracks were to be located to the west of the warehouses. The sewage treatment plant and three incinerators were to be erected away from the inhabited sections of the camp, about a mile southwest of the juncture between the northwest and southern segments of the triangle.

With the acceptance by the War Department of the triangular plan, Mead, Ward and Hunt were able to complete detailed plans for laying out the cantonment and constructing the necessary roads, railroad spurs, and utilities (Figure 2-4). Constructed of primarily 800 series buildings were 464 enlisted barracks, 42 officers' barracks, 176 mess halls, and 184 combined administrative, supply, and recreation buildings for a total of 1277 buildings with 1144 for the main post, 12 in the stockade, and 121 in the hospital area. The finished capacity of the cantonment was 36,836 officers and enlisted men; the total cost at the end of 1942 was \$32,383,000.* In October 1942, the 100th Infantry Regiment from Hawaii became the first full Army detachment to occupy the McCoy cantonment.

* Garner, John S. *World War II Temporary Military Buildings* (Champaign, IL: USACERL, 1993), 72.

Figure 2-4. Master Plan for Camp McCoy, 1941 (DPW, Fort McCoy).

1.3 Block Areas

Early installation cantonment designs for WWII were based on a regimental grouping (Figure 2-5). At Fort McCoy, each leg of the triangular plan for Camp McCoy contained a segment of a division. Three parallel roads traced each leg of the layout. Smaller connecting roads cut across these to subdivide the three legs into the three regimental units with a 250-foot firebreak in between each. Two blocks comprised a regiment. At Fort McCoy, a block was composed of eight companies, depending on the type of unit that was involved (Figure 2-6). Standard plans for a company included three barracks, one mess hall, one recreation building, and one supply building.* Along each street in a block were four mess halls at center, and ten or more barracks, with a company usually occupying three barracks and eating in one of the mess halls. To the rear of the barracks at either end of each street, were company administration buildings, one for each company. Across from the battalion blocks and within the large trian-

* Wasch, et al. *World War II and the U.S. Army Mobilization Program: A History of the 700 and 800 Series Cantonment Program*. (Washington, DC: Legacy Resources Management Program, 1992), 35.

gular parade field, were the regimental buildings, including officers' barracks, post exchange, dispensary, chapel and field house and other structures. Motor pools were located between the second and third parallel roads in the northwest and northeast legs of the cantonment. A smaller firebreak separated each of the blocks, in addition to the larger firebreaks between each regiment (Figure 2-7 and Figure 2-8).

Figure 2-5. Plan of cantonment regimental grouping, 1940 (Garner 1993, 66).

Figure 2-6. Typical block plan from 1941 plan for Camp McCoy (barracks (B), mess halls (M), recreation buildings (RB) and administration (SA) (DPW, Fort McCoy).

Figure 2-7. Aerial view of the 1800 Block showing fire breaks, 1988 (Library of Congress).

Figure 2-8. General view looking north of fire break at end of East Eaton Road and East 12th Street, 1988 (Library of Congress).

1.4 Architectural Building Construction

There were approximately 100 building types erected at Camp McCoy.* The greatest number of building types were those devoted to housing, eating, storage and administration, and recreation. Structures in the troop housing blocks of the triangle were designed for use by certain sizes of Army units. For example, a barracks was intended to house a platoon, and a mess hall or a storehouse-administration-recreation building as intended for use by a company. Two battalion administration buildings and a row of bachelor office quarters were at the end of each battalion block. At the edge of each regimental area was a cluster of regimental buildings; post exchange, chapel, administration building, infirmary, and regimental commanders' quarters. Along the outer edges of the three segments in the triangle were motor pools and maintenance buildings and fire stations. Service (social) clubs and movie theaters were built at periodic junctures between regimental and detachment groupings.

* Footnote in HABS WIS, 41-SPAR.V, 1-(1988): "Some of the building types listed were built between the end of the initial construction campaign and the end of the war. Others were the results of remodeling during the war, such as the Personal and Separation Centers."

The structural systems used in Camp McCoy buildings were constructed with either balloon framing or platform framing, entirely compassed of wood members. Wall sheathing and flooring were of softwood. The exteriors in the troop housing sections were of uniform appearance; grayish white, asbestos shingle siding with a scalloped bottom edge on the walls with each piece measuring 11" x 24", yellow wooden trim, gray wooden foundation skirting, and red asphalt shingle roofs. The temporary nature of a mobilization cantonment was emphasized using concrete piers for foundations and wooden porch stoops with wood handrails.

Typical exterior doors were of standard design and each contained four lights in its upper half and three horizontal recessed panels in its lower section (Types B and D). Typical wooden sash double-hung windows used throughout the cantonment were three types of standard 800 Series window designs used; Standard Type A consisted of eight-over-eight, Standard Type C composed of a six-over-six lights, Type E, which consisted of four-over-four lights and a single sash four-light hopper window. The architraves of the openings were of the same simple board design found throughout the cantonment. Wooden wire insect screen hung on the outside of all the windows. Chimneys were constructed of red brick.

The interiors were unfinished, with neither plaster nor paint applied. Instead, tempered pressed wood, fiber wallboard, and gypsum board were used to cover walls and ceilings. Typical flooring used in the mobilization buildings were of unfinished softwood and were constructed with 3-1/4" wide boards, except for poured concrete in the service spaces of the buildings such as washrooms, storehouses, and boiler rooms. In many of the building types, the roof's wood structural system was left exposed and unfinished. The interior doors were standard-issue solid wood doors constructed in the typical interior pattern: five, horizontal, recessed panels. Interior wooden screen doors were used in many of the buildings. Interior lighting consisted of a metal base with a white glass globe fixture. The mechanical and HVAC systems were typically suspended from the exposed ceiling structural members.

This portion of this chapter will group and discuss the mobilization buildings as types; living quarters, administration/recreation, administration, recreation, mess halls, storehouses, repair shops, and support buildings. For this section of the report to describe the history of each building type, Historic American Building Survey (HABS) documentation for both the

700 and 800 Series standardized plans and photographs were utilized. However, when a type did not have any associated HABS, the researchers used current photographs to describe that building type. Please refer to the inventory forms in the appendix for more detailed descriptions and photographs.

1.4.1 Living Quarters

1.4.1.1 74-man barracks

A total of 464 74-man barracks were erected at Camp McCoy in 1942 and were constructed from the War Department's 800 Series of standard plans (see Figure 2-9 to Figure 2-11). Each barracks during WWII housed a squad. The squad rooms were on the first and second floor, three non-commissioned officer (NCO) rooms were on the second floor, and the wash, shower, and toilet rooms were on the first floor.

The overall dimension of the barracks were a long rectangular shape measuring 29'-6" wide by 90'-0" long and were two-stories in height rising approximately 27'-0" from grade to the ridge of the roof (see Figure 2-9 and Figure 2-10). The foundation was a system of poured concrete piers and footings except for the heater room, located in one corner of each barracks, which had a concrete block foundation. A wooden foundation skirting wrapped around the portion of the building with the pier foundation system.

There were two wood porches with wood handrails at ground level; one on each short end side. A wooden platform was attached to the end side where the squad rooms were located and provided access to two exit doors for the second-floor squad room. The platform consisted of a deck supported by two wooden brackets and balustrade of board rails and posts. An opening on one side of the rail allowed for exit, in case of fire, down a wooden ladder that was attached to the wall adjacent the platform (see Figure 2-11 and Figure 2-14).

There were two types of windows on the barracks building; a double-hung and a single-sash. The double-hung windows were of the standard design found in all 800 Series mobilization buildings; eight-over-eight wood frame. Six of these type windows lined each side of both squad rooms, five were placed on the exterior wall of both NCO rooms, one was placed in the

furnace room, one was placed over the main entry doors, and two were located in the latrine room. The single-sash wood hopper window was a small four-light window was located shower room (see Figure 2-12).

There were six doorways in the exterior of the barracks: (a) the main entrance was defined by a set of double doors; (b) the double entry to the furnace room; (c) two single exit door for the first floor squad room; and (d) two single exit door for the second-floor squad room.

The first floor was entered through a set of double doors (see Figure 2-13). There was vestibule, followed by a stair hall that lead to the second floor. To the left was the door to the washroom, which was the center of a suite of three rooms; showers, washroom, and the toilets and urinal. On the right side of the entry hall was the furnace room, which was only accessible through the exterior doors. The majority of the first floor was occupied by the undivided squad room, which measured approximately 65-feet in length. Originally, this room contained bunk for thirty-two enlisted men (see Figure 2-15).

Near the opening at the top of the staircase were two NCO rooms. Originally, one room housed two men and the other, three. On the other side of the hall was a door to a three-man NCO room and an entrance to a fourth NCO room for two men. Like the first floor, the second floor was occupied by a squad room for thirty-two enlisted men.*

The interior structure in the squad room of the first and second floors were defined by wooden posts arranged in two parallel rows directly above the concrete piers of the foundation.

The flooring throughout the barracks was unfinished wood except for the wash, toilet, shower, and boiler rooms. In the wash and toilet rooms, all walls were covered with horizontal, unfinished fiberboard (see Figure 2-16). The same-sized boards were used for the ceilings in those two rooms. In the shower room, the hard, manufactured wallboard covered the walls and ceiling.

* Fort McCoy, Building T-1129 (Barracks). Photographs and Written Historical and Descriptive Data. HABS No. WI-308-A. Historic American Building Survey. National Park Service. Department of the Interior. Washington, D.C.

Figure 2-9. 800 Series floor plans for 74-man barracks, Plan Number 800-443, 1941 (Library of Congress).

Figure 2-10. 74-man barracks framing details, Plan Number 800-444, 1941 (courtesy Fort McCoy DPW).

Figure 2-11. Details of wooden platform and wooden ladder on rear elevation of 74-man barracks, Plan Number 800-445, 1941 (courtesy of Fort McCoy DPW).

Figure 2-12. Southeast oblique of Building 1129, 74-man barracks, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-A-2).

Figure 2-13. South (front) side of 800 Series 74-man barracks at Fort McCoy, 1988 (Library of Congress, HABS WIS, 41-SPAR. V, 1-A-6).

Figure 2-14. Rear side of a 74-man barracks, showing one set of original doors, wooden platform, and wooden ladder and the removal and opening modification of the other set, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-A-7).

Figure 2-15. Second floor squad room in Building 1129, 74-Man barracks at Fort McCoy, 1988 (Library of Congress, HABS WIS, 41-SPAR.V,1-A-16).

Figure 2-16. Interior view of the toilet room on the first floor in Building 1129, 74-Man barracks at Fort McCoy, 1988 (Library of Congress, HABS WIS,41-SPAR.V,1-A-13).

1.4.1.2 Officers' quarters – Types BOQ-40, OBQ-40, OQM-40, OQ-40

A total of 42 officers' quarters were erected at Camp McCoy in 1942 and were constructed from the War Department's 800 Series of standard plans, Plan Number 800-317 (see Figure 2-17).^{*} The overall dimensions of officers' quarters were a long rectangular shape measuring 29'-6" wide by 146'-0" long and were two-stories in height rising approximately 27'-0" from grade to the ridge of the roof.

The foundation was a system of poured concrete piers and footings with the furnace room, located in one corner of each barracks, having a concrete block foundation. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment.

There were three porches with metal handrails at ground level; one on each short end side and one on the long side side. A wooden platform was attached to the end sides that provided access to two exit doors for the second-floor central hall. The platform consisted of a deck supported by two wooden brackets and balustrade of board rails and posts. An opening on one side of the rail allowed for exit, in case of fire, down a wooden ladder that was attached to the wall adjacent the platform.

There was one type of windows on the barracks building; a double-hung and a single-sash. The double-hung windows were of the standard design found in all 800 Series mobilization buildings; eight-over-eight wood frame (see Figure 2-18-Figure 2-20). There were a total 56 of these windows used on this type of building. There were three main entries into the building; one on each end side and one in the middle of a long side. On the opposite side was a set of doors leading into the heater room. These doors were of standard type used throughout the cantonment (see Figure 2-20).

The first floor was entered through a single-entry door on either end or on the long side. There was vestibule, followed by a stair hall that lead to the second floor off the side entry (see Figure 2-21). A central corridor provided access to 15 single room quarters (see Figure 2-23), a large dayroom (see Figure 2-22), a washroom and a toilet room. The second floor consisted of a central corridor provided access to 21 single room quarters.

The flooring throughout the barracks was unfinished wood except for the wash, toilet, shower, and boiler rooms. In the wash and toilet rooms, all

^{*} History of the Planning and Construction of Camp McCoy, Wisconsin, 1940-1946. September 1988. Historic American Building Survey.

walls were covered with horizontal, unfinished fiberboard. The same-sized boards were used for the ceilings in those two rooms. In the shower room, the hard, manufactured wallboard covered the walls and ceiling.

Figure 2-17. Quarters and Mess, Officers, Type OMQ-40, Plan Number 700-1257 (modified at McCoy), 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-S-7).

Figure 2-18. Northeast oblique of Building 655, bachelor officers' quarters, Type BOQ-40, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-S-2).

Figure 2-19. Southeast oblique of Building 655, bachelor officers' quarters, Type BOQ-40, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-S-1).

Figure 2-20. Northwest oblique of Building 655, officers' quarters, Type BOQ-40, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-S-3).

Figure 2-21. Interior view of entry vestibule looking at the staircase leading to the second floor in Building 655, officers' quarters, Type BOQ-40, 1988 (Library of Congress, HABS WI, 41-SPAR. V, 1-S-4).

Figure 2-22. Interior view of dayroom in Building 655, officers' quarters, Type BOQ-40, 1988 (Library of Congress, HABS WI, 41-SPAR. V, 1-S-5).

Figure 2-23. Interior view of typical single bedroom in Building 655, officers' quarters, Type BOQ-40, 1988 (Library of Congress, HABS WI, 41-SPAR. V, 1-S-6).

1.4.1.3 Officers' quarters – Type BOQ-44

There were 34 officers' quarters (without mess), Type BOQ-44 at Camp McCoy in 1942. The overall dimensions of officers' quarters were a long rectangular shape measuring 29'-6" wide by 136'-4" long and were two-stories in height rising approximately 27'-0" from grade to the ridge of the roof (see Figure 2-24).

The foundation was a system of poured concrete piers and footings with the furnace room, located in one corner of each barracks, having a concrete block foundation. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment.

There were two porches with metal handrails at ground level; one on one end side and one on a long side. A wooden platform was attached to the end side that provided access to exit doors for the second floor central hall (see Figure 2-25). The platform consisted of a deck supported by two wooden brackets and balustrade of board rails and posts. An opening on one side of the rail allowed for exit, in case of fire, down a wooden ladder that was attached to the wall adjacent the platform.

There was one type of windows on the barracks building; a double-hung and a single-sash. The double-hung windows were of the standard design found in all 800 Series mobilization buildings; eight-over-eight wood frame. There were a total 59 of these windows used on this type of building. There were three entries into the building; one on each end side and slightly off center on of the sides. On the opposite side was a set of doors leading into the heater room. These doors were of standard type used throughout the cantonment.

The first floor consisted of a vestibule with an adjacent stairwell that lead to the second floor. A central corridor provided access to 10 single room quarters with adjacent living rooms (see Figure 2-26), one single bedroom, a washroom with a toilet room and shower room (see Figure 2-27), a janitor's closet, and a heater room. The second floor consisted of a central corridor that provided access to 11 single room quarters with adjacent living rooms, one single bedroom, a washroom with a toilet room and shower room.

The flooring throughout the barracks was unfinished wood except for the wash, toilet, shower, and boiler rooms. In the wash and toilet rooms, all walls were covered with horizontal, unfinished fiberboard. The same-sized boards were used for the ceilings in those two rooms. In the shower room, the hard, manufactured wallboard covered the walls and ceiling.

Figure 2-24. Northeast oblique of Building 453, bachelor officers' quarters, Type BOQ-44, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1Q-1).

Figure 2-25. Southwest oblique of Building 453, bachelor officers' quarters, Type BOQ-44, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1Q-2).

Figure 2-26. Typical bedroom in Building 453, bachelor officers' quarters, Type BOQ-44, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1Q-4).

Figure 2-27. Interior view of washroom in Building 453, bachelor officers' quarters, Type BOQ-44, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1Q-5).

1.4.1.4 Officers' quarters – Type OQ-23, 700 Series

There were six Type OQ-23, officers' quarters constructed at Fort McCoy utilizing the 700 Series standardized plans in 1942. The overall dimension of the quarters were a rectangular shape measuring 29'-6" wide by 80'-0" long and were two-stories in height rising approximately 25'-0" from grade to the ridge of the roof (see Figure 2-28 and Figure 2-29) with a total square footage of 4,720. The foundation was a system of poured concrete piers and footings with a wooden foundation skirting. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment. Aqua medias were constructed over the first- and second-floor windows. They extended 3'-0" from the building walls and were covered with red asphalt shingles (see Figure 2-32).*

A red brick chimney was located on the outside of the quarters and stood approximately 21' in height (see Figure 2-30).

There were poured concrete steps with cast iron railing at the front, rear, and side entrances. There were two second-floor wooden balconies above the front and rear doors (see Figure 2-31). A wooden ladder was attached to the wall adjacent the balconies.†

All the windows on the officers' quarters were standard eight-over-eight wood sash double-hung with a simple architrave. Wooden screens were placed over all the windows. The entry doors consisted of a four-light tripartite-panel recessed door. A set of double doors provided access to the boiler room. The first floor was entered through a single entry at either end of the building or from a single entry on one side of the building. There were also wooden screen doors at each exit on the first floor.

A central corridor divided the space on both floors (see Figure 2-33). The first floor consisted of six, 10'-0" x 8'-0" single bedrooms, a combination toilet/wash area, a dayroom, mess hall, a kitchen, two storage rooms, and

* Fort McCoy, Building T-1863 (Officers' Quarters). Photographs and Written Historical and Descriptive Data. HABS No. WI-308-G. Historic American Building Survey. National Park Service. Department of the Interior. Washington, D.C.

† Fort McCoy, Building T-1863 (Officers' Quarters). Photographs and Written Historical and Descriptive Data. HABS No. WI-308-G. Historic American Building Survey. National Park Service. Department of the Interior. Washington, D.C.

a boiler room. The second floor consisted of seventeen, 10'-0" x 8'-0" single bedrooms.

There was a switchback stairway in the interior of each quarters leading from the first floor to the second floor located directly opposite the side entry door (see Figure 2-33).

The flooring throughout the quarters was unfinished wood except for the toilet, shower, and boiler rooms. The interior walls are covered with pressed board and were painted. In the shower and toilet rooms, all walls were covered with horizontal plank boards (see Figure 2-36). All of the interior doors were standard wooden five-panel doors (see Figure 2-33).

Figure 2-28. Plan Number 700-1254 (modified at Fort McCoy) – Quarters and Mess Officers' Type OQM-9-9 Officers, Type OQM-3-3 Officers, two-story building, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-13).

Figure 2-29. Plan Number 700-1300 – Quarters and Mess Officers', two-story building, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-14).

Figure 2-30. Front side of Building 1863, officers' quarters – 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-5).

Figure 2-31. Rear and side of Building 1863, officers' quarters - 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-6).

Figure 2-32. Detailed view of the front eaves on Building 1863, officers' quarters - 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-8).

Figure 2-33. Interior view of central corridor, looking from the front entry in Building 1863, officers' quarters - 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-9).

Figure 2-34. Interior view of central stair hall from the side entry in Building 1863, officers' quarters - 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-10).

Figure 2-35. Interior view of dayroom in Building 1863, officers' quarters – 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-12).

Figure 2-36. Interior view of toilet room in Building 1863, officers' quarters – 700 Series, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-G-11).

1.4.1.5 Brigade general's quarters – Type BGQ-1

There were two brigade general's quarters, Type BGQ-1 constructed in 1942 at Camp McCoy utilizing the standardized Plan Number 800-307. The overall footprint of the small structure was L-shaped. Unlike, the majority of the other mobilization buildings at Camp McCoy, this building type had a concrete foundation. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment (see Figure 2-37 to Figure 2-38).

A red brick chimney rose approximately 25' above the rear wing roof ridge. There was a set of poured concrete steps with cast iron railing at the front entrance.

All the windows on the brigade general's quarters were standard eight-over-eight wood sash double-hung with a simple architrave. Wooden screens were placed over all the windows. There was one main entry door on the front side that consisted of a four-light triple-panel recessed door with a wooden screen door and one similar door into the heater room. A set of double doors are provided access to the boiler room (see Figure 2-39 to Figure 2-40).

The interior of the brigade general's quarters consisted of a living room, a bedroom, a bath, a closet, and a heater room. The living room and bedroom had wall board ceilings and interior walls with wood chair rail and a wood floor, while the bathroom had tongue-and-groove ceiling and walls and a concrete floor. The heater room ceiling and walls were covered with gypsum sheathing and the floor was concrete (see Figure 2-41 to Figure 2-42).

Figure 2-37. Plan Number 800-307, architectural, structural, and details for brigade general's quarters, Type BGQ-1, 1941 (Library of Congress, HABS WIS, 41- SPAR.V, 1-EY-6).

Figure 2-38. Southeast oblique of Building 1247, brigade general's quarters, Type BGQ-1, 1988 (Library of Congress, HABS WIS, 41- SPAR.V, 1-EY-1).

Figure 2-39. Northeast oblique of Building 1247, brigade general's quarters, Type BGQ-1, 1988 (Library of Congress, HABS WIS, 41- SPAR.V, 1-EY-2).

Figure 2-40. Southwest oblique of Building 1247, brigade general's quarters, Type BGQ-1, 1988 (Library of Congress, HABS WIS, 41- SPAR.V, 1-EY-3).

Figure 2-41. Interior view of living room in Building 1247, brigade general's quarters, Type BGQ-1, 1988 (Library of Congress, HABS WIS, 41- SPAR.V, 1-EY-4).

Figure 2-42. Interior view of kitchen (former heater room) in Building 1247, brigade general's quarters, Type BGQ-1, 1988 (Library of Congress, HABS WIS, 41- SPAR.V, 1-EY-5).

1.4.1.6 *Regimental commander's quarters, Type RCQ-1*

There were nine regimental commander's quarters, Type RCQ-1 constructed in 1942 at Camp McCoy utilizing the standardized Plan Number 800-308. The overall footprint of the small structure was L-shaped with a poured concrete foundation. This building type is similar in design as to the brigade general's quarters, but slightly smaller in overall size. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment (see Figure 2-43 to Figure 2-44).

A red brick chimney rose approximately 25' above the rear wing roof ridge. There was a set of poured concrete steps with cast iron railing at the front entrance (see Figure 2-45 to Figure 2-46).

All the windows on the regimental commander's quarters were standard eight-over-eight wood sash double-hung with a simple architrave. Wooden screens were placed over all the windows. There was one main entry door on the front side that consisted of a four-light triple-panel recessed door with a wooden screen door and one similar door into the heater room. A set of double doors are provided access to the boiler room.

The interior of the regimental commander's quarters consisted of a living room, a bedroom, a bath, a closet, and a heater room. The living room and bedroom had wall board ceilings and interior walls with wood chair rail and a wood floor, while the bathroom had tongue-and-groove ceiling and walls and a concrete floor. The heater room ceiling and walls were covered with gypsum sheathing and the floor was concrete (see Figure 2-47).

Figure 2-43. Plan Number 800-308, architectural, structural, and details for regimental commander's quarters, Type RCQ -1, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-U-7).

Figure 2-44. Plan Number 800-308, close-up of the floor plan for regimental commander's quarters, Type RCQ -1, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-U-7).

Figure 2-45. West side of Building 901, regimental commander's quarters, Type RCQ -1, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-U-7).*

Figure 2-46. Northeast oblique of Building 901, regimental commander's quarters, Type RCQ -1, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-U-3).

* This building was relocated to the museum area.

Figure 2-47. Interior view of bedroom in Building 901, regimental commander's quarters, Type RCQ-1, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-U-4).

1.4.2 Administration/Recreation Buildings

1.4.2.1 Company storehouse, administration, and recreation building

The construction of company storehouse, administration, and recreation buildings were based off two separate standard War Department 800 Series drawings for a company recreation building (Series 800-460 – Recreation Building type RB-4) and a company storehouse and administration building (Series 800-661 – Single Storehouse and Company Administration-Types SA-1 & SA-2, Stockade/Office Building Type SO-1) dated May 23 and June 3, 1941, respectively. At Camp McCoy the two plans were combined in the early spring of 1942 with the construction of 184 WWII

company storehouse, administration, and recreation buildings.* These buildings each served as a headquarters for a company that occupied adjacent barracks (see Figure 2-48 to Figure 2-50).

The foundation of the company storehouse and administration section was concrete block, along with the foundation and lower wall of the heater room. The recreation portion of the buildings had three longitudinal rows of square concrete piers and wooden foundation skirting.

There were three types of standard 800 Series window designs used in the combined company storehouse and recreation buildings. Standard Type A consisted of eight-over-eight found on all four sides, Standard Type C composed of a six-over-six lights and was used one place to provide light into the heater room, and the third was Type E, which consisted of four-over-four lights and appears outside the two latrines. All windows were wood-sash double-hung with a simple wooden architrave. A heavy wooden track door lead into the storehouse. The other four exterior doors were of standard design, Type D, which was a four-light, three-panel wood door.

Rising from near the center of the recreation section of the buildings, from within a concrete block cubicle adjacent to the heater room, a brick chimney reached a height of 30'-0" above grade, approximately 13 feet of which extends above the roof.†

The combination of the storehouse and administration design with the recreation building plan at Camp McCoy produced a single headquarters for each company. At one end of the buildings was the company office and the office of the first sergeant. Next was a storeroom for company supplies. At the rear end of the combined building was the recreation section, consisting of a day room and study room. The floor plan was a split-level. A short flight of stairs at the end of the storehouse led up into the day room of the recreation section (see Figure 2-51 to Figure 2-52).

The storehouse and administration section had a concrete floor, while a wooden floor was in the recreation section. The storehouse section, the exterior walls and roof structure were left exposed and painted a cream

* History of the Planning and Construction of Camp McCoy, Wisconsin, 1940-1946. September 1988. Historic American Building Survey.

† Fort McCoy, Building T-801 (Storehouse, Administration, and Recreation Building). Photographs and Written Historical and Descriptive Data. HABS No. WI-308-B. Historic American Building Survey. National Park Service. Department of the Interior. Washington, D.C.

color. In the administration section (two company offices), insulation board covered the lower portion of the walls, while wallboard with wood battens covers the upper portion of the walls. In the water closet adjacent to the first sergeant's room, all four walls were of standard-sized, tongue and groove boards laid horizontally on the bottom portion of the walls. Above the boards were insulation board panels. The same sized tongue and groove boards were used for sheathing the exterior walls of the storehouse. The two main rooms of the recreation section had insulation boards on the lower part of the walls and fiber board on the upper portion of these walls. The ceilings of the rooms were wallboards nailed in place by battens. The interior doors were standard-issue solid wood doors constructed in the typical interior pattern: five, horizontal, recessed panels (see Figure 2-53 to Figure 2-55).

Figure 2-48. Plan 800-661 (modified at Fort McCoy), single storehouse and company administration – Types SA-1 and SA-2, stockade/office building Type SO-1. Plans, elevations, and sections, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-B-13).

Figure 2-49. Plan 800-460, recreation building Type RB-4, 1941 (Library of Congress, HABS, WIS, 41-SPAR.V, 1-B-14).

Figure 2-50. Fort McCoy drawing 6150-38B, combined building revised floor plan (Library of Congress, HABS WIS, 41 SPAR.V, 1-B-12).

Figure 2-51. Southwest oblique of Building 801, company storehouse, administration, and recreation building, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-B-2).

Figure 2-52. Close-up detail of concrete stoop, cast-iron metal handrails, wood panel and divided-light doors, and multi-pane wood sash window and screen on Building 801, company storehouse, administration, and recreation building, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-5).

Figure 2-53. Interior view of the storeroom showing the wood sliding door and exposed structural system in Building 801, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-B-7).

Figure 2-54. Interior view of the recreation area in Building 801, looking south into the storeroom, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-B-10).

Figure 2-55. Interior view of recreation area looking towards the storeroom in Building 801, 1988 (Library of Congress, HABS WIS, 4-SPAR.V, 1-B-10).

1.4.3 Administration Buildings

1.4.3.1 Interior battalion administration building – Type IBA-1

There were 28 Type IBA-1, Interior Battalion Administration Building, constructed in 1942 at Camp McCoy. The construction of this type of building was based off standard War Department Series Plan Number 800-222.

The rectangular building measured 70'-0" x 25'-0." The foundation of one-half of the building was poured concrete supporting the large storage room and heater room. The other half of the building had a concrete pier foundation system supporting the administration section with a wooden foundation skirting. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment and the roof was clad with red asphalt shingles (see Figure 2-56 to Figure 2-59).

The exterior doors were of standard design. There was a set of doors at one end of the building leading into the storage room, a single entry door located on one of the long sides of the building leading into the administration section, and another set of doors on the opposite long side leading into the heater room. There were a total of 15 Standard Type A consisted of eight-over-eight windows found on all four sides.

Rising from near the center of the buildings was a brick chimney that was approximately 25'-0" tall. A poured concrete stoop with metal handrails was located on the long side with single entry door.

The interior of the building included a storage room located at one end of the building. A full partition wall separated this room from the rest of the building and the only access was through the set of double exterior doors. The other end of the building consisted of a large open office space, a clerk's toilet, an officer's toilet, a commanding officer's office, an adjutant officer's office, and a heater room (see Figure 2-60 to Figure 2-63).

The floors in the storage room and heater room were concrete, while the rest of the building had wooden flooring. The walls and ceilings in the administration spaces were covered with wallboard, the walls and ceilings in the toilet rooms were covered with tongue-and-grove boards, and the walls and ceiling heater room were covered with gypsum board. All interior doors were of standard design used throughout the cantonment.

Figure 2-56. Plan Number 800-222, administration building, Type IBA-1, plans and elevations, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-7).

Figure 2-57. Close-up of Plan Number 800-222, administration building, Type IBA-1, floor plan, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-7).

Figure 2-58. Southeast oblique of Building 555, administration building, Type IBA-1, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-1).

Figure 2-59. Northwest oblique of Building 555, administration building, Type IBA-1, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-2).

Figure 2-60. Interior view of office area in Building 555, administration building, Type IBA-1, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-3).

Figure 2-61. Interior view of private office spaces in Building 555, administration building, Type IBA-1, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-4).

Figure 2-62. Interior view of clerk's toilet room in Building 555, administration building, Type IBA-1, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-5).

Figure 2-63. Interior view of storeroom in oblique of Building 555, administration building, Type IBA-1, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-R-6).

1.4.3.2 Unit guard house, Type UGH-24

There were 5 Unit Guard House, Type UGH-24 constructed in 1942 at Camp McCoy. The construction of this type of building was based off standard War Department 800 Series, Plan Number 800-1007.

The rectangular building measured 70'-0" x 25'-0." The foundation was a system of poured concrete piers and footings except for the heater room, located in one corner of each building, which had a concrete block foundation. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment and the roof was clad with red asphalt shingles (see Figure 2-64 to Figure 2-67).

The exterior doors were of standard design. There were two sets of doors at one end of the building, one leading into the heater room and one leading into the building. A poured concrete stoop with cast iron handrails was located at each end entry. There were a total of 13 Standard Type A windows consisted of eight-over-eight windows found on all four sides with a simple wood architrave.

Rising from one end of the buildings was a brick chimney that was approximately 25'-0" tall. There were two metal roof ventilators placed along the ridge.

The interior of the building included short corridor at one end of the building. On one side of the corridor was the heater room and on the other side was small office space and a toilet room. The majority of the building interior was a large open space used as a guard room (see Figure 2-68 to Figure 2-69).

The floors in the toilet room and heater room were concrete, while the rest of the building had wooden flooring. The walls and ceilings in the corridor, office, and guard room were covered with wallboard on the top half and horizontal wooden boards on the bottom half. The walls and ceilings in the toilet rooms were covered with tongue-and-groove boards and the walls and ceiling heater room were covered with gypsum board. All interior doors were of standard design used throughout the cantonment.

Figure 2-64. Plan Number 800-1007, floor plan for unit guard house, Type UGH-24, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-O-7).

Figure 2-65. Southeast oblique of Building 449, unit guard house, Type UGH-24, 1988
(Library of Congress, HABS WI, 41-SPAR.V, 1-O-1).

Figure 2-66. Northeast oblique of Building 449, unit guard house, Type UGH-24, 1988
(Library of Congress, HABS WI, 41-SPAR.V, 1-O-2).

Figure 2-67. Northwest oblique of Building 449, unit guard house, Type UGH-24, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-O-3).

Figure 2-68. Interior view of guard room in Building 449, unit guard house, Type UGH-24, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-O-5).

Figure 2-69. Interior view of corridor looking towards the guard room in Building 449, unit guard house, Type UGH-24, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-0-4).

1.4.3.3 Unit guard house – Type UGH-36

There were six Type UGH-36, unit guard houses constructed in 1942 using Plan Number 800-1009 at Camp McCoy. The construction of this type of building was based off standard War Department 800 Series, Plan Number 800-1009.

The rectangular building measured 98'-0" x 25'-0." The foundation was a system of poured concrete piers and footings except for the heater room, located in one corner of each building, which had a concrete block foundation. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment and the roof was clad with red asphalt shingles (see Figure 2-70 to Figure 2-74).

The exterior doors were of standard design. There were two sets of doors at one end of the building, one leading into the heater room and one leading into the building. A poured concrete stoop with cast iron handrails was located at each end entry. There were a total of 19 Standard Type A windows consisted of eight-over-eight windows found on all four sides with a simple wood architrave.

Rising from one end of the buildings was a brick chimney that was approximately 25'-0" tall. There were two metal roof ventilators placed along the ridge.

The interior of the building included a central corridor at one end of the building. On one side of the corridor was the heater room and on the other side was a small office space and a toilet room. The majority of the building interior was a large open space used as a guard room (see Figure 2-75 to Figure 2-76).

The floors in the toilet room and heater room were concrete, while the rest of the building had wooden flooring. The walls and ceilings in the corridor and office were covered with wallboard on the top half and horizontal wooden boards on the bottom half. The walls and ceiling in the guard room were covered wallboard. The walls and ceilings in the toilet rooms were covered with tongue-and-grove boards and the walls and ceiling heater room were covered with gypsum board. All interior doors were of standard design used throughout the cantonment.

Figure 2-70. Plan Number 800-1009, unit guard house, Type UGH-36, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-FV-6).

Figure 2-71. Close-up of the floor plan for Plan Number 800-1009, unit guard house, Type UGH-36, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-FV-6).

Figure 2-72. Southwest oblique of Building 2671, unit guard house, Type UGH-36, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FV-1).

Figure 2-73. Northwest oblique of Building 2671, unit guard house, Type UGH-36, 1988
(Library of Congress, HABS WI, 41-SPAR.V, 1-FV-2).

Figure 2-74. Southeast oblique of Building 2671, unit guard house, Type UGH-36, 1988
(Library of Congress, HABS WI, 41-SPAR.V, 1-FV-3).

Figure 2-75. Interior view of guard room Building 2671, unit guard house, Type UGH-36, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FV-4).

Figure 2-76. Interior view of toilet room showing original fixtures in Building 2671, unit guard house, Type UGH-36, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FV-5).

1.4.3.4 Post administration building, Division Headquarters, Type DHQ-1 Headquarters

The post administration building, Division Headquarters, Type DHQ-1, was built utilizing the 800 Series Plan Number 800-204 and was finished in 1942 at Camp McCoy. The two-story building has an H-shaped footprint with a main block and two wings. The main structure measures 29'-6" x 60'-0" and the wings measure 29'-6" x 70'-0" (Figure 2-77 and Figure 2-78).*

Figure 2-77. Floor plans for Building 100, post headquarters, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-K-5).

* Fort McCoy, Building T-100 (Post Administration). Photographs and Written Historical and Descriptive Data. HABS No. WI-308-K. Historic American Building Survey. National Park Service. Department of the Interior. Washington, D.C.

Figure 2-78. Sections for Building 100, post headquarters, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-K-5).

The foundation was a system of poured concrete piers and footings. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment and the roof was clad with red asphalt shingles.

The building had a gable covered porch on the south (front) side that measures 11'-6" x 26'-0." The roof is supported by six simple columns resting on brick pedestals.* A red brick chimney, that was 50'-0" in height, was located on the northwest corner of the middle section of the building (Figure 2-79 and Figure 2-80).

The exterior doors were of standard design. There was one set of doors at the middle of the south front side. There were single entry doors at the north end of each wing with a poured concrete stoop with cast iron handrails and there were two single entry doors at the second-floor north end of each wing with a wooden access staircase. There was also a set of wooden doors on the north side of the middle section leading into the heater room. There were 23 Standard Type A windows at both the south front and north

* Fort McCoy, Building T-100 (Post Administration). Photographs and Written Historical and Descriptive Data. HABS No. WI-308-K. Historic American Building Survey. National Park Service. Department of the Interior. Washington, D.C.

rear, and ten windows at both the east and west sides. The windows had wooden screens and a simple wood architrave.

The first floor had three central corridors in each section of the building (Figure 2-81). Partition walls divided the two wing spaces up into smaller offices. There were two toilet rooms, three larger enclosed offices, a heater room, and a lobby area in the middle section of the building. The second-floor plan of the middle section consisted of a central corridor with three open offices on one side and three open offices, an officers' toilet, and an enlisted men's toilet on the other side. The east and west wings were both large open offices spaces dotted with wood square column supports. There are two sets of wooden switchback open staircases located on either side of the south wall of the middle section of the building and a stairway to the second level immediately off the rear entrance on the north side of the building.

The flooring throughout the building was wood flooring, except for the heater room and toilet rooms which was concrete. The interior walls throughout the main office spaces, lobby, and corridors were covered in wallboards and the heater room walls were covered with gypsum boards. The interior doors were of standard design used throughout the cantonment.

Figure 2-79. South (front) side of Building 100, post headquarters, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-K-2).

Figure 2-80. North (rear) side of Building 100, post headquarters, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-K-4).

Figure 2-81. Interior view of main entrance in Building 100, post headquarters, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-K-5).

1.4.4 Recreation Buildings

2.1.1.1 Recreation building - gymnasium

A total of 12 recreation buildings - gymnasium were erected at Camp McCoy in 1942 and were constructed from the War Department's 700 Series of standardized Plan Number 700-310.

The overall dimensions of the gymnasium were 99'-7" long x 37'-6" wide, approximate area of 3,663 and was a double-height structure.

The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment and the roof was clad with red asphalt shingles. The foundation was a system of poured concrete piers and footings except for the heater room, which had a concrete block foundation. A wooden foundation skirting wrapped around the portion of the building with the pier foundation system. A large detached brick chimney stack was located near the front corner of the building (see Figure 2-82).

There was one type of window on the recreation building of the standard design found in all 800 Series mobilization buildings; eight-over-eight double-hung wood frame. These were either used as single windows or paired together on the sides.

There were three entries into the building. The doors were of standard design used throughout the cantonment and were set in pairs. There was one set on each end side and one set on the long side. On the opposite side was a similar set of doors that lead into the heater room.

The main floor consisted of a single bay containing the auditorium/recreation area and a stage. The original plans called for the inclusion of two dressing rooms and a vestibule behind the stage, two coat rooms on either side, and an altar at the rear of the stage. At the front of the building was a heater room, an office, and a projection room above the entrance. A wooden stairway lead from the office to the projection room.*

* Camp Edwards, Building T-1233 (Recreation Building). Photographs and Written Historical and Descriptive Data. HABS No. MA-1249-D. Historic American Building Survey. National Park Service. Department of the Interior. Washington, D.C.

Figure 2-82. Looking east at Building 2667 in 2019 (HABS photos were not found for this building type (ERDC-CERL, 2019).

2.1.1.2 Service clubs – Type SC-3

There were four service clubs (two were used as the officers' club) erected at Camp McCoy in 1942 using the Construction Division Office of the Quartermaster General, Mobilization Building, Service Club, Type SC-3, Plan Number 800-517 standardized plan of the War Department.

The service clubs were built as a T-shaped building with a main hall and two wings. The main structure measured 40'-0" x 199'-8" and the wings measured 70'-0" x 59'-8" with an approximate area of 18,791 square feet. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment and the roof was clad with red asphalt shingles. The foundation was a system of poured concrete piers and footings with wooden foundation skirting. A large brick chimney stack was located on the rear wing of the building (see Figure 2-83 to Figure 2-84 and Figure 2-86).

The building was designed with a long wooden porch that stretched across the front side measuring 80'-0" in length. Three sets of wood stairs provided access to this porch with the center set being the widest (Figure 2-85).

There were two types of windows used on the service clubs. The one used the most was of standard design type used throughout the cantonment; an

eight-over-eight double-hung wood sash and the other was an eight-pane fixed sash wood window. There were three sets of doors on the front side. The door types were of standard design used throughout the cantonment. Wooden screen doors were used.

The T-shape of the main floor consisted of an entry hall flanked on one side by a men's toilet room and the other by a storage room, and librarian's office, a café, kitchen area with storage rooms, and a boiler room in the west wing, a library, a storage room, and an office in the right wing, and a dance hall in the north wing. The middle section of the second floor had a women's restroom and toilet, and a game room. The right wing was the second floor for the library. There was no second floor over the left wing and the majority of the second level of the rear wing was open to the dance hall below.

The entry hall had a wood floor, wallboards covered the walls, and the space was filled with built-in coat racks. The library was a two-story space. On the first floor, a grid pattern of wood columns supports dotted the open space. The floor of the library was wood (see Figure 2-88). An interior wood staircase leads up to the second floor where exposed wood trusses highlighted the vaulted ceiling. The dance hall was an open two-story space with a wood balcony that encompassed the perimeter of the space (see Figure 2-87). The balcony had a simple wood balustrade. The floor of the hall and balcony was wood. Exposed wood trusses highlighted the vaulted ceiling (see Figure 2-91). Metal and porcelain light fixtures were suspended from the trusses. A fireplace was located on the north wall on both the main floor and the balcony level (see Figure 2-90). Four wood staircases, one at each corner of the dance hall provided access to the balcony (see Figure 2-89). A café was located in the left wing with an adjacent kitchen space. The café had a wood floor.

The flooring in the kitchen, toilet rooms, and boiler room was concrete. The remainder of the structure had wood floors. The ceiling and walls are finished with Masonite presswood and painted.

There were two type of interior doors used; one was a four-light three-panel wood door and the other was a five-panel wood door. Both were of standard types used throughout the WWII cantonment construction.

The original light fixtures in the dance hall area were porcelain enameled fixtures.

Figure 2-83. First floor plan for Building 2000, service club, Drawing #800-517, 1941 (courtesy Fort McCoy DPW).

Figure 2-85. South front side of Building 2000, service club, 1952 (NARA College Park, RG 111-SC).

Figure 2-86. Northwest oblique of the north wing of Building 2000, service club, 1988 (Library of Congress, HABS WIS,41-SPAR.V,1-J-6).

Figure 2-87. Interior view of the dance hall looking north towards the fireplaces in Building 2000, service club, 1952 (NARA College Park, RG 111-SC).

Figure 2-88. Interior view of the first-floor library in the east wing of Building 2000, service club, 1952 (NARA College Park, RG 111-SC).

Figure 2-89. Interior view of the second floor of the billiards room in Building 2000, service club, 1988 (Library of Congress, HABS WIS,41-SPAR.V,1-J-11).

Figure 2-90. Close-up of the fireplace, hearth, and mantle on the balcony level of the dance hall in Building 2000, service club, 1988 (Library of Congress, HABS WIS,41-SPAR.V,1-J-12).

Figure 2-91. Interior view of truss in main roof of the dance hall showing the skylight in Building 2000, service club, 1988 (Library of Congress, HABS WIS,41-SPAR.V,1-J-10).

1.4.4.1 Recreation building – Type RB-2

The recreation building, Type RB-2, was constructed from a standardized Plan Number 800-459. There were four of this type of building constructed at Camp McCoy in 1942.

The rectangular building measured 50'-0" x 25'-0." The foundation was a concrete pier foundation system with wooden foundation skirting. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment and the roof was clad with red asphalt shingles (see Figure 2-92 to Figure 2-94).

The exterior doors were of standard design. There were two single entry doors, one on the front side and one on the end side. There were a total of 13 Standard Type A windows on all four sides. The windows each had a wooden screen and simple wood architrave.

The interior of the building was one large open space. There were three Cannon stoves placed on concrete footing in the middle of the space. The flooring was wood planks, while the walls were covered with wallboards.

Figure 2-92. Close-up of the floor plan for a recreation building, Type RB-2, Plan Number 800-459, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-DZ-1).

Figure 2-93. South oblique of Building 10118, recreation building Type RB-2, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-EA-1).

Figure 2-94. North oblique of Building 10118, recreation building Type RB-2, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-EA-2).

1.4.5 Mess Halls

1.4.5.1 Type M- 112-, 152-, 172-, 228-man mess halls

There were a total of 176 mess halls constructed in 1942 at Camp McCoy. Architecturally, there were five plan variations used to erect these mess halls based off standardized War Department plans 800-805 and 800-806. The rectangular footprint design plans could be expanded depending on the size of the units using each mess hall. Type M 112-, 152-, 162-, 172-, 228-, or a combined mess hall where the enlisted men ate their meals and food was prepared, served, and stored. There was a total of 19 Type M 112-man, 12 152-man, 4 162-man, 16 172-man, 120 228-man, and 5 combined, mess halls constructed in 1942 at Camp McCoy.

The 112-man mess hall measured 25'-0" by 90'-0" with an approximate area of 2,250 square feet, the 152-man mess hall measured 25'-0" by 100'-0" with an approximate area of 2,500 square feet, the 172-man mess hall measured 25'-0" by 106'-0" with an approximate area of 2,650 square feet, and the 228-man mess hall measured 25'-0" by 118'-0" with an approximate area of 2,950 square feet. The mess halls were one-story tall and the height from grade to the roof ridge was approximately 15'-0". The foundation was a system of concrete piers. The crawl space below each building was screened by a wooden skirting composed of vertical boards. The exterior walls consisted of three layers: (a) wooden sheathing, (b) black construction paper, and (c) siding composed of asbestos shingle siding with a scalloped bottom edge

measuring 11" x 24", the standard size used throughout the cantonment. The siding pieces had a scalloped bottom edge detail. The buildings were erected from the 800 Series standard plans and are of balloon construction. The roof was a low-pitched gable clad red asphalt shingles. The overhanging eaves had wood fascia and soffit. There was a brick chimney stack and three large circular metal vent stacks that projected from the slope of the roof over the kitchen area where the range was located. There were two metal vent stacks that projected from the roof over the dining area. A wood louvered vent was located in both gable ends. The original drawing version of standard Plans 800-851 show wooden stairs and porches at each of the four entries on the exterior of the mess halls; however, in the 1950s these were removed and the current concrete stoop with cast iron handrails were constructed (see Figure 2-95 to Figure 2-105).

The interior of the mess halls consisted of an open dining room in one half, in which the troops sat at tables, and a kitchen and storeroom in the other half, where food was prepared, served, and stored. During WWII, the enlisted men assigned to each mess hall entered the dining room through the exterior doorways on either long side or at one end side. They received their food at the serving counter between the mess hall section and the kitchen and ate at standard issue tables placed in rows. Through an opening in the counter was the kitchen, where the cooks and "K.P." staff prepared the food and cleaned up following each meal. They stored foodstuffs on shelves in the storeroom and placed perishable items in the large cooler. The kitchen staff entered and exited the mess hall through a set of double doors at the rear of the building (see Figure 2-106 to Figure 2-110).

*

There are two concrete platforms in the mess section of the buildings. These were intended for Cannon stoves that originally heated the room. The kitchen and storeroom areas had concrete floors, while the dining area had a wood floor.

In the dining room, there was a wainscoting of manufactured board, called "tempered pressed wood" in the standard plans and was used on the bottom three feet of the walls. Insulation board was used on the upper six feet

* Fort McCoy, Building T-635 (Mess Hall). Photographs and Written Historical and Descriptive Data. HABS No. WI-308-C. Historic American Building Survey. National Park Service. Department of the Interior. Washington, D.C.

of the walls above the wainscoting. The ceiling was wallboard. Pairs of exposed structural knee braces ran between the upper walls into the attic between each bay. In the kitchen, there was 6'-0" high wainscoting composed of pressed wood. Insulation board was installed above the wainscoting. A fourteen foot wide glazed terra cotta tile surface was used along the kitchen wall to provide fireproof backing for the cooking ranges. The storeroom walls were composed of tongue and groove boards nailed horizontally across the studs. On three of the walls were built-in shelves and counters. The ceiling in the storeroom was composed of wallboard.*

Wooden tables and benches were used in the dining room. A work/prep table stood in the center of the kitchen. A serving counter placed on top of partition walls between the kitchen and dining room had a pressed board top. There were two detached "scullery sinks" made of galvanized steel and both consisting of double sinks and side counters were located in the kitchen. Also, in the one corner of the kitchen was a 6'-0" high wooden pie safe.

Figure 2-95. Plan Number 800-805, floor plans and schedules for Type M 112-, 152-, 172-, and 228-man mess halls, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-9).

* Fort McCoy, Building T-635 (Mess Hall). Photographs and Written Historical and Descriptive Data. HABS No. WI-308-C. Historic American Building Survey. National Park Service. Department of the Interior. Washington, D.C.

Figure 2-96. Close-up of floor plan and expansion details Type M 112-, 152-, 172, and 228-man mess halls, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-9).

Figure 2-97. Plan Number 800-806 elevations and details for Type M 112-, 152-, 172, and 228-man mess halls, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-10).

Figure 2-98. Northeast oblique of Building 1106, 112-man mess hall, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EV-1).

Figure 2-99. Southwest oblique of Building 1106, 112-man mess hall, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EV-3).

Figure 2-100. Side of Building 635, 152-man mess hall. Left side of the door is the dining area and the right side is the kitchen space, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-4).

Figure 2-101. Oblique of kitchen and storage area entry and long side of Building 635, 152-man mess hall, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-2).

Figure 2-102. Front side of Building 635, 152-man mess hall, showing entry door into the dining area, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-3).

Figure 2-103. Southeast oblique of Building 450, 172-man mess hall, (Library of Congress, HABS WIS, 41-SPAR.V, 1-P-1).

Figure 2-104. Northwest oblique of Building 450, 172-man mess hall, (Library of Congress, HABS WIS, 41-SPAR.V, 1-P-2).

Figure 2-105. Southwest oblique of Building 1506, 228-man mess hall, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-FC-3).

Figure 2-106. Interior view of the kitchen looking into the dining area in Building 1106, 112-man mess hall, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EV-4).

Figure 2-107. Interior view of Building 635, 152-man mess hall, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-C-6).

Figure 2-108. Interior view of the kitchen space in Building 635, 152-man mess hall. The kitchen sink has been removed from the wall and is placed in the middle of the room in this photo, 1988 (Library of Congress, HABS WIS, 41- SPAR.V, 1-C-7).

Figure 2-109. Interior view of the kitchen in Building 450, 172-man mess hall (Library of Congress, HABS WIS, 41-SPAR.V, 1-P-4).

Figure 2-110. Interior view of the storeroom in Building 1506, 228-man mess hall (Library of Congress, HABS WIS, 41-SPAR.V, 1-FC-6).

1.4.6 Storehouse Buildings

2.1.1.3 Standard storehouse, Type SH-8

There were seven storehouse building, Type SH-8, constructed from a standardized Plan Number 800-663 in 1942 at Camp McCoy.

The rectangular building measured 54'-0" x 25'-0." The building had a poured concrete foundation. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment and the roof was clad with red asphalt shingles. There were two metal roof ventilators placed on the ridgeline (see Figure 2-111 to Figure 2-113).

There was one wooden sliding door located on the front side. There were a total of 12 Standard Type A windows on all four sides. The windows had a simple wood architrave and a fixed window guard.

The interior of the building was one large open space with concrete flooring and exposed roof truss system (see Figure 2-114 to Figure 2-115).

Figure 2-111. Close-up of the floor plan storehouse, Type SH-8, Plan Number 800-663, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-EZ-6),

Figure 2-112. Northeast oblique of Building 1263, standard storehouse, Type SH-8, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EZ-1).

Figure 2-113. Southwest oblique of Building 1263, standard storehouse, Type SH-8, 1988
(Library of Congress, HABS WIS, 41-SPAR.V, 1-EZ-2).

Figure 2-114. Overall interior view in Building 1263, standard storehouse, Type SH-8, 1988
(Library of Congress, HABS WIS, 41-SPAR.V, 1-EZ-3).

Figure 2-115. Front door detail in Building 1263, standard storehouse, Type SH-8, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-EZ-5).

1.4.6.1 Standard storehouse, Type SH-9

The storehouse building, Type SH-9, was constructed from a standardized Plan Number 800-663. There were five of the 800 Series, standard storehouse, Type SH-9 constructed in 1942 at Camp McCoy.

The rectangular building measured 108'-0" x 25'-0." The building had a poured concrete foundation. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment and the roof was clad with red asphalt shingles. There were three metal roof ventilators placed on the ridgeline (see Figure 2-116 to Figure 2-118).

There were two wooden sliding doors located on the front side. There were a total of 19 Standard Type A windows on all four sides. The windows each had a simple wood architrave and a fixed window guard.

The interior of the building was one large open space with concrete flooring and exposed roof truss system.

Figure 2-116. Plan Number 800-664, plans, elevations, sections for standard storehouse 25'-0" wide, Type SH-9, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-FA-4).

Figure 2-117. Northeast oblique of Building 1264, standard storehouse, Type SH-9, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-FA-1).

Figure 2-118. Southwest oblique of Building 1264, standard storehouse, Type SH-9, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-FA-2).

1.4.6.2 Standard storehouse, Type SH-13 and SH-18

The exterior of the Type SH-13 and SH-18 warehouses was constructed from a standardized Plan Number 800-652 and standardized Plan Number 800-654 respectively. There were 17 of the 800 Series, standard storehouse, Type SH-13 and 11 of the 800 Series, standardized storehouse, Type SH-18 constructed in 1942 at Camp McCoy.

They were both rectangular buildings set up in long rows with firewalls between each building. The building was raised up to the level of the floor of railroad boxcars. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment and the roof was clad with red asphalt shingles. There were metal roof ventilators placed on the ridgeline (see Figure 2-119 to Figure 2-120).

There were wooden sliding doors located on the front side and Standard Type A windows were on all four sides. The windows each had a simple wood architrave and a fixed window guard.

The interior of this type of building was mostly open space that was dotted with a wood column grid system. The flooring used was wood planks. The walls were covered with horizontal plank boards. The ceilings were left exposed to the wood truss system (see Figure 2-121 to Figure 2-122).

Figure 2-119. Plan Number 800-654 for standard storehouse, Type SH-18, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-FJ-8).

Figure 2-120. South side of Building 2122, storehouse, Type SH-18, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FJ-2).

Figure 2-121. Interior view of storehouse area in Building 2122, storehouse, Type SH-18, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FJ-3).

Figure 2-122. Detail of original wooden storehouse sliding door in Building 2122, storehouse, Type SH-18, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FJ-5).

1.4.7 Repair and Service Buildings

1.4.7.1 Grease rack enclosure building

There were eight enclosed grease rack buildings constructed in 1942 at Camp McCoy using standardized Plan Number 800-1026.

The rectangular building measured 120'-0" x 40'-0." The building had a poured concrete foundation. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used throughout the cantonment and the roof was clad with red asphalt shingles. There were six metal roof ventilators placed on the ridgeline (see Figure 2-123 to Figure 2-126).

The original standardized plan did not call for heater room; however, according to the HABS photographs below, a lean-to appendage was added to one of the long sides. A detached brick chimney was adjacent the appendage and a set of standard design doors provided access into the heater room.

There were two large wood overhead doors at each end of the building and one single entry standard design exterior door on each long side of the building. There were 18 Standard Type A windows with an eight-pane fixed window on top of each window. There were also one fixed eight-pane window above each single entry on the sides. The windows had a simple wood architrave and a fixed window guard.

The interior of the building was one large open space with concrete flooring and exposed roof truss system. Two sets of long grease and inspection racks spanned the length of the building. The interior walls were left unfinished (see Figure 2-127).

Figure 2-123. Plans, elevations, and sections for enclosure for grease racks, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-FF-6).

Figure 2-124. Southwest oblique of Building 1876, grease rack enclosure building, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FF-1).

Figure 2-125. Southeast oblique of Building 1876, grease rack enclosure building, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FF-2).

Figure 2-126. East side of Building 1876, grease rack enclosure building, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FF-1).

Figure 2-127. Interior view of Building 1876, grease rack enclosure building, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FF-1).

1.4.8 Support Buildings

1.4.8.1 G.U. Dispensary – Type G.U.D.-1

The dispensary was designed according to standard Plan Number 800-1559 for a G.U.D.-1, G.U. Dispensary. There were thirteen of this type of building constructed in 1942 at Camp McCoy. The dispensary was an infirmary-like facility where soldiers would be diagnosed and examined for genitourinary illness. The building housed a pharmacy, laboratory, an N.C.O. room, and supply rooms.

The dispensary is a one-story wood building with a concrete pier foundation with a wood foundation skirting. It is rectangular in shape with a recessed porch at one end. The concrete porch had cast iron metal handrails. The exterior walls were clad with the standard asbestos shingle siding with a scalloped bottom edge used on other WWII building in the cantonment. The roofing is covered in red asphalt shingles. A red brick chimney rose from the roof near the front of the building where the heater room was located (see Figure 2-128 to Figure 2-129).

There were 26 Standard Type A windows with simple wood architraves and wood screens on this type of building. The exterior doors were of

standard design. There was one single entry at the porch level on the front side, a set of doors leading into the boiler room, and a single-entry door on the rear side.

The interior consisted of a waiting room at the front of the building. Off the waiting room was an office, laboratory, and an examination room. There was a central corridor that provided access to a pharmacy, an officers' toilet, a janitor's room, a toilet room, two treatment rooms, two rest rooms, and an NCO room. The floors were wood except for the toilet rooms and heater room, which were concrete (see Figure 2-130 to Figure 2-132).

There were two types of interior doors used; one was the standard design wood five panel and the other was the standard design three-light three-panel wood door. The interior walls and ceiling were finished with wall-board. Many of the interior rooms had wood built-in shelving and storage units, along with sinks and countertop workspace.

Figure 2-128. Plan Number 800-1559, G.U. Dispensary, Type G.U.D.-1, 1941 (ERDC-CERL, architectural files).

Figure 2-129. Oblique of a G.U. dispensary, Type G.U.D.-1, Building 2556, (ERDC-CERL, 2019).

Figure 2-130. Interior view of lab area in Building 1033, clinic/dispensary, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-AZ-3).

Figure 2-131. Interior view of storeroom showing cabinet and drawers in Building 1003, clinic/dispensary, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-1X-1).

Figure 2-132. Interior view of a storage room and lab space in Building 1033, clinic/dispensary, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-AZ-5).

1.4.8.2 Dental clinic – Type DC-1

There were two DC-1, dental clinics constructed in 1942 at Camp McCoy using the standardized Plan Number 800-1432.

The overall dimensions of the dental clinics were a long rectangular shape measuring 29'-6" wide by 110'-0" long and were two-stories in height rising approximately 27'-0" from grade to the ridge of the roof. The exterior walls were clad with standard asbestos shingle siding with a scalloped bottom edge. The foundation was a system of poured concrete piers and footings except for the heater room, which had a concrete block foundation. A wooden foundation skirting wrapped around the portion of the building with the pier foundation system. The roof was clad with red asphalt shingles (see Figure 2-133 to Figure 2-134).

There were three porches with cast iron handrails at ground level; one on each short end side and one in the middle of one of the long sides. A wooden platform was attached to the end side on the second floor where the open general treatment room was located. A wood staircase provided access from the platform.

There were 51 standard Type A windows used on the four sides of the building. There were three single entry standard design Type D exterior doors and one set of double doors, which were of standard design Type B., which provided access into the boiler room.

A detached red brick chimney stack was located adjacent the boiler room entrance.

The first floor consisted of a large general reception and waiting room. Off this room was a reception and preliminary examination room. Two interior corridors fed off the centralized waiting room. At one end was an extraction room, an x-ray room, a dark room, a boiler room, an emergency room, and a storage room. At the other end of the building was an office records room, an officers' reception and waiting room, a janitor's closet, an officers' toilet, and a general toilet (see Figure 2-135 to Figure 2-137).

A set of switchback wood stairs lead from the first floor to the second floor. The majority of the second floor was utilized as open space as a general treatment room with 14 treatment stations. At the other end of the building is a corridor that provided access to the interior staircase, a storage room, a toilet room, an enlisted men's locker room, an officers' toilet and

locker room, a laboratory storage room, a large laboratory, a treatment room, and a specialized room.

The interior support system was designed similar to the barracks and officers' quarters buildings, whereas, the interior structure of the lobby and corridor on the first floor and the general treatment room on the second floor were defined by wooden posts arranged in two parallel rows directly above the concrete piers of the foundation.

The flooring throughout the building was wood planks, except for the toilet rooms and boiler room, which were concrete. The wall and ceiling finishes throughout the building were covered with wallboards, while the toilet room had tongue-and-groove boards and the boiler room had gypsum boards.

There were two type of interior doors in the building. A four-light, three-panel wood door was located at the entrance into both corridors from the lobby on the first floor. The rest of the interior doors were standard design wood five-panel doors. There were wood built-in shelving and storage space in the storage rooms and the second-floor laboratory.

Figure 2-133. Northeast oblique of Building 656, dental clinic, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-T-1).

Figure 2-134. Southwest oblique of Building 656, dental clinic, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-T-2).

Figure 2-135. Interior view, first floor hall in Building 656, dental clinic, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-T-3).

Figure 2-136. Interior view, second floor in Building 656, dental clinic, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-T-4).

Figure 2-137. Interior view of toilet room on the second floor in Building 656, dental clinic, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-T-5).

1.4.8.3 *Regimental exchange*

There were eleven regimental exchange, Type E-3 buildings constructed in 1942 at Camp McCoy using the standardized Plan Number 800-480.

The overall dimensions of the regimental exchange buildings were a long rectangular shape measuring 50'-0" wide by 144'-0" long and were one-story in height with a small lean-to appendage on one corner of the building. The exterior walls were clad with standard asbestos shingle siding with a scalloped bottom edge. The foundation was a system of poured concrete piers and footings except for the heater room, which had a concrete block foundation. There was a small appendage located near the heater room that had a poured concrete foundation. A wooden foundation skirting wrapped around the portion of the building with the pier foundation system. The roof was clad with red asphalt shingles (see Figure 2-138 to Figure 2-141).

There were six concrete porches with cast iron handrails at ground level.

There were 31 standard Type A windows used on the four sides of the building. The windows had a simple wood architrave and wooden screens. There were four sets of double doors, which were of standard design Type B and one single entry standard design Type D exterior doors.

Main entry into the building was at one of the short ends through a set of double doors which lead into a corridor. Off the corridor was a barber shop on one side and a tailor shop on the other side. The corridor opened in a small lobby space. Off the lobby space was built-in telephone booths, a women's toilet, a men's toilet, and an office with the cashier space. The lobby opened into a large open space, the main exchange area. At one corner of the exchange is where a single-entry door lead to the lean-to appendage which was used for empties. At the end of the exchange was a storeroom, a scullery with a small storeroom, and the heater room (see Figure 2-142 to Figure 2-144).

The interior support system was designed similar to the barracks and officers' quarters buildings, whereas, the interior structure of the main exchange space was defined by wooden posts arranged in two parallel rows directly above the concrete piers of the foundation. The wood truss roof system was left exposed in this space.

The flooring throughout the building was wood planks, except for the toilet rooms, scullery room, and heater room, which were concrete. The wall finishes throughout the building were covered with wallboards on the bottom half and horizontal plank boards on the bottom half, except for the toilet rooms and heater room. The walls in the toilet rooms were covered with tongue-and-groove boards and the walls in the heater room were covered with gypsum boards. Ceilings were covered with wallboard, except for the heater room and toilet room, which were covered with wallboard.

There were two type of interior doors in the building. A four-light, three-panel wood door was located at the entrance from corridors into the exchange room. The rest of the interior doors were standard design wood five-panel doors. There were standard design interior screen doors located at all the exits. There was wood built-in shelving in the storage rooms.

Figure 2-138. Close-up of the floor plan for a regimental exchange, Type E-3 from Plan Number 800-480, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-N-8).

Figure 2-139. Plan Number 800-479, miscellaneous details for a regimental exchange, 1941 (Library of Congress, HABS WIS, 41-SPAR.V, 1-N-7).

Figure 2-140. Southeast oblique of Building 352, regimental exchange, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-N-1).

Figure 2-141. Southwest oblique of Building 352, regimental exchange, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-N-3).

Figure 2-142. Interior view of the exchange room in Building 352, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-N-4).

Figure 2-143. Interior view of the scullery in Building 352, regimental exchange, 1988
(Library of Congress, HABS WIS, 41-SPAR.V, 1-N-5).

Figure 2-144. Interior view of the barber shop in Building 352, regimental exchange, 1988
(Library of Congress, HABS WIS, 41-SPAR.V, 1-N-6).

1.4.8.4 Regimental chapels – Type CH-1

There were eleven, Type CH-1 chapels constructed at Fort McCoy in 1942. The chapels were built from the 800 Series plan number 800-553. Approximately 37 x 83 feet in plan, these one-and-a-half story buildings were divided into seven bays; the first bay was occupied by the entry and overhead choir loft, the end bay contained the altar, and the central bays (nave) were open to the roof to expose the chapels exposed beam structure.* There is a front entry vestibule and a rear appendage housing the boiler room. The steeple and lighting rod rise an approximate 29' above the roof ridge (see Figure 2-145 to Figure 2-147).†

Two types of double-hung wooden sash windows were used on the chapels, six-over-six and sixteen-over-sixteen, both with a simple architrave surround. The two front vestibule doors were three-panel doors with no lights, a six-light double recessed panel door at the single rear entry, and four-light three-pane door on the entry to the boiler room.

There were fifteen rooms in the chapel; the covered entry, the balcony, the vestibule, the cloak room with a water closet, the consultation room, the nave, the sanctuary, two chaplain's offices, the water closet, the boiler room, two closets, and a passage.* There was a two-flight, L-shaped wooden stairway leading from the cloak room to the balcony. The chapels had hardwood floors (see Figure 2-148 to Figure 2-150).

Vertical wood wainscoting covered all interior walls of the sanctuary. All doorways and moldings in the chapels were made of simple square wood trim. The sanctuary exhibited the open exposed wooden truss systems, suspended mechanical system, and suspended light fixtures (see Figure 2-151). There were twelve "type-1", four 100-watt bulb light fixtures suspended on a chain from the ceiling trusses.§

* World War II Temporary Military Buildings, a Brief History of Architecture and Planning of Cantonments and Training Stations in the United States. Garner, John S. U.S. Army Corps of Engineers. Construction Engineering Research Laboratories. Technical Report CRC-93-01. Champaign, IL. 1993.

† Fort McCoy, Building T-1146 (Chapel). Photographs and Written Historical and Descriptive Data. HABS No. WI-308-H. Historic American Building Survey. National Park Service. Department of the Interior. Washington, D.C.

‡ Fort McCoy, Building T-1146 (Chapel). Photographs and Written Historical and Descriptive Data. HABS No. WI-308-H. Historic American Building Survey. National Park Service. Department of the Interior. Washington, D.C.

§ Fort McCoy, Building T-1146 (Chapel). Photographs and Written Historical and Descriptive Data. HABS No. WI-308-H. Historic American Building Survey. National Park Service. Department of the Interior. Washington, D.C.

Figure 2-145. Southwest oblique of Building 1146, chapel, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-2).

Figure 2-146. South side of Building 1146, chapel, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-5).

Figure 2-147. North side of Building 1146, chapel, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-6).

Figure 2-148. Interior view of the nave looking towards the altar in Building 1146, chapel, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-7).

Figure 2-149. Interior view of the nave looking towards the entrance in Building 1146, chapel, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-8).

Figure 2-150. Close-up view of the exposed wood truss system in Building 1146, chapel, 1988 (Library of Congress, HABS WIS, 41-SPAR.V, 1-H-10).

Figure 2-151. Plan Number 800-558, regimental chapel, Type CH-1, details of truss, 1941 ((Library of Congress, HABS WIS, 41-SPAR.V, 1-H-11).

1.4.8.5 Fire stations

There were four WWII fire stations erected in 1942 using the Construction Division Office of the Quartermaster General, Mobilization Building, Fire Station-Type F-2, Plan Number 800-800a standardized plan of the War Department (see Figure 2-152 to Figure 2-154).

The structural systems of the fire stations were platform construction, entirely composed of wood members. The exterior was clad with asbestos shingle siding with a scalloped bottom edge on the walls, yellow wood trim, gray wooden foundation “skirting,” and red asphalt shingle roofs. A concrete wall foundation was used for the apparatus room, while concrete pier foundation system was used for the living section of the building. A brick furnace stack rose from the roof line at the apex of the apparatus room and living section of the building. The original windows were standard design, multi-pane wood double-hung with mesh screens and wood trim. The original entry doors were wood panel and divided light with interior wood screen doors. The original bay overhead garage doors were wood and glass panel designed. The interiors were not finished with either plaster or paint. Instead, “tempered pressed wood,” wallboard, and gypsum

board were used to cover walls and ceilings. Wood flooring was used throughout the living area of the building (see Figure 2-155 to Figure 2-156).

The building was designed with two distinct areas, an apparatus room, and an elevated living quarters for an officer, NCOs, and a large open bay squad room. The apparatus room was a high-bay area with concrete floors and walls clad with gypsum board. The room had two small enclosed areas, one as an alarm room and the other as a work room. A set of wood steps led into the elevated living area of the fire house.

The living area was rectangular in shape with a central corridor that separated a heater room and officers bunk area on the north side and a latrine and a room for NCOs on one side of the corridor. At the end of the corridor was a large open bay used as the squad room bunks. All walls in toilet room to be finished with tongue and groove boards. The floor of the toilet room was concrete. The room had a toilet, urinal, a shower stall, and two sinks with mirrors and light fixtures above. The squad room had wood plank floor, walls and ceiling clad with wallboard, and a suspended mechanical system.

Figure 2-152. Original construction drawing, Series 800-800, plans and elevations for Building 550, Fire Station (courtesy Fort McCoy DPW).

Figure 2-153. Northwest side of Building 1555, fire station, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FD-1).

Figure 2-154. Fire hose tower from the northeast, Building 1555, fire station, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FD-4).

Figure 2-155. Interior view of apparatus room in Building 1555, fire station, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FD-5).

Figure 2-156. Interior view of the squad room in Building T-1555, Fire Station, DATE (HABS WIS, 41-SPAR.V, 1FD-6).

1.4.8.6 Post office – Type PO-2

There were either three post offices, Type PO-2 constructed in 1942 at Camp McCoy using the standardized Plan Number 800-217. The overall dimensions of the post offices were a rectangular shape measuring 37'-0" wide by 110'-0" long and were one-story in height with a small lean-to appendage on one corner of the building. The exterior walls were clad with standard asbestos shingle siding with a scalloped bottom edge. The foundation was a system of poured concrete piers and footings except for the heater room, which had a concrete block foundation. A wooden foundation skirting wrapped around the portion of the building with the pier foundation system. The roof was clad with red asphalt shingles (see Figure 2-157 to Figure 2-159).

There were two concrete porches with cast iron handrails that provided access into the two main entries into the buildings. A wood platform with shed roof projected off the rear of the buildings. A red brick chimney extended above the roof near the rear of the building.

There were 27 standard Type A windows used on the four sides of the building. The windows had a simple wood architrave and wooden screens. There were three sets of double doors, which were of standard design Type B and one set of double doors of standard design Type C, which lead into the heater room.

Two main entries, one on an end side and one adjacent on the long side, lead into an L-shaped lobby space. An L-shaped built-in counter and clerk windows divided the lobby and the rest of the large open working space behind the counter. In the corner of the working space was two toilet rooms and the heater room. At the end of the working space was a set of double doors that lead out to a mailing platform (see Figure 2-160 to Figure 2-161).

The flooring throughout the building was wood planks, except for the toilet rooms and heater room, which were concrete. The wall finishes in the lobby were covered with wallboard on the top half and horizontal plank boards on the bottom half. The walls in the work space were covered with wallboard. The walls in the toilet rooms were covered with tongue-and-groove boards and the walls in the heater room were covered with gypsum boards. Ceilings were covered with wallboard, in the lobby, work space, and toilet rooms. The ceiling in the heater room was covered with gypsum board.

The few interior doors in this type of building were of standard design. The interior screen doors were of standard design.

Figure 2-157. Plan Number 800-217, plans, elevations, sections for Type PO-2 post office, 1941 (Library of Congress, HABS WI, 41-SPAR.V, 1-FW-7).

Figure 2-158. East side of Building 2675, post office, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FW-1).

Figure 2-159. Northwest oblique of Building 2675, post office (Library of Congress, HABS WI, 41-SPAR.V, 1-FW-2).

Figure 2-160. Interior view of lobby in Building 2675 (modified since original), 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FW-4).

Figure 2-161. Interior view of Building 2675, post office, 1988 (Library of Congress, HABS WI, 41-SPAR.V, 1-FW-5).

3 Character-defining features

This chapter describes the character-defining features of the landscape (Section 3.1) and of the buildings (Section 3.2) of Fort McCoy. The National Park Service (NPS) defines historic character-defining features as prominent or distinctive aspects, qualities, or characteristics of a property that contribute significantly to its physical character.^{*} At Fort McCoy, the character-defining features are those elements which remain from the WWII-era and help convey the details, materials, craftsmanship and feeling of that time period.

1.5 Landscape Features

In historic landscape studies, the term “landscape characteristic” has a specific meaning. Landscape characteristics are defined as the “tangible evidence of the activities and habits of the people, who occupied, developed, used, and shaped the land to serve human needs; they may reflect the beliefs, attitudes, traditions and values of these people.”[†] Identifying the characteristics of the military landscape requires an understanding of the natural and cultural forces that have shaped it. This section will describe these processes and the resulting landscape features that together comprise the military landscape.

To identify the prominent or distinctive characteristics that make a landscape historic, the physical features of the site are divided into eight areas: site and layout, land use, expressions of military cultural values, transportation networks, views and viewsheds, buildings and structures, vegetation, and small-scale features.

1.5.1 Layout and design

Sites for military installations are selected because a location meets the physical requirements of the mission. The landscape is then spatially organized to accommodate the land use needs of the inhabiting military forces.

^{*} Birnbaum, Charles A., National Park Service Preservation Brief #36 – *Protecting Cultural Landscapes: Planning, Treatment and Management of Historic Landscapes*, (Washington, DC: National Park Service 1996), 4.

[†] National Park Service, National Register Bulletin #30 – *Guidelines for Evaluating and Documenting Rural Historic Landscapes*, (Washington, DC: US Department of the Interior, National Park Service, 1999), 3.

The design of a military installation's built environment incorporates relationships between environmental features with the necessities of the specific military mission.* The layout of any military installation is based on the relationships among the pre-existing landscape's predominant landforms, topography, climate, water bodies, and vegetation and the military's lands use requirements.† The mission and needs of the military actions dictates the spatial organization of an installation and the way the military uses the land.

Camp McCoy, a mobilization cantonment capable of housing 35,000 soldiers of the United States Army, was constructed near Sparta, Wisconsin. The layout and design of Camp McCoy in 1942 was based on the triangular plan for infantry division. Typical layout plans were prepared by Leon Zach and the Site Planning Unit of the Construction Division and designed by the architectural firm of Mead, Ward and Hunt, of Madison, WI. Although other camps and cantonments were built during the early 1940s, none was larger than Camp McCoy.

The WWII cantonment was located north of the former camp and formed a triangle (Figure 3-1). Each of the three legs of the triad was positioned to put tactical units in close proximity to their training areas. The headquarters and officers' club were prominently located in the center of the triangle surrounded by open space for parade field and recreation. Two service clubs are located at the west and east ends of the southern leg of the cantonment. The hospital complex was located east of the cantonment away from units and training. The railroad and warehouse area was located to the south of the main cantonment near the current main gate area.

Each leg of the triad was designed to accommodate a segment of a division. The northeast leg was designed for three infantry regiments. Each regiment was composed of two individual blocks and each block could accommodate eight companies. Each block was laid out along two streets with barracks lining the streets with the mess halls in the middle, the recreation buildings along the perpendicular avenues and the regiment supporting buildings to one end, and the motor pool and storage areas to the other end (Figure 3-2). The infantry training area was located northeast of

* Suzanne Keith Loechl, Susan I. Enscoe, Megan W. Tooker, and Samuel A. Batzli. *Guidelines for Identifying and Evaluating Historic Military Landscapes*. (Champaign, IL: Construction Engineering Research Laboratory), 2009, 67.

† Ibid.

this leg. The southern leg was designed for one artillery regiment, one for special troops and non-division troops. The artillery range was located south of the cantonment and rail lines. The northwest leg of the cantonment was for all non-division troops and was composed of five individual blocks.

Figure 3-1. Cantonment map of Camp McCoy, 1942 (Garner 1993, 71).

Figure 3-2. Close up of 1600 Block in southern leg of cantonment showing arrangement of barracks (red), mess halls (purple) and other buildings to motor storage area, 1941 (DPW, Fort McCoy).

1.5.2 Land use

The military mission directs how the military uses the land, making how the land is used another important landscape feature of a site. Because military installations are planned and organized to efficiently accommodate the military mission, the landscape is often utilitarian where function is prioritized over aesthetics. Most landscape changes on a military installation are related to military mission; some mission-related land use changes occur directly while others occur indirectly.* Land use areas that are directly related to the mission at Fort McCoy include the training areas and motor pools. Areas that support the military mission include the housing areas, administrative areas, recreation, retail/commercial, and education.

The design of the cantonment for Camp McCoy was based on the layout of strong land use areas. The infantry regiments were laid out along the northeast leg of the triangle, with the motor pool and training areas adjacent to the north (Figure 3-3). The non-division troops were located along

* Loechl et al. 2009, 70.

the northwest leg, with the motor storage and drill field to the north, and the special troops, artillery division, and non-division troops located along the southern leg with the motor storage, quartermaster, rail lines and artillery range to the south. The hospital was sited to the east and located away from noisy training, traffic, and troops. The headquarters and parade field were located equidistant from all legs in the center of the triangle. Each block contained barracks and mess halls in the center with the support buildings such as the officers' barracks, chapels, PX, dispensary, and field house adjacent toward the inside of the triangle. The motor pools were located to the outside of the triangle in close walking distance to the blocks. All land use areas were laid out for efficient movement of the troops, which was necessary with 36,000 men.

Figure 3-3. Layout of Camp McCoy showing land use patterns, March 1942 (*Engineering Manual of the Office of the Chief of Engineers*).

1.5.3 Transportation networks

Transportation networks on military installations are an important characteristic of military landscapes because the movement of troops and equipment is vital to the military mission. Most military transportation systems have a distinct hierarchy to facilitate efficient mobilization of troops and distribution of supplies.* In general, Army installations were planned to connect with regional systems of trails, primary and secondary roads, railroads, or navigable waterways.

* Loechl et al. 2009, 77.

The layout of the circulation and roads at Camp McCoy followed the triangular plan. The north cantonment at Camp McCoy is accessed by State Highway 21, which runs along the southern edge of the cantonment. The three legs of the triangle of the cantonment are made up of three parallel, numbered avenues. These avenues are bisected by lettered streets to subdivide the three legs into blocks. The post headquarters buildings in the center of the triangle are accessible from each of the legs: South Headquarters Avenue, West Headquarters Avenue and East Headquarters Avenue.

The design and layout of the roads was influenced by the scale and footprint of the company blocks as shown in the postcard from WWII (Figure 3-4) and to provide easy access from the units to the support and training areas. At either end of the southern leg, a curve was designed in the roads connecting the southern leg to the northeast and northwest legs. This flourish was believed to be a nod to urban and suburban planning principles of varied street patterns laid out by pioneer landscape architect Frederick Law Olmsted and others. The service clubs were prominently located in the center of these curved roads (Figure 3-5).

The railroad and rail lines were located to the south of the cantonment and connected to the Chicago and North Western Railway (acquired by Union Pacific in 1995) (Figure 3-6). The rail lines from the main track led to the warehouse area south of the cantonment with the coal yards to the south and the warehouse buildings to the north (Figure 3-7 and Figure 3-8).

Sidewalks appear to be a part of the original design and construction of Camp McCoy. Although as can be seen in early photographs and postcards, the smaller streets may have originally been dirt and while there were walks to each building door, there were not sidewalks along the streets until later (see Figure 3-4). Walkways are seen in the rear of the buildings (Figure 3-9). It is possible sidewalks along the streets in the blocks were added when the streets were paved. It is not known when that happened. It also appears that many of the sidewalks have been replaced in later years. In many areas the walkways and sidewalks go over drainage culverts alongside of the streets (Figure 3-10). Some culverts are concrete, possibly older, and others are corrugated metal (Figure 3-11 and Figure 3-12).

Figure 3-4. Historic postcard view down an unknown block at Camp McCoy, circa 1940s (ERDC-CERL Collection).

Figure 3-5. Close up of curved road at west end of southern leg and site of service club (Building 2000), 1941 (DPW, Fort McCoy).

Figure 3-6. Rail lines south of Fort McCoy cantonment, 1988 (HABS, Library of Congress).

Figure 3-7. Close up of warehouse area located to the south of the cantonment, 1941 (DPW, Fort McCoy).

Figure 3-8. Rail lines at South H Street and South 6th Avenue looking east (ERDC-CERL 2018).

Figure 3-9. Historic postcard showing walkways at rear of barracks in an unknown block, date unknown (ERDC-CERL Collection).

Figure 3-10. Sidewalks and culverts in the 1300 Block (ERDC-CERL 2018).

Figure 3-11. Older style culverts in the 2700 Block (ERDC-CERL 2018).

Figure 3-12. View showing newer sidewalks and corrugated metal culverts in the 1600 Block (ERDC-CERL 2018).

1.5.4 Expressions of military culture

Military cultural traditions are reflected on military installations through both spatial organization and design aesthetics. The military is a unique culture that values hierarchy, discipline, utility, and patriotism. These ideologies are physically reinforced in the landscape, giving military installations a distinct appearance and sense of place that makes their design easily recognizable.*

The cantonment at Fort McCoy exhibit uniformity through the size, style, and location of the buildings. Repetition of mass and scale is seen in the number of buildings, the layout and formation of the company units, regiments, and legs of the cantonment. Hierarchy is expressed through the placement of the officers' quarters relative to the barracks.

The post headquarters building (Building 100) is prominently located in the center of the triad. The post flagpole is located in front of the post headquarters as well as a prominent sign reading Fort McCoy dating to the WWII-era (Figure 3-13). The officers' club, no longer extant, was located

* Loechl et al., 2009, 73.

behind the post headquarters. The service clubs were located at either end of the southern leg, equidistant to soldiers in each leg of the triad.

At most installations a strong sense of discipline is reflected in the regular maintenance of lawns in public areas and the use of neatly trimmed evergreen plantings. From early postcards the use of these evergreens is visible. The use of foundation plantings is most visible in front of the more prominent buildings: the headquarters, service clubs, and chapels.

Figure 3-13. Photograph of Headquarters Building (100) and flagpole, 1965 (NARA College Park).

1.5.5 Building Clusters

Clusters of buildings and structures are often similar in style and function as a cohesive unit. Clusters are usually designed to create a symbiotic relationship with the buildings' exteriors and interiors relating to one another through similar scales, mass, styles, or functions.* The footprints of buildings, their masses, the spaces in between the buildings, and the circulation between buildings are integral to defining the historic landscape.

The Fort McCoy cantonment is made up of many clusters of buildings with similar function and use. The same or similar clusters are replicated across the landscape. The company buildings at Fort McCoy are designed with front and rear egress and many have connected walkways and the spaces between the buildings are used for exterior functions such as courtyards, parking, or storage areas (Figure 3-14 and Figure 3-15).

Historically, the most ubiquitous of the standardized building plans are World War II temporary buildings. While many of these temporary wood buildings have been demolished, the standardized size, scale, shape, and materials have been replicated all over the cantonment at Fort McCoy. These clusters clearly reflect the mobilization mission of Camp McCoy and the WWII period.

Today, some of these whole clusters have been demolished, specifically the 200, 300, 400, 500, and 1500 Blocks (Figure 3-16). The 1500 area was replaced by two large modern buildings (Buildings 1537 and 1538) but in the 200-500 Blocks only a few buildings remain, and the blocks are empty. These empty blocks have a large impact on the landscape in the northeast corner of the cantonment. Other clusters are missing one or two buildings, or an addition/connection has been constructed between two mess halls.

In addition, new buildings are being constructed in the company blocks. These modern buildings are typically laundromats and mess halls with large parking lots. At least one has been constructed in the firebreak, but others are being built in the motor pool and motor pool storage areas.

* Ibid, 87.

Figure 3-14. Aerial of 600 Block, 1988 (HABS, Library of Congress).

Figure 3-15. Showing close-up of 600 Block and building cluster arrangement, 2014 (DPW, Fort McCoy).

sense of discipline is reflected in the regular maintenance of lawns around the buildings and in public areas. The use of foundation plantings is most visible in front of the more prominent buildings: the headquarters, service clubs, and chapels (Figure 3-19 and Figure 3-20). Most of these plantings were evergreens, which were favored by the military since they were easily maintained, were rigid in form, and provided green color year-round. There appears that no street trees were planted at Fort McCoy during WWII. While today there are scattered street trees along South Headquarters Avenue, historic photos show no trees in this area during the period of significance (Figure 3-21).

Today there is no shrubs or foundation plantings around the barracks and mess halls and the trees are sparsely scattered around the buildings with most on the edges of the blocks near the fire breaks (Figure 3-22). Some foundation plantings remain around the most prominent building types (Figure 3-23 - Figure 3-25).

Areas of natural vegetation include in the center of the triangle, most probably areas with topography and therefore not needed for drill or recreation, and also to the north of the northeast and northwest legs of the cantonment between the motor pool and motor storage areas and the training areas (Figure 3-26).

Figure 3-17. Historic postcard showing evergreen plantings along walkways to buildings, date unknown (ERDC-CERL Collection).

Figure 3-18. Historic photograph showing trees planted around barracks in regimental block areas, date unknown (HABS, Library of Congress)

Figure 3-19. Historic postcard view showing evergreen foundation plantings around chapel (location unknown), date unknown (ERDC-CERL Collection).

Figure 3-20. View of foundation plantings around service club (Building 2000) located in the southwest corner of triad, 1978 (NARA, College Park).

Figure 3-21. View today showing scattered trees along South Headquarters Avenue toward Building 100 (ERDC-CERL, 2018).

Figure 3-22. Scattered trees adjacent to Building 2545 (ERDC-CERL, 2018).

Figure 3-23. Ornamental trees seen in front of service club (Building 2000), undergoing renovation (ERDC-CERL, 2018)

Figure 3-24. Service club (Building 905) [reconstructed in 1952] and Building 904 with foundation plantings in the southeast corner of the triad (ERDC-CERL, 2018).

Figure 3-25. Regimental commander's quarters (Building 2566) with heavy foundation plantings (ERDC-CERL, 2018).

Figure 3-26. Aerial showing large areas of vegetation and scattered trees in cantonment, 1988 (HABS, Library of Congress).

1.5.7 Small-scale features

Small-scale features can range in size and be stationary or moveable objects that often contribute to the historic character of the installation.* These features may include monuments, light poles, benches, flagpoles, fencing, or signs and can be functional or purely decorative. The pragmatic small-scale features are arranged through the site according to their use; benches, signs, and trashcans are placed where people need them while fences, lighting, and material choices subtly inform the larger landscape.

A flagpole exists in front of the post headquarters (Building 100). It was visible in many historic postcards and images (Figure 3-27). The original Fort McCoy flagpole was replaced circa 2008, but the location remains the same. A plaza was built around the flagpole prior to 1945 which included a walkway which led from Building 100 around the flagpole and a gun monument in front. A bed of white stones reading Fort McCoy was also added

* Loechl et al., 2009, 90.

prior to 1945 in front of the flagpole and gun monument. These remain to-day although the base of the flagpole is different and the bed of stones has been redefined (Figure 3-28 and Figure 3-29).

There are very few small-scale features in the Fort McCoy cantonment landscape. Very few buildings have fencing or walls (Figure 3-30 and Figure 3-31). There are some old gazebo structures that may have been used as smoking areas and new bus stop shelters scattered about (Figure 3-32 and Figure 3-33). Newer way finding signs depict the blocks and building numbers (Figure 3-34). It is a stark landscape of buildings, with little vegetation or small-scale features to detract from the mission.

Figure 3-27. View of flagpole in front of Building 100, 1961 (NARA College Park).

Figure 3-28. View of Fort McCoy sign in front of flagpole and Building 100 (ERDC-CERL, 2018).

Figure 3-29. View of flagpole and plaza in front of Building 100 (ERDC-CERL 2018).

Figure 3-30. Chain link fencing around Building 855 (ERDC-CERL, 2018).

Figure 3-31. View of bollards and chain used around museum and picnic area (ERDC-CERL, 2018).

Figure 3-32. Remnants of a gazebo in 2700 Block (ERDC-CERL, 2018).

Figure 3-33. Addition of a bus stop shelter in 2700 Block (ERDC-CERL, 2018).

Figure 3-34. Way finding signage throughout cantonment (ERDC-CERL, 2018).

1.5.8 Views and viewsheds

Views and viewsheds are intentionally designed features in a landscape. Views and viewsheds are created by landscape-scale physical elements. In the process of identifying and evaluating historic views and viewsheds, the historic physical elements are compared with the contemporary site context. Many historic views are reinforced by historic images and historic postcards.

The most noteworthy view is looking north up South Headquarters Avenue towards the post headquarters building (Building 100). Prominent in this WWII view were the post headquarters, the flagpole, and the Fort McCoy sign in white stones (Figure 3-35). Building 100 and the surrounding semi-circle of supporting buildings are still there, but the officers' club (Building 101), originally located behind Building 100, is no longer extant. The view is similar today with the addition of a few trees along the road along South Headquarters Road (Figure 3-36).

In addition, there are historic photographs and historic postcard views down the company streets (Figure 3-37). While most of the buildings are still present in the views, most have had modifications that have affected their integrity or new buildings have been constructed with in the company block (Figure 3-38 and Figure 3-39).

While there may have been historic views along the parallel streets (12th, 13th or 14th), none were found in photographs or historic postcards. It is likely the changes to the buildings plus major alterations to the motor pools have altered those views as well.

Figure 3-35. Historic postcard view towards headquarters and flagpole, circa early 1940s (DPW, Fort McCoy).

Figure 3-36. View looking north of Building 100, flagpole, and Fort McCoy sign from South Headquarters Avenue (ERDC-CERL, 2018).

Figure 3-37. Historic postcard view down an unknown regimental street, date unknown (ERDC-CERL Collection).

Figure 3-38. View down East R Street from East 12th Avenue in the 800 Block, 1988 (HABS, Library of Congress).

Figure 3-39. View looking southeast down West H Street from West 13th Avenue in the 2700 Block (ERDC-CERL 2018).

1.6 WWII temporary building features for the 800 Series

In Preservation Brief #17*, Nelson reminds readers that the Secretary of the Interior's Standards for the Treatment of Historic Properties[†] embodies two important goals: (1) the preservation of historic materials, and (2) the preservation of a building's distinguishing character. Every old building is unique, with its own identity and its own distinctive character. Character refers to all those visual aspects and physical features that comprise the appearance of every historic building. Character-defining elements include the overall shape of the building; its materials, craftsmanship, decorative details, interior spaces, and features; and various aspects of its site and environment.

* Nelson, Lee H. *National Park Service Preservation Brief 17: Architectural Character-Identifying the Visual Aspect of Historic Buildings as an Aid to Preserving their Character* (Washington, DC: U.S. Department of the Interior, National Park Service, 1998), <http://www.nps.gov/tps/how-to-preserve/briefs/17-architectural-character.htm>.

† Grimmer, Anne E. *Secretary of the Interior's Standards for the Treatment of Historic Properties with Guidelines for Preserving, Rehabilitating, Restoring and Reconstructing Historic Buildings*, Revised, (Washington, DC: U.S. Department of the Interior, National Park Service, 2017), <https://www.nps.gov/tps/standards/treatment-guidelines-2017.pdf>.

If the various materials, features, and spaces that give a building its visual character are not recognized and preserved, then essential aspects of its character may be damaged in the process of change.

A building's character can be irreversibly damaged or changed in many ways, and some ways that damage or change can occur are listed below:

- inappropriate repointing of the brickwork
- removal of a distinctive side porch
- changes to the window sash
- changes to the setting around the building
- changes to the major room arrangements
- introduction of an atrium
- painting previously unpainted woodwork, etc.

1.6.1 Exterior

The following are exterior features of WWII temporary buildings. A combination of historic and contemporary photos of various Fort McCoy buildings show examples.

Massing – generally long rectilinear and 1- or 2-story (Figure 3-40).

Figure 3-40. Detail from War Department 800 Series plans for mess hall, 1942 (Library of Congress).

Cladding material –asbestos shingle siding with scalloped bottom edge (Figure 3-41).

Figure 3-41. Asbestos shingle siding with scalloped bottom on Building 550 (ERDC-CERL, 2018).

Roofing material – red asphalt shingles (Figure 3-42).

Figure 3-42. Close-up of Camp McCoy postcard showing red asphalt roofing, 1942 (ERDC-CERL Collection).

Windows –Double-hung wood windows with multipaned sashes and wood exterior screens (Figure 3-43).

Figure 3-43. Multipaned window with screen on Building 849 (ERDC-CERL, 2018).

Window trim – simple wood architrave around windows (Figure 3-44).

Figure 3-44. Detail of wood window trim on Building 849 (ERDC-CERL, 2018).

Doors – wood with multipaned lights and panel insets and wood interior screens (Figure 3-45 and Figure 3-46).

Figure 3-45. Multipaned doors with panels below on Building 849 (ERDC-CERL, 2018).

Figure 3-46. Interior wooden screen door in Building 1129 (ERDC-CERL, 2018).

Door trim – simple wood detailing around the doors (Figure 3-47).

Figure 3-47. Wood door trim on Building 849 (ERDC-CERL, 2018).

Foundation skirting – wood slate details at the foundation (Figure 3-48).

Figure 3-48. Wood foundation skirting on Building 849 (ERDC-CERL, 2018).

Chimneys (external or internal) – red brick (Figure 3-49 and Figure 3-50).

Figure 3-49. External brick chimney on Building 629 (ERDC-CERL, 2018).

Figure 3-50. Example of an internal brick chimney at Camp McCoy, 1965 (NARA College Park, RG111SC).

Exterior steps and handrails – wood (Figure 3-51).

Figure 3-51. Example of wood steps and railing at Camp McCoy, 1951 (NARA College Park, RG111SC).

Platforms – wood (Figure 3-52–Figure 3-54).

Figure 3-52. Detail of platform and ladder from War Department 800 Series plans for barracks, 1942 (Library of Congress).

Ladders – wood (Figure 3-52 and Figure 3-53).

Figure 3-53. Detail of Camp McCoy postcard showing ladders and platforms, 1942 (ERDC-CERL Collection).

Figure 3-54. Detail of barracks showing ladders and platforms, 1950 (NARA College Park, RG111SC).

1.6.2 Interior

The following are interior features of various WWII temporary buildings. A combination of historic and contemporary photos of various Fort McCoy buildings are shown as examples.

Squad bays – open on both floors of barracks (Figure 3-55).

Figure 3-55. Example of an open squad bay in Building 1129 (ERDC-CERL, 2018).

First floor latrines in barracks (Figure 3-56–Figure 3-58).

Figure 3-56. Example of the sink area in a barracks latrine in Building 1129 (ERDC-CERL, 2018).

Figure 3-57. Example of the toilet area in a barracks latrine in Building 1129 (ERDC-CERL, 2018).

Figure 3-58. Example of the shower heads in a barracks latrine in Building 1129 (ERDC-CERL, 2018).

Noncommissioned Officer (NCO) rooms second floor in barracks (Figure 3-59).

Figure 3-59. Example of the NCO room in Building 1129 (ERDC-CERL, 2018).

Open bay in mess halls (Figure 3-60).

Figure 3-60. Open mess hall area in Building 2008 (ERDC-CERL, 2018).

Kitchen in mess halls – including all original aspects like hoods, terra cotta fire tile, sinks, serving counters, etc. (Figure 3-61).

Figure 3-61. Stove area in Building 2008 (ERDC-CERL, 2018).

Floors – bare wood floors in most interior spaces (Figure 3-62).

Figure 3-62. Bare wood floor in barracks, Building 1129 (ERDC-CERL, 2018).

Floors – concrete in latrines, kitchens, and heater rooms (Figure 3-63).

Figure 3-63. Concrete floor in the latrine of Building 550 (ERDC-CERL, 2018).

Walls – fiberboard (Figure 3-64) or fiberboard with a wood tongue-and-groove wainscot (Figure 3-65).

Figure 3-64. Fiberboard walls in Building 849 (ERDC-CERL, 2018).

Figure 3-65. Fiberboard walls with wainscoting in Building 1866 (ERDC-CERL, 2018).

Ceilings – fiberboard with wood trim (Figure 3-66).

Figure 3-66. Fiberboard ceiling in Building 550 (ERDC-CERL, 2018).

Ceiling vents – (Figure 3-67).

Figure 3-67. Ceiling vent in Building 550 (ERDC-CERL, 2018).

Heater ducts – exposed suspended metal systems (Figure 3-68).

Figure 3-68. Metal heater duct in Building 1129 (ERDC-CERL, 2018).

Ballroom – two-story area in service clubs (Figure 3-69).

Figure 3-69. Former ballroom in Building 2000 (ERDC-CERL, 2018).

Trusses – exposed wood in service club library and billiard room (Figure 3-70).

Figure 3-70. Exposed wood trusses in library of Building 2000 (ERDC-CERL, 2018).

Fireplace – red brick in service club ballroom (Figure 3-71).

Figure 3-71. Brick fireplace in Building 2000 (ERDC-CERL, 2018).

Light fixtures – pendant glass globe fixtures (see Figure 3-72).

Figure 3-72. Original glass globes for pendant light fixtures (ERDC-CERL, 2019).

2 Current Condition Buildings

A list of 786 WWII temporary buildings was given to ERDC-CERL researchers to be inventoried and evaluated based on their current condition. The researchers initially performed a windshield survey to take stock of all the buildings located within the cantonment. With such a large number of buildings to investigate, the researchers first performed a quick look at the buildings and realized there were basically three categories of condition types: mostly intact, somewhat intact, and completely modified. The researchers divided the 786 into Number 1 Type, Number 2 Type, and Number 3 Type. The photos in this chapter will give the reader a general idea of the exterior of the buildings. Type 3 buildings have had their interiors completely modified.

2.1 Number 1 Type

Number 1 Type is defined as having all original exterior construction features from the 1942 construction date including asbestos shingle siding with a scalloped bottom edge, wood sash windows and window trim, wood and divided light doors and wood trim, wood foundation skirting, roofing material type, and chimneys. The only exception of modification is to the 74-man barracks rear side where the original wood platforms and ladders have been removed. The interiors of the Number 1 Type are mostly intact with the majority of the original space and features present including squad bays, latrines, open bays in mess halls, kitchen in mess halls, wood floors, concrete floors, wood panel doors, fiberboard interior walls, exposed wood rafters, trusses and supports, and exposed and suspended mechanical system.

The researchers found 48 WWII temporary buildings that retained all the features of a Number 1 Type (Table 2-1). Please refer to individual inventory forms for more detailed descriptions and photographs for the 48 Number 1 Types.

Table 2-1. Number 1 Type WWII buildings (compiled by ERDC-CERL, 2019).

Fac. No.	Year Built	Original Use	Current Use
109	1942	Standard Storehouse, Type SH-9	Organizational Storage Building
550	1942	Fire Station	Vehicle Storage Installation
623	1942	74-Man Barracks	Transient Training Enlisted Barracks
624	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
625	1942	74-Man Barracks	Transient Training Enlisted Barracks
626	1942	Type M - 172-Man Mess Hall	General Instruction Building
627	1942	Type M - 172-Man Mess Hall	General Instruction Building
628	1942	74-Man Barracks	Transient Training Enlisted Barracks
629	1942	74-Man Barracks	Transient Training Enlisted Barracks
633	1942	Company Storehouse, Administration, and Recreation	General Instruction Building
656	1942	Dental Clinic	Battalion Headquarters Building Transient Training
848	1942	Interior Battalion Administration Building	Company Headquarters Building Transient Training
849	1942	Unit Guard House - Type Ugh-24	Company Headquarters Building Transient Training
855	1942	Company Storehouse, Administration, and Recreation Building	United States Army Reserve Center
857	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1113	1942	74-Man Barracks	Transient Training Enlisted Barracks
1114	1942	74-Man Barracks	Transient Training Enlisted Barracks
1116	1942	Type M - 152-Man Mess Hall	Physical Fitness Center
1117	1942	74-Man Barracks	Transient Training Enlisted Barracks
1118	1942	74-Man Barracks	Transient Training Enlisted Barracks
1129	1942	74-Man Barracks	Organizational Storage Building
1132	1942	Company Storehouse, Administration, and Recreation	Company Headquarters Building Transient Training
1133	1942	Company Storehouse, Administration, and Recreation	Skill Development (Na)
1153	1942	Standard Storehouse, Type SH-8	Organizational Storage Building
1154	1942	Standard Storehouse, Type SH-8	Organizational Storage Building
1232	1942	Company Storehouse, Administration, and Recreation	Organizational Storage Building
1233	1942	Company Storehouse, Administration, and Recreation	Company Headquarters Building Transient Training
1237	1942	Type M - 112-Man Mess Hall	Organizational Storage Building
1415	1942	Type M - 112-Man Mess Hall	Organizational Storage Building
1427	1942	Type M - 112-Man Mess Hall	Organizational Storage Building
1750	1942	Regimental Exchange Building	Organizational Storage Building
1866	1942	Unit Guard House - Type UGH-36	Confinement Facility
1869	1942	Recreation Building - Type RB-1	Battalion Headquarters Building
1950	1942	Interior Battalion Administration	Organizational Storage Building
2006	1942	Type M - 228-Man Mess Hall	Limit Use Instruction
2008	1942	Type M - 228-Man Mess Hall	Limit Use Instruction
2545	1942	Type M - 228-Man Mess Hall	Company Headquarters Building Transient Training
2550	1942	Type M - 228-Man Mess Hall	Company Headquarters Building Transient Training
2556	1942	G.U. Dispensary	Company Headquarters Building Transient Training
2557	1942	Recreation Building - Type RB-1	Auditorium General Purpose

Fac. No.	Year Built	Original Use	Current Use
2560	1942	Unit Guard House –Type Ugh-36	Company Headquarters Building Transient Training
2563	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
2667	1942	Recreation Building – Type RB-1	Auditorium General Purpose
2762	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
2767	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
2872	1942	Unit Guard House –Type UGH-36	Company Headquarters Building Transient Training
2873	1942	G.U. Dispensary	Company Headquarters Building Transient Training
2876	1942	Recreation Building – Type RB-1	Auditorium General Purpose

2.1.1 Living Quarters

2.1.1.1 74-man barracks

The researchers determined that there were ten 74-man barracks within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type barracks building (Figure 2-1 to Figure 2-9).

- Buildings 623, 624, 625, 628, 629, 1113, 1114, 1117, 1118, and 1129

Figure 2-1. Southwest oblique of Building 1117, 74-man barracks (ERDC-CERL, 2019).

Figure 2-2. South oblique of Building 624, 74-man barracks (ERDC-CERL, 2019).

Figure 2-3. Typical 8/8 wood-sash double-hung window, window trim, and asbestos shingle siding with scalloped bottom edge on a 74-man barracks (ERDC-CERL, 2019).

Figure 2-4. Interior view of the open bunk area in a 74-man barracks, Building 624 (ERDC-CERL, 2019).

Figure 2-5. Original built-in wooden shelving in the bunk room in a 74-man barracks, Building 624 (ERDC-CERL, 2019).

Figure 2-6. Interior view of the washroom on the first floor in Building 624, 74-man barracks (ERDC-CERL, 2019).

Figure 2-7. Interior view of the toilet room on the first floor of Building 629, 74-man barracks (ERDC-CERL, 2019).

Figure 2-8. Wooden staircase in Building 624, 74-man barracks (ERDC-CERL, 2019).

Figure 2-9. Typical interior wood panel door for 74-man barracks (ERDC-CERL, 2019).

2.1.2 Administration/Recreation Combination

3.1.1.1 Company storehouse, administration, and recreation building

The researchers determined that there were five company storehouse, administration, and recreation buildings within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type storehouse, administration, and recreation building (Figure 2-10 to Figure 2-18).

- Buildings 633, 1132, 1133, 1232 and 1233

Figure 2-10. Northwest oblique of Building 1132, company storehouse, administration, and recreation building (ERDC-CERL, 2019).

Figure 2-11. South side of Building 1132, company storehouse, administration, and recreation building (ERDC-CERL, 2019).

Figure 2-12. Original asbestos shingle siding with scalloped bottom edge, 8/8 wood window with simple window trim, and original divided-light wood panel door, on a company storehouse, administration, and recreation building (ERDC-CERL, 2019).

Figure 2-13. Original 4/4 wood-sash double-hung window, window trim, and asbestos shingle siding with a scalloped bottom edge on a company storehouse, administration, and recreation building (ERDC-CERL, 2019).

Figure 2-14. Close-up of original wood foundation skirting underneath added metal skirting (ERDC-CERL, 2019).

Figure 2-15. Interior view of the company storehouse area in a company storehouse, administration, and recreation building, Building 1133 (ERDC-CERL, 2019).

Figure 2-16. Interior view of the recreation area in a company storehouse, administration, and recreation building, Building 1133 (ERDC-CERL, 2019).

Figure 2-17. Close-up of original exposed wood rafters and wallboard interior walls in a company storehouse, administration, and recreation building, Building 1133 (ERDC-CERL, 2019).

Figure 2-18. Original wood divided-light and panel interior doors and wood steps leading from the storehouse area to the recreation area in a company storehouse, administration, and recreation building, Building 1133 (ERDC-CERL, 2019).

3.1.1.1 Company storehouse, administration, and recreation building [MOD}

There was a modification of the company storehouse, administration, and recreation buildings that were constructed at Camp McCoy in 1942. These buildings had the same overall design and function as the previous described company storehouse, administration, and recreation buildings except for the single roof ridge instead of two different roof heights. No HABS documentation was found on this built structure. Figure 2-19 to Figure 2-25 show the design, layout, and materials used to construct these buildings.

The researchers determined that there were two of the company storehouse, administration, and recreation building modified type within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type bachelor officers' quarters.

- Buildings 855 and 857

Figure 2-19. Northeast oblique of Building 857, company storehouse, administration, and recreation building (ERDC-CERL, 2019).

Figure 2-20. Southwest oblique of Building 857, company storehouse, administration, and recreation building (ERDC-CERL, 2019).

Figure 2-21. Original 4/4 and 8/8 wood-sash double-hung windows with wooden screens and a simple architrave and original asbestos shingle siding with a scalloped bottom edge on company storehouse, administration, and recreation building type (ERDC-CERL, 2019).

Figure 2-22. Original wood sliding door on company storehouse, administration, and recreation building type (ERDC-CERL, 2019).

Figure 2-23. Original divided-light wood panel exterior door on company storehouse, administration, and recreation building type (ERDC-CERL, 2019).

Figure 2-24. Interior view of the administration space in company storehouse, administration, and recreation building type (ERDC-CERL, 2019).

Figure 2-25. Original globe ceiling fixture in company storehouse, administration, and recreation building type (ERDC-CERL, 2019).

2.1.3 Administration Buildings

2.1.3.1 Administration building – Type IBA-1

The researchers determined that there were two of the interior battalion administration buildings, Type IBA-1, within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-26 to Figure 2-31).

- Buildings 848 and 1950

Figure 2-26. Northeast oblique of Building 848, interior battalion administration building, Type IBA-1 (ERDC-CERL, 2019).

Figure 2-27. Southwest oblique of Building 848, interior battalion administration building, Type IBA-1 (ERDC-CERL, 2019).

Figure 2-28. Original 8/8 wood-sash double-hung window with wooden screen and simple architrave on an interior battalion administration building, Type IBA-1 (ERDC-CERL, 2019).

Figure 2-29. Original divided-light and wood panel door with concrete porch on an interior battalion administration building, Type IBA-1 (ERDC-CERL, 2019).

Figure 2-30. Original set of divided-light and wood panel exterior doors leading into the heater room, concrete block foundation of the heater room, and wood foundation skirting of the pier foundation for an interior battalion administration building, Type IBA-1 (ERDC-CERL, 2019).

Figure 2-31. Original asbestos shingle siding with a scalloped bottom edge and wood foundation skirting on an interior battalion administration building, Type IBA-1 (ERDC-CERL, 2019).

2.1.3.2 Unit guard house – Type UGH-24

The researchers determined that there was one-unit guard house, Type UGH-24 within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-32 to Figure 2-38).

- Building 849

Figure 2-32. Northeast oblique of Building 849, unit guard house, Type UGH-24 (ERDC-CERL, 2019).

Figure 2-33. Southwest oblique of Building 849, unit guard house, Type UGH-24 (ERDC-CERL, 2019).

Figure 2-34. Original 8/8 wood-sash double-hung window with wooden screen and simple architrave of a unit guard house, Type UGH-24 (ERDC-CERL, 2019).

Figure 2-35. Original divided-light and wood panel exterior door with a concrete porch and cast-iron handrails on a unit guard house, Type UGH-24 (ERDC-CERL, 2019).

Figure 2-36. Original set of divided-light and wood panel exterior doors leading into the heater room of a unit guard house, Type UGH-24 (ERDC-CERL, 2019).

Figure 2-37. Original asbestos shingle siding with a scalloped bottom edge, concrete block foundation of the heater room, and wood foundation skirting of a unit guard house, Type UGH-24 (ERDC-CERL, 2019).

Figure 2-38. Interior view of the guard room looking towards the corridor, heater room, and toilet room in a unit guard house, Type UGH-24 (ERDC-CERL, 2019).

2.1.3.3 Unit guard house – Type UGH-36

The researchers determined that there were three of the unit guard house, Type UGH-36, within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-39 to Figure 2-50).

- Buildings 1866, 2560, and 2872

Figure 2-39. West oblique of Building 2560, unit guard house, Type UGH-36 (ERDC-CERL, 2019).

Figure 2-40. East oblique of Building 2560, unit guard house, Type UGH-36 (ERDC-CERL, 2019).

Figure 2-41. Original 8/8 wood-sash double-hung window with wooden screen and a simple wood architrave on a unit guard house, Type UGH-36 (ERDC-CERL, 2019).

Figure 2-42. Original set of divided-light and wood panel exterior doors, concrete porch, and cast-iron handrails on a unit guard house, Type UGH-36 (ERDC-CERL, 2019).

Figure 2-43. Original asbestos shingle siding with a scalloped bottom edge on a unit guard house, Type UGH-36 (ERDC-CERL, 2019).

Figure 2-44. Original wood foundation skirting on a unit guard house, Type UGH-36 (ERDC-CERL, 2019).

Figure 2-45. Original interior view of the open guard space in a unit guard house, Type UGH-36 (ERDC-CERL, 2019).

Figure 2-46. Interior view in the corridor leading into the guard space in a unit guard house, Type UGH-36 (ERDC-CERL, 2019).

Figure 2-47. Interior view of a toilet room with original tongue-and-groove walls, concrete floor, and fixtures (ERDC-CERL, 2019).

Figure 2-48. Original standard five-panel wood interior door in a unit guard house, Type UGH-36 (ERDC-CERL, 2019).

Figure 2-49. Original standard divided-light and wood panel interior door leading from corridor into the guard space in a unit guard house, Type UGH-36 (ERDC-CERL, 2019).

Figure 2-50. Original exposed suspended mechanical ducts in a unit guard house, Type UGH-36 (ERDC-CERL, 2019).

2.1.4 Recreation Buildings

2.1.4.1 Recreation building – gymnasium (RB-1)

The researchers determined that there were four recreation buildings, Type RB-1, within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-51 to Figure 2-61).

- Buildings 1869, 2557, 2667, and 2876

Figure 2-51. Oblique of a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019).

Figure 2-52. Oblique of a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019).

Figure 2-53. Original 8/8 wood-sash double-hung windows, wooden screen, simple wood architrave, and asbestos shingle siding with a scalloped bottom edge on a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019).

Figure 2-54. Original paired 8/8 wood-sash double-hung windows, wooden screen, and a simple wood architrave, recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019).

Figure 2-55. Original set of divided-light and wood panel entry doors and simple wood door surround on a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019).

Figure 2-56. Original divided-light and wood panel door, concrete porch, and cast-iron handrails on a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019).

Figure 2-57. Original wooden interior screen door on a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019).

Figure 2-58. Original wooden foundation skirting on a recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019).

Figure 2-59. Interior view of the open recreation area in the recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019).

Figure 2-60. Looking towards the main vestibule space in the recreation building Type RB-1, Building 2557 (ERDC-CERL, 2019).

Figure 2-61. Original standard five-panel wood interior door in a recreation building Type RB-1 type, Building 2557 (ERDC-CERL, 2019).

2.1.5 Mess Halls

2.1.5.1 Type M-112-man mess halls

The researchers determined that there were three Type M-112 Mess halls within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-62 to Figure 2-63).

- Buildings 1237, 1415, and 1427

Figure 2-62. Oblique of Building 1237, 112-man mess hall (ERDC-CERL, 2019).

Figure 2-63. Interior view of dining area in a 112-man mess hall, Building 1237 (ERDC-CERL, 2019).

2.1.5.2 Type M-152-man mess halls

The researchers determined that there was one Type M-152 Mess halls within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-64 to Figure 2-65).

- Building 1116

Figure 2-64. Oblique of Building 1116, 152-man mess hall (ERDC-CERL, 2019).

Figure 2-65. Interior view of from kitchen area to the dining area in a 152-man mess hall, Building 1116 (ERDC-CERL, 2019).

2.1.5.3 Type M-172-man mess halls

The researchers determined that there were two Type M-172 Mess halls within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-66 to Figure 2-70).

- Buildings 626 and 627

Figure 2-66. Oblique of Building 627, 172-man mess hall (ERDC-CERL, 2019).

Figure 2-67. Original asbestos shingle siding with scalloped bottom edge and original wooden foundation skirting on Building 627, 172-man mess hall (ERDC-CERL, 2019).

Figure 2-68. Interior view of kitchen area in Building 627, 172-man mess hall looking at the glazed tile wall where the stove and ovens would have been located (ERDC-CERL, 2019).

Figure 2-69. Interior view of the kitchen area in Building 627, 172-man mess hall looking at the original washing station (ERDC-CERL, 2019).

Figure 2-70. Interior view of dining area in a 172-man mess hall, Building 627 (ERDC-CERL, 2019).

2.1.5.4 Type M-228-man mess halls

The researchers determined that there were seven Type M-228 Mess halls within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-71 to Figure 2-73).

- Buildings 2006, 2008, 2545, 2550, 2563, 2762, and 2767

Figure 2-71. Oblique of Building 2006, 228-man mess hall (ERDC-CERL, 2019).

Figure 2-72. Interior view of from kitchen area to the dining area in a 228-man mess hall, Building 2008 (ERDC-CERL, 2018).

Figure 2-73. Typical interior wood panel door leading into the storeroom room (ERDC-CERL, 2019).

2.1.6 Storehouse Buildings

3.1.1.2 Standard storehouse – Type SH-8

The researchers determined that there were two of the standard storehouse buildings, Type SH-8, within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-74 to Figure 2-79).

- Buildings 1153 and 1154

Figure 2-74. Front side of a standard storehouse building, Type SH-8, Building 1153 (ERDC-CERL, 2019). (ERDC-CERL, 2019).

Figure 2-75. Oblique of a standard storehouse building, Type SH-8, Building 1153 (ERDC-CERL, 2019).

Figure 2-76. Oblique of a standard storehouse building, Type SH-8, Building 1153 (ERDC-CERL, 2019).

Figure 2-77. Original 8/8 wood-sash double-hung window, simple wood architrave, and asbestos shingle siding with a scalloped bottom edge for a standard storehouse, Type SH-8, Building 1153 (ERDC-CERL, 2019).

Figure 2-78. Original wood sliding door and metal track for a standard storehouse, Type SH-8, Building 1153 (ERDC-CERL, 2019).

Figure 2-79. Interior view of a of a standard storehouse building, Type SH-8, Building 1153 (ERDC-CERL, 2019).

3.1.1.3 *Standard storehouse – Type SH-9*

The researchers determined that there was one of the standard storehouse buildings, Type SH-9, within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-80 to Figure 2-84).

- Building 109

Figure 2-80. Front side of a standard storehouse, Type SH-9, Building 109 (ERDC-CERL, 2019).

Figure 2-81. Oblique of a standard storehouse, Type SH-9 (ERDC-CERL, 2019).

Figure 2-82. Original 8/8 wood-sash double-hung window, simple wood architrave, and asbestos shingle siding for a standard storehouse, Type SH-9, Building 109 (ERDC-CERL, 2019).

Figure 2-83. Original wood sliding door and metal track for a standard storehouse, Type SH-9, Building 109 (ERDC-CERL, 2019).

Figure 2-84. Interior view of the open space in a standard storehouse, Type SH-9, Building 109 (ERDC-CERL, 2019).

2.1.7 Support Buildings

2.1.7.1 G.U. Dispensary – Type G.U.D.-1

The researchers determined that there were two of the G.U. dispensary, Type G.U.D.-1, within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-85 to Figure 2-97).

- Buildings 2556 and 2873

Figure 2-85. Oblique of a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019).

Figure 2-86. Oblique of a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019).

Figure 2-87. Oblique of a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019).

Figure 2-88. Original 8/8 wood-sash double-hung windows, wooden screen, simple wood architrave, and asbestos shingle siding for a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019).

Figure 2-89. Original divided-light and wood panel entry door with wooden screen door for a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019).

Figure 2-90. Original set of divided-light and wood panel doors leading into the heater room for a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019).

Figure 2-91. Original wooden foundation skirting and concrete pier foundation for a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019).

Figure 2-92. Interior view of the original waiting room in a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019).

Figure 2-93. Original corridor with wood flooring and horizontal plank wainscoting on the walls in a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019).

Figure 2-94. Original wood built-ins and cabinets in a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019).

Figure 2-95. Original standard five-panel wood interior door in a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019).

Figure 2-96. Treatment Room in a G.U. dispensary, Type G.U.D.-1, Building 2556, (ERDC-CERL, 2019).

Figure 2-97. Original standard glass globe ceiling fixture in a G.U. dispensary, Type G.U.D.-1, Building 2556 (ERDC-CERL, 2019).

2.1.7.2 Dental Clinic

The researchers determined that there was one dental clinic, Type DC-1, within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-98 to Figure 2-105).

- Building 656

Figure 2-98. Oblique of a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019).

Figure 2-99. Rear side of a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019).

Figure 2-100. Original 8/8 wood-sash double-hung windows with a simple architrave and brick chimney stack for a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019).

Figure 2-101. Original divided-light and wood panel exterior door and asbestos shingle siding with a scalloped bottom edge with a concrete porch and cast-iron handrails, for a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019).

Figure 2-102. Original set of divided-light and wood panel exterior doors leading into the heater room, and concrete block foundation for a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019).

Figure 2-103. Original wooden foundation skirting for a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019).

Figure 2-104. Interior view of the open general treatment room on the second floor of the dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019).

Figure 2-105. Interior wood switchback staircase in a dental clinic, Type DC-1, Building 656 (ERDC-CERL, 2019).

2.1.7.3 Regimental exchange

The researchers determined that there was one regimental exchange within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-106 to Figure 2-111).

- Building 1750

Figure 2-106. Oblique of Building 1750, regimental exchange (Fort McCoy, 2020).

Figure 2-107. Oblique of regimental exchange, Building 1750 (Fort McCoy, 2020).

Figure 2-108. Original divided-light and wood panel doors with a concrete stoop and cast-iron metal handrails on a regimental exchange, Building 1750 (Fort McCoy, 2020).

Figure 2-109. Original wooden foundation skirting and replacement in-kind asbestos shingle siding on regimental exchange, Building 1750 (Fort McCoy, 2020).

Figure 2-110. Replacement divided-light vinyl window and replacement metal security screen on the regimental exchange, Building 1750 (Fort McCoy, 2020).

Figure 2-111. Interior view of open exchange space in regimental exchange building, Building 1750 (Fort McCoy, 2020).

2.1.7.4 Fire station

The researchers determined* that there was one fire station within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-112).

- Building 550

Figure 2-112. Southwest oblique of fire station, Building 550 (ERDC-CERL, 2019).

* Building 550 was determined eligible in the *Determination of NRHP Eligibility for 26 Buildings at Fort McCoy, Wisconsin (2018)* report. It is repeated here to be consistent in covering all WWII-era buildings.

2.2 Number 2 Type

Number 2 Type is defined as having most of the original exterior features from the 1942 construction date such as footprint, massing, asbestos shingle siding with a scalloped or squared bottom edge, and roofing material. However, the original wood-sash windows, divided-light and wood panel door, and wooden foundation skirting have been removed and replaced with newer materials. The interiors of the Number 2 Type have some features intact, but most have been modified with new finishes and spaces; all interiors were checked, but not all were photographed. The researchers found 209 WWII temporary buildings that retained the features of a Number 2 Type (see Table 2-2).

Table 2-2. Table of Number 2 Type buildings (compiled by ERDC-CERL, 2019).

Fac, No.	Year Built	Original Use	Current Use
100	1942	Post Administration Building, Division Headquarters	Post Administration Building, Division Headquarters
104	1942	Administration	Brigade Headquarters Building Transient Training
105	1942	Brigade General Quarters	Recreation Billets
106	1942	Type M – 152-Man Mess Hall	Company Headquarters Building Transient Training
107	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers' Quarters
108	1942	Brigade General Quarters	Unaccompanied Officers' Quarters Military
451	1942	Officers' Quarters – Type BOQ-44	Training Collective UH
452	1942	Officers' Quarters – Type BOQ-44	Training Collective UH
453	1942	Officers' Quarters – Type BOQ-44	Training Collective UH
454	1942	Officers' Quarters – Type BOQ-44	Training Collective UH
547	1942	Grease Rack Enclosure Building	Vehicle Storage Installation
601	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
621	1942	Company Storehouse, Administration, and Recreation Building	Unaccompanied Personal Housing Laundry Detached
622	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
638	1942	Company Storehouse, Administration, and Recreation	General Instruction Building
639	1942	Type M – 152-Man Mess Hall	Dining Facility Transient Training
640	1942	74-Man Barracks	Transient Training Enlisted Barracks
641	1942	74-Man Barracks	Transient Training Enlisted Barracks
642	1942	74-Man Barracks	Transient Training Enlisted Barracks
659	1942	Brigade General's Quarters – Type BGQ-1	Recreational Billets
743	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
839	1942	Type M – 112-Man Mess Hall	Heritage Center Facility
840	1942	74-Man Barracks	Heritage Center Facility

Fac, No.	Year Built	Original Use	Current Use
841	1942	74-Man Barracks	Heritage Center Facility
842	1942	74-Man Barracks	Heritage Center Facility
843	1942	Company Storehouse, Administration, and Recreation Building	Heritage Center Facility
851	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers' Quarters
852	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers' Quarters
853	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers' Quarters
901	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets
902	1942	Administration	Heritage Center Facility
903	1942	Recreation Building – Type RB-2	Heritage Center Facility
904	1942	Bachelor Officers' Quarters - 700-Series, Type OQ-23	Transient Training Officers Quarters
1105	1942	74-Man Barracks	Transient Training Enlisted Barracks
1121	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building
1130	1942	74-Man Barracks	Transient Training Enlisted Barracks
1145	1942	Administration	Brigade Headquarters Building Transient Training
1152	1942	Grease Rack Enclosure Building	Engineering/Housing Maintenance
1201	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1203	1942	74-Man Barracks	Transient Training Enlisted Barracks
1204	1942	74-Man Barracks	Transient Training Enlisted Barracks
1205	1942	Type M – 112-Man Mess Hall	Miscellaneous Facilities, Detached
1206	1942	Type M – 112-Man Mess Hall	Company Headquarters Building Transient Training
1207	1942	Type M – 112-Man Mess Hall	Brigade Headquarters Building Transient Training
1208	1942	74-Man Barracks	Transient Training Enlisted Barracks
1209	1942	74-Man Barracks	Transient Training Enlisted Barracks
1210	142	74-Man Barracks	Transient Training Enlisted Barracks
1211	1942	Company Storehouse, Administration, and Recreation Building	Eng/Housing Maintenance
1213	1942	74-Man Barracks	Transient Training Officers Quarters
1214	1942	74-Man Barracks	Transient Training Enlisted Barracks
1215	1942	Type M – 172-Man Mess Hall	Company Headquarters Building Transient Training
1216	1942	Type M – 112-Man Mess Hall	Brigade Headquarters Building Transient Training
1217	1942	74-Man Barracks	Transient Training Enlisted Barracks
1221	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1222	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1224	1942	74-Man Barracks	Training Collective UH
1225	1942	74-Man Barracks	Training Collective UH
1229	1942	74-Man Barracks	Transient Training Enlisted Barracks
1230	1942	74-Man Barracks	Transient Training Enlisted Barracks
1231	1942	74-Man Barracks	Transient Training Enlisted Barracks
1235	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac, No.	Year Built	Original Use	Current Use
1236	1942	74-Man Barracks	Transient Training Enlisted Barracks
1239	1942	74-Man Barracks	Transient Training Enlisted Barracks
1243	1942	Recreation Building – Type RB-2	Battalion Headquarters Building Transient Training
1244	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1246	1942	G.U. Dispensary	Company Headquarters Building Transient Training
1247	1942	Brigade General's Quarters – Type BGQ-1	Recreation Bilets
1248	1942	Type M – 152-Man Mess Hall	Company Headquarters Building Transient Training
1249	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
1250	1942	Officers' Quarters – Type BOQ-44	Training Collective UH
1251	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
1254	1942	Administration	Battalion Headquarters Building Transient Training
1256	1942	Regimental Exchange Building	General Instruction Building
1257	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1258	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1260	1942	Motor Repair Shop	Organizational Storage Building
1261	1942	Motor Repair Shop	Organizational Storage Building
1262	1942	Motor Repair Shop	Organizational Storage Building
1263	1942	Standard Storehouse – Type SH-8	Organizational Storage Building
1264	1942	Standard Storehouse – Type SH-9	Organizational Storage Building
1265	1942	Standard Storehouse – Type SH-8	Organizational Storage Building
1301	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1304	1942	74-Man Barracks	Transient Training Enlisted Barracks
1305	1942	74-Man Barracks	Transient Training Enlisted Barracks
1308	1942	74-Man Barracks	Transient Training Enlisted Barracks
1311	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1315	1942	Type M – 112-Man Mess Hall	General Instruction Building
1316	1942	Type M – 112-Man Mess Hall	General Instruction Building
1324	1942	74-Man Barracks	Transient Training Enlisted Barracks
1325	1942	74-Man Barracks	Transient Training Enlisted Barracks
1326	1942	Type M – 112-Man Mess Hall	General Instruction Building
1327	1942	Type M – 112-Man Mess Hall	General Instruction Building
1328	1942	Type M – 112-Man Mess Hall	General Instruction Building
1337	1942	Type M – 152-Man Mess Hall	General Instruction Building
1338	1942	Type M – 112-Man Mess Hall	General Instruction Building
1339	1942	74-Man Barracks	Transient Training Enlisted Barracks
1343	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1344	1942	Company Storehouse, Administration, and Recreation Building	Drug/Alcohol Abuse Building
1345	1942	Administration	Brigade Headquarters Building Transient Training

Fac, No.	Year Built	Original Use	Current Use
1346	1942	G. U. Dispensary	Brigade Headquarters Building Transient Training
1347	1942	Infirmary	Company Headquarters Building Transient Training
1348	1942	Unit Guard House – Type Ugh-24	Brigade Headquarters Building Transient Training
1349	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1359	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1401	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1404	1942	74-Man Barracks	Transient Training Enlisted Barracks
1405	1942	Type M – 112-Man Mess Hall	General Instruction Building
1406	1942	Type M – 112-Man Mess Hall	General Instruction Building
1407	1942	74-Man Barracks	Transient Training Enlisted Barracks
1408	1942	74-Man Barracks	Transient Training Enlisted Barracks
1409	1942	74-Man Barracks	Transient Training Enlisted Barracks
1411	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1413	1942	74-Man Barracks	Transient Training Enlisted Barracks
1414	1942	74-Man Barracks	Transient Training Enlisted Barracks
1416	1942	Type M – 112-Man Mess Hall	Organizational Storage Building
1417	1942	74-Man Barracks	Transient Training Enlisted Barracks
1424	1942	74-Man Barracks	Transient Training Enlisted Barracks
1425	1942	74-Man Barracks	Transient Training Enlisted Barracks
1426	1942	74-Man Barracks	Transient Training Enlisted Barracks
1428	1942	Type M – 112-Man Mess Hall	General Instruction Building
1429	1942	74-Man Barracks	Transient Training Enlisted Barracks
1435	1942	74-Man Barracks	General Instruction Building
1436	1942	74-Man Barracks	Transient Training Enlisted Barracks
1439	1942	74-Man Barracks	Transient Training Enlisted Barracks
1440	1942	74-Man Barracks	General Instruction Building
1441	1942	74-Man Barracks	Transient Training Enlisted Barracks
1443	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building
1444	1942	Company Storehouse, Administration, and Recreation Building	Unaccompanied Personal Housing Laundry Detached
1445	1942	Post Exchange	General Instruction Building
1446	1942	Administration	Brigade Headquarters Building Transient Training
1447	1942	Unit Guard House – Type UGH-12	General Instruction Building
1448	1942	Recreation Building - Gymnasium	Auditorium General Purpose
1643	1942	Company Storehouse, Administration, and Recreation Building	Arms Storage-Battalion
1646	1942	Company Storehouse, Administration, and Recreation Building	Exchange Branch
1647	1942	Recreation Building – Type RB-4	Brigade Headquarters Building Transient Training
1648	1942	Administration	Company Headquarters Building Transient Training

Fac, No.	Year Built	Original Use	Current Use
1649	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1653	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training
1654	1942	Company Storehouse, Administration, and Recreation Building	Print Plant
1656	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets
1657	1942	Officers' Quarters – Type BOQ-44	Unaccompanied Personal Housing Senior Non-Commissioned Officer
1658	1942	Officers' Quarters – Type BOQ-44	Recreation Billets
1659	1942	Vehicle Storage Building	Organizational Storage Building
1660	1942	Officers' Quarters – Type BOQ-44	Recreation Billets
1661	1942	Officers' Quarters – Type BOQ-44	Recreation Billets
1662	1942	Bachelor Officers' Quarters - 700-Series, Type OQ-23	Transient Training Officers Quarters
1663	1942	G.U. Dispensary	Exchange Service Outlet
1664	1942	Infirmary	Company Headquarters Building Transient Training
1701	1942	Company Storehouse, Administration, and Recreation Building	Unaccompanied Personal Housing Laundry Detached
1720	1942	74-Man Barracks	Transient Training Enlisted Barracks
1721	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1722	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1744	1942	74-Man Barracks	Transient Training Enlisted Barracks
1745	1942	Administration	Child Development Center Under 6 Years
1747	1942	Company Storehouse, Administration, and Recreation Building	Child Development Center Under 6 Years
1748	1942	Unit Guard House – Type Ugh-36	Battalion Headquarters Building Transient Training
1749	1942	G. U. Dispensary	Company Headquarters Building Transient Training
1751	1942	Recreation Building – Type RB-4	Battalion Headquarters Building Transient Training
1753	1942	Administration	Company Headquarters Building Transient Training
1754	1942	Regimental Commander's Quarters – Type RCQ-1	Child Development Center Under 6 Years
1755	1942	Administration	Battalion Headquarters Building Transient Training
1756	1942	Type M – 228-Man Mess Hall	Organizational Storage Building
1757	1942	Recreation Building – Type RB-4	Battalion Headquarters Building Transient Training
1758	1942	Recreation Building - Gymnasium	Auditorium General Purpose
1759	1942	Regimental Chapel	Chapel
1853	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets
1858	1942	Officers' Quarters – Type BOQ-44	Recreation Billets
1859	1942	Officers' Quarters – Type BOQ-44	Recreation Billets
1862	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
1865	1942	G. U. Dispensary	Company Headquarters Building Transient Training
1868	1942	Post Exchange	Battalion Headquarters Building Transient Training
1921	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training

Fac, No.	Year Built	Original Use	Current Use
1922	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1932	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
1943	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1945	1942	Administration	Company Headquarters Building Transient Training
1946	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building
1947	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building
1948	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1949	1942	Type M – 228-Man Mess Hall	Organizational Storage Building
2001	1942	Regimental Exchange Building	Brigade Headquarters Building Transient Training
2009	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
2010	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
2011	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
2168	1942	Administration	Administration General Purpose
2448	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets
2544	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2566	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets
2611	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2644	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2657	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2658	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2659	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2660	1942	Administration	Company Headquarters Building Transient Training
2662	1942	Company Storehouse, Administration, and Recreation Building	Exchange Branch
2663	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2664	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2666	1942	Officers' Quarters – Type BOQ-40	Battalion Headquarters Building Transient Training
2711	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2765	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2770	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2772	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
2774	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters

Fac, No.	Year Built	Original Use	Current Use
2775	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters
2780	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets
2832	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2833	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2864	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2865	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training

2.2.1 Living Quarters

2.2.1.1 74-man barracks

The researchers determined that there were 49 74-man barracks within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type barracks building (Figure 2-113 to Figure 2-114).

- Buildings 640, 641, 642, 840, 841, 842, 1105, 1130, 1203, 1204, 1208, 1209, 1210, 1213, 1214, 1217, 1224, 1225, 1229, 1230, 1231, 1235, 1236, 1239, 1304, 1305, 1308, 1324, 1325, 1339, 1404, 1407, 1408, 1409, 1413, 1414, 1417, 1424, 1425, 1426, 1429, 1435, 1436, 1439, 1440, 1441, 1720, 1744, and 1932

Figure 2-113. Oblique of a 74-man barracks, Building 1209 (ERDC-CERL).

Figure 2-114. Oblique of a 74-man barracks, Building 1209 (ERDC-CERL, 2019).

2.2.1.2 Officers' quarters – Type BOQ-40

The researchers determined that there was one officers' quarters, Type BOQ-40, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type officers' quarters (Figure 2-115).

- Building 2666

Figure 2-115. Oblique of an officers' quarters, Type BOQ-40, Building 2666, (ERDC-CERL, 2019).

2.2.1.3 Officers' quarters – Type BOQ-44

The researchers determined that there were 24 officers' quarters, Type BOQ-44, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type quarters building. The end side on several of the quarters has been modified from three windows with the removal of the middle window on the first and second floors (Figure 2-116 to Figure 2-117).

- Buildings 107, 451, 452, 453, 454, 851, 852, 853, 1249, 1250, 1251, 1657, 1658, 1660, 1661, 1858, 1859, 1862, 2009, 2010, 2011, 2772, 2774, and 2775

Figure 2-116. Oblique of an officers' quarters, Type BOQ-44, Building 452, (ERDC-CERL, 2019).

Figure 2-117. Oblique of an officers' quarters, Type BOQ-44, Building 1250, (ERDC-CERL, 2019).

2.2.1.4 Bachelor officers' quarters – 700 Series, Type OQ-23

The researchers determined that there were two 700 Series bachelor officers' quarters, Type OQ-23 within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type quarters building (Figure 2-118).

- Buildings 904 and 1662

Figure 2-118. Oblique of a 700 Series bachelor officers' quarters, Type OQ-23, Building 904 (ERDC-CERL, 2019).

2.2.1.5 *Brigade general quarters – Type BGQ-1*

The researchers determined that there were four brigade general quarters, Type BGQ-1, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type quarters building (Figure 2-119).

- Buildings 105, 108, 659, and 1247

Figure 2-119. Rear side of a brigade general quarters, Type BGQ-1, Building 659 (ERDC-CERL, 2019).

2.2.1.6 *Regimental commander's quarters – Type RCQ-1*

The researchers determined that there were seven regimental commander's quarters, Type RCQ-1, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type quarters building (Figure 2-120 to Figure 2-121).

- Buildings 901, 1656, 1754, 1853, 2448, 2566, and 2780

Figure 2-120. Front side of a regimental commander's quarters, Type RCQ-1, Building 1754 (ERDC-CERL, 2019).

Figure 2-121. Typical modified interior of a regimental commander's quarters, Type RCQ-1, Building 1754 (ERDC-CERL, 2019).

2.2.2 Administration/Recreation Combination Buildings

2.2.2.1 Company storehouse, administration, and recreation building

The researchers determined that there were 49 company storehouse, administration, and recreation buildings within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-122 to Figure 2-123).

- Buildings 601, 621, 622, 638, 743, 843, 1121, 1201, 1211, 1221, 1222, 1244, 1257, 1258, 1301, 1311, 1343, 1344, 1349, 1359, 1401, 1411, 1443, 1444, 1643, 1649, 1654, 1701, 1721, 1722, 1747, 1921, 1922, 1943, 1946, 1947, 1948, 2544, 2611, 2644, 2657, 2658, 2659, 2662, 2663, 2664, 2711, 2765, and 2770

Figure 2-122. Rear and side view of a company storehouse, administration, and recreation building, Building 1201 (ERDC-CERL, 2019).

Figure 2-123. Front and side view of a company storehouse, administration, and recreation building, Building 1211 (ERDC-CERL, 2019).

3.1.1.1 Company storehouse, administration, and recreation building [MOD]

The researchers determined that there were five company storehouse, administration, and recreation that are the modified version of this type of

building within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-124).

Buildings 1646, 2832, 2833, 2864, and 2865

Figure 2-124. South oblique of a one roof version of, company storehouse, administration, and recreation building, Building 2832 (ERDC-CERL, 2019).

2.2.3 Administration Buildings

2.2.3.1 Post administration building, Division Headquarters, Type DHQ-1

The researchers determined that there was one division headquarters [used as the Post Headquarters], Type DHQ-1, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-125).

- Building 100

Figure 2-125. Front side of a division headquarters [Post Headquarters], Type DHQ-1, Building 100 (ERDC-CERL, 2019).

2.2.3.2 Administration building – Type IBA-1

The researchers determined that there were five of the interior battalion administration buildings, Type IBA-1, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-126).

- Building 1446, 1648, 1745, 1753, and 2660

Figure 2-126. Front side of an administration building, Type IBA-1, Building 1446 (ERDC-CERL, 2019).

2.2.3.3 Administration building – Type A-3

The researchers determined that there were three administration building Type A-3 within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-127).

- Buildings 1145, 1254, and 1345

Figure 2-127. Oblique of an administration building, Type A-3, Building 1254 (ERDC-CERL, 2019).

2.2.3.4 Administration building – Type A-10

The researchers determined that there were five administration building Type A-10 within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-128).

- Buildings 104, 902, 1755, and 1945, and 2168

Figure 2-128. Oblique of an administration building, Type A-10, Building 2168 (ERDC-CERL, 2019).

2.2.3.5 Unit guard house, Type UGH-12

The researchers determined that there was one-unit guard house, Type UGH-12, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building.

- Building 1447

2.2.3.6 Unit guard house – Type UGH-24

The researchers determined that there was one-unit guard house, Type UGH-24, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building.

- Building 1348

Figure 2-129. Front side of recreation building, gymnasium, Building 1448, (ERDC-CERL, 2019).

2.2.3.7 Unit guard house – Type UGH-36

The researchers determined that there was one-unit guard house, Type UGH-36, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-130).

- Building 1748

Figure 2-130. Oblique of a unit guard house, Type UGH-36, Building 1748 (ERDC-CERL, 2019).

2.2.4 Recreation Buildings

2.2.4.1 Recreation building – gymnasium (RB-1)

The researchers determined that there were two recreation buildings, Type RB-1, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-131).

- Buildings 1448 and 1758

Figure 2-131. Front side of recreation building, gymnasium, Building 1448, (ERDC-CERL, 2019).

2.2.4.2 Recreation building – Type RB-2

The researchers determined that there were two recreation buildings, Type RB-2, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-132).

- Buildings 903 and 1243

Figure 2-132. Oblique of a recreation building, Type RB-2, Building 1243 (ERDC-CERL, 2019).

3.1.1.1 Recreation building – Type RB-4

The researchers determined that there were four recreation buildings, Type RB-4, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-133).

- Buildings 1647, 1653, 1751, and 1757

Figure 2-133. Front side of a recreation building, Type RB-4, Building 1653 (ERDC-CERL, 2019).

2.2.5 Mess Halls

2.2.5.1 Type M-112-man mess halls

The researchers determined that there were fifteen Type M-112 Mess halls within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-134 to Figure 2-135).

- Buildings 839, 1205, 1206, 1207, 1216, 1315, 1316, 1326, 1327, 1328, 1338, 1405, 1406, 1416, and 1428

Figure 2-134. Oblique of a 112-man mess hall, Building 1205 (ERDC-CERL, 2019).

Figure 2-135. Oblique of a 112-man mess hall, Building 1206 (ERDC-CERL, 2019).

2.2.5.2 Type M-152-man mess halls

The researchers determined that there were four Type M-152 Mess halls within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-136).

- Buildings 106, 639, 1248, and 1337

Figure 2-136. Oblique of Building 639, 152-man mess hall (ERDC-CERL, 2019).

2.2.5.3 Type M-172-man mess halls

The researchers determined that there was one Type M-172 Mess halls within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-137).

- Building 1215

Figure 2-137. Oblique of Building 1215, 172-man mess hall (ERDC-CERL, 2019).

2.2.5.4 Type M-228-man mess halls

The researchers determined that there were two Type M-228 Mess halls within the Fort McCoy cantonment that exhibited the features to be a Number 1 Type (Figure 2-138).

- Buildings 1756 and 1949

Figure 2-138. Oblique of Building 1756, 228-man mess hall (ERDC-CERL, 2019).

2.2.6 Storehouse Buildings

2.2.6.1 Standard storehouse – Type SH-8

The researchers determined that there were two standard storehouse, Type SH-8, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-139).

- Buildings 1263 and 1265

Figure 2-139. Oblique of a standard storehouse, Type SH-8, Building 1263 (ERDC-CERL, 2019).

2.2.6.2 Standard storehouse – Type SH-9

The researchers determined that there was one standard storehouse, Type SH-9, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-140).

- Building 1264

Figure 2-140. Oblique of a standard storehouse, Type SH-9, Building 1264 (ERDC-CERL, 2019).

2.2.7 Repair and Service Buildings

2.2.7.1 Grease rack enclosure building

The researchers determined that there were two* grease rack enclosure buildings within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-141 to Figure 2-143).

- Building 547 and 1152

Figure 2-141. Oblique of a grease rack enclosure building, Building 547 (ERDC-CERL, 2019).

* There are technically three Number 2 Type grease rack enclosures, but 1152 and 1152A were joined together at an unknown date.

Figure 2-142. Interior view of the open space of grease rack enclosure building, Building 547 (ERDC-CERL, 2019).

Figure 2-143. Front side of a grease rack enclosure building, Building 1152 [both of these have the same building number] (ERDC-CERL, 2019).

2.2.7.2 Vehicle storage building

The researchers determined that there was one vehicle storage building within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-144).

- Building 1659

Figure 2-144. Oblique of vehicle storage building, Building 1659 (ERDC-CERL, 2019).

2.2.7.3 Motor repair shop

The researchers determined that there were three motor repair shops within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-145).

- Building 1260, 1261, and 1262

Figure 2-145. Oblique of motor repair shop building, Building 1262 (ERDC-CERL, 2019).

2.2.8 Support Buildings

2.2.8.1 G.U. dispensary – Type G.U.D.-1

The researchers determined that there were five G. U. dispensary buildings, Type G.U.D.-1, within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-146 to Figure 2-149).

- Buildings 1246, 1346, 1663, 1749, and 1865

Figure 2-146. Oblique of a G.U. dispensary building, Building 1347 (ERDC-CERL, 2019).

Figure 2-147. Interior view of the waiting room in a G.U. dispensary, Building 1865 (ERDC-CERL, 2019).

Figure 2-148. Interior view of the hallway with exam and storage rooms in a G.U. dispensary, Building 1865 (ERDC-CERL, 2019).

Figure 2-149. Original wood built-in shelves and cabinets in a G.U. dispensary, Building 1865 (ERDC-CERL, 2019).

3.1.1.1 *Infirmary*

The researchers determined that there were two infirmary buildings within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building.

- Buildings 1347 and 1664

2.2.8.2 *Regimental exchange building*

The researchers determined that there were three regimental exchange buildings within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-150 to Figure 2-153).

- Buildings 1256, 1445, 1868, and 2001

Figure 2-150. Oblique of a regimental exchange building, Building 1256 (ERDC-CERL, 2019).

Figure 2-151. View of modified interior of a regimental exchange building, Building 1256 (ERDC-CERL, 2019).

Figure 2-152. Modified interior of a regimental exchange building, Building 1256 (ERDC-CERL, 2019).

Figure 2-153. Oblique of a regimental exchange building, Building 1445 (ERDC-CERL, 2019).

2.2.8.3 Regimental chapels

The researchers determined that there was one regimental chapel within the Fort McCoy cantonment that exhibited the features to be a Number 2 Type building (Figure 2-154 to Figure 2-155).

- Building 1759

Figure 2-154. Rear oblique of a regimental chapel, Building 1759 (ERDC-CERL, 2019).

Figure 2-155. Interior view of a modified regimental chapel, Building 1759 (ERDC-CERL, 2019).

2.3 Number 3 Type

Number 3 Type was defined as having no original exterior features from the 1942 construction date. The buildings are clad with vinyl siding, all the windows and doors have been replaced, window patterns have been modified, ladders and balconies removed, and chimneys demolished. All the interiors of the Number 3 Types have been completely remodeled with new

finishes and spaces with added partition walls. The researchers found 529 WWII temporary buildings with no original exterior features (Table 2-3).

Table 2-3. Number 3 Type WWII buildings (compiled by ERDC-CERL, 2019).

Fac. No.	Year Built	Original Use	Current Use
102	1942	Administration	Administration General Purpose
103	1942	Administration (Finance)	Administration General Purpose
110	1942	Exchange	Administration General Purpose
352	1942	Regimental Exchange Building	General Instruction Building
602	1942	74-Man Barracks	Transient Training Enlisted Barracks
603	1942	74-Man Barracks	Transient Training Enlisted Barracks
604	1942	74-Man Barracks	Transient Training Enlisted Barracks
605	1942	Type M - 228-Man Mess Hall	General Instruction Building
606	1942	Type M - 228-Man Mess Hall	General Instruction Building
607	1942	74-Man Barracks	Battalion Headquarters Building Transient Training
608	1942	74-Man Barracks	Company Headquarters Building Transient Training
609	1942	74-Man Barracks	Company Headquarters Building Transient Training
610	1942	74-Man Barracks	Company Headquarters Building Transient Training
611	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
612	1942	74-Man Barracks	Transient Training Enlisted Barracks
613	1942	74-Man Barracks	Transient Training Enlisted Barracks
614	1942	74-Man Barracks	Transient Training Enlisted Barracks
616	1942	Type M - 228-Man Mess Hall	Company Headquarters Building Transient Training
617	1942	Type M - 228-Man Mess Hall	Company Headquarters Building Transient Training
618	1942	74-Man Barracks	Transient Training Enlisted Barracks
619	1942	74-Man Barracks	Transient Training Enlisted Barracks
620	1942	74-Man Barracks	Transient Training Enlisted Barracks
632	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
634	1942	Company Storehouse, Administration, and Recreation	Battalion Headquarters Building Transient Training
649	1942	Administration	Company Headquarters Building Transient Training
652	1942	Officers' Quarters - Type BOQ-44	Transient Training Enlisted Barracks
653	1942	Officers' Quarters - Type BOQ-44	Transient Training Enlisted Barracks
654	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers' Quarters
655	1942	Officers' Quarters - Type BOQ-40	Transient Training Enlisted Barracks
657	1942	Administration	General Instruction Building
658	1942	Recreation Building - Type RB-2	General Instruction Building
660	1942	Recreation Building - Type RB-2	Battalion Headquarters Building Transient Training
701	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
702	1942	74-Man Barracks	Transient Training Enlisted Barracks
703	1942	74-Man Barracks	Brigade Headquarters Building Transient Training

Fac. No.	Year Built	Original Use	Current Use
704	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
705	1942	Type M - 228-Man Mess Hall	Brigade Headquarters Building Transient Training
706	1942	Type M - 228-Man Mess Hall	Brigade Headquarters Building Transient Training
707	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
708	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
709	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
710	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
711	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
712	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
713	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
714	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
718	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
719	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
720	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
721	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
722	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
723	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
724	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
725	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
726	1942	Type M - 228-Man Mess Hall	Brigade Headquarters Building Transient Training
727	1942	Type M - 228-Man Mess Hall	Brigade Headquarters Building Transient Training
728	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
729	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
730	1942	74-Man Barracks	Brigade Headquarters Building
731	1942	74-Man Barracks	Brigade Headquarters Building Transient Training
732	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
733	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
734	1942	74-Man Barracks	Transient Training Enlisted Barracks
735	1942	74-Man Barracks	Transient Training Enlisted Barracks
736		74-Man Barracks	Transient Training Enlisted Barracks
740	1942	74-Man Barracks	Transient Training Enlisted Barracks
741	1942	74-Man Barracks	Transient Training Enlisted Barracks
742	1942	74-Man Barracks	Transient Training Enlisted Barracks
744	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
749	1942	Administration	General Instruction Building
750	1942	G.U. Dispensary - Type G.U.D. -1	General Instruction Building
751	1942	Regimental Exchange Building	General Instruction Building

Fac. No.	Year Built	Original Use	Current Use
756	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building
757	1942	Company Storehouse, Administration, and Recreation Building	Battalion Headquarters Building
801	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
802	1942	74-Man Barracks	Transient Training Enlisted Barracks
803	1942	74-Man Barracks	Transient Training Enlisted Barracks
804	1942	74-Man Barracks	Transient Training Enlisted Barracks
805	1942	Type M - 228-Man Mess Hall	General Instruction Building
806	1942	Type M - 228-Man Mess Hall	General Instruction Building
807	1942	74-Man Barracks	Transient Training Enlisted Barracks
808	1942	74-Man Barracks	Transient Training Enlisted Barracks
809	1942	74-Man Barracks	Transient Training Enlisted Barracks
810	1942	74-Man Barracks	Transient Training Enlisted Barracks
811	1942	Company Storehouse, Administration, and Recreation Building	ARM Force Center
812	1942	74-Man Barracks	USAR Center
813	1942	74-Man Barracks	Transient Training Enlisted Barracks
814	1942	74-Man Barracks	Transient Training Enlisted Barracks
816	1942	Type M - 228-Man Mess Hall	General Instruction Building
817	1942	Type M - 228-Man Mess Hall	General Instruction Building
818	1942	74-Man Barracks	Transient Training Enlisted Barracks
819	1942	74-Man Barracks	Transient Training Enlisted Barracks
820	1942	74-Man Barracks	Transient Training Enlisted Barracks
821	1942	Company Storehouse, Administration, and Recreation Building	ARM Force Center
823	1942	74-Man Barracks	USAR Center
824	1942	74-Man Barracks	USAR Center
825	1942	74-Man Barracks	USAR Center
826	1942	Type M - 172-Man Mess Hall	ARM Force Center
827	1942	Type M - 152-Man Mess Hall	ARM Force Center
828	1942	74-Man Barracks	USAR Center
829	1942	74-Man Barracks	USAR Center
832	1942	Company Storehouse, Administration, and Recreation Building	ARM Force Center
833	1942	Company Storehouse, Administration, and Recreation Building	ARM Force Center
1101	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1106	1942	Type M - 112-Man Mess Hall	Administration General Purpose
1108	1942	74-Man Barracks	Administration General Purpose
1111	1942	Company Storehouse, Administration, and Recreation Building	Administration General Purpose
1115	1942	Type M - 152-Man Mess Hall	Simulation Center

Fac. No.	Year Built	Original Use	Current Use
1226	1942	Type M - 112-Man Mess Hall	Organizational Classroom
1227	1942	Type M - 112-Man Mess Hall	Organizational Classroom
1228	1942	Type M - 112-Man Mess Hall	Brigade Headquarters Building Transient Training
1245	1942	Administration	USAR Center
1255	1942	Recreation Building - Gymnasium	General Instruction Building
1313	1942	74-Man Barracks	Transient Training Enlisted Barracks
1314	1942	74-Man Barracks	Transient Training Enlisted Barracks
1321	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1329		74-Man Barracks	Transient Training Enlisted Barracks
1330	1942	74-Man Barracks	Transient Training Enlisted Barracks
1331	1942	74-Man Barracks	Transient Training Enlisted Barracks
1332	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1335	1942	74-Man Barracks	Transient Training Enlisted Barracks
1336	1942	74-Man Barracks	Transient Training Enlisted Barracks
1421	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1432	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1437	1942	Type M - 112-Man Mess Hall	General Instruction Building
1501	1942	Company Storehouse, Administration, and Recreation Building	Credit Union
1601	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1602	1942	74-Man Barracks	Transient Training Enlisted Barracks
1603	1942	74-Man Barracks	Transient Training Enlisted Barracks
1604	1942	74-Man Barracks	Transient Training Enlisted Barracks
1605	1942	Type M - 228-Man Mess Hall	General Instruction Building
1606	1942	Type M - 228-Man Mess Hall	General Instruction Building
1607	1942	74-Man Barracks	Transient Training Enlisted Barracks
1608	1942	74-Man Barracks	Transient Training Enlisted Barracks
1609	1942	74-Man Barracks	Transient Training Enlisted Barracks
1610	1942	74-Man Barracks	Transient Training Enlisted Barracks
1612	1942	74-Man Barracks	Transient Training Enlisted Barracks
1613	1942	74-Man Barracks	Transient Training Enlisted Barracks
1614	1942	74-Man Barracks	Transient Training Enlisted Barracks
1615	1942	74-Man Barracks	Transient Training Enlisted Barracks
1616	1942	Type M - 228-Man Mess Hall	General Instruction Building
1617	1942	Type M - 228-Man Mess Hall	General Instruction Building
1618	1942	74-Man Barracks	Transient Training Enlisted Barracks
1619	1942	74-Man Barracks	Transient Training Enlisted Barracks
1620	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
1621	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1622	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building
1623	1942	74-Man Barracks	Transient Training Enlisted Barracks
1624	1942	74-Man Barracks	Transient Training Enlisted Barracks
1625	1942	74-Man Barracks	Transient Training Enlisted Barracks
1626	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
1627	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
1628	1942	74-Man Barracks	Transient Training Enlisted Barracks
1629	1942	74-Man Barracks	Transient Training Enlisted Barracks
1630	1942	74-Man Barracks	Transient Training Enlisted Barracks
1631	1942	74-Man Barracks	Transient Training Enlisted Barracks
1632	1942	Bachelor Officers' Quarters - 700-Series, Type OQ-23	Transient Training Enlisted Barracks
1634	1942	74-Man Barracks	Transient Training Enlisted Barracks
1635	1942	74-Man Barracks	Transient Training Enlisted Barracks
1636	1942	74-Man Barracks	Transient Training Enlisted Barracks
1637	1942	74-Man Barracks	Transient Training Enlisted Barracks
1638	1942	Type M - 228-Man Mess Hall	General Instruction Building
1639	1942	Type M - 228-Man Mess Hall	General Instruction Building
1640	1942	74-Man Barracks	Transient Training Enlisted Barracks
1641	1942	74-Man Barracks	Transient Training Enlisted Barracks
1642	1942	74-Man Barracks	Transient Training Enlisted Barracks
1644	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1645	1942	Type M - 228-Man Mess Hall	Military Clothing Sale
1650	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building
1651	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1652	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1702	1942	74-Man Barracks	Transient Training Enlisted Barracks
1703	1942	74-Man Barracks	Transient Training Enlisted Barracks
1704	1942	74-Man Barracks	Transient Training Enlisted Barracks
1705	1942	Type M - 228-Man Mess Hall	General Instruction Building
1706	1942	Type M - 228-Man Mess Hall	General Instruction Building
1707	1942	74-Man Barracks	Transient Training Enlisted Barracks
1708	1942	74-Man Barracks	Transient Training Enlisted Barracks
1709	1942	74-Man Barracks	Transient Training Enlisted Barracks
1710	1942	74-Man Barracks	Transient Training Enlisted Barracks
1712	1942	74-Man Barracks	Transient Training Enlisted Barracks
1713	1942	74-Man Barracks	Transient Training Enlisted Barracks
1714	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
1715	1942	74-Man Barracks	Transient Training Enlisted Barracks
1716	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
1717	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
1718	1942	74-Man Barracks	Transient Training Enlisted Barracks
1719	1942	74-Man Barracks	Transient Training Enlisted Barracks
1723	1942	74-Man Barracks	Transient Training Enlisted Barracks
1724	1942	74-Man Barracks	Transient Training Enlisted Barracks
1725	1942	74-Man Barracks	Transient Training Enlisted Barracks
1728	1942	74-Man Barracks	Transient Training Enlisted Barracks
1729	1942	74-Man Barracks	Transient Training Enlisted Barracks
1730	1942	74-Man Barracks	Transient Training Enlisted Barracks
1731	1942	74-Man Barracks	Transient Training Enlisted Barracks
1732	1942	74-Man Barracks	Transient Training Enlisted Barracks
1736	1942	74-Man Barracks	Transient Training Enlisted Barracks
1737	1942	74-Man Barracks	Transient Training Enlisted Barracks
1738	1942	Type M - 228-Man Mess Hall	General Instruction Building
1739	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
1740	1942	74-Man Barracks	Transient Training Enlisted Barracks
1741	1942	74-Man Barracks	Transient Training Enlisted Barracks
1742	1942	74-Man Barracks	Transient Training Enlisted Barracks
1743	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1760	1942	Recreation Building - Type RB-4	Company Headquarters Building Transient Training
1761	1942	Recreation Building - Type RB-4	Company Headquarters Building Transient Training
1764	1942	Motor Repair Shop	Organizational Storage Building
1801	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1802	1942	74-Man Barracks	Transient Training Enlisted Barracks
1803	1942	74-Man Barracks	Transient Training Enlisted Barracks
1804	1942	74-Man Barracks	Transient Training Enlisted Barracks
1805	1942	Type M - 228-Man Mess Hall	General Instruction Building
1806	1942	Type M - 228-Man Mess Hall	General Instruction Building
1807	1942	74-Man Barracks	Transient Training Enlisted Barracks
1808	1942	74-Man Barracks	Transient Training Enlisted Barracks
1809	1942	74-Man Barracks	Transient Training Enlisted Barracks
1810	1942	74-Man Barracks	Transient Training Enlisted Barracks
1812	1942	74-Man Barracks	Transient Training Enlisted Barracks
1813	1942	74-Man Barracks	Transient Training Enlisted Barracks
1814	1942	74-Man Barracks	Transient Training Enlisted Barracks
1815	1942	74-Man Barracks	Transient Training Enlisted Barracks
1816	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
1817	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
1818	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
1819	1942	74-Man Barracks	Transient Training Enlisted Barracks
1820	1942	74-Man Barracks	Transient Training Enlisted Barracks
1821	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1822	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1823	1942	74-Man Barracks	Transient Training Enlisted Barracks
1824	1942	74-Man Barracks	Transient Training Enlisted Barracks
1825	1942	74-Man Barracks	Transient Training Enlisted Barracks
1826	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
1827	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
1828	1942	74-Man Barracks	Transient Training Enlisted Barracks
1829	1942	74-Man Barracks	Transient Training Enlisted Barracks
1830	1942	74-Man Barracks	Transient Training Enlisted Barracks
1831	1942	74-Man Barracks	Transient Training Enlisted Barracks
1832	1942	74-Man Barracks	Transient Training Enlisted Barracks
1834	1942	74-Man Barracks	Transient Training Enlisted Barracks
1835	1942	74-Man Barracks	Transient Training Enlisted Barracks
1836	1942	74-Man Barracks	Transient Training Enlisted Barracks
1837	1942	74-Man Barracks	Transient Training Enlisted Barracks
1838	1942	Type M - 228-Man Mess Hall	General Instruction Building
1840	1942	74-Man Barracks	Transient Training Enlisted Barracks
1842	1942	74-Man Barracks	Transient Training Enlisted Barracks
1843	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1844	1942	74-Man Barracks	Transient Training Enlisted Barracks
1846	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1847	1942	Administration	Company Headquarters Building Transient Training
1848	1942	Administration	Company Headquarters Building Transient Training
1851	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1852	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1854	1942	Administration	Company Headquarters Building Transient Training
1855	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
1857	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters
1863	1942	Bachelor Officers' Quarters - Type OQ-23	Transient Training Officers Quarters
1864	1942	Bachelor Officers' Quarters - Type OQ-23	Transient Training Officers Quarters
1913	1942	74-Man Barracks	Administration General Purpose
1914	1942	74-Man Barracks	Transient Training Enlisted Barracks
1915	1942	74-Man Barracks	Transient Training Enlisted Barracks
1916	1942	Type M - 228-Man Mess Hall	Dining Facility: Transient Training
1918	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
1919	1942	74-Man Barracks	Transient Training Enlisted Barracks
1920	1942	74-Man Barracks	Transient Training Enlisted Barracks
1923	1942	74-Man Barracks	Transient Training Enlisted Barracks
1924	1942	74-Man Barracks	Transient Training Enlisted Barracks
1925	1942	74-Man Barracks	Transient Training Enlisted Barracks
1926	1942	Type M - 228-Man Mess Hall	General Instruction Building
1928	1942	74-Man Barracks	Transient Training Enlisted Barracks
1929	1942	74-Man Barracks	Transient Training Enlisted Barracks
1930	1942	74-Man Barracks	Transient Training Enlisted Barracks
1931	1942	74-Man Barracks	Transient Training Enlisted Barracks
1934	1942	74-Man Barracks	Transient Training Enlisted Barracks
1935	1942	74-Man Barracks	Transient Training Enlisted Barracks
1936	1942	74-Man Barracks	Transient Training Enlisted Barracks
1937	1942	74-Man Barracks	Transient Training Enlisted Barracks
1940	1942	74-Man Barracks	Transient Training Enlisted Barracks
1941	1942	74-Man Barracks	Transient Training Enlisted Barracks
1944	1942	74-Man Barracks	Transient Training Enlisted Barracks
1951	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
2000	1942	Service Club	Administration General Purpose
2004	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2005	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2007	1942	74-Man Barracks	Transient Training Officers Quarters
2107	1942	Storehouse - Type SH-13	Storage General Purpose
2108	1942	Storehouse - Type SH-13	Storage General Purpose
2109	1942	Railroad Equipment	Maintenance Storage DOL
2111	1942	Fire Station	ACS Center
2113	1942	Bakery	Televideo Center
2115	1942	Carpenter Shop	Engineering/Housing Maintenance
2116	1942	Utility Shop	Maintenance Storage DOL
2117	1942	Administration	Company Headquarters Building Transient Training
2119	1942	Storehouse - Type SH-18	Storage General Purpose
2121	1942	Storehouse - Type SH-18	Storage General Purpose
2123	1942	Storehouse - Type SH-18	Storage General Purpose
2125	1942	Storehouse - Type SH-18	Storage General Purpose
2141	1942	Storehouse - Type SH-13	Storage General Purpose
2142	1942	Storehouse - Type SH-13	Central Issue Facility
2143	1942	Storehouse - Type SH-13	Storage General Purpose
2145	1942	Storehouse - Type SH-13	Storage General Purpose
2147	1942	Storehouse - Type SH-13	Storage General Purpose
2149	1942	Storehouse - Type SH-13	Storage General Purpose

Fac. No.	Year Built	Original Use	Current Use
2161	1942	Storehouse – Type SH-18	Organizational Storage Building
2171	1942	WAC Barracks	Administration General Purpose
2180	1942	Administration	Administration General Purpose
2184	1942	Storehouse – Type SH-18	Organizational Storage Building
2402	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2403	1942	74-Man Barracks	Transient Training Enlisted Barracks
2404	1942	74-Man Barracks	Transient Training Enlisted Barracks
2405	1942	74-Man Barracks	Transient Training Enlisted Barracks
2406	1942	Type M – 228-Man Mess Hall	General Instruction Building
2407	1942	Type M – 228-Man Mess Hall	General Instruction Building
2408	1942	74-Man Barracks	Transient Training Enlisted Barracks
2409	1942	74-Man Barracks	Transient Training Enlisted Barracks
2410	1942	74-Man Barracks	Transient Training Enlisted Barracks
2411	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2412	1942	74-Man Barracks	Transient Training Enlisted Barracks
2413	1942	74-Man Barracks	Transient Training Enlisted Barracks
2414	1942	74-Man Barracks	Transient Training Enlisted Barracks
2415	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2416	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2417	1942	74-Man Barracks	Transient Training Enlisted Barracks
2418	1942	74-Man Barracks	Transient Training Enlisted Barracks
2419	1942	74-Man Barracks	Transient Training Enlisted Barracks
2420	1942	74-Man Barracks	Transient Training Enlisted Barracks
2421	1942	74-Man Barracks	Transient Training Enlisted Barracks
2423	1942	74-Man Barracks	Transient Training Enlisted Barracks
2424	1942	74-Man Barracks	Transient Training Enlisted Barracks
2425	1942	74-Man Barracks	Transient Training Enlisted Barracks
2426	1942	74-Man Barracks	Transient Training Enlisted Barracks
2427	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2428	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training
2429	1942	74-Man Barracks	Transient Training Enlisted Barracks
2430	1942	74-Man Barracks	Transient Training Enlisted Barracks
2431	1942	74-Man Barracks	Transient Training Enlisted Barracks
2432	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2433	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2434	1942	74-Man Barracks	Transient Training Enlisted Barracks
2435	1942	74-Man Barracks	Transient Training Enlisted Barracks
2436	1942	74-Man Barracks	Transient Training Enlisted Barracks
2439	1942	74-Man Barracks	Transient Training Enlisted Barracks
2440	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
2441	1942	74-Man Barracks	Transient Training Enlisted Barracks
2442	1942	74-Man Barracks	Transient Training Enlisted Barracks
2444	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2445	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2446	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2447	1942	Type M - 228-Man Mess Hall	General Instruction Building
2501	1942	74-Man Barracks	Transient Training Enlisted Barracks
2502	1942	74-Man Barracks	Transient Training Enlisted Barracks
2503	1942	74-Man Barracks	Transient Training Enlisted Barracks
2504	1942	74-Man Barracks	Transient Training Enlisted Barracks
2505	1942	74-Man Barracks	Transient Training Enlisted Barracks
2508	1942	74-Man Barracks	Transient Training Enlisted Barracks
2509	1942	74-Man Barracks	Transient Training Enlisted Barracks
2510	1942	74-Man Barracks	Transient Training Enlisted Barracks
2511	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2512	1942	74-Man Barracks	Transient Training Enlisted Barracks
2513	1942	74-Man Barracks	Transient Training Enlisted Barracks
2514	1942	74-Man Barracks	Transient Training Enlisted Barracks
2515	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
2516	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
2517	1942	74-Man Barracks	Transient Training Enlisted Barracks
2518	1942	74-Man Barracks	Transient Training Enlisted Barracks
2519	1942	74-Man Barracks	Transient Training Enlisted Barracks
2520	1942	74-Man Barracks	Transient Training Enlisted Barracks
2521	1942	74-Man Barracks	Transient Training Enlisted Barracks
2523	1942	74-Man Barracks	Transient Training Enlisted Barracks
2524	1942	74-Man Barracks	Transient Training Enlisted Barracks
2525	1942	74-Man Barracks	Transient Training Enlisted Barracks
2526	1942	74-Man Barracks	Transient Training Enlisted Barracks
2527	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
2528	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
2529	1942	74-Man Barracks	Transient Training Enlisted Barracks
2530	1942	74-Man Barracks	Transient Training Enlisted Barracks
2531	1942	74-Man Barracks	Transient Training Enlisted Barracks
2532	1942	Recreation Building - Type RB-4	Company Headquarters Building Transient Training
2533	1942	Recreation Building - Type RB-4	Company Headquarters Building Transient Training
2534	1942	74-Man Barracks	Transient Training Enlisted Barracks
2535	1942	74-Man Barracks	Transient Training Enlisted Barracks
2536	1942	74-Man Barracks	Transient Training Enlisted Barracks
2539	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
2540	1942	74-Man Barracks	Transient Training Enlisted Barracks
2541	1942	74-Man Barracks	Transient Training Enlisted Barracks
2546	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2547	1942	Administration	General Instruction Building
2548	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2549	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2551	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2552	1942	Administration	Company Headquarters Building Transient Training
2553	1942	Administration	Company Headquarters Building Transient Training
2554	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2555	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2558	1942	Regimental Exchange Building	Auditorium General Purpose
2561	1942	Bachelor Officers' Quarters - Type BOQ-23	Transient Training Officers Quarters
2562	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters
2564	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters
2565	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters
2601	1942	74-Man Barracks	Transient Training Enlisted Barracks
2602	1942	74-Man Barracks	Transient Training Enlisted Barracks
2603	1942	74-Man Barracks	Transient Training Enlisted Barracks
2604	1942	74-Man Barracks	Transient Training Enlisted Barracks
2605	1942	74-Man Barracks	Transient Training Enlisted Barracks
2606	1942	Type M - 228-Man Mess Hall	General Instruction Building
2607	1942	Type M - 228-Man Mess Hall	General Instruction Building
2608	1942	74-Man Barracks	Transient Training Enlisted Barracks
2609	1942	74-Man Barracks	Transient Training Enlisted Barracks
2610	1942	74-Man Barracks	Transient Training Enlisted Barracks
2612	1942	74-Man Barracks	Transient Training Enlisted Barracks
2613	1942	74-Man Barracks	Transient Training Enlisted Barracks
2614	1942	74-Man Barracks	Transient Training Enlisted Barracks
2615	1942	Type M - 228-Man Mess Hall	General Instruction Building
2617	1942	74-Man Barracks	Transient Training Enlisted Barracks
2618	1942	74-Man Barracks	Transient Training Enlisted Barracks
2619	1942	74-Man Barracks	Transient Training Enlisted Barracks
2620	1942	74-Man Barracks	Transient Training Enlisted Barracks
2621	1942	74-Man Barracks	Transient Training Enlisted Barracks
2623	1942	74-Man Barracks	Transient Training Enlisted Barracks
2624	1942	74-Man Barracks	Transient Training Enlisted Barracks
2625	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
2626	1942	74-Man Barracks	Transient Training Enlisted Barracks
2627	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
2628	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
2629	1942	74-Man Barracks	Transient Training Enlisted Barracks
2630	1942	74-Man Barracks	Transient Training Enlisted Barracks
2631	1942	74-Man Barracks	Transient Training Enlisted Barracks
2632	1942	Recreation Building - Type RB-4	Company Headquarters Building Transient Training
2633	1942	Recreation Building - Type RB-4	Company Headquarters Building Transient Training
2634	1942	74-Man Barracks	Transient Training Enlisted Barracks
2635	1942	74-Man Barracks	Transient Training Enlisted Barracks
2636	1942	74-Man Barracks	Transient Training Enlisted Barracks
2637	1942	Type M - 228-Man Mess Hall	General Instruction Building
2638	1942	Type M - 228-Man Mess Hall	General Instruction Building
2639	1942	74-Man Barracks	Transient Training Enlisted Barracks
2640	1942	74-Man Barracks	Transient Training Enlisted Barracks
2641	1942	74-Man Barracks	Transient Training Enlisted Barracks
2642	1942	74-Man Barracks	Transient Training Enlisted Barracks
2656	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2661	1942	Type M - 228-Man Mess Hall	General Instruction Building
2665	1942	Administration	Company Headquarters Building Transient Training
2668	1942	Administration	Company Headquarters Building Transient Training
2669	1942	Regimental Exchange Building	Battalion Headquarters Building Transient Training
2672	1942	Regimental Chapel	Chapel
2675	1942	Post Office	Religious Educational Facility
2701	1942	74-Man Barracks	Transient Training Enlisted Barracks
2702	1942	74-Man Barracks	Transient Training Enlisted Barracks
2703	1942	74-Man Barracks	Transient Training Enlisted Barracks
2704	1942	74-Man Barracks	Transient Training Enlisted Barracks
2705	1942	74-Man Barracks	Transient Training Enlisted Barracks
2706	1942	Type M - 228-Man Mess Hall	General Instruction Building
2707	1942	Type M - 228-Man Mess Hall	General Instruction Building
2708	1942	74-Man Barracks	Transient Training Enlisted Barracks
2709	1942	74-Man Barracks	Transient Training Enlisted Barracks
2710	1942	74-Man Barracks	Transient Training Enlisted Barracks
2712	1942	74-Man Barracks	Transient Training Enlisted Barracks
2713	1942	74-Man Barracks	Transient Training Enlisted Barracks
2714	1942	74-Man Barracks	Transient Training Enlisted Barracks
2715	1942	Type M - 228-Man Mess Hall	General Instruction Building
2717	1942	74-Man Barracks	Transient Training Enlisted Barracks
2718	1942	74-Man Barracks	Transient Training Enlisted Barracks
2719	1942	74-Man Barracks	Transient Training Enlisted Barracks
2720	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
2721	1942	74-Man Barracks	Transient Training Enlisted Barracks
2723	1942	74-Man Barracks	Transient Training Enlisted Barracks
2724	1942	74-Man Barracks	Transient Training Enlisted Barracks
2725	1942	74-Man Barracks	Transient Training Enlisted Barracks
2726	1942	74-Man Barracks	Transient Training Enlisted Barracks
2727	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
2728	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
2729	1942	74-Man Barracks	Transient Training Enlisted Barracks
2730	1942	74-Man Barracks	Transient Training Enlisted Barracks
2731	1942	74-Man Barracks	Transient Training Enlisted Barracks
2732	1942	Recreation Building - Type RB-4	Company Headquarters Building Transient Training
2733	1942	Recreation Building - Type RB-4	Company Headquarters Building Transient Training
2734	1942	74-Man Barracks	Transient Training Enlisted Barracks
2735	1942	74-Man Barracks	Transient Training Enlisted Barracks
2736	1942	74-Man Barracks	Transient Training Enlisted Barracks
2737	1942	Type M - 228-Man Mess Hall	General Instruction Building
2738	1942	Type M - 228-Man Mess Hall	General Instruction Building
2739	1942	74-Man Barracks	Transient Training Enlisted Barracks
2740	1942	74-Man Barracks	Transient Training Enlisted Barracks
2741	1942	74-Man Barracks	Transient Training Enlisted Barracks
2742	1942	74-Man Barracks	Transient Training Enlisted Barracks
2744	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2764	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2766	1942	Administration	Company Headquarters Building Transient Training
2768	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2769	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2771	1942	Administration	Company Headquarters Building Transient Training
2773	1942	Type M - 228-Man Mess Hall	General Instruction Building
2778	1942	Bachelor Officers' Quarters - Type OQ-23	Transient Training Officers Quarters
2779	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters
2801	1942	74-Man Barracks	Transient Training Enlisted Barracks
2802	1942	74-Man Barracks	Transient Training Enlisted Barracks
2803	1942	74-Man Barracks	Transient Training Enlisted Barracks
2804	1942	74-Man Barracks	Transient Training Enlisted Barracks
2805	1942	74-Man Barracks	Transient Training Enlisted Barracks
2806	1942	Type M - 228-Man Mess Hall	General Instruction Building
2807	1942	Type M - 228-Man Mess Hall	General Instruction Building
2808	1942	74-Man Barracks	Transient Training Enlisted Barracks
2809	1942	74-Man Barracks	Transient Training Enlisted Barracks
2810	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
2811	1942	74-Man Barracks	Company Headquarters Building Transient Training
2812	1942	74-Man Barracks	Transient Training Enlisted Barracks
2814	1942	74-Man Barracks	Transient Training Enlisted Barracks
2815	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
2816	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
2817	1942	74-Man Barracks	Transient Training Enlisted Barracks
2818	1942	74-Man Barracks	Transient Training Enlisted Barracks
2819	1942	74-Man Barracks	Transient Training Enlisted Barracks
2820	1942	74-Man Barracks	Transient Training Enlisted Barracks
2821	1942	74-Man Barracks	Transient Training Enlisted Barracks
2823	1942	74-Man Barracks	Transient Training Enlisted Barracks
2824	1942	74-Man Barracks	Transient Training Enlisted Barracks
2825	1942	74-Man Barracks	Transient Training Enlisted Barracks
2826	1942	74-Man Barracks	Transient Training Enlisted Barracks
2827	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
2828	1942	Type M - 228-Man Mess Hall	Dining Facility Transient Training
2829	1942	74-Man Barracks	Transient Training Enlisted Barracks
2830	1942	74-Man Barracks	Transient Training Enlisted Barracks
2831	1942	74-Man Barracks	Transient Training Enlisted Barracks
2863	1942	Administration	Company Headquarters Building Transient Training
2867	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2868	1942	Type M - 228-Man Mess Hall	General Instruction Building
2869	1942	Administration	Company Headquarters Building Transient Training
2870	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2871	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training
2874	1942	Regimental Exchange Building	Auditorium General Purpose
2875	1942	Administration	Company Headquarters Building Transient Training
*Note: Determined Eligible Under Criteria A and C In TR-18-38, Determination of NRHP Eligibility Of 26 Buildings at Fort McCoy, Wisconsin.			

2.3.1 Living Quarters

2.3.1.1 74-man barracks

The researchers determined that there were 309 74-man barracks within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-156 to Figure 2-160).

- Buildings 602, 603, 604, 607, 608, 609, 610, 612, 613, 614, 618, 619, 620, 702, 703, 704, 707, 708, 709, 710, 712, 713, 714, 718, 719, 720, 723, 724, 725, 728, 729, 730, 731, 734, 735, 736, 740, 741, 742,

802, 803, 804, 807, 808, 809, 810, 812, 813, 814, 818, 819, 820, 823, 824, 825, 828, 829, 1108, 1313, 1314, 1329, 1330, 1331, 1335, 1336, 1602, 1603, 1604, 1607, 1608, 1609, 1610, 1612, 1613, 1614, 1615, 1618, 1619, 1620, 1623, 1624, 1625, 1628, 1629, 1630, 1631, 1634, 1635, 1636, 1637, 1640, 1641, 1642, 1702, 1703, 1704, 1707, 1708, 1709, 1710, 1712, 1713, 1714, 1715, 1718, 1719, 1723, 1724, 1725, 1728, 1729, 1730, 1731, 1732, 1736, 1737, 1740, 1741, 1742, 1802, 1803, 1804, 1807, 1808, 1809, 1810, 1812, 1813, 1814, 1815, 1818, 1819, 1820, 1823, 1824, 1825, 1828, 1829, 1830, 1831, 1832, 1834, 1835, 1836, 1837, 1840, 1842, 1844, 1913, 1914, 1915, 1918, 1919, 1920, 1923, 1924, 1925, 1928, 1929, 1930, 1931, 1934, 1935, 1936, 1937, 1940, 1941, 1944, 2007, 2403, 2404, 2405, 2408, 2409, 2410, 2412, 2413, 2414, 2417, 2418, 2419, 2420, 2421, 2423, 2424, 2425, 2426, 2429, 2430, 2431, 2434, 2435, 2436, 2439, 2440, 2441, 2442, 2501, 2502, 2503, 2504, 2505, 2508, 2509, 2510, 2512, 2513, 2514, 2517, 2518, 2519, 2520, 2521, 2523, 2524, 2525, 2526, 2529, 2530, 2531, 2534, 2535, 2536, 2539, 2540, 2541, 2601, 2602, 2603, 2604, 2605, 2608, 2609, 2610, 2612, 2613, 2614, 2617, 2618, 2619, 2620, 2621, 2623, 2624, 2625, 2626, 2629, 2630, 2631, 2634, 2635, 2636, 2639, 2640, 2641, 2642, 2701, 2702, 2703, 2704, 2705, 2708, 2709, 2710, 2712, 2713, 2714, 2717, 2718, 2719, 2720, 2721, 2723, 2724, 2725, 2726, 2729, 2730, 2731, 2734, 2735, 2736, 2739, 2740, 2741, 2742, 2801, 2802, 2803, 2804, 2805, 2808, 2809, 2810, 2811, 2812, 2814, 2817, 2818, 2819, 2820, 2821, 2823, 2824, 2825, 2826, 2829, 2830, and 2831

Figure 2-156. Oblique of a 74-man barracks, Building 608 (ERDC-CERL, 2019).

Figure 2-157. Oblique of a 74-man barracks, Building 1603 (ERDC-CERL, 2019).

Figure 2-158. Interior view of the modified bunk area in a 74-man barracks (ERDC-CERL, 2019).

Figure 2-159. Interior view of a modified NCO room in a 74-man barracks (ERDC-CERL, 2019).

Figure 2-160. Interior view of the latrine in a 74-man barracks (ERDC-CERL, 2019).

2.3.1.2 Officers' quarters – Type BOQ-40

The researchers determined that there was one officers' quarters, Type BOQ-40 within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-161).

- Buildings 655

Figure 2-161. Oblique of an officers' quarters, Type BOQ-40, Building 655 (ERDC-CERL, 2019).

2.3.1.3 Officers' quarters – Type BOQ-44

The researchers determined that there were eight officers' quarters, Type BOQ-44 within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-162).

- Buildings 652, 653, 654, 1857, 2562, 2564, 2565, and 2779

Figure 2-162. Oblique of an officers' quarters, Type BOQ-44, Building 2562 (ERDC-CERL, 2019).

2.3.1.4 Bachelor officers' quarters – Type OQ-23

The researchers determined that there were five 700 Series bachelor officers' quarters, Type OQ-23 within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-163).

- Buildings 1632, 1863, 1864, 2561, and 2778

Figure 2-163. Oblique of a 700 Series bachelor officers' quarters, Type OQ-23, Building 2561 (ERDC-CERL, 2019).

3.1.1.1 WAC barracks

The researchers determined that there was one WAC barracks within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building. The formerly separated barracks were joined together (Figure 2-164).

- Building 2171

Figure 2-164. Oblique looking northeast of the WACS barracks, Building 2171 (ERDC-CERL, 2019).

2.3.2 Administration/Recreation Combination Buildings

2.3.2.1 Company storehouse, administration, and recreation

The researchers determined that there were 61 company storehouse, administration, and recreation buildings within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-165 to Figure 2-169).

- Buildings 611, 632, 701, 711, 721, 722, 732, 733, 744, 756, 757, 801, 811, 821, 832, 833, 1101, 1111, 1321, 1332, 1421, 1432, 1501, 1601, 1621, 1622, 1644, 1650, 1651, 1652, 1743, 1801, 1821, 1822, 1843, 1846, 1851, 1852, 1855, 1951, 2004, 2005, 2402, 2411, 2432, 2433, 2444, 2445, 2446, 2511, 2546, 2548, 2549, 2551, 2554, 2555, 2656, 2744, 2764, 2768, and 2769

Figure 2-165. Oblique of a company storehouse, administration, and recreation building, Building 1111 (ERDC-CERL, 2019).

Figure 2-166. Interior view of a modified storehouse space with newer partition wall in a company storehouse, administration, and recreation building (ERDC-CERL, 2019).

Figure 2-167. Interior view of a modified storehouse space looking towards a new ramp leading to the administration space in a company storehouse, administration, and recreation building (ERDC-CERL, 2019).

Figure 2-168. Interior view of a modified administration space new partition walls, flooring, and ceiling in a company storehouse, administration, and recreation building (ERDC-CERL, 2019).

Figure 2-169. Interior view of a modified administration and recreation space with all new finishes in a company storehouse, administration, and recreation building (ERDC-CERL, 2019).

2.3.2.2 *Company storehouse, administration, and recreation building [MOD]*

The researchers determined that there were four company storehouse, administration, and recreation buildings modified version within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-170).

- Building 634, 2867, 2870, and 2871

Figure 2-170. Oblique of a company storehouse, administration, and recreation building with modified roofline, Building 634 (ERDC-CERL, 2019).

2.3.3 Administration Buildings

2.3.3.1 *Administration building – Type IBA-1*

The researchers determined that there was eleven of the interior battalion administration buildings, Type IBA-1, within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-171).

- Building 649, 749, 1847, 1848, 2552, 2553, 2665, 2766, 2771, 2863, and 2869

Figure 2-171. Front side of administration building Type IBA-1 building, Building 1848 (ERDC-CERL, 2019).

3.1.1.2 Administration building – Type A-10

The researchers determined that there were ten administration building Type A-10 within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-172 to Figure 2-173).

- Buildings 102, 103, 657, 1254, 1854, 2117, 2180, 2547, 2668, and 2875

Figure 2-172. Oblique of a Type A-10 building, Building 657 (ERDC-CERL, 2019).

Figure 2-173. North side of a Type A-10 building, Building 2117 (ERDC-CERL, 2019).

2.3.4 Recreation Buildings

2.3.4.1 Recreation building – gymnasium (RB-1)

The researchers determined that there was one recreation buildings, gymnasium (RB-1), within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-174 to Figure 2-175).

- Building 1255

Figure 2-174. Oblique of a recreation building, gymnasium, Building 1255 (ERDC-CERL, 2019).

Figure 2-175. View of modified interior space in a recreation building – gymnasium, Building 1255 (ERDC-CERL, 2019).

2.3.4.2 Recreation building – Type RB-2

The researchers determined that there were two recreation buildings, Type RB-2, within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-176).

- Buildings 658 and 660

Figure 2-176. Oblique of a Type RB-2 building, Building 658 (ERDC-CERL, 2019).

2.3.4.3 Recreation building – Type RB-4

The researchers determined that there were eight recreation buildings, Type RB-4, within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building.

- Buildings 1760, 1761, 2532, 2533, 2632, 2633, 2732, and 2733

2.3.4.4 Service club

The researchers determined that there were one service club* within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-177 to Figure 2-179).

- Building 2000

Figure 2-177. Front side of service club, Building 2000 (ERDC-CERL, 2019).

* Building 2000 was determined eligible in the *Determination of NRHP Eligibility for 26 Buildings at Fort McCoy, Wisconsin (2018)* report. In between the publication of that report and the publication of this report, the building underwent a renovation that removed its WWII character-defining features.

Figure 2-178. Rear side of service club, Building 2000 (ERDC-CERL, 2019).

Figure 2-179. Interior of dance hall space in modified service club, Building 2000 (ERDC-CERL, 2019).

2.3.5 Mess Halls

2.3.5.1 Type M- 112-man mess halls

The researchers determined that there were five Type M-112 mess halls within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building.

- 1106, 1226, 1227, 1228, and 1437

2.3.5.2 Type M-152-man mess halls

The researchers determined that there were two Type M-152 mess halls within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building. These two mess halls have been heavily modified with newer cross-gable side additions.

- 827 and 1115

2.3.5.3 Type M-172-man mess halls

The researchers determined that there was one Type M-172 mess halls within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building. This mess hall has been heavily modified with a newer cross-gable side addition.

- 826

2.3.5.4 Type M-228-man mess halls

The researchers determined that there were 70 Type M mess halls within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building. Some of these mess halls have been heavily modified with newer cross-gable side additions, some with large side additions, while others have been connected together via the construction of hyphen that houses bathroom and storage rooms (Figure 2-181 to Figure 2-187).

- 605, 606, 616, 617, 705, 706, 726, 727, 805, 806, 816, 817, 1605, 1606, 1616, 1617, 1626, 1627, 1638, 1639, 1645, 1705, 1706, 1716, 1717, 1738, 1739, 1805, 1806, 1816, 1817, 1826, 1827, 1838, 1916, 1926, 2406, 2407, 2415, 2416, 2427, 2428, 2447, 2515, 2516, 2527, 2528, 2606, 2607, 2615, 2627, 2628, 2637, 2638, 2661, 2706, 2707, 2715, 2727, 2728, 2737, 2738, 2773, 2806, 2807, 2815, 2816, 2827, 2828, and 2868

Figure 2-180. Example of modified mess-hall with cross-gable side addition, Building 2637 (ERDC-CERL, 2019).

Figure 2-181. Example of a modified mess hall with a large side addition that houses bathroom and storage rooms, Building 1606 (ERDC-CERL, 2019).

Figure 2-182. Example of a modified mess hall with a hyphen addition connecting two mess halls together Building 2615 (ERDC-CERL, 2019).

Figure 2-183. Example of a modified mess hall with a hyphen addition connecting two mess halls together, Building 2827 (left) and Building 2828 (right) (ERDC-CERL, 2019).

Figure 2-184. Interior view of a modified mess hall currently used for classroom space (ERDC-CERL, 2019).

Figure 2-185. Interior view of the bathroom addition on a mess hall, Building 1606 (ERDC-CERL, 2019).

Figure 2-186. Interior view of a modified mess hall, Building 1616 (ERDC-CERL, 2019).

Figure 2-187. Interior view of the hallway addition connecting two mess halls, standing in Building 1617 looking towards Building 1616 (ERDC-CERL, 2019).

2.3.6 Storehouse Buildings

2.3.6.1 Standard storehouse – Type SH-13

The warehouse area has eight standard storehouse, Type SH-13, within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-188).

- Buildings 2107, 2108, 2141, 2142, 2143, 2145, 2147, and 2149

Figure 2-188. Oblique of standard storehouse, Type SH-13 buildings, Buildings 2149, 2147, 2143, and 2141 (ERDC-CERL, 2019).

2.3.6.2 Standard storehouse – Type SH-18

The warehouse area has six standard storehouse, Type SH-18, within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-189).

- Building 2119, 2121, 2123, 2125, 2161, and 2184

Figure 2-189. Oblique of standard storehouse, Type SH-18 buildings, Buildings 2125, and 2121 (ERDC-CERL, 2019).

3.1.1 Repair and Service Buildings

2.3.6.3 Carpentry shop

The researchers determined that there was one carpentry shop within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-190).

- Building 2115

Figure 2-190. Front side of a carpentry shop, Building 2115 (ERDC-CERL, 2019).

2.3.6.4 Motor Repair Shop

The researchers determined that there was one motor repair shop within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type.

- Building 1764

2.3.6.5 Railroad Shop

The researchers determined that there was one railroad shop within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type (Figure 2-191).

- Building 2109

Figure 2-191. Oblique of railroad shop, Building 2109 (ERDC-CERL, 2019).

2.3.6.6 *Utility Shop*

The researchers determined that there was one utility shop within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type (Figure 2-192).

- Building 2116

Figure 2-192. Looking at the north side of the utility shop, Building 2116 (ERDC-CERL, 2019).

2.3.7 Support Buildings

2.3.7.1 G.U. Dispensary – Type G.U.D-1

The researchers determined that there was one G.U. dispensary, Type G.U.D.-1, within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-193).

- Building 750

Figure 2-193. Oblique of a G.U. dispensary, Building 750 (ERDC-CERL, 2019).

2.3.7.2 Regimental exchange building

The researchers determined that there were six regimental exchange buildings within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-194 to Figure 2-196).

- Buildings 110, 352, 751, 2558, 2669, and 2874

Figure 2-194. East side of exchange, Building 110 (ERDC-CERL, 2019).

Figure 2-195. Oblique of a regimental exchange, Building 2558 (ERDC-CERL, 2019).

Figure 2-196. View of modified interior space in a regimental exchange building, Building 2874 (ERDC-CERL, 2019).

2.3.7.3 Bakery

The researchers determined that there was one bakery within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type (Figure 2-197).

- Building 2113

Figure 2-197. View of the west side of the bakery, Building 2113 (ERDC-CERL, 2019).

2.3.7.4 *Regimental chapels*

The researchers determined that there was one regimental chapel within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-198).

- Building 2672

Figure 2-198. Front oblique of a regimental chapel, Building 2672 (ERDC-CERL, 2019).

2.3.7.5 *Fire station*

The researchers determined that there was one fire station within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type (Figure 2-199).

- Building 2111

Figure 2-199. Oblique of fire station, Building 2111 (ERDC-CERL, 2019).

2.3.7.6 Post offices

The researchers determined that there was one post office building within the Fort McCoy cantonment that exhibited the features to be a Number 3 Type building (Figure 2-200).

- Building 2675

Figure 2-200. Oblique of a post office, Building 2675 (ERDC-CERL, 2019).

4 Current Condition of Landscape

4.1 Whole Cantonment Landscape

The Camp McCoy cantonment was designed and constructed in a triangular layout or triad (Figure 4-1). The three legs of the triad are referred to in this section as the northeast, northwest and southern legs based on their orientation. This triangular form and grid of streets and avenues remains today (Figure 4-2). While many of the original WWII temporary buildings remain in the landscape of Fort McCoy today, some significant changes have been made.

One of the biggest changes in the layout of the landscape is the demolition of several entire blocks of buildings. Only seven WWII-era buildings remain in the 200, 300, 400 and 500 blocks of the northeastern leg of the cantonment. New construction, of a different mass and scale occupies a portion of the 200 Block. In the southern leg, most of the 1500 Block was also demolished to make room for a new PX, commissary and community center. Only one building remains in this block. In this case three massive buildings have replaced many smaller buildings. The mass and scale have changed. In addition, the buildings are set back in the lot and massive parking lots are along the streets.

Another large change is at the motor pools. During the period of significance, these areas had smaller buildings that lined the roads. This allowed the soldiers to be able to walk from their barracks to the motor pools for training or work. Today, larger metal buildings have replaced the smaller buildings and they are setback far from the road and fenced in so no longer as accessible to the units they support. The mass and scale have changed as well.

Below is a block by block discussion to highlight missing buildings, new construction, and changes in the landscape between 1942 and today.

Figure 4-1. Master Plan for Camp McCoy showing triad layout, 1941 (DPW, Fort McCoy).

Figure 4-2. Current map of Fort McCoy, 2014 (Fort McCoy).

4.2 Company Blocks

The landscape of Fort McCoy is divided into company blocks by the layout and design, the roads and circulation patterns, the land use patterns, the mission, military culture and the use of standardized plans during a period of and need for rapid mobilization of large numbers of troops. These blocks were physically and visually separated by fire breaks and create a repetition visual throughout the landscape. These blocks provide the character of Fort McCoy. However, over the years these blocks have been modified.

Each block is discussed in detail below, including a comparison of how it appeared in 1941 and how it appears today. A crop of the 1941 map is provided as well as a crop of a 2014 installation map. The 1941 map used was color coded by the installation based on building use. The color key is provided below (Figure 4-3).

Figure 4-3. Color key for 1941 plan (Fort McCoy).

L E G E N D
ADMINISTRATION
BARRACKS
RECREATION
FOOD (MESS & FOOD SUPPLY BLDGS)
STOREHOUSES
REPAIR SHOPS
OFFICERS QUARTERS
SPECIAL BLDGS.

2.3.8 Number 1, 2, 3 Types in Cantonment Blocks

Based upon the evaluation and categorization of the WWII buildings described in Section 4.1 – 4.3, the researchers used a Fort McCoy 2014 cantonment map and color-coded the buildings according to the findings to better highlight the individual cantonment blocks and the overall volume of WWII buildings left within the Triad (see Figure 4-4).

Figure 4-4. Number 1 Type buildings are shown in red, Number 2 Type buildings in blue and Number Type 3 buildings in green on Fort McCoy map, 2014. (Fort McCoy DPW, modified by ERDC-CERL, 2019).

2.3.9 100 Block

Of the 13 original WWII-era buildings in the 100 Block, the only one missing is the Officers Club (Building 101) (Figure 4-5 - Figure 4-7). It is unknown when it was removed but it was still extant in 1978. Other buildings in the complex included the Headquarters Building (100), support buildings (102 and 109), administration buildings (103 and 104), quarters (105 and 108), barracks (107), and an exchange (110).

A flagpole is located in a plaza in front of Building 100 and Fort McCoy is written in white at the base (Figure 4-8 and Figure 4-9).

Figure 4-5. Crop of 100 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-6. Crop of 100 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 100 Block:

- Number 1 Type – 1 (red)
- Number 2 Type – 5 (blue)
- Number 3 Type – 3 (green)
- Demolished – 1

Figure 4-7. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 100 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-8. View north to Building 100 (ERDC-CERL, 2018).

Figure 4-9. View toward flagpole and Buildings 100 and 110 (in background) (ERDC-CERL, 2018).

4.2.1 200 Block

Nothing remains of the 200 Block from the WWII-era (Figure 4-10 - Figure 4-11). New buildings have been built in the block but were not photographed for the report.

Figure 4-10. Crop of 200 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-11. Crop of 200 Block, 2014 map (Fort McCoy).

4.2.2 300 Block

Only one of the 15 WWII building (Building 352) remains of the 300 Block (Figure 4-12 - Figure 4-15). No new buildings have been built in the block.

Figure 4-12. Crop of 300 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-13. Crop of 300 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 300 Block:

Number 3 Type (green) – 1

Demolished – 14

Figure 4-14. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 300 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-15. View to the southeast of the 300 Block with Building 352 (ERDC-CERL, 2018).

4.2.3 400 Block

Only four WWII buildings (Buildings 451-454) remain of the original 52 WWII buildings on the southwest side of East 12th Street (Figure 4-16 - Figure 4-19). The four buildings were BOQs.

Figure 4-16. Crop of 400 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-17. Crop of 400 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 400 Block:

Number 2 Type (blue) – 4

Demolished - 48

Figure 4-18. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 400 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-19. View to the southwest of the 400 Block and Buildings 451-454 (ERDC-CERL, 2018).

4.2.4 500 Block

Only two WWII buildings remain in the 500 Block, a fire station* (Building 450) and a vehicle storage building (Building 457) (Figure 4-20 and Figure 4-21). The other 53 buildings have been demolished.

* Building 550 was determined eligible in the *Determination of NRHP Eligibility for 26 Buildings at Fort McCoy, Wisconsin (2018)* report.

Figure 4-20. Crop of 500 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-21. Crop of 500 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 500 Block
(Figure 4-22 - Figure 4-24):

- Number 1 Type – 1 (red)
- Number 2 Type (blue) – 1
- Demolished - 53

Figure 4-22. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 500 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-23. Southwest oblique of the fire station (Building 550) (ERDC-CERL, 2018).

Figure 4-24. View of front side of vehicle storage building (Building 547) (ERDC-CERL, 2018).

4.2.5 600 Block

Most of the WWII-era buildings remain in the 600 Block. Building 634 was added to the landscape (or possibly moved, as not on 1942 map and not in correct numbered sequence) (Figure 4-25 - Figure 4-29). A new laundromat (Building 651) was built and a new ammunition storage building (Building 615) (Figure 4-30). The associated motor pool buildings are all gone and have been replaced with new buildings with larger mass, scale, and setbacks.

Figure 4-25. Crop of 600 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-26. Crop of 600 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 600 Block:

- Number 1 Type (red) – 9
- Number 2 Type (blue) – 9
- Number 3 Type (green) – 27
- Demolished – 5
- New construction – 6

Figure 4-27. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 600 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-28. View of front side of Building 626 (ERDC-CERL, 2019).

Figure 4-29. Oblique view of Building 625 (ERDC-CERL, 2019).

Figure 4-30. View of new ammunition storage building (Building 615), in brick veneer on right, looking north up East N Street (ERDC-CERL, 2019).

4.2.6 700 Block

Most of the buildings are intact in the 700 Block. Missing barracks buildings are not on 1941 map. Two new ammunition lockers were added (AV07 A and B) and a new laundromat (Building 755) was added. The associated motor pool buildings are all gone and have been replaced with new building with larger mass, scale and setbacks (Figure 4-31 - Figure 4-36).

Figure 4-31. Crop of 700 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-32. Crop of 700 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 700 Block:

- Number 2 Type (blue) – 1
- Number 3 Type (green) - 42
- Demolished – 8
- New construction – 9

Figure 4-33. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 700 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-34. View south down East P Street with Building 710 on right (ERDC-CERL, 2019).

Figure 4-35. View south at front side of Building 732 and walkway along rears of Buildings 731, 730 and 729 (ERDC-CERL, 2019).

Figure 4-36. View looking south down East Q Street with Building 731 on right (ERDC-CERL, 2019).

4.2.7 800 Block

The 800 Block landscape is mostly intact. There is one missing building in the south (maybe Building 850). Also, the WWII-era motor pool buildings are demolished and replaced with Buildings 844 and 851. Building 855 has been fenced in (Figure 4-37 - Figure 4-43).

Figure 4-37. Crop of 800 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-38. Crop of 800 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 800 Block:

- Number 1 Type (red) – 4
- Number 2 Type (blue) – 8
- Number 3 Type (green) – 28
- Demolished – 6
- New construction – 1

Figure 4-39. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 800 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-40. View south down East R Street with Building 810 on right (ERDC-CERL, 2019).

Figure 4-41. Oblique view looking west at Building 806 (ERDC-CERL, 2019).

Figure 4-42 Oblique view of Building 855 (ERDC-CERL, 2019).

Figure 4-43. View looking north at front side of Building 857 (ERDC-CERL, 2019).

4.2.8 900 Block

The 900 Block is comprised of the second service club (905 which was destroyed by a fire in 1951 and reconstructed in 1952 and is not covered in this report) and a BOQ (904). The WWII theater building was demolished. A picnic pavilion has been added and building 900 on the site. Three other buildings (901, 902 and 903), two recreation buildings and a CO quarters have been incorporated into the museum complex (Figure 4-44 - Figure 4-48).

Figure 4-44. Crop of 900 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-45. Crop of 900 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 900 Block:

Number 2 Type (blue) – 4

New construction – 3

Figure 4-46. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 900 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-47. Front side of service club (Building 905) which was reconstructed in 1952 after a fire (ERDC-CERL, 2018).

Figure 4-48. View of side of Building 904, in background, and the new picnic pavilion and restroom Building 900, in middle ground (ERDC-CERL, 2019).

4.2.9 1000 Block

The 1000 Block was the hospital complex, no longer extant. In 1942, the complex was made up of a series of specialized buildings for the hospital, officers' quarters, barracks, store houses, mess halls and administration (Figure 4-49 - Figure 4-53). The complex was demolished in the 1990s after the completion of HABS documentation.

Figure 4-49. Crop of hospital complex (1000 Block) from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-50. Aerial view of hospital complex (1000 Block), 1988 (HABS, Library of Congress).

Figure 4-51. Oblique view of Building 1046, 1988 (HABS, Library of Congress).

Figure 4-52. Current aerial of hospital complex, 2019 (google.com, accessed 8 November 2019)

Figure 4-53. View of hospital complex looking east down South 9th Avenue from South V Street (ERDC-CERL 2019).

4.2.10 1100 Block

The 1100 Block was a small block. One mess hall is missing (Building 1128) and a large new Building 1122 and associated Building 1127 have been added to the landscape. The original storehouse buildings (1154 and 1153) and the grease rack enclosure building (1152) remain (Figure 4-54 - Figure 4-59).

Figure 4-54. Crop of 1100 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-55. Crop of 1100 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 1100 Block:

- Number 1 Type (red) – 10
- Number 2 Type (blue) – 6
- Number 3 Type (green) – 7
- Demolished – 5
- New construction - 2

Figure 4-56. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1100 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-57. View of front sides of storehouse buildings (Buildings 1154 and 1153) (ERDC-CERL, 2019).

Figure 4-58. Oblique view of grease rack enclosure building (Building 1152) (ERDC-CERL, 2019).

Figure 4-59. View looking west at infill construction (Buildings 1122 and 1127) (ERDC-CERL, 2018).

4.2.11 1200 Block

Most of the buildings remain in the 1200 Block. The two that have been demolished were adjacent to Building 1254 and in the motor pool (Building 1259). While six other motor pool buildings remain, new buildings were constructed behind these (Buildings 1268 and 1270) (Figure 4-60 - Figure 4-65).

The following building types have been identified for the 1200 Block:

- Number 1 Type (red) – 3
- Number 2 Type (blue) - 42
- Number 3 Type (green) – 5
- Demolished – 2
- New construction – 2

Figure 4-60. Crop of 1200 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-61. Crop of 1200 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 1200 Block:

- Number 1 Type (red) – 3
- Number 2 Type (blue) - 42
- Number 3 Type (green) – 5
- Demolished – 2
- New construction – 2

Figure 4-62. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1200 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-63. Obliques of Buildings 1255 and 1256 (ERDC-CERL, 2019).

Figure 4-64. View looking east along South 10th Avenue in 1200 Block (ERDC-CERL, 2019).

Figure 4-65. View of motor pool buildings in 1200 Block (ERDC-CERL, 2019).

4.2.12 1300 Block

Eleven WWII buildings were demolished in the 1300 Block. The recreation buildings have been joined by additions. A new metal building has been added to the landscape (Building 1395). The NCO Academy was built on the site of the old motor pool. Parking lots have been added in the open space throughout the block (Figure 501 - Figure 4-71).

Figure 4-66. Crop of 1300 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-67. Crop of the 1300 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 1300 Block:

- Number 2 Type (blue) – 23
- Number 3 Type (green) – 11
- Demolished – 11
- New construction – 7

Figure 4-68. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1300 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-69. Oblique of Building 1332 (ERDC-CERL, 2019).

Figure 4-70. View of side of Building 1331 from South 11th Avenue (ERDC-CERL, 2019).

Figure 4-71. View down South N Street toward NCO Academy (ERDC-CERL, 2019).

4.2.13 1400 Block

Sixteen building have been demolished in the 1400. A new building, Building 1454, was constructed for the Signal Brigade. The four recreation buildings have additions and are now two large building (Buildings 1421 and 1442). The motor pool buildings are all gone and a new building (Building 1478) has been built in its place as well as a large parking lot (Figure 4-72 - Figure 4-75).

Figure 4-72. Crop of 1400 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-73. Crop of 1400 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 1400 Block:

- Number 1 Type (red) – 2
- Number 2 Type (blue) – 28
- Number 3 Type (green) – 6
- Demolished – 16
- New construction – 3

Figure 4-74. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1400 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-75. Obliques of Buildings 1448, 1446 and 1445 front South 11th Avenue (ERDC-CERL, 2019).

4.2.14 1500 Block

Only one WWII building remains in the 1500 Block, Building 1501; the other 33 WWII have been demolished. It is a brick covered former company administration building now a Credit Union with no integrity. Construction of three large buildings has changed the landscape drastically. The new community center (Building 1571), PX (Building 1538) and commissary (Building 1537) and their associated parking lots fill the block (Figure 4-76 - Figure 4-79).

Figure 4-76. Crop of 1500 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-77. Crop of 1500 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 1500 Block:

Number 3 Type (green) – 1

Demolished – 33

New construction – 11

Figure 4-78. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1500 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-79. View to the southwest of Building 1501 (ERDC-CERL, 2018).

4.2.15 1600 Block

For the central portion of the 1600 Block all the buildings are present. New ammunition vaults were added south of Building 1632. New motor pool buildings were built where formerly there were none (Building 1673-1679). New buildings (Buildings 1671, 1669, 1655 and 1668) have also been added east of Building 1645 in the site of a missing recreation building. Building 1662 appears to be a 700 series barracks (Figure 4-80 - Figure 4-85).

Figure 4-80. Crop of 1600 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-81. Crop of 1600 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 1600 Block:

- Number 2 Type (blue) – 17
- Number 3 Type (green) – 43
- Demolished – 3
- Additional buildings – 18

Figure 4-82. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1600 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-83. View looking west of Building 1645 on left and new building 1655 on right (ERDC-CERL, 2019).

Figure 4-84. View of front side of Building 1645 showing addition (ERDC-CERL, 2019).

Figure 4-85. View looking west on South Regimental Avenue with Building 1649 on left (ERDC-CERL, 2019).

4.2.16 1700 Block

A new dining hall (Building 1770) was constructed in the fire break between the 1600 and 1700 blocks as well as a large associated parking lot. A new laundromat was constructed (Building 1735). Many new motor pool buildings were constructed (Buildings 1762, 1763, 1764, 1781, 1782, and

1783). Building 1764 appears to be a WWII-era motor pool building. Two new ammunition vaults were added south of Building 1732. Building 1745 is a newer metal garage. Chain link fences were added to enclose a daycare facility. WWII-era buildings along South F Street north of the company block include a chapel, and two support buildings. New buildings in this area include Buildings 1796 and 1792, a new daycare facility (Figure 4-86 - Figure 4-91).

Figure 4-86. Crop of 1700 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-87. Crop of 1700 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 1700 Block:

- Number 2 Type (blue) – 17
- Number 3 Type – 36
- Demolished – 2
- New construction – 10

Figure 4-88. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1700 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-89. Looking south down South G Street from South Regimental Avenue (ERDC-CERL, 2019).

Figure 4-90. Front side of Building 1751 (ERDC-CERL, 2019).

Figure 4-91. View toward chapel (Building 1759) looking north on South F Street (ERDC-CERL, 2019).

4.2.18 1800 Block

In the north section of the 1800 Block, buildings 1860, 1861, 1845 and 1867 have been demolished. In the central portion of the block Buildings 1839 and 1841 have been demolished. The motor pool is missing all of the WWII-era buildings. These buildings have been replaced by Buildings 1870, 1871, 1877, 1878, 1879, 1887, and 1884. Two ammunition vaults have been added as well as a new laundromat (Buildings 1856) (Figure 4-92 - Figure 4-98).

Figure 4-92. Crop of 1800 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-93. Crop of 1800 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 1800 Block:

- Number 1 Type (red) – 2
- Number 2 Type (blue) – 6
- Number 3 Type – 50
- Demolished – 15
- New construction – 10

Figure 4-94. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1800 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-95. View looking west toward Buildings 1864, 1865, and 1861 (ERDC-CERL, 2019).

Figure 4-96. Side view of Building 1868 (ERDC-CERL, 2019).

Figure 4-97. View south down South E Street from South Regimental Avenue (ERDC-CERL, 2019).

Figure 4-98. Looking southwest along South 11th Avenue with Building 1856 on right and new dining hall on left (ERDC-CERL, 2018).

4.2.19 1900 Block

Two mess halls are missing from the 1900 Block (Buildings 1939 and 1938). Two recreation buildings (maybe Buildings 1946 and 1947) in the north end of the block were demolished and a parking lot has replaced them. Two barracks were joined into one building (now called Building 1913). A new picnic shelter was added. Construction was started in a new dining hall in the fire break between the 1800 and 1900 blocks in 2018 (Figure 4-99 - Figure 4-103).

Figure 4-99. Crop of 1900 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-100. Crop of 1900 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 1900 Block:

- Number 1 Type (red) – 1
- Number 2 Type (blue) – 9
- Number 3 Type – 27
- Demolished – 2
- New construction – 1

Figure 4-101. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 1900 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-102. View east on South 10th Avenue with Buildings 1923 and 1941 on left (ERDC-CERL, 2019).

Figure 4-103. Front sides of Buildings 1921 and 1922 with new picnic shelter in rear (ERDC-CERL, 2019).

4.2.20 2000 Block

The 2000 Block contains a WWII service club. Adjacent to the service club were four buildings, a theater, another support building, and an administration building. Three of these buildings were demolished: the theater, the administration building and one of the support buildings. The service club was undergoing a complete rehabilitation in 2018.*

North of the service club along Post Road were two administration buildings, several officers' quarters, mess halls and two recreation buildings. Most of these buildings remain today except the two administration buildings and one of the mess halls. A new laundromat (Building 2002) has been added on West 12th Street (Figure 4-104 - Figure 4-112).

* Building 2000 was determined eligible in the *Determination of NRHP Eligibility for 26 Buildings at Fort McCoy, Wisconsin (2018)* report. In between the publication of that report and the publication of this report, the building underwent a renovation that removed its WWII character-defining features.

Figure 4-104. Crop of 2000 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-105. Crop of 2000 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 2000 Block:

- Number 1 Type (red) – 2
- Number 2 Type (blue) – 4
- Number 3 Type (green) – 4
- Demolished – 6

Figure 4-106. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 2000 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-107. View of front side of Service Club (Building 2000) during renovation (ERDC-CERL, 2019).

Figure 4-108. Front side of Building 2001 (ERDC-CERL, 2019).

Figure 4-109. Front side of new laundromat (Building 2002) (ERDC-CERL, 2019).

Figure 4-110. Oblique view of two recreation buildings (Buildings 2004 and 2005) (ERDC-CERL, 2019).

Figure 4-111. Front side of Building 2005 (ERDC-CERL, 2019).

Figure 4-112. Front side of Buildings 2008 and 2009 (ERDC-CERL, 2019).

4.2.21 2100 Block

The 2100 Block is the support, warehouse, quartermaster areas and the rail lines into the cantonment. The block originally had 71 WWII buildings, but 48 of those have been demolished. Several buildings have been demolished and 25 new buildings were constructed in the block. Missing are the old laundry building and the storage buildings in the western portion of the area (everything between South F Street and South H Street). Also demolished were four administration buildings east of the laundry, and two others one north of and four mess halls. Also missing are three barracks north of South 8th Avenue. New construction in the 2100 Block are all larger in scale and mass (Buildings 2100, 2171, and 2187). All of the WWII storage buildings along the rail lines east of South H Street remain today, but their exteriors were heavily modified (Figure 4-113 - Figure 4-117).

Figure 4-113. Crop of 2100 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-114. Crop of 2100 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 2100 Block:

- Number 1 Type (red) – 0
- Number 2 Type (blue) – 0
- Number 3 Type (green) – 23
- Demolished – 6

Figure 4-115. Side view of Buildings 2107 and 2117 from South H Street (ERDC-CERL, 2019).

Figure 4-116. Oblique view of Buildings 2125, 2121 and 2119 from South H Street (ERDC-CERL, 2019).

Figure 4-117. Oblique view of Buildings 2149, 2147, 2143, and 2141 from South H Street (ERDC-CERL, 2019).

4.2.22 2200 Block

In 1942, the 2200 Block was a motor pool with 5 buildings. It was located west of the stockade (2300 Block). Nothing remains of the 2300 Block from the WWII-era Today the stockade is a dirt lot with one building that is not from the WWII-era (Figure 4-118 - Figure 4-119).

Figure 4-118. Crop of stockade complex (2200 Block) from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-119. Aerial view of 2200 Block, 2019 (www.google, accessed 8 November 2019).

4.2.23 2300 Block

In 1942, the 2300 Block was the stockade. Consisting of 4 barracks buildings 2 special buildings and a mess hall within a fenced compound, and 2 barracks and a third fenced barracks outside the fenced compound and 4 towers on each corner (Figure 4-120 - Figure 4-121). All of the WWII buildings have been demolished. Today the stockade is a dirt lot.

Figure 4-120. Crop of stockade complex (2300 Block) from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-121. Aerial view of 2300 Block, 2019 ([www.google](http://www.google.com), accessed 8 November 2019).

2.3.10 2400 Block

Of the original WWII-era buildings only a mess hall (Building 2437 or 2438) appears to have been demolished. It was not replaced. Five new buildings were added west of the bend in West A Street (Buildings 2450-2454) and a laundromat was built (Figure 4-122 - Figure 4-128).

Figure 4-122. Crop of 2400 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-123. Crop of 2400 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 2400 Block:

- Number 2 Type – 1
- Number 3 Type – 42
- Demolished – 1
- New construction – 5

Figure 4-124. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 2400 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-125. View along West 13th Avenue looking north in 2400 Block (ERDC-CERL, 2019).

Figure 4-126. View looking northeast down West B Street in 2400 Block (ERDC-CERL, 2019).

Figure 4-127. View northeast down West C Street showing missing mess hall (Building 2437 or 2438) on left (ERDC-CERL, 2019).

Figure 4-128. Oblique view of new buildings (Buildings 2450-2454) along West A Street (ERDC-CERL, 2019).

4.2.24 2500 Block

The 2500 Block there are missing four WWII-era mess halls (Buildings 2506, 2507, 2537 and 2438). New buildings added to the 2500 Block include Buildings 2538, 2570, 2571, 2572, 2573, and 2574. Two new ammunition storage buildings were built behind Building 2521. New motor pool type buildings (Buildings 2576-2580) have been added across West 13th Street where there were no buildings in 1942 (Figure 4-129 - Figure 4-137).

Figure 4-129. Crop of 2500 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-131. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 2500 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-132. View northeast down West D Street with Buildings 2512 and 2510 in foreground. Note demolished mess halls on right (ERDC-CERL, 2019).

Figure 4-133. View northeast down West E Street, missing mess halls on left (ERDC-CERL, 2019).

Figure 4-134. Front side of Building 2557 (ERDC-CERL, 2019).

Figure 4-135. Oblique view of Buildings 2566, 2565, 2564 and 2463 (ERDC-CERL, 2019).

Figure 4-136. Oblique view of Building 2545 (ERDC-CERL, 2019).

Figure 4-137. View of new motor pool buildings (Buildings 2576 and 2577) from West 13th Avenue (ERDC-CERL, 2019).

4.2.25 2600 Block

Most of WWII-era company buildings remain. However, a new laundromat (Building 2671) was constructed in 2600 Block as well as a new large mess hall (Building 2674) to the north in the fire break. Another large administration building was constructed south of West 12th Avenue (Building 2643). In addition, many new large motor pool buildings were constructed west of West 13th Avenue. The newly constructed buildings are different in size, scale, and setback and are surrounded by parking lot. Two new ammunition lockers (AV26A and B) were added, as well as a covered pavilion behind Building 2632.

Also on South F Street, two buildings were constructed (Buildings 2691 and 2692) and a recreation building was removed and replaced by Buildings 2693 and 2694 (Figure 4-138 - Figure 4-145).

Figure 4-138. Crop of 2600 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-139. Crop of 2600 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 2600 Block:

- Number 1 Type – 1
- Number 2 Type – 10
- Number 3 Type – 45
- Demolished – 2
- New construction – 17

Figure 4-140. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 2600 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-141. View of front sides of Buildings 2656 and 2657 with new brick dining facility in rear on left and new brick laundromat in rear on right (ERDC-CERL, 2019).

Figure 4-142. View of new dining facility (Building 2674) and large parking lot (ERDC-CERL, 2019).

Figure 4-143. View of new ammunition storage lockers (AV26 A and B) from West 12th Avenue (ERDC-CERL, 2019).

Figure 4-144. View along West 12th Avenue with Building 2665 to right (ERDC-CERL, 2019).

Figure 4-145. View of new motor pool buildings 2681-2688 west of West 13th Avenue (ERDC-CERL, 2019).

4.2.26 2700 Block

In the 2700 Block, most of the WWII-era company buildings remain. A new building (Building 2776) was added and two new ammunition lockers were constructed behind Building 2721.

Many new large motor pool buildings were constructed west of West 13th Avenue. New buildings are different in size, scale, and setback and are surrounded by parking lots. In addition, many buildings were added west of West 14th Street changing the scale and feeling of the landscape (Figure 4-146 - Figure 4-151).

Figure 4-146. Crop of 2700 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-147. Crop of 2700 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 2700 Block:

- Number 1 Type – 2
- Number 2 Type – 7
- Number 3 Type – 48
- Demolished – 9
- New construction – 18

Figure 4-148. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 2700 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-149. View south down West 13th Avenue with Building 2744 on left (ERDC-CERL, 2019).

Figure 4-150. View down West I Street with Building 2734 on left (ERDC-CERL, 2019).

Figure 4-151. View of new motor pool complex west of 2700 Block (ERDC-CERL, 2019).

4.2.27 2800 Block

The 2800 Block is missing one building (Building 2813). A large new building (Building 2840) was constructed on the north side of West J ST. In addition, a new laundromat (Building 2877) and two new ammunition storage lockers were built. The largest change was in the motor pool area, where many small WWII buildings were demolished and replaced with larger, metal buildings with a large setback and removed connection with the rest of the unit (Figure 4-152 - Figure 4-160).

Figure 4-152. Crop of 2800 Block from Camp McCoy plan, 1941 (Fort McCoy).

Figure 4-153. Crop of 2800 Block, 2014 map (Fort McCoy).

The following building types have been identified for the 2800 Block:

- Number 1 Type – 4
- Number 2 Type – 4
- Number 3 Type – 36
- Demolished – 16
- New construction – 12

Figure 4-154. 1941 map (left) and 2014 map (right): Fort McCoy color-coded map of the 2800 Block area (Fort McCoy DPW, modified by ERDC-CERL, 2019).

Figure 4-155. View of West J Street and missing Building 2813. (ERDC-CERL, 2019).

Figure 4-156. View along West 13th Avenue of Buildings 2812, 2833, 2832, and 2831 (ERDC-CERL, 2019).

Figure 4-157. View along West 13th Avenue showing changes to motor pool area (ERDC-CERL, 2019).

Figure 4-158. View down West K Street at new Building 2840 (ERDC-CERL, 2019).

Figure 4-159. Oblique view of new laundromat (Building 2877) (ERDC-CERL, 2019).

Figure 4-160. Oblique view of Building 2829 and new ammunition storage lockers in rear (ERDC-CERL, 2019).

5 Determination of Significance

5.1 Categories of Historic Properties

The identification of historically significant properties is achieved through evaluation of their position within a larger historic context. According to the NRHP, historic contexts are defined as “...the patterns, themes, or trends in history by which a specific occurrence, property, or site is understood and its meaning (and ultimately its significance) within prehistory or history is made clear.”* A historic property is determined significant or not significant by applying the standardized National Register Criteria for Evaluation within a property’s historic context. The NRHP categorizes significant properties as buildings, sites, districts, structures, or objects.† Definitions of these five property types are summarized below:‡

Building: A building is created principally to shelter any form of human activity. Examples of buildings include: administration building, house, barn, stable, train station, church, or shed.

Structure: Structures are distinguished from buildings by being functional constructions made for purposes other than creating human shelter. Examples of structures include: aircraft hangars, bandstands, bridges, canals, fences, kilns, or windmills.

Object: The term object is used to distinguish from buildings and structures those constructions that are primarily artistic in nature or are relatively small in scale and simply constructed. Although it may be, by nature or design, movable, an object is associated with a specific setting or environment. Examples of objects include boundary markers, fountains, monuments, sculptures or statues.

Site: A site is the location of a significant event, a prehistoric or historic occupation or activity, or a building or structure, whether standing, ruined, or vanished, where the location itself possesses historic, cultural, or archeological value regardless of the value of any existing structure. Examples of sites include: battlefield, campsite, ceremonial site, designed landscape, rock shelter, or village site.

District: A district possesses a significant concentration, linkage, or continuity of sites, buildings, structures, or objects united historically or aesthetically by plan or physical development. A district can comprise both features that lack individual distinction and individually distinctive features that serve as focal points. A group of features lacking in individual distinction may even be considered eligible if the grouping achieves significance as a whole within its historic context. While a district derives its importance from being a unified

* National Park Service (NPS), *National Register Bulletin #15*, 7.

† *ibid.*, 9.

‡ *ibid.*, 4–5.

entity, it can contain buildings, structures, sites, objects, or open spaces that do not contribute to the significance of the district if these properties do not adversely affect the district's integrity.

5.2 NRHP Definitions and Criteria

The identification of historically significant properties is achieved only through the evaluation of their position within the larger historic context. According to the NRHP, historic contexts are defined as “...the patterns, themes, or trends in history by which a specific occurrence, property, or site is understood, and its meaning (and ultimately its significance) within prehistory or history is made clear.”* A historic property is determined significant or not significant based on the application of standardized NRHP criteria within the property's historical context. To qualify as historic, a property must have an association with a relevant historic context as well as having retained its physical integrity through which its historic significance is conveyed.

The NRHP Criteria for Evaluation describe how properties and districts are significant for their association with important events or persons (Criterion A and Criterion B), for their importance in design or construction (Criterion C), or for their information potential (Criterion D). A property may be significant under one or more criteria. The following is a brief description of each of the four NRHP Criteria for Evaluation, excerpted from *National Register Bulletin #15: How to Apply the National Register Criteria for Evaluation*:†

A. Event—associated with events that have made a significant contribution to the broad patterns of our history; or

B. Person—associated with the lives of persons significant in our past; or

C. Design/Construction—embodies the distinctive characteristics of a type, period, or method of construction; or that represents the work of a master; or that possesses high artistic values; or that represents a significant and distinguishable entity whose components may lack individual distinction; or

* NPS, *National Register Bulletin #15*, 7.

† NPS, *National Register Bulletin #15*, 2.

D. Information Potential—yielded, or may be likely to yield, information important in prehistory or history.

Criteria Consideration G—a property achieving significance within the past fifty years is eligible if it is of exceptional importance.

A property that has achieved significance within the past fifty years can be evaluated only when sufficient historical perspective exists to determine that the property is exceptionally important. The necessary perspective can be provided by scholarly research and evaluation and must consider both the historic context and the specific property's role in that context.

5.3 Final recommendations of significance

The temporary wood buildings constructed at Camp McCoy with the War Department's 700 Series or 800 Series plans during the WWII era from 1939-1946 were determined significant for listing on the National Register of Historic Places (NRHP) in 1986. That year is when the Programmatic Memorandum of Agreement (PMOA) was signed between the Department of Defense (DoD), the Advisory Council on Historic Preservation (ACHP), and the National Council of State Historic Preservation Officers (NCSHPO).^{*} In the early 1990s, this significance was reaffirmed by the writing of the "World War II and the U.S. Army Mobilization Program: A History of the 700 and 800 Series Cantonment Program"[†] and the performance of the Historic American Building Survey (HABS) across the country on a variety of the 700 and 800 Series planned buildings. Many of the 800 Series of buildings at Fort McCoy were utilized for the HABS documentation.

The Fort McCoy Real Property database has several of these buildings marked as semi-permanent instead of temporary, but the PMOA is clear in its wording, saying that all 700 and 800 Series plans are covered.

^{*} American Council on Historic Preservation, "Demolition of World War II Temporary Buildings," Programmatic Memorandum of Agreement among The United States Department of Defense, The Advisory Council on Historic Preservation, National Conference of State Historic Preservation Officers, and the Historic American Buildings Survey/Historic American Engineering Record (Washington, DC: ACHP, 1986).

[†] Wasch, et al., *World War II and the U.S. Army Mobilization Program*.

There are 786 buildings reviewed that were built during the 1939-1946 period of significance (see Table 1-1), and their integrity is addressed in Chapter 7.

1. Fort McCoy is significant under Criterion A at the national level in the category of Military, which is defined as “the system of defending the territory and sovereignty of a people.”

The Period of Significance for the above is 1939 - 1946.

2. Fort McCoy is also significant under Criterion C at the national level in the category of Military for its design and layout.

The Period of Significance for the above is 1939 - 1946.

Fort McCoy was not found to be significant for either Criteria B or D.

2.3.11 WWII temporary buildings significance

The following sections detail findings regarding the historical significance of WWII temporary buildings.

For Criterion A – Event

The WWII temporary buildings are significant under Criterion A for WWII temporary building construction (1939-1946).

For Criterion B – Person

There is no significant person associated with WWII temporary buildings.

For Criterion C – Design/Construction

The design and construction of the WWII temporary buildings could not be linked to a specific architect due to their construction from standardized War Department mobilization building plans. They do not possess high artistic values; however, WWII temporary buildings in general were found to be significant for their design, construction, and technological innovation.

For Criterion D – History

The available historical records provided no indication that WWII temporary buildings have yielded, or were likely to yield, any information important in history.

2.3.12 Historic District

While the WWII-era street system of the Triad appears to be intact, many of the buildings constructed for WWII have been demolished per the 1986 PMOA, and most of the remaining buildings do not have their integrity from the period of significance. Out of the 786 overall buildings evaluated; 48 have their integrity (described as Number 1 Type in this report), 209 have only some of their integrity (described as Number 2 Type in this report), and 529 have no integrity at all (described as Number 3 Type in this report).

2.3.13 National, state, or local significance

WWII temporary buildings are significant at the national level for their contribution to the war effort during the period 1939-1946.

6 Aspects of Integrity

In addition to possessing historical significance, a property must also retain sufficient physical integrity of features in order to convey its significance and be eligible for listing on NRHP.* Integrity has very specific connotations in defining historic and cultural resources. Integrity is the authenticity of physical characteristics from which resources obtain their significance. Historic properties convey their significance through their integrity. Historic properties both retain integrity and convey their significance, or they do not.

6.1 Seven aspects of integrity

The National Register recognizes seven aspects or qualities of a property that define the concept of integrity. To retain historic integrity, a property must possess several, and usually most, of the seven aspects. The retention of specific aspects of historic integrity is paramount for a property to convey its significance. Determining which of these aspects are most important to a particular property requires knowing why, where, and when the property is significant. The seven aspects of integrity are listed in *National Register Bulletin #15: How to Apply the National Register Criteria for Evaluation* and summarized below:†

1. *Location* is the place where the historic property was constructed, or the place where the historic event occurred.
2. *Design* is the combination of elements that create the form, plan, space, structure, and style of a property. It results from conscious decisions made during the original conception and planning of a property (or its significant alteration) and applies to activities as diverse as community planning, engineering, architecture, and landscape architecture. Design includes such elements as organization of space, proportion, scale, technology, ornamentation, and materials.
3. *Setting* is the physical environment of a historic property. Setting refers to the character of the place in which the property played its historical role. It

* NPS, *National Register Bulletin #15*, 44–45.

† *ibid.*

- involves how, not just where, the property is situated and its relationship to surrounding features and open space.
4. *Materials* are the physical elements that were combined or deposited during a particular period of time and in a particular pattern or configuration, to form a historic property.
 5. *Workmanship* is the physical evidence of the crafts of a particular culture or people during any given period in history or prehistory.
 6. *Feeling* is a property's expression of the aesthetic or historic sense of a particular time period.
 7. *Association* is the direct link between an important historic event or person and a historic property.

Historic districts and individual resources are considered significant if they possess a majority of the seven aspects outlined above. Properties are classified as either “contributing” or “noncontributing” resources. Contributing resources date from the historic period of significance that has been established. They contribute significance and character through their historical associations and/or architectural values. Noncontributing resources are those that—due to the date of construction, alterations, or other factors—do not contribute to the district's historic significance or character.

6.2 Integrity determinations

1. *Location* is the place where the historic property was constructed, or the place where the historic event occurred.

All 786 buildings from the WWII era retain their integrity of location.

2. *Design* is the combination of elements that create the form, plan, space, structure, and style of a property. It results from conscious decisions made during the original conception and planning of a property (or its significant alteration) and applies to activities as diverse as community planning, engineering, architecture, and landscape architecture. Design includes such elements as organization of space, proportion, scale, technology, ornamentation, and materials.

Only 48 WWII temporary buildings retain the key elements of their WWII design (as outlined in Chapter 2) such as layout, massing, door openings, and window openings.

3. *Setting* is the physical environment of a historic property. Setting refers to the character of the place in which the property played its historical role. It involves how, not just where, the property is situated and its relationship to surrounding features and open space.

Sections of the Fort McCoy cantonment retain the massing and scale of a WWII triad cantonment; however, blocks are missing all buildings, and new construction has been added within the historic setting. In addition, most buildings have lost their integrity. Fort McCoy is missing the key elements of a WWII cantonment.

4. *Materials* are the physical elements that were combined or deposited during a particular period of time and in a particular pattern or configuration, to form a historic property.

Only 48 WWII temporary buildings retain the key elements of their WWII architectural materials such as wood door, wood windows, asbestos shingle siding with a scalloped bottom edge, wood foundation skirting, concrete porches with cast iron handrails, asphalt roofs, red brick chimneys, wood floors, concrete floors in kitchens and bathrooms, fiber-board walls, wood wainscots, plumbing fixtures, exposed suspended mechanical fixtures, exposed wood structural members, and light fixtures.

5. *Workmanship* is the physical evidence of the crafts of a particular culture or people during any given period in history or prehistory.

Workmanship is not a key part of integrity for WWII temporary buildings.

6. *Feeling* is a property's expression of the aesthetic or historic sense of a particular time period.

Only 48 buildings retain their feeling of WWII temporary buildings. The landscape retains some feeling as the layout of the cantonment, the roadways and building mass and scale remain.

7. *Association* is the direct link between an important historic event or person and a historic property.

Out of the overall 786 buildings evaluated for this report, only 48 buildings from the WWII era retain their integrity of association.

The following sections give a variety of examples of the loss of integrity of the WWII temporary buildings.

2.3.14 General exterior architectural elements

Number 1 Type is defined as having all or majority of the original exterior construction features from the 1942 construction date (Figure 6-1 and Figure 6-2). The interiors of the Number 1 Type are mostly intact with most of the original space and features present.

Number 2 Type is defined as having most of the original exterior features from the 1942 construction date. The interiors of the Number 2 type have some features intact, but most have been modified with new finishes and spaces.

Number 3 Type was defined as having no original exterior features from the 1942 construction date. Also, Number 3 Type buildings have had additions and hyphens constructed to connect two buildings. All the interiors of the Number 3 Types have been completely remodeled with new finishes and spaces with added partition walls.

Figure 6-1. Window comparison of the original eight-over-eight wood double-hung window with a simple wood architrave and asbestos shingle siding with a scalloped bottom edge on a 74-man barracks (left) to the current replacement one-over-one vinyl window and vinyl siding (right) (left: Library of Congress, HABS; right: ERDC-CERL, 2018).

Figure 6-2. Original asbestos shingle siding with a scalloped bottom edge detail and wood foundation skirting (left) compared to current replacement vinyl siding and plywood foundation skirting (right) (left: Library of Congress, HABS; right: ERDC-CERL, 2018).

2.3.15 74-man barracks

There were ten Number 1 Type 74-man barracks that retained their integrity from the WWII construction period. There were 49 Number 2 Type and 309 Number 3 Type barracks at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-1 and Figure 6-3 to Figure 6-8).

Table 6-1. List of 74-man barracks buildings per Number 1, 2, or 3 type classification (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	<p>Buildings 623, 624, 625, 628, 629, 1113, 1114, 1117, 1118, 1129</p>
<p>NUMBER 2 TYPE</p>	<p>Buildings 640, 641, 642, 840, 841, 842, 1105, 1130, 1203, 1204, 1208, 1209, 1210, 1213, 1214, 1217, 1224, 1225, 1229, 1230, 1231, 1235, 1236, 1239, 1304, 1305, 1308, 1324, 1325, 1339, 1404, 1407, 1408, 1409, 1413, 1414, 1417, 1424, 1425, 1426, 1429, 1435, 1436, 1439, 1440, 1441, 1720, 1744, 1932</p>
<p>NUMBER 3 TYPE</p>	<p>Buildings 602, 603, 604, 607, 608, 609, 610, 612, 613, 614, 618, 619, 620, 702, 703, 704, 707, 708, 709, 710, 712, 713, 714, 718, 719, 720, 723, 724, 725, 728, 729, 730, 731, 734, 735, 736, 740, 741, 742, 802, 803, 804, 807, 808, 809, 810, 812, 813, 814, 818, 819, 820, 823, 824, 825, 828, 829, 1108, 1313, 1314, 1329, 1330, 1331, 1335, 1336, 1602, 1603, 1604, 1607, 1608, 1609, 1610, 1612, 1613, 1614, 1615, 1618, 1619, 1620, 1623, 1624, 1625, 1628, 1629, 1630, 1631, 1634, 1635, 1636, 1637, 1640, 1641, 1642, 1702, 1703, 1704, 1707, 1708, 1709, 1710, 1712, 1713, 1714,</p>

	1715, 1718, 1719, 1723, 1724, 1725, 1728, 1729, 1730, 1731, 1732, 1736, 1737, 1740, 1741, 1742, 1802, 1803, 1804, 1807, 1808, 1809, 1810, 1812, 1813, 1814, 1815, 1818, 1819, 1820, 1823, 1824, 1825, 1828, 1829, 1830, 1831, 1832, 1834, 1835, 1836, 1837, 1840, 1842, 1844, 1913, 1914, 1915, 1918, 1919, 1920, 1923, 1924, 1925, 1928, 1929, 1930, 1931, 1934, 1935, 1936, 1937, 1940, 1941, 1944, 2007, 2403, 2404, 2405, 2408, 2409, 2410, 2412, 2413, 2414, 2417, 2418, 2419, 2420, 2421, 2423, 2424, 2425, 2426, 2429, 2430, 2431, 2434, 2435, 2436, 2439, 2440, 2441, 2442, 2501, 2502, 2503, 2504, 2505, 2508, 2509, 2510, 2512, 2513, 2514, 2517, 2518, 2519, 2520, 2521, 2523, 2524, 2525, 2526, 2529, 2530, 2531, 2534, 2535, 2536, 2539, 2540, 2541, 2601, 2602, 2603, 2604, 2605, 2608, 2609, 2610, 2612, 2613, 2614, 2617, 2618, 2619, 2620, 2621, 2623, 2624, 2625, 2626, 2629, 2630, 2631, 2634, 2635, 2636, 2639, 2640, 2641, 2642, 2701, 2702, 2703, 2704, 2705, 2708, 2709, 2710, 2712, 2713, 2714, 2717, 2718, 2719, 2720, 2721, 2723, 2724, 2725, 2726, 2729, 2730, 2731, 2734, 2735, 2736, 2739, 2740, 2741, 2742, 2801, 2802, 2803, 2804, 2805, 2808, 2809, 2810, 2811, 2812, 2814, 2817, 2818, 2819, 2820, 2821, 2823, 2824, 2825, 2826, 2829, 2830, 2831
--	--

Figure 6-3. Front side of a 74-man barracks with comparison of the original construction, design, and materials from 1950 (left) to 1988 (middle) to 2018 (right). Note, the original wood porches, steps, and handrails have already been removed and replaced with a concrete stoop and metal handrails in the middle images (left: NARA; middle: Library of Congress, HABS; right: ERDC-CERL).

Figure 6-4. Left side of a 74-man barracks with comparison of the original construction, design, and materials as extant in 1988 (left) to 2018 (right) (left: Library of Congress, HABS; right: ERDC-CERL).

Figure 6-5. Interior view of the original open-bay entry vestibule with wood screen doors leading to the first floor and to the open wood staircase (left) compared to the modified entry vestibule with partition wall and replacement wood interior doors (right) (left: Library of Congress, HABS; right: ERDC-CERL, 2018).

Figure 6-6. Interior view of an open-bay squad room in a 74-man barracks (left) compared to the modified squad room in 2018 (left: ERDC-CERL; right: ERDC-CERL, 2018).

Figure 6-7. Interior view of an original NCO room on the second floor of a 74-man barracks (left) compared to a modified NCO room from 2018 (right) (left: ERDC-CERL; right: ERDC-CERL).

Figure 6-8. Interior view of the original sink area in the latrine on the first floor of a 74-man barracks (left) compared to the modified sink area in 2018 (left: ERDC-CERL; right: ERDC-CERL).

2.3.16 Officers' quarters – Types BOQ-40, OBQ-40, OQM-40, OQ-40

There were no Number 1 Type officers' quarters, Type BOQ-40 that retained their integrity from the WWII construction period. There was one Number 2 Type and one Number 3 Type quarters at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-2 and Figure 6-9).

Table 6-2. List of officers' quarters, Type BOQ-40 buildings per Number 1, 2, or 3 type classification (ERDC-CERL).

NUMBER 1 TYPE	None
<p>NUMBER 2 TYPE</p>	Buildings 2666
<p>NUMBER 3 TYPE</p>	Buildings 655

Figure 6-9. Front and side of an officers' quarters, Type BOQ-40 with comparison of the original construction, design, and materials as extant in 1988 (left) to a Number 2 type (middle) and a Number 3 type (right) (left; Library of Congress, HABS; middle and right: ERDC-CERL).

2.3.17 Officers' quarters – Types BOQ-44

There were no Number 1 Type officers' quarters, Type BOQ-44 that retained their integrity from the WWII construction period. There were 24 Number 2 Type and eight Number 3 Type quarters at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-3 and Figure 6-10).

Table 6-3. List of officers' quarters, Type BOQ-44 buildings per Number 1, 2, or 3 type designation (ERDC-CERL).

NUMBER 1 TYPE	None
Buildings 107, 451, 452, 453, 454, 851, 852, 853, 1249, 1250, 1251, 1657, 1658, 1660, 1661, 1858, 1859, 1862, 2009, 2010, 2011, 2772, 2774, 2775
NUMBER 2 TYPE
Buildings 652, 653, 654, 1857, 2562, 2564, 2565, 2779
NUMBER 3 TYPE	

Figure 6-10. Front and sides of an officers' quarters, Type BOQ-44 with comparison of the original construction, design, and materials as extant in 1988 (left) to a Number 2 type (middle) and a Number 3 type (right) (left; Library of Congress, HABS; middle and right: ERDC-CERL).

2.3.18 Officers' quarters – Type OQ-23, 700 Series

There were no Number 1 Type officers' quarters, Type OQ-23, 700 Series that retained their integrity from the WWII construction period. There were two Number 2 Type and five Number 3 Type quarters at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-4).

Table 6-4. List of officers' quarters, Type OQ-23, 700 Series buildings per Number 1, 2, or 3 type designation (ERDC-CERL).

NUMBER 1 TYPE	None
Buildings 904, 1662
Buildings 1632, 1863, 1864, 2561, 2778

2.3.19 WAC barracks

There were no Number 1 Type or Number 2 Type WAC barracks that retained their integrity from the WWII construction period. There was one Number 3 Type WAC barracks at Fort McCoy that did not retain its integrity for a WWII temporary building (see Table 6-5).

Table 6-5. List of WAC barracks buildings per Number 1, 2, or 3 type designation (ERDC-CERL).

NUMBER 1 TYPE	None
NUMBER 2 TYPE	None
NUMBER 3 TYPE	Building 2171

2.3.20 Brigade general's quarters – Type BGQ-1

There were no Number 1 Type brigade general's quarters, Type BGQ-1 that retained their integrity from the WWII construction period. There were four Number 2 Type that did not retain their integrity for a WWII temporary building and no Number 3 Type quarters at Fort McCoy (see Table 6-6).

Table 6-6. List of brigade general's quarters, Type BGQ-1 per Number 1, 2, or 3 type designation (ERDC-CERL).

NUMBER 1 TYPE	None
NUMBER 2 TYPE	Buildings 105, 108, 659, 1247
NUMBER 3 TYPE	None

2.3.21 Regimental commander's quarters – Type RCQ-1

There were no Number 1 Type regimental commander's quarters, Type RCQ-1 that retained their integrity from the WWII construction period. There were seven Number 2 Type that did not retain their integrity for a WWII temporary building and no Number 3 Type quarters at Fort McCoy (see Table 6-7).

Table 6-7. List of regimental commander's quarters, Type RCQ-1 per Number 1, 2, or 3 type designation (ERDC-CERL).

NUMBER 1 TYPE	None
Buildings 901, 1656, 1754, 1853, 2448, 2566, 2780
NUMBER 2 TYPE	
NUMBER 3 TYPE	None

2.3.22 Company storehouse, administration, and recreation building

There were five Number 1 Type company storehouse, administration and recreation building that retained their integrity from the WWII construction period. There were 49 Number 2 Type and 61 Number 3 Type company storehouse, administration, and recreation buildings at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-8).

Table 6-8. List of company storehouse, administration, and recreation building per Number 1, 2, or 3 type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	<p>Buildings 633, 1132, 1133, 1232 1233</p>
<p>NUMBER 2 TYPE</p>	<p>Buildings 601, 621, 622, 638, 743, 843, 1121, 1201, 1211, 1221, 1222, 1244, 1257, 1258, 1301, 1311, 1343, 1344, 1349, 1359, 1401, 1411, 1443, 1444, 1643, 1649, 1654, 1701, 1721, 1722, 1747, 1921, 1922, 1943, 1946, 1947, 1948, 2544, 2611, 2644, 2657, 2658, 2659, 2662, 2663, 2664, 2711, 2765, 2770</p>
<p>NUMBER 3 TYPE</p>	<p>Buildings 611, 632, 701, 711, 721, 722, 732, 733, 744, 756, 757, 801, 811, 821, 832, 833, 1101, 1111, 1321, 1332, 1421, 1432, 1501, 1601, 1621, 1622, 1644, 1650, 1651, 1652, 1743, 1801, 1821, 1822, 1843, 1846, 1851, 1852, 1855, 1951, 2004, 2005, 2402, 2411, 2432, 2433, 2444, 2445, 2446, 2511, 2546, 2548, 2549, 2551, 2554, 2555, 2656, 2744, 2764, 2768, 2769</p>

2.3.23 Company storehouse, administration, and recreation building [MOD]

There were two Number 1 Type company storehouse, administration and recreation building the single roof version that retained their integrity from the WWII construction period. There were five Number 2 Type and four Number 3 Type at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-9).

Table 6-9. List of company storehouse, administration, and recreation building with single roof per Number 1, 2, or 3 type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	Buildings 855, 857
<p>NUMBER 2 TYPE</p>	Buildings 1646, 2832, 2833, 2864, 2865
<p>NUMBER 3 TYPE</p>	Building 634, 2867, 2870, 2871

2.3.24 Administration building – Type IBA-1

There were two Number 1 Type interior battalion administration building, Type IBA-1 that retained their integrity from the WWII construction period. There were five Number 2 Type and eleven Number 3 Type interior battalion administration building at Fort McCoy (see Table 6-10).

Table 6-10. List of interior administration building, Type IBA-1 per Number 1, 2, or 3 type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	<p>Buildings 848, 1950</p>
<p>NUMBER 2 TYPE</p>	<p>Buildings 1446, 1648, 1745, 1753, 2660</p>
<p>NUMBER 3 TYPE</p>	<p>Buildings 649, 749, 1847, 1848, 2552, 2553, 2665, 2766, 2771, 2863, 2869</p>

2.3.25 Administration building – Type A-3

There were no Number 1 Type administration, Type A-3 buildings that retained their integrity from the WWII construction period. There were three Number 2 Type and no Number 3 Type at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-11).

Table 6-11. List of Administration buildings, Type A-3 per Number 1, 2, or 3 type designation (ERDC-CERL).

NUMBER 1 TYPE	None
Buildings, 1145, 1254, 1345
NUMBER 2 TYPE	
NUMBER 3 TYPE	None

2.3.26 Administration building – Type A-10

There were no Number 1 Type administration, Type A-10 buildings that retained their integrity from the WWII construction period. There were five Number 2 Type and ten Number 3 Type at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-12).

Table 6-12. List of administration Type A-10 buildings per Number 1, 2, or 3 type designation (ERDC-CERL).

NUMBER 1 TYPE	None
Buildings 104, 902, 1755, and 1945, 2168
NUMBER 2 TYPE
Buildings 102, 103, 657, 1254, 1854, 2117, 2180, 2547, 2668, 2875
NUMBER 3 TYPE	

2.3.27 Unit guard house, Type UGH-12

There were no Number 1 Type unit guard house, Type UGH-12 buildings that retained their integrity from the WWII construction period. There was one Number 2 Type and no Number 3 Types at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-13).

Table 6-13. List of unit guard house Type UGH-12 buildings per Number 1, 2, or 3 type designation (ERDC-CERL).

NUMBER 1 TYPE	None
NUMBER 2 TYPE	Building 1447
NUMBER 3 TYPE	None

2.3.28 Unit guard house, Type UGH-24

There was one Number 1 Type unit guard house, Type UGH-24 that retained their integrity from the WWII construction period. There was one Number 2 Type that did not retain its integrity for a WWII temporary building and no Number 3 Type guard houses at Fort McCoy (see Table 6-14).

Table 6-14. List of unit guard house, Type UGH-24 per Number 1, 2, or 3 type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	Building 849
<p>NUMBER 2 TYPE</p>	Building 1348
<p>NUMBER 3 TYPE</p>	None

2.3.29 Unit guard house, Type UGH-36

There were three Number 1 Type unit guard house, Type UGH-36 that retained their integrity from the WWII construction period. There was one Number 2 Type that did not retain their integrity for a WWII temporary building and no Number 3 Type guard houses at Fort McCoy (see Table 6-15).

Table 6-15. List of unit guard house, Type UGH-36 per Number 1, 2, or 3 type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	Buildings 1866, 2560, 2872
<p>NUMBER 2 TYPE</p>	Buildings 1748
<p>NUMBER 3 TYPE</p>	None

2.3.30 Post administration building, Division Headquarters, Type DHQ-1

There were no Number 1 Type post administration building, Division Headquarters, Type DHQ-1 that retained its integrity from the WWII construction period. There were no Number 2 Type and no Number 3 Type Division Headquarters at Fort McCoy (see Table 6-16).

Table 6-16. List of post administration building, Division Headquarters, Type DHQ-1 per Number 1, 2, or 3 type designation (ERDC-CERL).

NUMBER 1 TYPE	None
Building 100
NUMBER 2 TYPE	
NUMBER 3 TYPE	None

2.3.31 Recreation building – gymnasium (RB-1)

There were four Number 1 Type recreation buildings – gymnasium (Type RB-1) that retained their integrity from the WWII construction period. There were two Number 2 Type and one Number 3 Type at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-17).

Table 6-17. List of recreation building – gymnasium (Type RB-1) per Number 1, 2, or 3 type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	Buildings 1869, 2557, 2667, 2876
<p>NUMBER 2 TYPE</p>	Buildings 1448, 1758
<p>NUMBER 3 TYPE</p>	Building 1255

2.3.32 Recreation building – Type RB-2

There were no Number 1 Type recreation building, Type RB-2 that retained their integrity from the WWII construction period. There were two Number 2 Type that did not retain their integrity for a WWII temporary building and there were two Number 3 Type recreation buildings, Type RB-2 at Fort McCoy (see Table 6-18).

Table 6-18. List of recreation buildings, Type RB-2 per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	None
<p>NUMBER 2 TYPE</p>	Buildings 903, 1243
<p>NUMBER 3 TYPE</p>	Buildings 658, 660

2.3.33 Recreation building – Type RB-4

There were no Number 1 Type recreation building, Type RB-4 buildings that retained their integrity from the WWII construction period. There were four Number 2 Type and eight Number 3 Type at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-19).

Table 6-19. List of recreation buildings, Type RB-4 per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	None
NUMBER 2 TYPE	Buildings 1647, 1653, 1751, 1757
NUMBER 3 TYPE	Buildings 1760, 1761, 2532, 2533, 2632, 2633, 2732, 2733

2.3.34 Service clubs

There were no Number 1 Type service clubs that retained their integrity from the WWII construction period. There were no Number 2 Types and one Number 3 Type service club at Fort McCoy that did not retain its integrity for a WWII temporary building (see Table 6-20).

Table 6-20. List of service clubs per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	None
NUMBER 2 TYPE	None
NUMBER 3 TYPE	Building 2000

2.3.35 Type M-112-man mess halls

There were three Number 1 Type mess hall, Type M-112 that retained their integrity from the WWII construction period. There were fifteen Number 2 Type that did not retain their integrity for a WWII temporary building and five Number 3 Type mess hall, Type M-112 at Fort McCoy (see Table 6-21 to Table 6-24).

Table 6-21. List of Type M 112-man mess hall per Number 1, 2, or 3 Type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	<p>Buildings 1237, 1415, 1427</p>
<p>NUMBER 2 TYPE</p>	<p>Buildings 839, 1205, 1206, 1207, 1216, 1315, 1316, 1326, 1327, 1328, 1338, 1405, 1406, 1416, 1428</p>
<p>NUMBER 3 TYPE</p>	<p>Buildings 1106, 1226, 1227, 1228, 1437</p>

2.3.36 Type M-152-man mess halls

There was one Number 1 Type mess hall, Type M-152 that retained its integrity from the WWII construction period. There were four Number 2 Type that did not retain their integrity for a WWII temporary building and there were two Number 3 Type mess hall, Type M-152 at Fort McCoy (see Table 6-22).

Table 6-22. List of Type M 152-man mess hall per Number 1, 2, or 3 Type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	<p>Building 1116</p>
<p>NUMBER 2 TYPE</p>	<p>Buildings 106, 639, 1248, 1337</p>
<p>NUMBER 3 TYPE</p>	<p>Buildings 827, 1115</p>

2.3.37 Type M-172-man mess halls

There were two Number 1 Type mess hall, Type M-172 that retained their integrity from the WWII construction period. There was one Number 2 Type mess hall, Type M-172 building and one Number 3 Type mess hall, Type M-172 at Fort McCoy (see Table 6-23).

Table 6-23. List of Type M 172-man mess hall per Number 1, 2, or 3 Type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	Buildings 626, 627
<p>NUMBER 2 TYPE</p>	Building 1215
<p>NUMBER 3 TYPE</p>	Building 826

2.3.38 Type M-228-man mess halls

There were seven Number 1 Type mess hall, Type M-228 that retained their integrity from the WWII construction period. There were two Number 2 Type that did not retain their integrity for a WWII temporary building and 70 Number 3 Type mess hall, Type M-228 at Fort McCoy (see Table 6-24).

Table 6-24. List of Type M 228-man mess hall per Number 1, 2, or 3 Type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	<p>Buildings 2006, 2008, 2545, 2550, 2563, 2762, 2767</p>
<p>NUMBER 2 TYPE</p>	<p>Buildings 1756, 1949</p>
<p>NUMBER 3 TYPE</p>	<p>Buildings 605, 606, 616, 617, 705, 706, 726, 727, 805, 806, 816, 817, 1605, 1606, 1616, 1617, 1626, 1627, 1638, 1639, 1645, 1705, 1706, 1716, 1717, 1738, 1739, 1805, 1806, 1816, 1817, 1826, 1827, 1838, 1916, 1926, 2406, 2407, 2415, 2416, 2427, 2428, 2447, 2515, 2516, 2527, 2528, 2606, 2607, 2615, 2627, 2628, 2637, 2638, 2661, 2706, 2707, 2715, 2727, 2728, 2737, 2738, 2773, 2806, 2807, 2815, 2816, 2827, 2828, and 2868</p>

2.3.39 Standard storehouse, Type SH-8

There were two Number 1 Type standard storehouse, Type SH-8 that retained their integrity from the WWII construction period. There were two Number 2 Type that did not retain their integrity for a WWII temporary building and no Number 3 Type standard storehouse, Type SH-8 at Fort McCoy (see Table 6-25).

Table 6-25. List of standard storehouses, Type SH-8 per Number 1, 2, or 3 Type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	Buildings 1153, 1154
<p>NUMBER 2 TYPE</p>	Buildings 1263, 1265
<p>NUMBER 3 TYPE</p>	None

2.3.40 Standard storehouse, Type SH-9

There was one Number 1 Type standard storehouse, Type SH-9 that retained its integrity from the WWII construction period. There was one Number 2 Type that did not retain its integrity for a WWII temporary building and no Number 3 Type standard storehouse, Type SH-9 at Fort McCoy (see Table 6-26).

Table 6-26. List of standard storehouses, Type SH-9 per Number 1, 2, or 3 Type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	Building 109
<p>NUMBER 2 TYPE</p>	Building 1264
<p>NUMBER 3 TYPE</p>	None

2.3.41 Standard storehouse, Type SH-13

There was no Number 1 Type standard storehouse, Type SH-13 that retained its integrity from the WWII construction period. There were no Number 2 Type that did not retain its integrity for a WWII temporary building and eight Number 3 Type standard storehouse, Type SH-13 at Fort McCoy (see Table 6-27).

Table 6-27. List of standard storehouses, Type SH-13 per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	None
NUMBER 2 TYPE	None
NUMBER 3 TYPE	Buildings 2107, 2108, 2141, 2142, 2143, 2145, 2147, 2149

2.3.42 Standard storehouse, Type SH-18

There was no Number 1 Type standard storehouse, Type SH-18 that retained its integrity from the WWII construction period. There were no Number 2 Type that did not retain its integrity for a WWII temporary building and six Number 3 Type standard storehouse, Type SH-18 at Fort McCoy (see Table 6-28).

Table 6-28. List of standard storehouses, Type SH-13 per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	None
NUMBER 2 TYPE	None
NUMBER 3 TYPE	Buildings 2119, 2121, 2123, 2125, 2161, 2184

2.3.43 Grease rack enclosure building

There were no Number 1 Type grease rack enclosure buildings that retained their integrity from the WWII construction period. There were two Number 2 Types that did not retain its integrity for a WWII temporary building and no Number 3 Type vehicle maintenance buildings at Fort McCoy (see Table 6-29).

Table 6-29. List of grease rack enclosure buildings per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	None
Buildings 547, 1152
NUMBER 2 TYPE	
NUMBER 3 TYPE	None

2.3.44 Vehicle storage building

There were no Number 1 Type vehicle storage buildings that retained their integrity from the WWII construction period. There was one Number 2 Type that did not retain its integrity for a WWII temporary building and no Number 3 Type at Fort McCoy (see Table 6-30).

Table 6-30. List of vehicle storage buildings per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	None
Building 1659
NUMBER 2 TYPE	
NUMBER 3 TYPE	None

2.3.45 Carpentry shop

There were no Number 1 Type carpentry shop that retained its integrity from the WWII construction period. There were no Number 2 Type carpentry shop at Fort McCoy and there was one Number 3 Type carpentry shop at Fort McCoy that did not retain its integrity for a WWII temporary building (see Table 6-31).

Table 6-31. List of carpentry shop per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	None
NUMBER 2 TYPE	None
NUMBER 3 TYPE	Building 2115

2.3.46 Motor repair shop

There were no Number 1 Type motor repair shops that retained its integrity from the WWII construction period. There were three Number 2 Type motor repair shop at Fort McCoy and there was one Number 3 Type motor repair shops at Fort McCoy that did not retain its integrity for a WWII temporary building (see Table 6-32).

Table 6-32. List of motor repair shops per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	None
NUMBER 2 TYPE	Buildings 1260, 1261, 1262
NUMBER 3 TYPE	Building 1764

2.3.47 Railroad shop

There were no Number 1 Type railroad shops that retained its integrity from the WWII construction period. There were no Number 2 Type railroad shop at Fort McCoy and there was one Number 3 Type railroad shop at Fort McCoy that did not retain its integrity for a WWII temporary building (see Table 6-33).

Table 6-33. List of railroad shops per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	None
NUMBER 2 TYPE	None
NUMBER 3 TYPE	Building 2109

2.3.48 Utility shop

There were no Number 1 Type utility shops that retained its integrity from the WWII construction period. There were no Number 2 Type utility shop at Fort McCoy and there was one Number 3 Type utility shop at Fort McCoy that did not retain its integrity for a WWII temporary building (see Table 6-34).

Table 6-34. List of utility shops per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	None
NUMBER 2 TYPE	None
NUMBER 3 TYPE	Building 2116

2.3.49 G.U. Dispensary – Type G.U.D.-1

There were two Number 1 Type G.U. dispensary, Type G.U.D.-1 buildings that retained their integrity from the WWII construction period. There were five Number 2 Type and one Number 3 Type dispensary buildings at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-35).

Table 6-35. List of G.U. dispensary, Type G.U.D.-1 buildings per Number 1, 2, or 3 Type designation (ERDC-CERL).

<p>NUMBER 1 TYPE</p>	Buildings 2556, 2873
<p>NUMBER 2 TYPE</p>	Buildings 1246, 1346, 1663, 1749, 1865
<p>NUMBER 3 TYPE</p>	Building 750

2.3.50 Dental clinic – Type DC-1

There was one Number 1 Type dental clinic, Type DC-1 that retained its integrity from the WWII construction period. There were no Number 2 Type and Number 3 Type dental clinics at Fort McCoy (see Table 6-36).

Table 6-36. List of dental clinics, Type DC-1 per Number 1, 2, or 3 Type designation (ERDC-CERL).

Building 656
NUMBER 1 TYPE	
NUMBER 2 TYPE	None
NUMBER 3 TYPE	None

2.3.51 Infirmary

There were no Number 1 Type infirmaries that retained their integrity from the WWII construction period. There were three Number 2 Types and no Number 3 Type dental clinics at Fort McCoy (see Table 6-37).

Table 6-37. List of dental clinics, Type DC-1 per Number 1, 2, or 3 Type designation (ERDC-CERL).

Building 1750
NUMBER 1 TYPE	
NUMBER 2 TYPE	Buildings 1347 and 1664
NUMBER 3 TYPE	None

2.3.52 Regimental exchange

There was one Number 1 Type regimental exchange building that retained its integrity from the WWII construction period. There were four Number 2 Type and six Number 3 Type regimental exchange buildings at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-38).

Table 6-38. List of regimental exchange buildings, Type E-3 per Number 1, 2, or 3 Type designation (ERDC-CERL).

<p>NUMBER TYPE 1</p>	<p>Building 1750</p>
<p>NUMBER TYPE 2</p>	<p>Buildings 1256, 1445, 1868, 2001</p>
<p>NUMBER 3 TYPE</p>	<p>Buildings 110, 352, 751, 2558, 2669, 2874</p>

2.3.53 Regimental chapels

There were no Number 1 Type regimental chapels that retained their integrity from the WWII construction period. There was one Number 2 Type and one Number 3 Type at Fort McCoy that did not retain their integrity for a WWII temporary building (see Table 6-39).

Table 6-39. List of regimental chapels per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	None
NUMBER 2 TYPE	Building 1759
NUMBER 3 TYPE	Building 2672

2.3.54 Fire stations

There was one Number 1 Type fire station that retained its integrity from the WWII construction period. There were no Number 2 Type and one Number 3 Type fire stations at Fort McCoy (see Table 6-40).

Table 6-40. List of fire stations per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER 1 TYPE	Building 550
NUMBER 2 TYPE	None
NUMBER 3 TYPE	Building 2111

2.3.55 Post office

There were no Number 1 Type post offices or Number 2 Type post offices, Type PO-2 that retained their integrity from the WWII construction period. There was one Number 3 Type that did not retain its integrity for a WWII temporary building (see Table 6-41).

Table 6-41. List of post offices per Number 1, 2, or 3 Type designation (ERDC-CERL).

NUMBER TYPE 1	None
NUMBER TYPE 2	None
<p>NUMBER 3 TYPE</p>	Building 2675

7 Final Recommendations for Eligibility and Conclusion

The identification of historically significant properties is achieved only through an evaluation which associates a property within a larger historic context. According to the NRHP, “Historic contexts are those patterns, themes, or trends in history by which a specific occurrence, property, or site is understood and its meaning (and ultimately its significance) within prehistory or history is made clear.”* Therefore, to qualify as historic, a property must have an association with a relevant historic context as well as having retained its physical integrity through which its historic significance is conveyed.

Sections 8.1 through 8.2 summarize this study’s findings regarding the eligibility of the WWII temporary buildings and the overall landscape. Below is a diagram outlining the six areas of the cantonment (Figure 7-1).

Figure 7-1. Diagram outlining major areas of the cantonment at Fort McCoy (ERDC-CERL).

* NPS, *National Register Bulletin #15*, 7.

2.4 WWII Temporary Buildings

A Programmatic Memorandum of Agreement for the disposal of WWII temporary buildings was signed by DoD, the ACHP, and the NCSHPO in 1986. The PMOA allows for the demolition of any WWII temporary building constructed between 1939 and 1945 without further Section 106 review. The PMOA does not allow for any other type of undertaking to WWII buildings without Section 106 consultation unless the buildings have been evaluated under Section 110 and determined not eligible for the NRHP. This report satisfies the Section 110 requirement.

For this report, 786 WWII temporary buildings at Fort McCoy extant within the cantonment were inventoried for Section 110. The majority of buildings retain their massing and location; however, only 48 of these buildings still have their exterior and interior character-defining features of WWII temporary buildings (these buildings in this report are identified as Number 1 Type). The remaining 742 buildings (identified in this report as Number 2 and 3 Types) have been modified with newer siding, windows, and doors and newer interior finishes, uses, and space layouts. Additionally, most of the original mess halls have large additions or a hyphen addition to connect two of the buildings.

Evaluation of the WWII buildings concluded that most of the buildings do not have integrity to be eligible for the NRHP. The researchers evaluated each building and determined that there were 529 (Number 3 Type) that had no integrity at all except for location, there were 213 (Number 2 Type) that had some aspects of integrity but not enough to convey the period of significance, and there were 48 (Number 1 Type) that had their integrity (see Sections 4.1-4.3). These 48 buildings with integrity are scattered throughout the cantonment. A further discussion of this is outlined in Section 5.5 and Section 8.2).

2.5 Overall WWII Military Landscape

The triangular (or Triad) design and layout of the cantonment still exists today as well as the supporting circulation patterns of the original design and layout. At first glance, it appears like the WWII landscape is intact due to the strong circulation patterns; however, each part of the Triad has seen some significant changes to the landscape of its buildings. The northeast leg of the cantonment has lost many of its building clusters, including all motor pools, through demolition has led to the appearance of this leg having vast

areas of open space when historically it was developed with WWII buildings (Figure 7-2). The southern leg of the cantonment has seen the construction of new larger buildings and building complexes and the removal or alteration of some of the connecting roads (Figure 7-3). The motor pool areas were replaced by a large PX, community center and the NCO Academy. New construction of larger buildings is not in the same scale and footprint as the WWII buildings. The northwest leg retains many of its buildings, but the demolition of the old motor pools and the construction of new larger buildings in the motor pools has affected the integrity (Figure 7-4). The mass and scale of the buildings is different as well as the setbacks as they are farther removed from their associated units. The landscape connection so important in the design and layout of Fort McCoy is missing.

Figure 7-2. This view of the 500 Block exemplifies the complete demolition of sections of the northeast leg of the cantonment (ERDC-CERL, 2019).

Figure 7-3. Aerial view of center of southern leg of cantonment showing large scale new buildings in place of original WWII regimental blocks (www.google.com, accessed 21 May 2020).

Figure 7-4. New construction (Building 651, laundromat) in northwest leg showing difference of materials, feeling, mass, and setback (ERDC-CERL, 2019).

The headquarters area, prominently located in the center of the Triad, remains largely intact as a landscape. The view to the flagpole and headquarters building still exists today and conveys much the same feeling as it did during WWII (Figure 7-5). In the warehouse area, half of the original WWII buildings have been demolished and east of the area has seen significant construction of large scale buildings and building complexes (Figure 7-6). The WWII hospital buildings have all been demolished and all that remains is the road system (Figure 7-7).

Figure 7-5. View of Headquarters Building, Building 100, and flagpole (ERDC-CERL 2018).

Figure 7-6. Looking northwest at new construction (Building 2100) in warehouse area (ERDC-CERL, 2018).

Figure 7-7. View looking northeast of former hospital area showing only trees and no WWII buildings left (ERDC-CERL, 2018).

So, while the remaining roads retain their integrity, there is not enough of a concentration of buildings and land use patterns that have integrity to form a cohesive historic district. The buildings with integrity (Number 1 Type) are scattered throughout the cantonment which makes it difficult to understand the historic character of the landscape. Individual buildings with integrity do not have the context of place to tell the story of the WWII landscape. Typically, the layout of the roads, the location of buildings, and predominant land uses are integrated together to form a historic district. For the reasons listed above, the Fort McCoy cantonment as a whole lacks the integrity as a WWII landscape or historic district.

2.6 Proposed Historic District

It is the recommendation of this report that the post headquarters (Building 100), flagpole, the flagpole plaza, Fort McCoy sign in white stones, and the view north from South Headquarters Road form a historic district (Figure 7-8 and Figure 7-9). Building 100, the flagpole, and associated landscape was highly significant as the post headquarters and was laid out and designed in the center of the cantonment. The view was featured on many historic post cards and photographs (Figure 7-10). The landscape re-

tains its WWII character-defining features (Figure 7-11). The Period of Significance for the Fort McCoy Post Headquarters Historic District should be 1942-1946.

Figure 7-8. Proposed Fort McCoy Headquarters historic district boundary (in blue) as shown on a map of the entire cantonment (ERDC-CERL, 2019).

Figure 7-9. Close-up view of proposed Historic District showing boundary in blue (ERDC-CERL on aerial map from google.com, accessed 21 May 2020).

Figure 7-10. View of Building 100 and flagpole in historic postcard, circa 1945 (DPW, Fort McCoy).

Figure 7-11. Current view of Building 100, flagpole, plaza, and sign (ERDC-CERL, 2019).

2.7 Conclusion

Evaluation of the WWII buildings and landscape concluded that there are too few buildings with integrity to form a cohesive historic district. While the circulation patterns and roads are still intact, the buildings with integrity are scattered throughout the cantonment affecting the historic character of the landscape.

This report concludes that of the Number 1 and 2 types, only Building 100 (post headquarters) [and its associated landscape], Building 656 (dental clinic), and Building 550 (fire station) are ELIGIBLE for listing on the NRHP at the national level under Criterion A for their association with World War II temporary building construction (1942-1946) and under Criterion C for their design, construction, and technological innovation. These three buildings are recommended as eligible because they are unique WWII buildings and still retain their surrounding military landscape. Table 7-1 (compiled by ERDC-CERL, 2019) lists the recommendations of eligibility for ALL 786 buildings inventoried for Fort McCoy by ERDC-CERL.

Table 7-1. Recommendations of eligibility for all 786 buildings inventoried (compiled by ERDC-CERL, 2019).

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
100	1942	Post Administration Building, Division Headquarters	Post Administration Building, Division Headquarters	Type 2	Yes (Criteria A and C)
102	1942	Administration	Administration General Purpose	Type 3	No
103	1942	Administration (Finance)	Administration General Purpose	Type 3	No
104	1942	Administration	Brigade Headquarters Building Transient Training	Type 2	No
105	1942	Brigade General Quarters	Recreation Billets	Type 2	No
106	1942	Type M – 152-Man Mess Hall	Company Headquarters Building Transient Training	Type 2	No
107	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers' Quarters	Type 2	No
108	1942	Brigade General Quarters	Unaccompanied Officers' Quarters Military	Type 2	No
109	1942	Standard Storehouse, Type SH-9	Organizational Storage Building	Type 1	No
110	1942	Exchange	Administration General Purpose	Type 3	No
352	1942	Regimental Exchange Building	General Instruction Building	Type 3	No
451	1942	Officers' Quarters – Type BOQ-44	Training Collective UH	Type 2	No
452	1942	Officers' Quarters – Type BOQ-44	Training Collective UH	Type 2	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
453	1942	Officers' Quarters – Type BOQ-44	Training Collective UH	Type 2	No
454	1942	Officers' Quarters – Type BOQ-44	Training Collective UH	Type 2	No
547	1942	Grease Rack Enclosure Building	Vehicle Storage Installation	Type 2	No
550	1942	Fire Station	Vehicle Storage Installation	Type 1	Yes (Criteria A and C)
601	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 2	No
602	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
603	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
604	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
605	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
606	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
607	1942	74-Man Barracks	Battalion Headquarters Building Transient Training	Type 3	No
608	1942	74-Man Barracks	Company Headquarters Building Transient Training	Type 3	No
609	1942	74-Man Barracks	Company Headquarters Building Transient Training	Type 3	No
610	1942	74-Man Barracks	Company Headquarters Building Transient Training	Type 3	No
611	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
612	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
613	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
614	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
616	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training	Type 3	No
617	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training	Type 3	No
618	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
619	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
620	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
621	1942	Company Storehouse, Administration, and Recreation Building	Unaccompanied Personal Housing Laundry Detached	Type 2	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
622	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building	Type 2	No
623	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 1	No
624	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 1	No
625	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 1	No
626	1942	Type M – 172-Man Mess Hall	General Instruction Building	Type 1	No
627	1942	Type M – 172-Man Mess Hall	General Instruction Building	Type 1	No
628	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 1	No
629	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 1	No
632	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building	Type 3	No
633	1942	Company Storehouse, Administration, and Recreation	General Instruction Building	Type 1	No
634	1942	Company Storehouse, Administration, and Recreation	Battalion Headquarters Building Transient Training	Type 3	No
638	1942	Company Storehouse, Administration, and Recreation	General Instruction Building	Type 2	No
639	1942	Type M – 152-Man Mess Hall	Dining Facility Transient Training	Type 2	No
640	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
641	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
642	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
649	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
652	1942	Officers' Quarters - Type BOQ-44	Transient Training Enlisted Barracks	Type 3	No
653	1942	Officers' Quarters - Type BOQ-44	Transient Training Enlisted Barracks	Type 3	No
654	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers' Quarters	Type 3	No
655	1942	Officers' Quarters - Type BOQ-40	Transient Training Enlisted Barracks	Type 3	No
656	1942	Dental Clinic	Battalion Headquarters Building Transient Training	Type 1	Yes (Criteria A and C)
657	1942	Administration	General Instruction Building	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
658	1942	Recreation Building – Type RB-2	General Instruction Building	Type 3	No
659	1942	Brigade General's Quarters – Type BGQ-1	Recreational Billets	Type 2	No
660	1942	Recreation Building – Type RB-2	Battalion Headquarters Building Transient Training	Type 3	No
701	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building	Type 3	No
702	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
703	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
704	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
705	1942	Type M – 228-Man Mess Hall	Brigade Headquarters Building Transient Training	Type 3	No
706	1942	Type M – 228-Man Mess Hall	Brigade Headquarters Building Transient Training	Type 3	No
707	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
708	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
709	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
710	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
711	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 3	No
712	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
713	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
714	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
718	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
719	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
720	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
721	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 3	No
722	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 3	No
723	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
724	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
725	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
726	1942	Type M – 228-Man Mess Hall	Brigade Headquarters Building Transient Training	Type 3	No
727	1942	Type M – 228-Man Mess Hall	Brigade Headquarters Building Transient Training	Type 3	No
728	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
729	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
730	1942	74-Man Barracks	Brigade Headquarters Building	Type 3	No
731	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 3	No
732	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 3	No
733	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 3	No
734	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
735	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
736		74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
740	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
741	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
742	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
743	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 2	No
744	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 3	No
749	1942	Administration	General Instruction Building	Type 3	No
750	1942	G.U. Dispensary - Type G.U.D. -1	General Instruction Building	Type 3	No
751	1942	Regimental Exchange Building	General Instruction Building	Type 3	No
756	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building	Type 3	No
757	1942	Company Storehouse, Administration, and Recreation Building	Battalion Headquarters Building	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
801	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
802	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
803	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
804	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
805	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
806	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
807	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
808	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
809	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
810	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
811	1942	Company Storehouse, Administration, and Recreation Building	ARM Force Center	Type 3	No
812	1942	74-Man Barracks	USAR Center	Type 3	No
813	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
814	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
816	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
817	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
818	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
819	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
820	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
821	1942	Company Storehouse, Administration, and Recreation Building	ARM Force Center	Type 3	No
823	1942	74-Man Barracks	USAR Center	Type 3	No
824	1942	74-Man Barracks	USAR Center	Type 3	No
825	1942	74-Man Barracks	USAR Center	Type 3	No
826	1942	Type M – 172-Man Mess Hall	ARM Force Center	Type 3	No
827	1942	Type M – 152-Man Mess Hall	ARM Force Center	Type 3	No
828	1942	74-Man Barracks	USAR Center	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
829	1942	74-Man Barracks	USAR Center	Type 3	No
832	1942	Company Storehouse, Administration, and Recreation Building	ARM Force Center	Type 3	No
833	1942	Company Storehouse, Administration, and Recreation Building	ARM Force Center	Type 3	No
839	1942	Type M – 112-Man Mess Hall	Heritage Center Facility	Type 2	No
840	1942	74-Man Barracks	Heritage Center Facility	Type 2	No
841	1942	74-Man Barracks	Heritage Center Facility	Type 2	No
842	1942	74-Man Barracks	Heritage Center Facility	Type 2	No
843	1942	Company Storehouse, Administration, and Recreation Building	Heritage Center Facility	Type 2	No
848	1942	Interior Battalion Administration Building	Company Headquarters Building Transient Training	Type 1	No
849	1942	Unit Guard House – Type Ugh-24	Company Headquarters Building Transient Training	Type 1	No
851	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers' Quarters	Type 2	No
852	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers' Quarters	Type 2	No
853	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers' Quarters	Type 2	No
855	1942	Company Storehouse, Administration, and Recreation Building	United States Army Reserve Center	Type 1	No
857	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 1	No
901	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets	Type 2	No
902	1942	Administration	Heritage Center Facility	Type 2	No
903	1942	Recreation Building – Type RB-2	Heritage Center Facility	Type 2	No
904	1942	Bachelor Officers' Quarters - 700-Series, Type OQ-23	Transient Training Officers Quarters	Type 2	No
1101	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1105	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1106	1942	Type M – 112-Man Mess Hall	Administration General Purpose	Type 3	No
1108	1942	74-Man Barracks	Administration General Purpose	Type 3	No
1111	1942	Company Storehouse, Administration, and Recreation Building	Administration General Purpose	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1113	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 1	No
1114	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 1	No
1115	1942	Type M – 152-Man Mess Hall	Simulation Center	Type 3	No
1116	1942	Type M – 152-Man Mess Hall	Physical Fitness Center	Type 1	No
1117	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 1	No
1118	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 1	No
1121	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building	Type 2	No
1129	1942	74-Man Barracks	Organizational Storage Building	Type 1	No
1130	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1132	1942	Company Storehouse, Administration, and Recreation	Company Headquarters Building Transient Training	Type 1	No
1133	1942	Company Storehouse, Administration, and Recreation	Skill Development (Na)	Type 1	No
1145	1942	Administration	Brigade Headquarters Building Transient Training	Type 2	No
1152	1942	Grease Rack Enclosure Building	Engineering/Housing Maintenance	Type 2	No
1153	1942	Standard Storehouse, Type SH-8	Organizational Storage Building	Type 1	No
1154	1942	Standard Storehouse, Type SH-8	Organizational Storage Building	Type 1	No
1201	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
1203	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1204	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1205	1942	Type M – 112-Man Mess Hall	Miscellaneous Facilities, Detached	Type 2	No
1206	1942	Type M – 112-Man Mess Hall	Company Headquarters Building Transient Training	Type 2	No
1207	1942	Type M – 112-Man Mess Hall	Brigade Headquarters Building Transient Training	Type 2	No
1208	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1209	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1210	142	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1211	1942	Company Storehouse, Administration, and Recreation Building	Eng/Housing Maintenance	Type 2	No
1213	1942	74-Man Barracks	Transient Training Officers Quarters	Type 2	No
1214	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1215	1942	Type M – 172-Man Mess Hall	Company Headquarters Building Transient Training	Type 2	No
1216	1942	Type M – 112-Man Mess Hall	Brigade Headquarters Building Transient Training	Type 2	No
1217	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1221	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
1222	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
1224	1942	74-Man Barracks	Training Collective UH	Type 2	No
1225	1942	74-Man Barracks	Training Collective UH	Type 2	No
1226	1942	Type M – 112-Man Mess Hall	Organizational Classroom	Type 3	No
1227	1942	Type M – 112-Man Mess Hall	Organizational Classroom	Type 3	No
1228	1942	Type M – 112-Man Mess Hall	Brigade Headquarters Building Transient Training	Type 3	No
1229	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1230	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1231	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1232	1942	Company Storehouse, Administration, and Recreation	Organizational Storage Building	Type 1	No
1233	1942	Company Storehouse, Administration, and Recreation	Company Headquarters Building Transient Training	Type 1	No
1235	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1236	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1237	1942	Type M – 112-Man Mess Hall	Organizational Storage Building	Type 1	No
1239	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1243	1942	Recreation Building – Type RB-2	Battalion Headquarters Building Transient Training	Type 2	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1244	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
1245	1942	Administration	USAR Center	Type 3	No
1246	1942	G.U. Dispensary	Company Headquarters Building Transient Training	Type 2	No
1247	1942	Brigade General's Quarters – Type BGQ-1	Recreation Billets	Type 2	No
1248	1942	Type M – 152-Man Mess Hall	Company Headquarters Building Transient Training	Type 2	No
1249	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters	Type 2	No
1250	1942	Officers' Quarters – Type BOQ-44	Training Collective UH	Type 2	No
1251	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters	Type 2	No
1254	1942	Administration	Battalion Headquarters Building Transient Training	Type 2	No
1255	1942	Recreation Building - Gymnasium	General Instruction Building	Type 3	No
1256	1942	Regimental Exchange Building	General Instruction Building	Type 2	No
1257	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
1258	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
1260	1942	Motor Repair Shop	Organizational Storage Building	Type 2	No
1261	1942	Motor Repair Shop	Organizational Storage Building	Type 2	No
1262	1942	Motor Repair Shop	Organizational Storage Building	Type 2	No
1263	1942	Standard Storehouse – Type SH-8	Organizational Storage Building	Type 2	No
1264	1942	Standard Storehouse – Type SH-9	Organizational Storage Building	Type 2	No
1265	1942	Standard Storehouse – Type SH-8	Organizational Storage Building	Type 2	No
1301	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
1304	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1305	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1308	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1311	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building	Type 2	No
1313	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1314	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1315	1942	Type M – 112-Man Mess Hall	General Instruction Building	Type 2	No
1316	1942	Type M – 112-Man Mess Hall	General Instruction Building	Type 2	No
1321	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building	Type 3	No
1324	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1325	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1326	1942	Type M – 112-Man Mess Hall	General Instruction Building	Type 2	No
1327	1942	Type M – 112-Man Mess Hall	General Instruction Building	Type 2	No
1328	1942	Type M – 112-Man Mess Hall	General Instruction Building	Type 2	No
1329		74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1330	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1331	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1332	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building	Type 3	No
1335	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1336	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1337	1942	Type M – 152-Man Mess Hall	General Instruction Building	Type 2	No
1338	1942	Type M – 112-Man Mess Hall	General Instruction Building	Type 2	No
1339	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1343	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
1344	1942	Company Storehouse, Administration, and Recreation Building	Drug/Alcohol Abuse Building	Type 2	No
1345	1942	Administration	Brigade Headquarters Building Transient Training	Type 2	No
1346	1942	G. U. Dispensary	Brigade Headquarters Building Transient Training	Type 2	No
1347	1942	Infirmary	Company Headquarters Building Transient Training	Type 2	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1348	1942	Unit Guard House - Type Ugh-24	Brigade Headquarters Building Transient Training	Type 2	No
1349	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 2	No
1359	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
1401	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
1404	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1405	1942	Type M - 112-Man Mess Hall	General Instruction Building	Type 2	No
1406	1942	Type M - 112-Man Mess Hall	General Instruction Building	Type 2	No
1407	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1408	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1409	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1411	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building	Type 2	No
1413	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1414	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1415	1942	Type M - 112-Man Mess Hall	Organizational Storage Building	Type 1	No
1416	1942	Type M - 112-Man Mess Hall	Organizational Storage Building	Type 2	No
1417	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1421	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building	Type 3	No
1424	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1425	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1426	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1427	1942	Type M - 112-Man Mess Hall	Organizational Storage Building	Type 1	No
1428	1942	Type M - 112-Man Mess Hall	General Instruction Building	Type 2	No
1429	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1432	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building	Type 3	No
1435	1942	74-Man Barracks	General Instruction Building	Type 2	No
1436	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1437	1942	Type M – 112-Man Mess Hall	General Instruction Building	Type 3	No
1439	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1440	1942	74-Man Barracks	General Instruction Building	Type 2	No
1441	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1443	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building	Type 2	No
1444	1942	Company Storehouse, Administration, and Recreation Building	Unaccompanied Personal Housing Laundry Detached	Type 2	No
1445	1942	Post Exchange	General Instruction Building	Type 2	No
1446	1942	Administration	Brigade Headquarters Building Transient Training	Type 2	No
1447	1942	Unit Guard House – Type UGH-12	General Instruction Building	Type 2	No
1448	1942	Recreation Building - Gymnasium	Auditorium General Purpose	Type 2	No
1501	1942	Company Storehouse, Administration, and Recreation Building	Credit Union	Type 3	No
1601	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1602	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1603	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1604	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1605	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1606	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1607	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1608	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1609	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1610	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1612	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1613	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1614	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1615	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1616	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1617	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1618	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1619	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1620	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1621	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1622	1942	Company Storehouse, Administration, and Recreation Building	General Instruction Building	Type 3	No
1623	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1624	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1625	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1626	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
1627	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
1628	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1629	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1630	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1631	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1632	1942	Bachelor Officers' Quarters - 700-Series, Type OQ-23	Transient Training Enlisted Barracks	Type 3	No
1634	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1635	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1636	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1637	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1638	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1639	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1640	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1641	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1642	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1643	1942	Company Storehouse, Administration, and Recreation Building	Arms Storage-Battalion	Type 2	No
1644	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 3	No
1645	1942	Type M – 228-Man Mess Hall	Military Clothing Sale	Type 3	No
1646	1942	Company Storehouse, Administration, and Recreation Building	Exchange Branch	Type 2	No
1647	1942	Recreation Building – Type RB-4	Brigade Headquarters Building Transient Training	Type 2	No
1648	1942	Administration	Company Headquarters Building Transient Training	Type 2	No
1649	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
1650	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building	Type 3	No
1651	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1652	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1653	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training	Type 2	No
1654	1942	Company Storehouse, Administration, and Recreation Building	Print Plant	Type 2	No
1656	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets	Type 2	No
1657	1942	Officers' Quarters – Type BOQ-44	Unaccompanied Personal Housing Senior Non-Commissioned Officer	Type 2	No
1658	1942	Officers' Quarters – Type BOQ-44	Recreation Billets	Type 2	No
1659	1942	Vehicle Storage Building	Organizational Storage Building	Type 2	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1660	1942	Officers' Quarters – Type BOQ-44	Recreation Billets	Type 2	No
1661	1942	Officers' Quarters – Type BOQ-44	Recreation Billets	Type 2	No
1662	1942	Bachelor Officers' Quarters - 700-Series, Type OQ-23	Transient Training Officers Quarters	Type 2	No
1663	1942	G.U. Dispensary	Exchange Service Outlet	Type 2	No
1664	1942	Infirmery	Company Headquarters Building Transient Training	Type 2	No
1701	1942	Company Storehouse, Administration, and Recreation Building	Unaccompanied Personal Housing Laundry Detached	Type 2	No
1702	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1703	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1704	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1705	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1706	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1707	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1708	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1709	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1710	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1712	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1713	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1714	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1715	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1716	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
1717	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
1718	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1719	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1720	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1721	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1722	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
1723	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1724	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1725	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1728	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1729	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1730	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1731	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1732	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1736	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1737	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1738	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1739	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
1740	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1741	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1742	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1743	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1744	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 2	No
1745	1942	Administration	Child Development Center Under 6 Years	Type 2	No
1747	1942	Company Storehouse, Administration, and Recreation Building	Child Development Center Under 6 Years	Type 2	No
1748	1942	Unit Guard House – Type Ugh-36	Battalion Headquarters Building Transient Training	Type 2	No
1749	1942	G. U. Dispensary	Company Headquarters Building Transient Training	Type 2	No
1750	1942	Regimental Exchange Building	Organizational Storage Building	Type 1	No
1751	1942	Recreation Building – Type RB-4	Battalion Headquarters Building Transient Training	Type 2	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1753	1942	Administration	Company Headquarters Building Transient Training	Type 2	No
1754	1942	Regimental Commander's Quarters – Type RCQ-1	Child Development Center Under 6 Years	Type 2	No
1755	1942	Administration	Battalion Headquarters Building Transient Training	Type 2	No
1756	1942	Type M – 228-Man Mess Hall	Organizational Storage Building	Type 2	No
1757	1942	Recreation Building – Type RB-4	Battalion Headquarters Building Transient Training	Type 2	No
1758	1942	Recreation Building - Gymnasium	Auditorium General Purpose	Type 2	No
1759	1942	Regimental Chapel	Chapel	Type 2	No
1760	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training	Type 3	No
1761	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training	Type 3	No
1764	1942	Motor Repair Shop	Organizational Storage Building	Type 3	No
1801	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1802	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1803	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1804	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1805	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1806	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1807	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1808	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1809	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1810	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1812	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1813	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1814	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1815	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1816	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1817	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
1818	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1819	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1820	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1821	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1822	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1823	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1824	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1825	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1826	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
1827	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
1828	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1829	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1830	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1831	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1832	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1834	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1835	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1836	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1837	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1838	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1840	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1842	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1843	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1844	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1846	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1847	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
1848	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
1851	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1852	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1853	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets	Type 2	No
1854	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
1855	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
1857	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters	Type 3	No
1858	1942	Officers' Quarters – Type BOQ-44	Recreation Billets	Type 2	No
1859	1942	Officers' Quarters – Type BOQ-44	Recreation Billets	Type 2	No
1862	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters	Type 2	No
1863	1942	Bachelor Officers' Quarters – Type OQ-23	Transient Training Officers Quarters	Type 3	No
1864	1942	Bachelor Officers' Quarters – Type OQ-23	Transient Training Officers Quarters	Type 3	No
1865	1942	G. U. Dispensary	Company Headquarters Building Transient Training	Type 2	No
1866	1942	Unit Guard House – Type UGH-36	Confinement Facility	Type 1	No
1868	1942	Post Exchange	Battalion Headquarters Building Transient Training	Type 2	No
1869	1942	Recreation Building – Type RB-1	Battalion Headquarters Building	Type 1	No
1913	1942	74-Man Barracks	Administration General Purpose	Type 3	No
1914	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1915	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1916	1942	Type M – 228-Man Mess Hall	Dining Facility: Transient Training	Type 3	No
1918	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1919	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1920	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1921	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 2	No
1922	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 2	No
1923	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1924	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1925	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1926	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
1928	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1929	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1930	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1931	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1932	1942	74-Man Barracks	Brigade Headquarters Building Transient Training	Type 2	No
1934	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1935	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1936	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1937	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1940	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1941	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1943	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 2	No
1944	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
1945	1942	Administration	Company Headquarters Building Transient Training	Type 2	No
1946	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building	Type 2	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
1947	1942	Company Storehouse, Administration, and Recreation Building	Organizational Storage Building	Type 2	No
1948	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 2	No
1949	1942	Type M – 228-Man Mess Hall	Organizational Storage Building	Type 2	No
1950	1942	Interior Battalion Administration	Organizational Storage Building	Type 1	No
1951	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training	Type 3	No
2000	1942	Service Club	Administration General Purpose	Type 3	No
2001	1942	Regimental Exchange Building	Brigade Headquarters Building Transient Training	Type 2	No
2004	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2005	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2006	1942	Type M – 228-Man Mess Hall	Limit Use Instruction	Type 1	No
2007	1942	74-Man Barracks	Transient Training Officers Quarters	Type 3	No
2008	1942	Type M – 228-Man Mess Hall	Limit Use Instruction	Type 1	No
2009	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters	Type 2	No
2010	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters	Type 2	No
2011	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters	Type 2	No
2107	1942	Storehouse – Type SH-13	Storage General Purpose	Type 3	No
2108	1942	Storehouse – Type SH-13	Storage General Purpose	Type 3	No
2109	1942	Railroad Equipment	Maintenance Storage DOL	Type 3	No
2111	1942	Fire Station	ACS Center	Type 3	No
2113	1942	Bakery	Televideo Center	Type 3	No
2115	1942	Carpenter Shop	Engineering/Housing Maintenance	Type 3	No
2116	1942	Utility Shop	Maintenance Storage DOL	Type 3	No
2117	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
2119	1942	Storehouse – Type SH-18	Storage General Purpose	Type 3	No
2121	1942	Storehouse – Type SH-18	Storage General Purpose	Type 3	No
2123	1942	Storehouse – Type SH-18	Storage General Purpose	Type 3	No
2125	1942	Storehouse – Type SH-18	Storage General Purpose	Type 3	No
2141	1942	Storehouse – Type SH-13	Storage General Purpose	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
2142	1942	Storehouse – Type SH-13	Central Issue Facility	Type 3	No
2143	1942	Storehouse – Type SH-13	Storage General Purpose	Type 3	No
2145	1942	Storehouse – Type SH-13	Storage General Purpose	Type 3	No
2147	1942	Storehouse – Type SH-13	Storage General Purpose	Type 3	No
2149	1942	Storehouse – Type SH-13	Storage General Purpose	Type 3	No
2161	1942	Storehouse – Type SH-18	Organizational Storage Building	Type 3	No
2168	1942	Administration	Administration General Purpose	Type 2	No
2171	1942	WAC Barracks	Administration General Purpose	Type 3	No
2180	1942	Administration	Administration General Purpose	Type 3	No
2184	1942	Storehouse – Type SH-18	Organizational Storage Building	Type 3	No
2402	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2403	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2404	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2405	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2406	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2407	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2408	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2409	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2410	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2411	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2412	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2413	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2414	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2415	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2416	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2417	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2418	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2419	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
2420	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2421	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2423	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2424	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2425	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2426	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2427	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2428	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2429	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2430	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2431	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2432	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2433	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2434	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2435	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2436	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2439	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2440	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2441	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2442	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2444	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2445	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2446	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
2447	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2448	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets	Type 2	No
2501	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2502	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2503	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2504	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2505	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2508	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2509	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2510	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2511	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2512	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2513	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2514	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2515	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2516	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2517	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2518	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2519	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2520	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2521	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2523	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2524	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2525	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2526	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
2527	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2528	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2529	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2530	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2531	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2532	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training	Type 3	No
2533	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training	Type 3	No
2534	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2535	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2536	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2539	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2540	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2541	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2544	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2545	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training	Type 1	No
2546	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2547	1942	Administration	General Instruction Building	Type 3	No
2548	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2549	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2550	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training	Type 1	No
2551	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2552	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
2553	1942	Administration	Company Headquarters Building Transient Training	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
2554	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2555	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2556	1942	G.U. Dispensary	Company Headquarters Building Transient Training	Type 1	No
2557	1942	Recreation Building – Type RB-1	Auditorium General Purpose	Type 1	No
2558	1942	Regimental Exchange Building	Auditorium General Purpose	Type 3	No
2560	1942	Unit Guard House – Type Ugh-36	Company Headquarters Building Transient Training	Type 1	No
2561	1942	Bachelor Officers' Quarters – Type BOQ-23	Transient Training Officers Quarters	Type 3	No
2562	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters	Type 3	No
2563	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training	Type 1	No
2564	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters	Type 3	No
2565	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters	Type 3	No
2566	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets	Type 2	No
2601	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2602	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2603	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2604	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2605	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2606	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2607	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2608	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2609	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2610	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2611	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2612	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
2613	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2614	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2615	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2617	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2618	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2619	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2620	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2621	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2623	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2624	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2625	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2626	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2627	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2628	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2629	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2630	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2631	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2632	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training	Type 3	No
2633	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training	Type 3	No
2634	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2635	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2636	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2637	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2638	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2639	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
2640	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2641	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2642	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2644	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2656	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2657	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2658	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2659	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2660	1942	Administration	Company Headquarters Building Transient Training	Type 2	No
2661	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2662	1942	Company Storehouse, Administration, and Recreation Building	Exchange Branch	Type 2	No
2663	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2664	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2665	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
2666	1942	Officers' Quarters – Type BOQ-40	Battalion Headquarters Building Transient Training	Type 2	No
2667	1942	Recreation Building – Type RB-1	Auditorium General Purpose	Type 1	No
2668	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
2669	1942	Regimental Exchange Building	Battalion Headquarters Building Transient Training	Type 3	No
2672	1942	Regimental Chapel	Chapel	Type 3	No
2675	1942	Post Office	Religious Educational Facility	Type 3	No
2701	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2702	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2703	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
2704	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2705	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2706	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2707	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2708	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2709	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2710	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2711	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2712	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2713	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2714	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2715	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2717	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2718	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2719	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2720	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2721	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2723	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2724	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2725	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2726	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2727	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2728	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2729	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2730	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
2731	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2732	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training	Type 3	No
2733	1942	Recreation Building – Type RB-4	Company Headquarters Building Transient Training	Type 3	No
2734	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2735	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2736	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2737	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2738	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2739	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2740	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2741	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2742	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2744	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2762	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training	Type 1	No
2764	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2765	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2766	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
2767	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training	Type 1	No
2768	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2769	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2770	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2771	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
2772	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters	Type 2	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
2773	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2774	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters	Type 2	No
2775	1942	Officers' Quarters – Type BOQ-44	Transient Training Officers Quarters	Type 2	No
2778	1942	Bachelor Officers' Quarters – Type OQ-23	Transient Training Officers Quarters	Type 3	No
2779	1942	Officers' Quarters - Type BOQ-44	Transient Training Officers Quarters	Type 3	No
2780	1942	Regimental Commander's Quarters – Type RCQ-1	Recreation Billets	Type 2	No
2801	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2802	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2803	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2804	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2805	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2806	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2807	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2808	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2809	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2810	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2811	1942	74-Man Barracks	Company Headquarters Building Transient Training	Type 3	No
2812	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2814	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2815	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2816	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2817	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2818	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2819	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2820	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
2821	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2823	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2824	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2825	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2826	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2827	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2828	1942	Type M – 228-Man Mess Hall	Dining Facility Transient Training	Type 3	No
2829	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2830	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2831	1942	74-Man Barracks	Transient Training Enlisted Barracks	Type 3	No
2832	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2833	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2863	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
2864	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2865	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 2	No
2867	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2868	1942	Type M – 228-Man Mess Hall	General Instruction Building	Type 3	No
2869	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
2870	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2871	1942	Company Storehouse, Administration, and Recreation Building	Company Headquarters Building Transient Training	Type 3	No
2872	1942	Unit Guard House – Type UGH-36	Company Headquarters Building Transient Training	Type 1	No
2873	1942	G.U. Dispensary	Company Headquarters Building Transient Training	Type 1	No

Fac. No.	Year Built	Original Use	Current Use	Integrity Category	Recommendations for Eligibility
2874	1942	Regimental Exchange Building	Auditorium General Purpose	Type 3	No
2875	1942	Administration	Company Headquarters Building Transient Training	Type 3	No
2876	1942	Recreation Building – Type RB-1	Auditorium General Purpose	Type 1	No

2.8 Inventory Forms

The following inventory forms were completed for all Number 1 Type buildings and Building 100, which is a Number 2 Type building. Building 100 has an inventory form since it is recommended eligible due to its location in a landscape which has its integrity. Number 1 Type buildings (Table 41) [along with a Building 100 form] forms were given separately to Fort McCoy.

Table 7-2. Number 1 Type WWII buildings (compiled by ERDC-CERL, 2019).

Fac. No.	Year Built	Original Use	Current Use
100	1942	Post Administration Building, Division Headquarters	Administration General Purpose
109	1942	Standard Storehouse, Type SH-9	Organizational Storage Building
550*	1942	Fire Station	Vehicle Storage Installation
623	1942	74-Man Barracks	Transient Training Enlisted Barracks
624	1942	74-Man Barracks	Transient Training Enlisted Barracks
625	1942	74-Man Barracks	Transient Training Enlisted Barracks
626	1942	Type M – 172-Man Mess Hall	General Instruction Building
627	1942	Type M – 172-Man Mess Hall	General Instruction Building
628	1942	74-Man Barracks	Transient Training Enlisted Barracks
629	1942	74-Man Barracks	Transient Training Enlisted Barracks
633	1942	Company Storehouse, Administration, and Recreation	General Instruction Building
656	1942	Dental Clinic	Battalion Headquarters Building Transient Training
848	1942	Interior Battalion Administration Building	Company Headquarters Building Transient Training
849	1942	Unit Guard House – Type UGH-24	Company Headquarters Building Transient Training
855	1942	Company Storehouse, Administration, and Recreation Building	United States Army Reserve Center
857	1942	Company Storehouse, Administration, and Recreation Building	Brigade Headquarters Building Transient Training
1113	1942	74-Man Barracks	Transient Training Enlisted Barracks
1114	1942	74-Man Barracks	Transient Training Enlisted Barracks

Fac. No.	Year Built	Original Use	Current Use
1116	1942	Type M – 152-Man Mess Hall	Physical Fitness Center
1117	1942	74-Man Barracks	Transient Training Enlisted Barracks
1118	1942	74-Man Barracks	Transient Training Enlisted Barracks
1129	1942	74-Man Barracks	Organizational Storage Building
1132	1942	Company Storehouse, Administration, and Recreation	Company Headquarters Building Transient Training
1133	1942	Company Storehouse, Administration, and Recreation	Skill Development (Na)
1153	1942	Standard Storehouse, Type SH-8	Organizational Storage Building
1154	1942	Standard Storehouse, Type SH-8	Organizational Storage Building
1232	1942	Company Storehouse, Administration, and Recreation	Organizational Storage Building
1233	1942	Company Storehouse, Administration, and Recreation	Company Headquarters Building Transient Training
1237	1942	Type M – 112-Man Mess Hall	Organizational Storage Building
1415	1942	Type M – 112-Man Mess Hall	Organizational Storage Building
1427	1942	Type M – 112-Man Mess Hall	General Instruction Building
1750	1942	Regimental Exchange Building	Organizational Storage Building
1866	1942	UNIT GUARD HOUSE – TYPE UGH-36	CONFINEMENT FACILITY
1869	1942	Recreation Building – Type RB-1	BATTALION HEADQUARTERS BUILDING
1950	1942	Interior Battalion Administration	Organizational Storage Building
2006	1942	Type M – 228-Man Mess Hall	Limit Use Instruction
2008	1942	Type M – 228-Man Mess Hall	Limit Use Instruction
2545	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
2550	1942	TYPE M – 248-MAN MESS HALL	COMPANY HEADQUARTERS BUILDING TRANSIENT TRAINING
2556	1942	G.U. Dispensary	Company Headquarters Building Transient Training
2557	1942	Recreation Building – Type RB-1	Auditorium General Purpose
2560	1942	Unit Guard House – Type UGH -36	Company Headquarters Building Transient Training
2563	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
2667	1942	Recreation Building – Type RB-1	Auditorium General Purpose
2762	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
2767	1942	Type M – 228-Man Mess Hall	Company Headquarters Building Transient Training
2872	1942	Unit Guard House – Type UGH-36	Company Headquarters Building Transient Training
2873	1942	G.U. Dispensary	Company Headquarters Building Transient Training
2876	1942	Recreation Building – Type RB-1	Auditorium General Purpose

* Inventory form for Building 550 was included in the *Determination of NRHP Eligibility for 26 Buildings at Fort McCoy, Wisconsin (2018)* report.

References

- Birnbaum, Charles A. *National Park Service Preservation Brief #36: Protecting Cultural Landscapes: Planning, Treatment and Management of Historic Landscapes*. Washington, DC: National Park Service. 1996.
- Garner, John S. *World War II Temporary Military Buildings; A Brief Historic of the Architecture and Planning of Cantonments and Training Stations in the United States* (USACERL TR CRC-93/01). Champaign, IL: USACERL. 1993.
- Grimmer, Anne E. *Secretary of the Interior's Standards for the Treatment of Historic Properties with Guidelines for Preserving, Rehabilitating, Restoring and Reconstructing Historic Buildings, Revised*, (Washington, DC: U.S. Department of the Interior, National Park Service, 2017),
<https://www.nps.gov/tps/standards/treatment-guidelines-2017.pdf>.
- HABS No. WI-308. "Fort McCoy (Camp McCoy)." (Washington, DC: Historic American Buildings Survey, National Park District, Department of the Interior, 1988). Catalogued by Library of Congress as HABS WIS, 41-SPAR.V, 1-:
<https://cdn.loc.gov/master/pnp/habshaer/wi/wi0200/wi0229/data/wi0229data.pdf>.
<https://cdn.loc.gov/master/pnp/habshaer/wi/wi0200/wi0229/data/wi0229data.pdf>.
- HABS No. WI-308-A. "Fort McCoy, Building T-1129, Sparta, Monroe County, Wisconsin." (Washington, DC: Historic American Buildings Survey, National Park District, Department of the Interior, 1988). Catalogued by Library of Congress as HABS WIS, 41-SPAR.V, 1-A-:
<https://cdn.loc.gov/master/pnp/habshaer/wi/wi0200/wi0261/data/wi0261data.pdf>.
- HABS No. WI-308-C. "Fort McCoy, Building T-801 (Storehouse, Administration & Recreation Building), Sparta vicinity, Monroe County, Wisconsin." (Washington, DC: Historic American Buildings Survey, National Park District, Department of the Interior, 1988). Catalogued by Library of Congress as HABS WIS, 41-SPAR.V, 1-B-: <https://cdn.loc.gov/master/pnp/habshaer/wi/wi0200/wi0262/data/wi0262data.pdf>.
- HABS No. WI-308-FD. "Fort McCoy, Building No. T-1555, Intersection of South Tenth Avenue & South "J" Street, Sparta, Monroe County, Wisconsin." (Denver, CO: Historic American Buildings Survey, National Park Service, Department of the Interior, 1988). Catalogued by Library of Congress as HABS, WIS, 41-SPAR.V, 1FD-: <https://cdn.loc.gov/master/pnp/habshaer/wi/wi0500/wi0557/data/wi0557data.pdf>.
- HABS No. WI-308-J. "Fort McCoy, Building T-2000 (Service Club)." (Washington, DC: Historic American Buildings Survey, National Park District, Department of the Interior, 1988). Catalogued by Library of Congress as HABS WIS, 41-SPAR.V, 1-J-7. Copy in unmarked wooden container in Meatlocker storage room, Building 2145, Fort McCoy, Wisconsin.
- HABS No. MD-1071-A. "Aberdeen Proving Ground, Company Administration Building (Building #4647)," Flare Loop, Aberdeen, Harford County, Maryland (Philadelphia, PA: Historic American Buildings Survey, National Park Service Northeast Region, Department of the Interior, 1988). Catalogued by Library of Congress as HABS MD 13-ABER, 2A-:
<https://cdn.loc.gov/master/pnp/habshaer/md/md1300/md1340/data/md1340data.pdf>.

- Loechl, Suzanne Keith, Susan I. Enscoe, Megan W. Tooker, and Samuel A. Batzli. *Guidelines for Identifying and Evaluating Historic Military Landscapes*. Champaign, IL: Construction Engineering Research Laboratory. 2009.
- Nelson, Lee H. *National Park Service Preservation Brief 17: Architectural Character-Identifying the Visual Aspect of Historic Buildings as an Aid to Preserving their Character*. Washington, DC: U.S. Department of the Interior, National Park Service. 1998. <http://www.nps.gov/tps/how-to-preserve/briefs/17-architectural-character.htm>.
- NPS. *National Register Bulletin #15: How to Apply the National Register Criteria for Evaluation*. Washington, DC: U.S. Department of the Interior, 1997 (rev.).
- Office of the Chief of Engineers [engineering manuals issued in chapters dated from March 1942 to February 1943]. Washington, DC: Corps of Engineers, 1942–43.
- _____. *National Register Bulletin #16A: How to Complete the National Register Registration Form*. Washington, DC: U.S. Department of the Interior, National Park Service, 1997.
- _____. *National Register Bulletin: How to Prepare National Historic Landmark Nominations*. Washington, DC: U.S. Department of the Interior, National Park Service, 1999.
- _____. *National Register Bulletin #30: Guidelines for Evaluating and Documenting Rural Historic Landscapes*. Washington, DC: US Department of the Interior, National Park Service. 1999.
- Smith, Adam D., and Sunny E. Adams. *Determination of NRHP Eligibility for 26 Buildings at Fort McCoy, Wisconsin* (ERDC-CERL TR-18-38). Champaign, IL: ERDC-CERL. 2018.
- Wasch, Diane Shaw, Perry Bush, Keith Landreth, and James Glass. *World War II and the U.S. Army Mobilization Program: A History of the 700 and 800 Series Cantonment Program*. Prepared for and funded by Legacy Resources Management Program. Washington, DC: Joint effort of HABS/HAER of National Park Service, Department of Interior; and DoD Legacy Resources Management Program of the Department of the Army Engineering and Housing Support Center, 24 March 1992. <http://archive.org/details/worldwariiusarmyOOwasc>.
- Weeks, Kay D. and Anne E. Grimmer. *Secretary of the Interior's Standards for the Treatment of Historic Properties with Guidelines for Treatment of Cultural Landscapes*. Washington, DC: U.S. Department of Interior, National Park Service. 1995.

Acronyms and Abbreviations

Term	Meaning
ACHP	Advisory Council on Historic Preservation
AT	annual training
CCC	Civilian Conservation Corps
CMTC	Citizens' Military Training Camp
CO HQ BLDG	Company Headquarters Building
CTR	Center
DoD	Department of Defense
DPW	Directorate of Public Works
ENL	Enlisted
ERDC-CERL	Engineer Research and Development Center – Construction Engineering Research Laboratory
FACIL	facility
FstFd/Snak Bar	fast food/snack bar
HABS	Historic American Buildings Survey
NARA	National Archives and Records Administration
NCSHPO	National Council of State Historic Preservation Officers
NHPA	National Historic Preservation Act
NPS	National Park Service
NRHP	National Register of Historic Places
PMOA	Programmatic Memorandum of Agreement
RADIOACT WH INS	radioactive storage, warehouse, installation
TT	transient training
USAR	U.S. Army Reserves
VEH STOR INST	vehicle storage building, installation
WWI	World War I
WWII	World War II

Conversion Factors

Multiply	By	To Obtain
acres	4,046.873	square meters
feet	0.3048	meters
inches	0.0254	meters
miles (U.S. statute)	1,609.347	meters
square feet	0.09290304	square meters
yards	0.9144	meters

REPORT DOCUMENTATION PAGE				<i>Form Approved</i> OMB No. 0704-0188	
<small>Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing this collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. PLEASE DO NOT RETURN YOUR FORM TO THE ABOVE ADDRESS.</small>					
1. REPORT DATE (DD-MM-YYYY) 11/01/2020		2. REPORT TYPE Final Technical Report (TR)		3. DATES COVERED (From - To)	
4. TITLE AND SUBTITLE Fort McCoy, Wisconsin WWII Buildings and Landscapes				5a. CONTRACT NUMBER	
				5b. GRANT NUMBER	
				5c. PROGRAM ELEMENT	
6. AUTHOR(S) Sunny E. Adams, Megan W. Tooker, and Adam Smith				5d. PROJECT NUMBER 474178	
				5e. TASK NUMBER	
				5f. WORK UNIT NUMBER	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Army Engineer Research and Development Center (ERDC) Construction Engineering Research Laboratory (CERL) PO Box 9005, Champaign, IL 61826-9005				8. PERFORMING ORGANIZATION REPORT NUMBER ERDC/CERL TR-20-12	
9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES) U.S. Army Garrison Fort McCoy 100 East Headquarters Road Fort McCoy, WI 54656-5263				10. SPONSOR/MONITOR'S ACRONYM(S)	
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)	
12. DISTRIBUTION / AVAILABILITY STATEMENT Approved for public release; distribution is unlimited.					
13. SUPPLEMENTARY NOTES					
14. ABSTRACT <p>The U.S. Congress codified the National Historic Preservation Act of 1966 (NHPA) mostly through the National Register of Historic Places (NRHP), which requires federal agencies to address their cultural resources. Section 110 of the NHPA requires federal agencies to inventory and evaluate their cultural resources, and Section 106 requires them to determine the effect of federal undertakings on those potentially eligible for the NRHP.</p> <p>This report provides a World War II development history and analysis of 786 buildings, and determinations of eligibility for those buildings, on Fort McCoy, Wisconsin. Evaluation of the WWII buildings and landscape concluded that there are too few buildings with integrity to form a cohesive historic district. While the circulation patterns and roads are still intact, the buildings with integrity are scattered throughout the cantonment affecting the historic character of the landscape. Only Building 100 (post headquarters), Building 656 (dental clinic), and Building 550 (fire station) are ELIGIBLE for listing on the NRHP at the national level under Criterion A for their association with World War II temporary building construction (1942-1946) and under Criterion C for their design, construction, and technological innovation.</p>					
15. SUBJECT TERMS Historic buildings--Conservation and Restoration, Historic sites--Wisconsin--Fort McCoy, National Register of Historic Places World War, 1939-1945					
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON
a. REPORT Unclassified	b. ABSTRACT Unclassified	c. THIS PAGE Unclassified			19b. TELEPHONE NUMBER (include area code)